

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6783J

DATE 27/11/2017

MAKE :

MODEL : HYUNDAI SONATA

Aigkia - LKsum

TS

LKE - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) X 2		\$ 38.00	\$ 76.00
	Rear Panel X 1			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Boot Lid Advertisement Logo ✓			\$ 100.00
	Rear No. Plate X			\$ 25.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Bumper Rubber Mat X			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓			\$ 200.00
				\$ 590.70
	Labour Charge			600
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,228.62

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.