

Signature

REF:

NS/INC17022671/Sgb02

## ASSIGNMENT

From:

Date:

Veh No:

SHB 1005A

Yr Regn:

7/5/2019

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Prius

c.c 1798

at Workshop m/s

Colour

Maroon

A/C: Insured / Std / NI / NA

of

Sp. Reading

526120

T/Radio: Insured / Std / NI / NA

Insured:

STY 749561

Eng/No:

Policy No.

BD4987029-06

230317-220318

C/No:

JIDKN 364405741816

Claims No.

MT/0971131-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

2 days

Res.: Yes or No

D.O.A. 24/11/2017

D.O.I. 24/11/2017

Lum Sum:

20 %

3 Val.: Yes or No

Survey held at

SMART

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHB 1005A - NS/INC15009510/Klg02

DA-060615

TA x/11/17/2153

STY 749561 - X

LKK.

13/12/17 4s \$ 1700

Cred: 5267, 1670.

NTUC

RECEIVED 14 DEC 2017

RECEIVED 20 DEC 2017

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

2

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

160

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

TP

Lump Sum / I.B.I: (\$

1700

TOTAL

149



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022671/Sgb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 29-11-2017

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |               |                |            |
|--------------|---------------|----------------|------------|
| Insured Veh. | SFY 7495G     | Veh. Inspected | SHB 1005A  |
| Policy No.   | 5049820229-06 | Coverage (\$)  | 0.00       |
| Claim No.    |               | Excess (\$)    | 0.00       |
| Assign From  |               | Assign Date    | 27/11/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 24/11/2017   | Inspection Date | 27/11/2017 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |            |

## 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

# TP Claims against NTUC Income: Follow-Through Survey

Date : 13/12/2017

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. | Date of Accident | Time of Accident | Estimate     |
|------|------------------|---------------------------------|----------------------|--------------------|------------------|------------------|--------------|
| 1    | MT/0971131-002   | SMRT TAXI PTE LTD               | SHB 1005A            | SFY 7495G          | 24/11/2017       | 16:50            | \$ 6,967.00  |
| 2    | MT/0970855-002   | SMRT TAXI PTE LTD               | SHF 176A             | SGW 996Y           | 22/11/2017       | 20:20            | \$ 15,532.24 |
| 3    | MT/0972945-002   | SMRT TAXIS PTE LTD              | SHD 6350J            | SKZ 3420J          | 6/12/2017        | 23:10            | \$ 5,696.39  |
| 4    | MT/0973546-001   | SMRT TAXIS PTE LTD              | SHB 1700B            | FBG 5631K          | 3/12/2017        | 21:40            | \$ 5,235.70  |

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)

| Select                           | Policy No.    | Policyholder Name | Policyholder NRIC | Product | Cover Type                | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|----------------------------------|---------------|-------------------|-------------------|---------|---------------------------|-------------|----------------|---------------|-------------|
| <input checked="" type="radio"/> | 5049820229-06 | KAJI THAPA        | S1205693A         | GPC     | Third Party, Fire & Theft | SFY7495G    | SFY7495G       | 23/03/2017    | 22/03/2018  |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                     |
|----------------------------|-------------------------------------|
| Date Of Report             | 25/11/2017 08:59                    |
| Date Of Accident           | 24/11/2017 16:50                    |
| Exact Location Of Accident | NICHOLL HIGHWAY TOWARDS SHENTON WAY |
| Country/State of Loss      | SINGAPORE                           |

### DETAILS OF OWN VEHICLE

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | SHB1005A           |
| <b>Insured/Policyholder</b> |                    |
| Name Of Registered Owner    | SMRT TAXIS PTE LTD |
| Co Reg No                   | 198905369K         |
| Email Address               | NOEMAIL            |
| Mobile Phone No             |                    |
| Alternative Phone No        | OFFICE-80000000    |

### Vehicle Particulars

|  |                    |
|--|--------------------|
| Manufacturer   | TOYOTA             |
| Model  | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | HIRE AND REWARD    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category   | TAXI               |

### Insurance Company

|                           |                               |
|---------------------------|-------------------------------|
| Name of Insurance Company | FIRST CAPITAL INSURANCE LTD   |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy              | YES                           |
| Policy Number             | D-17087562MFSH                |
| Cover Note Number         |                               |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LOON PENG PUI         |
| NRIC No              | S1610130C             |
| Date Of Birth        | 29/09/1963            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 07/07/1988            |
| Driving Experience   | 29 YEARS AND 4 MONTHS |
| Gender               | MALE                  |
| Mobile Number        |                       |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | NOEMAIL               |

Address  
Postcode  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
Weather Conditions RAINING  
Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING STRAIGHT IN MY LANE ALONG NICHOLL HIGHWAY TOWARDS SHENTON WAY WITH ONE PASSENGER (MALE INDIAN) ON BOARD. SUDDENLY A VEHICLE SFY7495G CUT TOWARDS MY LANE FROM THE RIGHT AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: FILE TOO LARGE  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFY7495G  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver KAJI THAFA  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

## Sketch Plan Pg. 1

### SKETCH PLAN

Nicoll Highway towards Shenton Way

A- SHB100SA

B-SFY7495G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

Date & Time: 25/11/17 0900H

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN

Nicoll Highway towards Shenton Way

A-5HB100SA

B-SFY7495G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

لا اله الا الله محمد بن عبد الله

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 25/11/17 0900H

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



## Enquire PARF/COE Rebate for Registered Vehicle

|   |                                      |
|---|--------------------------------------|
| <b>Vehicle Owner Particulars</b>  |                                      |
| Owner ID Type   | Company                              |
| Owner ID  | 5369K                                |
| <b>Vehicle Details</b>  |                                      |
| Vehicle No.   | SHB1005A                             |
| Vehicle to be Exported  | No                                   |
| Intended De-registration Date   | 28 Nov 2017                          |
| Vehicle Make  | TOYOTA                               |
| Vehicle Model   | PRIUS TAXI (SMRT)                    |
| Primary Colour  | Maroon                               |
| Manufacturing Year  | 2014                                 |
| Engine No.  | 2ZR6013895                           |
| Chassis No.   | JTDKN36U405741826                    |
| Maximum Power Output  | 100.0 kW (134 bhp)                   |
| Open Market Value   | \$33,120.00                          |
| Original Registration Date  | 07 May 2014                          |
| First Registration Date   | 07 May 2014                          |
| Transfer Count  | 0                                    |
| Actual ARF Paid   | \$8,368.00                           |
| <b>Intended PARF Rebate Details</b>   |                                      |
| PARF Eligibility  | Yes                                  |
| PARF Eligibility Expiry Date  | 06 May 2022                          |
| PARF Rebate Amount  | \$6,276.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date   | 06 May 2022                          |
| COE Category  | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years)   | 8                                    |
| PQP Paid  | \$60,414.00                          |
| COE Rebate Amount   | \$33,517.00                          |
| <b>Total Rebate Amount</b>  | <b>\$39,793.00</b>                   |
| <b>Message</b>  |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 28 Nov 2017



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

## SMRT Accident Vehicle Repair Estimates

NTUC

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1005A  
 Ref. No : TAX/11/17/2153  
 Reg. Date : 07/05/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : LOON PENG PUI  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 24/11/2017 04:50:00 PM  
 Accident Reported Date / Time : 25/11/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093287  
 Special Instruction to ARC, if any :  
 SFY7495G - NTUC IDAC  
 Prepared Date : 25/11/2017 09:20:49 AM



Sebastian.  
 27/11/2017.  
 - Lump Sum Repair.  
 - Question Mark Item  
 Photo  
 - Photo After Paint.

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405741826

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC     | Adjusted by Surveyor, if applicable |
|------------------------------|------------------------|-------------------------------------|
| Total Labour Charges         | 676.00                 | 0.00                                |
| Total Spray Painting Charges | 1,116.00               | 0.00                                |
| Total Material Charges       | 2,089.58               | 2,812.82                            |
| Other Charges                | 500.00                 | 0.00                                |
| <b>TOTAL</b>                 | <b>4,381.58</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>4,400.00</b>        | <b>0.00</b>                         |
| No. of Repair Days           | 5.00                   | 0.00                                |
| Prepared / Adjusted By       |                        | 2 days                              |
| Arc / Surveyor Sign Off Date | 25/11/2017 11:31:44 AM | 01/01/1900 12:00:00 AM              |

Prepared / Adjusted Date

Remarks

Prepared Date : 25/11/2017 11:31:44 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

# Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------|--------------------|-------------------------------------|
| TO REPAIR RH PORTION | 676.00             | 0.00 300                            |
| <b>Total Labour</b>  | <b>676.00</b>      | <b>0.00</b>                         |

## Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                         | 378.00             | 0.00 200                            |
| TO RESPRAY FRONT FENDER RH                      | 378.00             | 0.00 200                            |
| TO RESPRAY VIEW MIRROR                          | 180.00             | 0.00 50                             |
| TO RESPRAY RIM                                  | 180.00             | 0.00 50 X                           |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,116.00</b>    | <b>0.00</b>                         |

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00             | 0.00 30                             |
| TO REMOVE AND REFIX WING MIRROR         | 120.00 ?           | 0.00                                |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING  | 120.00             | 0.00 60                             |
| TO REPLACE SUNDRY PARTS                 | 100.00             | 0.00 20                             |
| TO WASH AND VACUUM                      | 60.00              | 0.00 X                              |
| <b>Total Other Costs</b>                | <b>500.00</b>      | <b>0.00</b>                         |

# Part 4 - Spare Parts / Material Usage

| Part Number                 | Portion | Stock No | Part Name               | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation   | Surveyor Approved  | Photos Attached |
|-----------------------------|---------|----------|-------------------------|-----|-----------------|--------------|------------------|----------------------|--------------------|-----------------|
| 52119-47930                 |         | 6505517  | BUMPER FRT              | 1   | 482.00          | 25.00        | 361.50           | Repair <i>R</i>      | Replace            | No              |
| 53801-47050                 |         | 6505557  | FENDER FRT/RH           | 1   | 723.40          | 25.00        | 542.55           | Repair               | Replace            | No              |
| 75374-47051                 |         |          | NAME PLATE (HYBRID)     | 1   | 51.90           | 25.00        | 38.92            | Replace <i>✓</i>     | Replace <i>NEC</i> | No              |
| 53875-47030                 |         | 6505553  | FENDER LINER FRT/RH     | 1   | 171.70          | 25.00        | 128.77           | Replace <i>?</i>     | Replace            | No              |
| 42611-47140 (Frt)           |         | 6505658  | WHEEL DISC. FRONT       | 1   | 1,484.20        | 25.00        | 1,113.15         | Replace <i>✓ Ant</i> | Replace            | No              |
| 87910-47330                 |         | 6505600  | MIRROR ASSY, RH         | 1   | 1,307.10        | 25.00        | 980.32           | Replace <i>?</i>     | Replace            | No              |
| 879157-4010                 |         | 6505598  | COVER, OUTER MIRROR, RH | 1   | 107.40          | 25.00        | 80.55            | Replace <i>✓ MS</i>  | Replace            | No              |
| 81730-52090                 |         | 6505466  | MIRROR LAMP RH          | 1   | 65.30           | 10.00        | 58.77            | Replace <i>?</i>     | Replace            | No              |
| 87931-47200                 |         |          | MIRROR GLASS RH         | 1   | 212.80          | 25.00        | 159.60           | Replace <i>X</i>     | Replace            | No              |
| 75710-47021                 |         |          | DOOR BELT FRT/RH        | 1   | 69.20           | 25.00        | 51.90            | Replace <i>X</i>     | Replace            | No              |
| TOTAL MATERIALS             |         |          |                         |     |                 |              |                  | 2,612.00             | 3,516.03           |                 |
| TOTAL MATERIALS(Discounted) |         |          |                         |     |                 |              |                  | 2,089.58             | 2,812.82           |                 |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number                   | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS |         |           |     |                 |              |                  |           |                |          |


6917



# SMRT Accident Vehicle Repair Estimates

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1005A  
 Ref. No : TAX/11/17/2153  
 Reg. Date : 07/05/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : LOON PENG PUI  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 24/11/2017 04:50:00 PM  
 Accident Reported Date / Time : 25/11/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093287  
 Special Instruction to ARC, if any :



SFY7495G - NTUC IDAC  
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121  
 LUMPSUM REPAIR

Prepared Date : 25/11/2017 09:20:49 AM

29/11/17 13.45 QC Reject mirror cover  
 16.35 PA SS Paint Peel

526120 KM

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1<sup>st</sup> witness

Date 22-11-17

2<sup>nd</sup> witness

Date

Supplementary

\* Refer to the Supplementary part 11/17

526187

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 29/11/2017

Vehicle Return Time: 11:36

SMRT staff sign: \_\_\_\_\_



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405741826


Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 676.00                 | 300.00                              |
| Total Spray Painting Charges | : 1,116.00               | 450.00                              |
| Total Material Charges       | : 1,536.31               | 1,291.39                            |
| Other Charges                | : 500.00                 | -341.39                             |
| <b>TOTAL</b>                 | <b>: 3,828.31</b>        | <b>1,700.00</b>                     |
| Lum Sum Total                | : 0.00                   | 0.00                                |
| No. of Repair Days           | : 5.00                   | 2.00 /                              |
| Prepared / Adjusted By       | :                        | SEBASTIAN (LKK)                     |
| Arc / Surveyor Sign Off Date | : 25/11/2017 11:31:44 AM | 27/11/2017 02:45:03 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/11/2017 11:31:44 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1712-0255

Invoice No :

Quotation Date : 11/12

Invoice Date :

Invoice Amount :

Prepared Date :

# Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------|--------------------|-------------------------------------|
| TO REPAIR RH PORTION | 676.00             | 300.00 /                            |
| <b>Total Labour</b>  | <b>676.00</b>      | <b>300.00</b>                       |

## Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                         | 378.00             | 200.00 /                            |
| TO RESPRAY FRONT FENDER RH                      | 378.00             | 200.00 /                            |
| TO RESPRAY VIEW MIRROR                          | 180.00             | 50.00 /                             |
| TO RESPRAY RIM                                  | 180.00             | 0.00                                |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,116.00</b>    | <b>450.00</b>                       |

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00             | 30.00 /                             |
| TO REMOVE AND REFIX WING MIRROR         | 120.00             | 0.00                                |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING  | 120.00             | 60.00 /                             |
| TO REPLACE SUNDRY PARTS                 | 100.00             | 20.00 /                             |
| TO WASH AND VACUUM                      | 60.00              | 0.00                                |
| Lump Sum Adjustment by Surveyor         | 0.00               | -451.39                             |
| <b>Total Other Costs</b>                | <b>500.00</b>      | <b>-341.39</b>                      |

6967.00

# Part 4 - Spare Parts / Material Usage

| Part Number                 | Portion | Stock No | Part Name               | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached        |
|-----------------------------|---------|----------|-------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|------------------------|
| 52119-47930                 |         | 6505517  | BUMPER FRT              | 1   | 482.00          | 100.00       | 0.00             | Repair             | Repair            | No <i>✓</i>            |
| 53801-47050                 |         | 6505557  | FENDER FRT/RH           | 1   | 723.40          | 100.00       | 0.00             | Repair             | Repair            | No <i>✓</i>            |
| 75374-47051                 |         |          | NAME PLATE (HYBRID)     | 1   | 51.90           | 25.00        | 38.92            | Replace            | Replace           | No <i>✓</i> <i>NEC</i> |
| 53875-47030                 |         | 6505553  | FENDER LINER FRT/RH     | 1   | 171.70          | 25.00        | 128.78           | Replace            | Check             | No <i>✓</i> <i>NW</i>  |
| 42611-47140 (Frt)           |         | 6505658  | WHEEL DISC. FRONT       | 1   | 1,484.20        | 25.00        | 1,113.15         | Replace            | Replace           | No <i>✓</i> <i>unt</i> |
| 87910-47330                 |         | 6505600  | MIRROR ASSY, RH         | 1   | 1,307.10        | 25.00        | 980.33           | Replace            | Check             | No <i>✓</i> <i>NW</i>  |
| 879157-4010                 |         | 6505598  | COVER, OUTER MIRROR, RH | 1   | 107.40          | 25.00        | 80.55            | Replace            | Replace           | No <i>✓</i> <i>MS</i>  |
| 81730-52090                 |         | 6505466  | MIRROR LAMP RH          | 1   | 65.30           | 10.00        | 58.77            | Replace            | Replace           | No <i>✓</i> <i>CRK</i> |
| 87931-47200                 |         |          | MIRROR GLASS RH         | 0   | 212.80          | 25.00        | 0.00             | Replace            | Not given         | No <i>✓</i> <i>NW</i>  |
| 75710-47021                 |         |          | DOOR BELT FRT/RH        | 0   | 69.20           | 25.00        | 0.00             | Replace            | Not given         | No <i>✓</i>            |
| TOTAL MATERIALS             |         |          |                         |     |                 |              | 2,400.50         | 1,291.39           |                   |                        |
| TOTAL MATERIALS(Discounted) |         |          |                         |     |                 |              | 1,536.31         | 1,291.39           |                   |                        |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number                   | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS |         |           |     |                 |              |                  |           |                |          |

1291.39  
 + 300.00  
 + 560.00

2151.39

- 20%

1721.11

US \$1700/-

Sebastian  
 13/12/2017



Thatcham escribe


## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



|  |  |                 |                  |   |
|--|--|-----------------|------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022671/Sgbe2   |  |                 |                  |   |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556   |  |                 | Date: 08-01-2018 |  |
|  |  |                 | Code: INC4       |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |                  |   |
| Insured Veh.   | SFY 7495G  | Veh. Inspected  | SHB 1005A        |   |
| Policy No.   | 5049820229-06  | Coverage (\$)   | 0.00             |   |
| Claim No.  | MT/0971131-002   | Excess (\$)     | 0.00             |   |
| Assign From  |  | Assign Date     | 27/11/2017       |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |                  |   |
| Make & Model   | TOYOTA PRIUS   | c.c             | 1798             |   |
| Engine No.   | HIDDEN   | Year of Reg.    | 2014             |   |
| Chassis No.  | JTDKN36U405741826  | Colour          | MAROON           |   |
| Odometer   | 526120   | Steering        | IN ORDER         |   |
| Brakes   | IN ORDER   | Modification    | NIL              |   |
| General  | FAIR   |                 |                  |   |
| <b>3. Conditions of Tyres</b>  |  |                 |                  |   |
|  | Size   | Make            | Balance          |   |
| R/H Front Tyre   | 195/65 R15   | FALKEN          | 6 mm             |   |
| L/H Front Tyre   | 195/65 R15   | FALKEN          | 6 mm             |   |
| R/H Rear Tyre  | 195/65 R15   | FALKEN          | 6 mm             |   |
| L/H Rear Tyre  | 195/65 R15   | FALKEN          | 6 mm             |   |
| <b>4. Description of Damages</b>   |  |                 |                  |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br>DAMAGES SEE DETAILS.   |  |                 |                  |   |
| <b>5. General Information</b>  |  |                 |                  |   |
| Accident Date  | 24/11/2017   | Inspection Date | 27/11/2017       |   |
| Survey held at   | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |                  |   |
| <b>5a. Remarks</b>   |  |                 |                  |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                  |   |
| <b>5b. Estimate Days of Repair</b>   |  |                 |                  |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 2 Working Days  |                  |   |

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1005A**

| Qty   | Description of Parts                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>   |   |               |                           |                   |
| 1   | NAME PLATE (HYBRID) (DISC 25%)                        | NECESSARY     | 51.90                     | 38.92             |
| 1   | WHEEL DISC FRONT (DISC 25%)                           | CUT           | 1,484.20                  | 1,113.15          |
| 1   | COVER, OUTER MIRROR, RH (DISC 25%)                    | MISSING       | 107.40                    | 80.55             |
| 1   | MIRROR LAMP RH (DISC 10%)                             | CRACKED       | 65.30                     | 58.77             |
| 1   | FENDER LINER FRT/RH                                   | NOT NECESSARY | 171.70                    | -                 |
| 1   | MIRROR ASSY, RH                                       | NOT NECESSARY | 1,307.10                  | -                 |
| 1   | MIRROR GLASS RH                                       | NOT NECESSARY | 212.80                    | -                 |
| 1   | DOOR BELT FRT / RH                                    | NOT NECESSARY | 69.20                     | -                 |
| 1   | BUMPER FRT  | TO REPAIR     | 482.00                    | -                 |
| 1   | FENDER FRT / RH                                       | TO REPAIR     | 723.40                    | -                 |
|   |   |               | 4,675.00                  | 1,291.39          |
| <b>LABOUR</b>   |   |               |                           |                   |
|   | THATCHAM STANDARD REPAIR TIME ON BODY WORKS.          |               | 916.00                    | 360.00            |
|   | THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR. |               | 1,216.00                  | 480.00            |
|   | TO REPLACE SUNDRY PARTS.                              |               | 100.00                    | 20.00             |
|   | TO WASH AND VACUUM.                                   | NOT NECESSARY | 60.00                     | -                 |
|   |   |               | 2,292.00                  | 860.00            |
| <b>GRAND TOTAL</b>  |   |               | <b>6,967.00</b>           | <b>2,151.39</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b> |   |               |                           | <b>1,700.00</b>   |

Report Ref No. NS/INC17022671/Sgbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.