

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 4564Y

DATE 28/11/2017 10:34

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) <i>Repair</i>			\$ 29.20
	Front Bumper Bracket (RH) ?			\$ 20.10
	Headlamp (RH) ✕			\$ 797.90
	Front Fender (RH) ✕ <i>Repair</i>			\$ 593.00
	Front Fender Shield (RH) ✕			\$ 86.00
	Front Fender Retainer ✕			\$ 9.20
	<b>SUB TOTAL</b>			<b>\$ 2,096.60</b>
	<b>LESS 20%</b>			<b>\$ 419.32</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,677.28</b>
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>560.00</del> 400
	Spray Painting Charge			\$ <del>400.00</del> 360
	Wiring Charge			\$ <del>50.00</del> ✕
	Tuff Kote			\$ <del>50.00</del> ✕
	<b>TOTAL LABOUR</b>			<b>\$ 1,060.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,837.28</b>
<p><i>1/Calvin 10/11/17</i></p> <p><i>✓ 28/11/17 1100hrs.</i></p> <p><i>2 Days</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				