

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 44972**  
Date Estimated : **27/11/2017**  
Prepared By : **Han Kwan Yong**

Page No. :

**REPAIR FOR -**  
**Stephanie Yong Chin Yee**  
**1 FARRER ROAD**  
**#12-05**  
**TULIP GARDEN**  
**Singapore 268817**

**- ACCOUNT - 66**  
**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJS9838Y	C228630	24/07/2009	525iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To replace front bumper and attachments, front RH fender include knocking out dented areas caused by the accident	1770.00		1,770.00
---	---------	--	----------

To respray front bumper and front RH fender	1730.00		1,730.00
---	---------	--	----------

To carry out body cavity preservation. (Per panel).	100.00		100.00
--	--------	--	--------

To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00
---	--------	--	--------

To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function	150.00		150.00
--	--------	--	--------

To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00
--	--------	--	--------

Sundries.	80.00		80.00
-----------	-------	--	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

FRT RH FENDER	800.15	1.00		800.15
# FRT BUMPER RH SIDE BKT *	17.70	1.00		17.70
FRT BUMPER W/PDC (-M-)	1,346.10	1.00		1,346.10
RIVET	0.45	10.00		4.50

### # SUPPLEMENTARY ITEMS

Total Labour :	4,431.00
Total Parts :	2,168.45
Total Labour & Parts :	6,599.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,599.45
GST @7%:	461.96
Grand Total :	7,061.41