

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/112017/3476**Accident date** : 25/11/2017**Your Ref** : SJV8729U**Invoice No.:****Date** : 28/11/2017

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel: 6419 3000

Not Authorised
Libby B 7
Penny Allen Paim
9claps

ESTIMATE COST OF REPAIRS TO TOYOTA CAMRY SJP8504H

1	pc	Front bumper	<i>Pr</i>	\$	486.70	✓
1	pc	Front bumper reinforcement		\$	421.74	?
1	pc	Front bumper sponge		\$	97.16	?
1	pc	Front bumper LH fog lamp	<i>Pr</i>	\$	248.52	X
1	pc	Front bumper LH fog lamp moulding	<i>Pr</i>	\$	101.90	X
1	pc	Front bumper LH fog lamp cover	<i>Pr</i>	\$	48.05	X
1	pc	Front bumper lower grille	<i>Di</i>	\$	77.63	✓
1	pc	Front radiator grille	<i>CM</i>	\$	446.13	✓
1	pc	Front LH headlamp		\$	737.37	?
1	pc	Front number plate holder	<i>Pr</i>	\$	71.10	✓
1	pc	Rear bumper	<i>CM</i>	\$	530.50	✓
1	pc	Rear bumper reinforcement	<i>R</i>	\$	420.00	X
1	pc	Rear bumper LH retainer	<i>Di</i>	\$	56.90	✓
1	pc	Rear bumper LH reflector		\$	56.90	?
1	pc	Rear LH lamp		\$	501.20	?
1	pc	Rear LH fender	<i>R</i>	\$	911.40	✓
1	pc	Rear LH fender air dust		\$	135.40	?
1	pc	Rear LH fender inner trim	<i>Pr</i>	\$	361.60	X
1	pc	Rear windscreen moulding		\$	88.20	✓
1	pc	Rear LH door	<i>R</i>	\$	950.16	✓
1	pc	Rear LH door protector	<i>R</i>	\$	80.10	✓
1	pc	Rear LH door regulator		\$	218.00	?
1	pc	Rear LH door regulator motor		\$	647.80	?
1	pc	Rear LH door rubber		\$	175.80	<i>Scdn</i>
		Balance c/f		\$	7,870.26	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref: TP/112017/3476

Page 2

	Balance b/d		\$ 7,870.26
1	pc	Rear LH door inner trim	\$ 733.20 ?
1	pc	LH rocker garnish	\$ 384.22 ?
1	pc	Rear LH wheel sport rim	<i>nd</i> \$ 731.30 ✓
1	pc	Rear LH wheel tyre	<i>Pr</i> \$ 210.00 <i>Polin</i>
1	pc	Rear LH shock absorber	\$ 384.90 ?
1	pc	Rear LH knuckle arm	<i>R</i> \$ 479.80 ✓
1	pc	Rear LH knuckle arm bearing	<i>m</i> \$ 750.00 ✓
1	pc	Rear LH lower arm	\$ 212.00 ?
1	pc	Rear LH side control arm (F)	\$ 276.00 ?
1	pc	Rear LH side control arm (R)	\$ 207.00 ?
			<u>\$ 12,238.68</u>
	Less: 25%		<u>\$ (3,059.67)</u>
			<u>\$ 9,179.01</u>
1	pc	Front number plate	<i>nd</i> \$ 40.00 N ✓
1	pc	Rear windscreen gum	<i>nd</i> \$ 60.00 N <i>40.00</i>
	To towing		<i>(Bill)</i> \$ 120.00 <i>60.00</i>
	To remove and refix rear glass		\$ 150.00 <i>120.00</i>
	To remove and refix seat cushion & roof lining		\$ 150.00 <i>120.00</i>
	To remove and refix rear undercarriage		\$ 180.00 <i>150.00</i>
	To check wheel alignment		\$ 90.00 <i>60.00</i>
	To repair front & side damages		\$ 1,200.00 <i>1000.00</i>
	To spray painting		\$ 1,200.00 <i>1100.00</i>
	To spray tuff kote		\$ 250.00 <i>60.00</i>
			<u><u>\$ 12,619.01</u></u>

VIN'S MOTOR PTE LTD