Weekend (\$

TOTAL

Lump Sum / I.B.I: (\$



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		12 - Village and Company and Company	nationale Des Experts En Auton	
CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI17022	709/Kha3
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 29-11-2017 Code: CTI	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	GBE 5197H	Veh. Inspected	SHB 7536U
	Policy No.	DMCVSN1686191600	Coverage (3)	0.00
	Claim No.	SNM17D06789C02	Excess (\$)	0.00
	Assign From		Assign Date	29/11/2017
2.		Vehicle P	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Cdometer		Steering	
	Brakes		Modification	
	General			
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damaç 95	
5.		Ge	neral Information	
٠.	Accident Date	24/11/2017	Inspection Date	28/11/2017
	Survey held at	TRANS-CAB AUTO SERVI	CES PTE LTD	
	July now we	NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref:

TBA

Date:

29.11.2017

Our ref:

CC3/CTI17022709/Kha3

The Motor Claims Department

M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 7536U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>28.11.2017</u> at the premises of <u>M/s Trans-Cab Auto Services Pte Ltd (Ang Mo Kio)</u> and have the following to report:-

Workshop Estimate Amount	: S\$	16,758.94
Revised Estimate Amount	: S\$	2,777.94
"Check" Items Amount	: S\$	57/2
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	1.0
Nett Value	: SS	

Description of Di mage:

The vehicle sustained damages at the

N/S Front Portion

rear Incarable Prori

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

2.0 days

Yours faithfully,

KENNETH KONG

Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3878K
Vehicle Details	
Vehicle No.	SHB7536U
Vehicle to be Exported	Yes
Intended De-registration Date	27 Nov 2017
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2 ODSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour	Red
Manufacturing Year	2011
Engine No.	Z20S1450917K
Chassis No.	KL1LA69RJBB077076
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$14,361.00
Original Registration Date	13 Mar 2012
First Registration Date	13 Mar 2012
Transfer Count	0
Actual ARF Paid	\$14,361.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Mar 2020
PARF Rebate Amount	\$10,052.00
Intended COE Rebate Details	
COE Expiry Date	12 Mar 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
PQP Paid	\$40,962.00
COE Rebate Amount	\$11.715.00
Total Rebate Amount	\$21,767.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Nov 2017

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330 CO/GST REG NO. 201019626G

SHB7536U - CHINA TAIPING

Not Northern 8 22001

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHB7536U - CANDY

KL1LA69RJBB077076

CHEVROLET

CHEVROLET EPICA 2.0

24.11.2017

CHINA TAIPING

PART	LIST

1	1	Front Bumper	\$	CPM 1,202.00
2	1	Front Bumper Reinforcement	\$	295.25
3	1	Front Bumper Lower Absorber	\$	√ 180.00
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	July 32.40
5	1	Front Bumper Lower Grille	\$	78.00
6	1	Front Bumper Lower Stiffener	\$	134.37
7	1	Front Bumper Retainer LH	5	Ne 102.00 /X
8	1	Front Headlamp LH	5	A 816.00
9	1	Front Support Panel Assy	s	1,222.32
10	1	Bonnet	S	1,250.00
11	1	Bonnet Moulding	5	161.97
12	1	Front Shock Absorber Assy LH	\$	J 216.17
13	1	Front Lower Arm LH	\$	283.00
14	1	Front Knuckle Arm LH	5	230.00
15	1	Side Rocker Panel Garnish LH	5	236.40
16	1	Front Fender LH	\$	P₂ 837.60 —
17	1	Front Fender Liner LH	\$	P. / 47.00
18	1	Resonator (B/S Fender LH) AIR BOX	\$	134.67
19	1	Resonator Hose	\$	54 37.00 x
20	1	Radiator Grille (Grille A-Rad)	\$	55 367.00 ¥
21	1	Front Door LH	\$	7 1,133.00 /
22	1	Front Side View Mirror LH	S	√L 939.00 X

TOTAL	\$ 9,935.15
10%	\$ 993.52
1	\$ 8,941.64

Specical Nett

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330 CO/GST REG NO. 201019626G

SHB7536U - CHINA TAIPING

2 1	Set	Front licence plate with holder	\$	J₁ 192.00 ×
		Radiator Grille Top Cover Clip	5	~~ 10.00 /
4 1	Set	Radiator Grille clip	5	22 35.00 /
5 1	Set	Front Fender Liner Clip	5	ME 30.00 -
6	1	Door Sticker "Trans-cab"	5	12 80.00 X
7	1	Front Tyre LH	s	√h 360.00 ×
8	1	Front Wheel Rim LH	\$	∫ 254.00 ×
9	1	Front Wheel Rim Hub Cap LH	S	∫4 166.30 K
		TOTAL	\$	1,157.30
		TOTAL PARTS	\$	10,098.94
		Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00
		To Rust-Proofing Of The Affected Areas.	\$	220.00 3
		Putty and Spray Painting Of The Affected		400
		Portion.	\$	2,700.00
		To Check Electrical Lighting Concerned.	\$	170.00 10
		To check steering geometry and computer wheel		
		alignment	\$	12 220.00 X
		To transfer of tire, rim and on wheel balancing.	\$	12 170.00 X
		To dismantle and refit front end suspension,		4
		undercarriage parts, final checking and testing.	S	22380.00 X
Y LOCA		TOTAL	S	6,660,00

LKK Auto Committees process		TOTAL	S	6,660.00
the Repairer of the following: • To resurvey below that some parties	900:	Over All Total	\$	16,758.94
To deplay during a part of the part of the parts are a part of the parts	REPAIR DAYS		ily si	2019,
A subject to their approvement and inquire Administratory by Republic Signature Dates	a contag			

Vic (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg> Wednesday, 21 February, 2018 3:55 PM

Sent: To:

Vic (LKKAuto)

Cc:

'Jasmine Tan'; claims@transcab.com.sg; Admin A

Subject:

RE: Your Ref: AAD1711-291 ACCIDENT INVOLVINH VEHICLES GBE 5197H AND SHB

7536U ON 24.11.17

Attachments:

AAD1711-291 - DV.pdf

WITHOUT PREJUDICE

Dear Vic

Attach duly signed DV for your action.

Original hard copy will mailed to you by post.

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]

Sent: Tuesday, 20 February, 2018 11:37 AM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>

Cc: claims@transcab.com.sg; 'Jasmine Tan' <jasminetan@transcab.com.sg>; Admin A <admin-a@lkkauto.com>; Vic

(LKKAuto) <vicalpeh@lkkauto.com>

Subject: Your Ref: AAD1711-291_ACCIDENT INVOLVINH VEHICLES GBE 5197H AND SHB 7536U ON 24.11.17

Your Ref: AAD1711-291

Without Prejudice

Our Ref: CC3/CTI17022709/Kha3

Dear Wai Yin,

ACCIDENT INVOLVINH VEHICLES GBE 5197H AND SHB 7536U ON 24.11.17

We refer to the above matter and we confirmed in receipt of the LOD dated 08/02/2018.

The matter was settled during the RTM at your good office on 25/01/2018 on a 50/50 basis at a global sum of \$1,310.00 (all in).

Kindly chop and sign the enclosed DV and forward back the original signed hard copy to us for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: <u>vicalpeh@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IKK Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref

: AAD1711-291

Your Ref

: GBE5197H

Date

: 08.February 2018

CHINA TAIPING INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHB7536U AND GBE5197H ON 24/11/17 02:15 PM ALONG RAFFLES BOULEVARD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below:-

1.	Cost of Repair (inclusive of 7% GST)	\$	2,354.00
2.	Loss of Rental for _ days @ \$ 75-35 per day	\$	150.50
3.	Loss of Income for days @ \$ per day	\$	100.00
4.	LTA Search Fee	\$	5.35
5.	Survey Fee	S	0.00
	Total	\$	2,609.85

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No.: 6603 1250 (DID)

Note: Please email any further correspondence to claims@transcab.com.sg (6603 1259)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC3/CTI17022709/Kha3

07 DECEMBER 2017

M/S DESHIN ENGINEERING & CONSTRUCTION PTE LTD

4 KAKI BUKIT VIEW SINGAPORE 415943

ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 5197H AND SHB 7536U ON 24/11/2017

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 18/12/2017, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh Case Handler DID: 6841 2096 FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd (Motor Claims Dept)

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHB7536U and GBE5197H along RAFFLES BOULEVARD on 24/11/17 02:15 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 8 (day) of February 2018

Yours Faithfully Trans-Cab Services Pte Ltd

Jasmine Tan General Manager To: vic

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN1686191600

Claim No :SNM17D06789/C02/7

Claimant : TRANS-CAB SERVICES PTE LTD

Amount : \$\$1,310.00

SINGAPORE DOLLARS ONE THOUSAND THREE HUNDRED TEN ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : 5HB 7536U Insured Vehicle No. : GBE 5197H

Date of Loss

: 24/11/2017

Place of Accident : RAFFLES BOULEVARD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

: M/S DESHIN ENGINEERING & CONSTRUCTION PTE LTD

Driver Name

: HOON MOW SING

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE, LTD.

(1) Global Sum (all in)

1,310.00 SS

1,310.00

LEWIS 1 - 50 - 19 54 -30 NRIC No : Claimant Name: . 20 FEB 2018

Signature

Date

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

Co. Reg. No.: 201019626G GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO:

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#15-02 SPRINGLEAF TOWER

079909 SINGAPORE

ATTENTION:

INVOICE NO.

: INV1802-030

DATE

: 9. February 2018

REFERENCE NO : AAD1711-291

TERMS DUE DATE

: 9. February 2018

PAGE : 1

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHB7536U;DOA 24.11.17(LUMP SUM-18)	1	2,354.00	2,354.00

Total SGD Excl. GST:

2,200.00

7% GST:

154.00

Total SGD Incl. GST:

2,354.00

^{****} TWO THOUSAND THREE HUNDRED FIFTY FOUR SGD ONLY **** 1) All cheques should be crossed and made payable to Trans-Cab Auto Services Pte Ltd*

²⁾ Please quote our Invoice Number during payment.

³⁾ We reserve the right to charge interest @ 1.5% per month on overdue invoice.

⁴⁾ Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

No. 2 Ang Mo Kio Street 63 Tel No.: 6287 6666 Fax No. 6281 1400 Co./GST Reg. No. 200303878K

08 February, 2018

To Whom It May Concern

Dear Sir / Madam.

Accident on 24/11/17 02:15 PM at RAFFLES BOULEVARD

- We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the
 registered owner of the taxi bearing vehicle registration no. SHB7536U. The taxi was hired to LIM KIM HAI
 a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned
 accident at a rental rate \$75.25 per day (inclusive of GST).
- Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
- Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan General Manager

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

24-11-2017

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.		
Accident No.	AAD1711-291	Acc	ident Date	24-11-2017
28/11/2017	29/11/2017	SHB7536U		

Yours Faithfully,

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager



Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
FBL9315X	25 Nov 2017 / 06:45:00	ALLIED WORLD ASSURANCE COMPANY, LTD (SINGAPORE BRANCH)
SLT4074M	25 Nov 2017 / 10:30:00	AXA INSURANCE PTE LTD
SJN2351G	25 Nov 2017 / 20:40:00	NTUC INCOME INS CO-OP LTD
GBE5197H	24 Nov 2017 / 14:15:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
WC1791E	24 Nov 2017 / 17:30:00	GREAT EASTERN GENERAL INSURANCE LIMITED



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

-		Affiliated to Federation Interna	ationale Des Experts En Autorr	nobile		
HIN	IA TAIPING INSUF	RANCE (S) PTE LTD	Ref : CC3/CTI17022	709/Kha3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 27-02-2018 Code: CTI			
		Policy Particula	rs :- THIRD PARTY CLA	M		
	Insured Veh.	GBE 5197H	Veh. Inspected	SHB 7536U		
	Policy No.	DMCVSN1686191600	Coverage (\$)	0.00		
	Claim No.	SNM17D06789/C02/7	Excess (\$)	0.00		
	Assign From		Assign Date	28/11/2017		
2.		Vehicle Pa	articulars & Condition			
	Make & Model	CHEVROLET EPICA (A)	c.c	1991		
	Engine No.	HIDDEN	Year of Reg.	2012		
	Chassis No.	KL1LA69RJBB077076	Colour	WHITE /RED		
	Odometer	512566	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	GOOD				
3.		Con	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	GITI	3 mm		
	L/H Front Tyre	195/65 R15	GITI	3 mm		
	R/H Rear Tyre	195/65 R15	FALKEN	7 mm		
	L/H Rear Tyre	195/65 R15	FALKEN	7 mm		
4.		Descr	iption of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S FRONT PORTION.			
	DAMAGES SEE D	ETAILS.				
5.		Gen	eral Information			
	Accident Date	24/11/2017	Inspection Date	28/11/2017		
	Survey held at	TRANS-CAB AUTO SERVIO	CES PTE LTD			
	1.5	NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.			Remarks			
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	S. WE HAVE NOT AUTHORI	SIS. SED REPAIRS.		
5b.		Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Da	ys		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7536U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRACKED	1,202.00	1,202.00
-1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	295.25	
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	
1	FRONT BUMPER FOG LAMP OUTER COVER LH	SERVICEABLE	32.40	
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	
1	FRONT HEADLAMP LH	SERVICEABLE	816.00	
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	1,222 32	,
-1	BONNET	TO REPAIR SEE LABOUR	1,250.00	
1	BONNET MOULDING	SERVICEABLE	161.97	
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	
- 1	FRONT LOWER ARM LH	SERVICEABLE	283.00	
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	
1	SIDE ROCKER PANEL GARNISH LH	SERVICEABLE	236.40	
1	FRONT FENDER LH	BENT	837.60	837.60
- 1	FRONT FENDER LINER LH	DISTORTED	47.00	47.00
1	RESONATOR (B/S FENDER LH) AIR BOX	SERVICEABLE	134.67	
1	RESONATOR HOSE	SERVICEABLE	37.00	
1	RADIATOR GRILLE (GRILLE A-RAD)	SERVICEABLE	367.00	
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,133.00	
1	FRONT SIDE VIEW MIRROR LH	SERVICEABLE	939.00	
	LESS 10% DISCOUNT		-993.52	-208.66
			8,941.63	1,877.94
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	192.00	

Report Ref No. CC3/CTI17022709/Kha3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No::2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NOT NECESSARY	10.00	-
- 1	SET RADIATOR GRILLE CLIP (SN)	NOT NECESSARY	35.00	
1	SET FRONT FENDER LINER CLIP (SN)	NECESSARY	30.00	30.00
- 11	DOOR STICKER TRANS-CAB' (SN)	NOT NECESSARY	80.00	
1	FRONT TYRE LH (SN)	SERVICEABLE	360.00	,
-1	FRONT WHEEL RIM LH (SN)	SERVICEABLE	254.00	
1	FRONT WHEEL RIM HUB CAP LH (SN)	SERVICEABLE	166,30	
			1,157.30	60.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER ,FRONT SUPPORT PANEL ASSY ,BONNET AND FRONT DOOR LH .		2,800.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION , UNDERCARRIAGE PARTS , FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	
			6,660.00	840.00
	GRAND TOTAL		16,758.93	2,777.94

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	2,200.00
--	----------

Report Ref No. CC3/CTI17022709/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.