

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB7536U - CHINA TAIPING

AAD1711-291

Not Withheld
11pm @ 2200

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB7536U - CANDY
 KL1LA69RJBB077076
 CHEVROLET
 CHEVROLET EPICA 2.0
 24.11.2017
CHINA TAIPING

PART		LIST	
1	1 Front Bumper	\$	<i>CM</i> 1,202.00 —
2	1 Front Bumper Reinforcement	\$	<i>R</i> 295.25
3	1 Front Bumper Lower Absorber	\$	<i>SL</i> 180.00
4	1 Front Bumper Fog Lamp Outer Cover LH	\$	<i>SL</i> 32.40
5	1 Front Bumper Lower Grille	\$	<i>SL</i> 78.00
6	1 Front Bumper Lower Stiffener	\$	<i>R</i> 134.37
7	1 Front Bumper Retainer LH	\$	<i>Dis</i> 102.00 } <i>X</i>
8	1 Front Headlamp LH	\$	<i>SL</i> 816.00
9	1 Front Support Panel Assy	\$	<i>R</i> 1,222.32
10	1 Bonnet	\$	<i>R</i> 1,250.00
11	1 Bonnet Moulding	\$	<i>SL</i> 161.97
12	1 Front Shock Absorber Assy LH	\$	<i>SL</i> 216.17
13	1 Front Lower Arm LH	\$	<i>SL</i> 283.00
14	1 Front Knuckle Arm LH	\$	<i>SL</i> 230.00
15	1 Side Rocker Panel Garnish LH	\$	<i>SL</i> 236.40
16	1 Front Fender LH	\$	<i>R</i> 837.60 —
17	1 Front Fender Liner LH	\$	<i>Dis</i> 47.00 —
18	1 Resonator (B/S Fender LH) AIR BOX	\$	<i>SL</i> 134.67 <i>X</i>
19	1 Resonator Hose	\$	<i>SL</i> 37.00 <i>X</i>
20	1 Radiator Grille (Grille A-Rad)	\$	<i>SL</i> 367.00 <i>X</i>
21	1 Front Door LH	\$	<i>R</i> 1,133.00 <i>X</i>
22	1 Front Side View Mirror LH	\$	<i>SL</i> 939.00 <i>X</i>

TOTAL	\$	9,935.15
10%	\$	993.52
	\$	8,941.64

Special Nett

1 1 Set Front Bumper Fastener Clip

\$

Net 30.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-291**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7536U - CHINA TAIPING

2	1 Set Front licence plate with holder	\$	Sn 192.00 X
3	1 Set Radiator Grille Top Cover Clip	\$	nn 10.00 X
4	1 Set Radiator Grille clip	\$	nn 35.00 X
5	1 Set Front Fender Liner Clip	\$	nn 30.00 ✓
6	1 Door Sticker "Trans-cab"	\$	nn 80.00 X
7	1 Front Tyre LH	\$	Sn 360.00 X
8	1 Front Wheel Rim LH	\$	Sn 254.00 X
9	1 Front Wheel Rim Hub Cap LH	\$	Sn 166.30 X

TOTAL	\$	1,157.30
TOTAL PARTS	\$	10,098.94

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *400*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected
Portion.

\$ 2,700.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

To check steering geometry and computer wheel
alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ nn 380.00 X

TOTAL	\$	6,660.00
Over All Total	\$	16,758.94

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DAYS

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

10 DAYS*2 days*