

INS. CASE OWNER:

Irene

CC 61CTI17022711 1 K1eazn2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

28/11/17

Date / Time:

28/11/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 1006S

Name of Insured:

R & M LEASING PTE LTD

Insured Tel No.:

HP:

Excess Sec II : \$S

D.O.A.:

27/11/17

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age: SALIMUL IKHWAN BIN NASARUDDIN

SALIM KEMHAY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHD 1114H



INSRS:

WSP: Premier Auto (Chai)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHD 1114H - X
 SJH 1006S - CC6/CTI17011323/Apt2 DOA: 07/06/17
 - CUT/OCB13008961/11/18 DOA: -
 - NA/CTI17012308/14 DOA: 07/06/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 14/12

After call ltr to OI:

04/12/17 (Asst)

8/12/17 c 11.12 CALLED OLD COMPANY CONFIRMED ACCIDENT. OLD REAR ENDED TP.
 INFORM TP CLAIM AGREED TO SETTLE AND AWARE ABOUT NCD RISK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 29/11/17

Sent By: Shirley Hwee

FINALIZATION

Date/Time: 29/11/17

Confirm with: GARY

Confirm by: FRICK

Repair Cost:

213 \$S 2,400

(3 days)

Reduction:

53 %

Email

Call

FINAL SETTLEMENT

Date/Time: 18/1/18

Confirm with: GARY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

10/451 \$S 2,568.00

OLD REAR ENDED TP

Loss of Rental (LOR):

\$S 340.13

(3.5 days)

x 97.18

Loss of Use (LOU):

\$S -

(\$ x days)

Loss of Income (LOI):

\$S -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$S 2.00

Medical:

\$S -

Disbursement:

\$S -

(e.g. Tow/ Independent)

Legal Cost

\$S -

Total:

\$S 2,910.13

Global Sum \$S:

FINAL PAYMENT

Date/Time: 18/1/18

Confirm with: GARY

Email

Call

Payee 1:

\$S 2,910.13

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

RECEIVED 22 JAN 2018

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

400

Kalvin

3 Feb 2016

CTI

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17022711/K1ea3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 29-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 1006S	Veh. Inspected	SHD 1114H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/11/2017	Inspection Date	28/11/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/CTI17022711/K1ea3

Date: 29.11.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1114H


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.11.2017 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report:-

Workshop Estimate Amount	: S\$	5,124.10
Revised Estimate Amount	: S\$	2,240.20
"Check" Items Amount	: S\$	929.70
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion




Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

 PREMIER TAXIS	HIRER / RELIEF / SUPER RELIEF
VEHICLE NO.	SHD 1114H
CONTACT NO.	90058186
NEW MAILING ADDRESS (if any)	

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	19/12/2013



	
NRIC No: S8117443A	
	
Blood Group	Date of issue
O+	15-03-2000
APT BLK 434B FERNVALE ROAD #05-236 SINGAPORE 792434	
NRIC No: S8117443A	Date: 25/04/2012 No: 7057896

Land Transport Authority


VOCATIONAL LICENCE

Licence No: S8117443A

NAME: YAM ZHONG RUI

EXPIRY DATE: 19/12/2013

Please visit www.lta.gov.sg to check the status of this vocational licence



PUBLIC OF SINGAPORE

IDENTITY CARD NO: S8117443A

NAME

YAM ZHONG RUI

嚴忠瑞

Race

CHINESE

Date of Birth



17-06-1981

Sex

M

Country of Birth

SINGAPORE

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	03 Feb 2016 / 09:16:54	Receipt No.:	AACCK001-AX239-160203-000014
Asset Type:	Vehicle	Transaction Amount:	\$66,720.00
Asset ID:	SHD1114H	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20160203091654705691		

Vehicle No.:	SHD1114H
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	03 Feb 2016
Original Registration Date:	03 Feb 2016
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5659604
Engine No.:	D4FDFH314402
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,528.00
Minimum PARF Benefit:	\$14,124.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	03 Feb 2016 09:16:54
COE No.:	2016020301003300N
COE Expiry Date:	02 Feb 2024
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$43,040.00
Lifespan Expiry Date:	02 Feb 2024

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

- | | |
|---|----------------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHD1114H |
| Chassis Number | : KNAGM414MF5659604 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 20 Oct 2017 |
| 4. Expiry Date of Insurance | : 19 Oct 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| (a) The Policyholder. | |
| (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use* | |
| (a) Use as a Taxi. | |
| (b) Use for social domestic and pleasure purposes. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: UNITED OVERSEAS BANK LIMITED
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	03 Feb 2016 / 09:16:54	Receipt No.:	AACCK001-AX239-160203-000014
Asset Type:	Vehicle	Transaction Amount:	\$88,720.00
Asset ID:	SHD1114H	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20160203091654705891		

Vehicle No.:	SHD1114H
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	03 Feb 2016
Original Registration Date:	03 Feb 2016
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5659604
Engine No.:	D4FDFH314402
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,528.00
Minimum PARF Benefit:	\$14,124.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	03 Feb 2016 09:16:54
COE No.:	2016020301003300N
COE Expiry Date:	02 Feb 2024
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$43,040.00
Lifespan Expiry Date:	02 Feb 2024

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1114 H

1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip ✕	\$	96.00
1 pc	End panel ✕ Regular	\$	250.00
1 pc	End panel garnish ?	\$	74.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @\$29 ?	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @\$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @\$18 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @\$46.00 ✕	\$	92.00
		\$	2,429.00
		Less 10%	\$ 242.90
		\$	2,186.10

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips ✕	\$	30.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	Rear bumper top protector ✓	\$	80.00 50

27-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1114 H

Sundry	\$	50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	1,000.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel,	\$	850.00 580
To apply rustproofing on the repaired and replaced panels.	\$	200.00 X
	\$	<u>5,124.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kelvin LUK
28/11/17 0940hrs
3 Days.
PIP
Before Rep photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1114 H

1 pc	Bootlid emblem — <i>new</i>	\$	27.00
1 pc	Bootlid CRDi — <i>new</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip X <i>sun</i>	\$	96.00
1 pc	End panel X <i>hep</i>	\$	250.00
1 pc	End panel garnish X <i>new</i>	\$	74.00
1 pc	Rear bumper — <i>Rehab</i>	\$	696.00
1 pc	Rear bumper lower cover — <i>new</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @\$29 X <i>sun</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>new</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>new</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @\$53.00 <i>new</i>	\$	108.00 <i>vol</i>
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 <i>new</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @\$18 <i>new</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @\$46.00 X <i>sun</i>	\$	92.00
		\$	2,429.00
		Less 10%	\$ 242.90
		\$	2,186.10
S/NETT			
1 set	Rear bumper clips — <i>new</i>	\$	48.00
1 set	End panel inner garnish clips X <i>new</i>	\$	30.00
1 set	Bootlid stickers — <i>new</i>	\$	100.00
1 set	Reverse sensor — <i>slide</i>	\$	280.00 <i>200</i>
1 pc	Rear bumper top protector — <i>new</i>	\$	80.00 <i>50</i>

27-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1114 H

Sundry <i>nec</i>	\$ 50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>Xm</i>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$ 1,000.00 400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel,	\$ 850.00 580
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 <i>Xm</i>
	<u>\$ 5,124.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kelvin LUKER

28/11/17 0940 L2

3 Days.

PIP

Before Part photo-

*29/12/17
Contract 4542400/3R2*

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts/repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17022711/K1ea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 1006S	Veh. Inspected	SHD 1114H
Policy No.	DMHCSN1736111700	Coverage (\$)	0.00
Claim No.	SNM17D06829C02	Excess (\$)	0.00
Assign From		Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAGM414MF5659604	Colour	SILVER
Odometer	165252	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/11/2017	Inspection Date	28/11/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1114H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	CRACKED	108.00	106.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-242.90	-185.70
			2,186.10	1,671.30
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			588.00	418.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF END PANEL.		1,000.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		850.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			2,350.00	960.00
GRAND TOTAL			5,124.10	3,049.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC3/CTI17022711/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.