

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9713B - III*Not Authorized
21 Sep & Food*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9713B - JHOW

VF1ABL15AUC276043

RENAULT

LATITUDE

25.11.2017

III**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Bu</i> 113.47	X
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Bu</i> 44.99	✓
9	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49	X
10	1	FENDER PANEL REAR LH	\$	<i>Bu</i> 3,299.13	✓
11	1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45	X
12	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	X
13	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	<i>R</i> 3,039.04	} X
14	1	KUCKLE ARM REAR LH	\$	<i>Sn</i> 736.67	
15	1	LOWER ARM REAR LH	\$	<i>Sn</i> 905.99	
16	1	ABSORBER REAR LH	\$	<i>Sn</i> 389.75	
17	1	TAILLAMP LH	\$	<i>Sn</i> 552.55	
18	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70	} X
19	1	EXHAUST REAR	\$	<i>R</i> 7,489.05	
20	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49	
21	1	DOOR PANEL REAR LH	\$	<i>Bu</i> 2,844.66	✓
22	1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82	} X
23	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50	
24	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55	
25	1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06	
26	1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75	
27	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96	
28	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49	
29	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52	
30	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89	
31	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22	
32	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60	
33	1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10	
34	1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i> 410.66	✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-280

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9713B - III

35	1	DOOR SEAL REAR LH	\$	Sn	162.02
36	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69
37	1	DOOR MOULDING REAR LH	\$	Sn	176.82
38	1	DOOR PANEL FRT LH	\$	N	2,844.66
39	1	DOOR HINGE UPPER RH	\$	N	274.50
40	1	DOOR HINGE LOWER RH	\$	N	300.55
41	1	DOOR MOULDING FRT RH	\$	Sn	176.82
42	1	DOOR HANDLE OUTER FRT LH	\$	Sn	258.12
43	1	DOOR HANDLE CAP FRT LH	\$	Sn	26.44
44	1	DOOR HANDLE SEAL FRT LH	\$	Sn	7.89
45	1	DOOR HANDLE COVER FRT LH	\$	Sn	13.22
46	1	DOOR HANDLE MODULE FRT LH	\$	Sn	133.60
47	1	DOOR MIRROR RH	\$	Sn	1,483.40
48	1	DOOR MIRROR GLASS RH	\$	Sn	148.20
49	1	DOOR MIRROR BACK COVER RH	\$	Sn	218.46
50	1	FENDER PANEL FRT RH	\$	N	783.83
51	1	FENDER INSULATOR RH	\$	Sn	130.84
52	1	FENDER BRACKET FRT RH	\$	N	34.14
53	1	WHEELARCH FRT RH	\$	Sn	278.84

TOTAL	\$	36,084.90
10%	\$	3,608.49
	\$	32,476.41

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00 X
2	1SET	REAR BUMPER CLIP	\$	Nr	66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	Nr	33.00 ✓
4	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	Nr	10.00 X
5	1SET	BUMEP R RETAINER LH CLIP RR	\$	Nr	20.00 X
6	1SET	BUMPER LOWER REAR RIVET	\$	Nr	22.00 X
7	1SET	BUMPER LOWER REAR CLIP	\$	Nr	66.00 X
8	1	EXHAUST MOUNTING REAR	\$	Sn	17.82 X
9	1	TAILLAMP CLIP LH	\$	Nr	5.00 X
10	1SET	WHEELARCH CLIP RR LH	\$	Nr	66.00 X
11	2	REAR WINDSCREEN SELANT	\$	Nr	80.00 40Sn
12	1	WINDSCREEN MOULDING	\$	Nr	100.00 ✓
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Nr	100.00 30Sn
14	1	CAP HUB LH RR	\$	Sn	35.00 X
15	1	RIM LH RR	\$	Sn	385.00 X
16	1	TYRE LH RR	\$	Sn	330.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-280**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9713B - III

17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
18	1	DOOR STICKER "Classic"	\$	nn	30.00	X
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	6555

TOTAL	\$	2,225.82
TOTAL PARTS	\$	34,702.23

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	669
To reinstall rear bumper parking sensor.	\$	170.00	669
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	809
To Rust-Proofing Of The Affected Areas.	\$	170.00	669
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1009
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	129
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	669
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	nn 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-280**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9713B - III

TOTAL	\$	10,990.00
Over All Total	\$	45,692.23

(PARTS BY PARTS)**Repair Days**~~15 Days~~

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: