

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

QBE INSURANCE (INTERNATIONAL) LIMITED

143 CECIL STREET #08-01 GB BUILDING

069542

Attention : Motor Claim Department

Contact : 2246633 Fax No. : 2252148

Estimate : ES00575

Date : 25/11/2017

Vehicle Num. : SLQ 6919D (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/11/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE (VEZEL) ✓ DT		1,450.00
2.	1	REAR TAILGATE HYBRID EMBLEM (VEZEL) ✓ NEC		86.80
3.	1	REAR TAILGATE VEZEL EMBLEM(VEZEL) ✓ NEC		86.80
4.	1	REAR WINDSCREEN GLASS MOULDING(VEZEL) ✓ NEC		195.00
5.	1	REAR TAILGATE WEATHERSTRIP (VEZEL) ✓ NEC Deform.		155.00
6.	1	REAR END PANEL TOP GARNISH (VEZEL)		155.00
7.	1	REAR END PANEL (VEZEL) ✓ DT		830.00
8.	1	REAR BUMPER ASSY (VEZEL) ✓ DT		955.00
List TotalS\$:				3,913.60
29.00% Discount S\$:				1,134.94
				2,778.66
SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT ✓ NEC		160.00 40
2.	8	REAR BUMPER CLIPS (VEZEL) ✓ NEC	9.80	78.40
3.	1	REVERSE SENSOR (VEZEL) ✓ DMG		280.00 200
4.	8	REAR END TOP PANEL TOP GARNISH CLIPS (VEZEL) ✓ NEC	9.80	-78.40 36
Special Nett Total S\$:				596.80
LABOUR :				
TRANSFER TAILGATE DOOR MECHANISM (VEZEL)				120.00 60

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

QBE INSURANCE (INTERNATIONAL) LIMITED
 143 CECIL STREET #08-01 GB BUILDING
 069542

Attention : Motor Claim Department
 Contact : 2246633 Fax No. : 2252148

Estimate : ES00575

Date : 25/11/2017
 Vehicle Num. : SLQ 6919D (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 24/11/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)	160.00	120
		To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts	1,000.00	600
		To respray rear tailgate, rear bumper, end panel	900.00	600
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	380.00	220
		To conduct a standard of opearting procedure poat repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs	380.00	220
		Labour Total S\$:	2,940.00	

E. & O.E.

Total S\$: 6,315.46

for WORLD AUTO PTE LTD

Sebastian.
 29/11/2017.

- Part by part repair.
 - Photo before paint.

90836121

sebastian.yeang@lkkauto.com

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: