


SMRT Accident Vehicle Repair Estimates

G1A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5237X
Ref. No : TAX/11/17/2162
Reg. Date : 03/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : SIM KING HOCK
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 26/11/2017 10:16:00 PM
Accident Reported Date / Time : 27/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093305
Special Instruction to ARC, if any :
DROVE IN /SJS8076K
Prepared Date : 27/11/2017 11:55:14 AM



Sebastian.
28/11/2017.
- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703573961

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,314.00	0.00
Total Material Charges	: 5,975.18	5,975.18
Other Charges	: 960.00	0.00
TOTAL	: 9,263.18	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00 4 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 27/11/2017 04:42:33 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/11/2017 04:42:14 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 11/27/2017 4:42:49 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 200
TO REPAIR REAR PORTION	676.00	0.00 200
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
Total Spray Painting & Panel Beating	1,314.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X Repeated.
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	960.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace R	No
52116470 50			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace 7	No
52115470 50			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace 7	No
52114471 90			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace 7	No
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace ✓ BT	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace ✓ BT	No
75310470 60			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace ✓ No	No
53101470 80			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace ✓ DT	No
53112472 40			GRILLE, RADIATOR	1	165.00	25.00	123.75	Replace	Replace 7	No
52611471 40			ABSORBER, FR BUMPER	1	70.30	25.00	52.72	Replace	Replace 7	No
52021471 10			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.32	Replace	Replace 7	No
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ DT	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace 7	No
55213471 50			PAD, DASH PANEL INSULATOR, NO.1	2	28.60	25.00	42.90	Replace	Replace X	No
55214470 70			PAD, DASH PANEL INSULATOR, NO.2	2	63.80	25.00	95.70	Replace	Replace X	No
55215470 70			PAD, DASH PANEL INSULATOR, NO.3	2	142.30	25.00	213.45	Replace	Replace X	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace X	No
52599680 30			STOPPER, RR BUMPER, RH & LH	2	4.30	25.00	6.45	Replace	Replace X	No
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace 7	No
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace 7	No
81591470 10			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace 7	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace 7	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓ NEC	No
52592470 40			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace 7	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓ Defor	No
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ✓ Dnc	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace 7	No
52566479 00			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace X	No
52565479 00			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7539235220			RETAINER, OUTSIDE, RH & LH	2	3.30	25.00	4.95	Replace	Replace	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace	No
6481947080			TAIL GATE SPACER, BACK DOOR GLASS, LH	1	6.90	25.00	5.17	Replace	Replace	No
6481847080			TAIL GATE SPACER, BACK DOOR GLASS, RH	1	6.90	25.00	5.17	Replace	Replace	No
6278547010			TAIL GATE SPACER, QUARTER BACK DOOR GLASS	1	5.50	25.00	4.12	Replace	Replace	No
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No
6481947100			TAIL GATE SPACER, BACK DOOR LOWER GLASS, LH	1	5.00	25.00	3.75	Replace	Replace	No
6481847100			TAIL GATE SPACER, BACK DOOR LOWER GLASS, RH	1	5.00	25.00	3.75	Replace	Replace	No
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No
7557447040			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	25.00	22.42	Replace	Replace	No
7557347110			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	25.00	22.42	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS								5,975.30	5,975.18	
TOTAL MATERIALS(Discounted)								5,975.18	5,975.18	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									