

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-293

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9281E - ECICS

Not Authored
L/Sy &

Vehicle No.:

SHD9281E - JHOW

Chassis No.:

KL1LA69RJBB067004

Date of Accident :

26.11.2017

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Third Party Insurer :

ECICS

PART**LIST**

1	1	Front Bumper	\$	S _h	1,202.00	X
2	1	Front Bumper Lower Absorber	\$	S _h	180.00	}
3	1	Front Bumper Reinforcement	\$	N	356.00	
4	1	Front Bumper side support LH	\$	S _h	76.20	
5	1	Front Bumper side support RH	\$	S _h	76.20	
6	1	Front Bumper Retainer RH	\$	S _h	102.00	
7	1	Front Bumper Retainer LH	\$	S _h	102.00	
8	1	Front Bumper Lower Grille	\$	S _h	78.00	
9	1	Front Bumper Lower Stiffener	\$	N	134.37	
10	1	Front Bumper Bracket LH	\$	N	10.00	
11	1	Front Bumper Bracket RH	\$	N	10.00	
12	1	Front Bumper Fog Lamp Outer Cover LH	\$	S _h	32.40	}
13	1	Front Support Panel Assy	\$	N	1,222.32	
14	1	Front brace panel	\$	N	134.37	
15	1	Headlamp LH	\$	S _h	816.00	
16	1	Front Fender LH	\$	N	837.60	
17	1	Front Fender Liner LH	\$	S _h	47.00	
18	1	Front Door LH	\$	N	1,133.00	
19	1	Front Door Outer Moulding LH	\$	S _h	220.00	
20	1	Front Door Outer Handle LH	\$	S _h	125.00	
21	1	Front Door Handle Support LH	\$	S _h	3.00	
22	1	Front Door Outer handle inner seal LH	\$	S _h	89.15	}
23	1	Front Door Outer key lock LH	\$	S _h	25.00	
24	1	Front Door Hinge Upper LH	\$	N	65.00	
25	1	Front Door Hinge Lower LH	\$	N	65.00	
26	1	Front Door Inner lock LH	\$	N	586.00	
27	1	Front Door Inner Lock Latch LH	\$	N	206.00	
28	1	Front Door Check / Arrestor LH	\$	S _h	67.50	
29	1	Front Door Weatherstrip LH	\$	S _h	138.79	
30	1	Front Side View Mirror LH	\$	S _h	939.00	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-293**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9281E - ECICS

31	1	Side Rocker Panel Garnish LH	\$	Bz	236.40	✓
32	1	Side Rocker Panel Outer LH	\$	n	433.26	X
33	1	Centre pillar outer LH	\$	n	446.00	X
34	1	Rear Door LH	\$	Bz	1,133.00	✓
35	1	Rear Door Top Hinge LH	\$	n	35.00	X
36	1	Rear Door Bottom Hinge LH	\$	n	35.00	X
37	1	Rear Door inner lock LH	\$	Tn	425.00	✓
38	1	Rear Door check / arrestor LH	\$	Sn	65.00	X
39	1	Rear Door lock striker / latch LH	\$	n	120.00	X
40	1	Rear Door outer weatherstrip moulding LH	\$	Sn	85.00	X
41	1	Rear Door outer handle LH	\$	Sn	60.00	X
42	1	Rear Door outer handle - rubber seal LH	\$	Sn	25.00	X
43	1	Rear Door inner opening handle LH	\$	Sn	45.50	X
44	1	Rear Door inner trim board LH	\$		455.69	?
45	1	Rear Door kicking plate / step garnish LH	\$		63.25	?
46	1	Rear door glass LH	\$	Sn	420.35	X
47	1	Rear Door window glass channel weatherstrip LH	\$	Sn	143.25	X
48	1	Rear Door window glass channel holder LH	\$	Sn	205.60	X
49	1	Rear Door channel weatherstrip / felt LH	\$	Sn	89.50	X
50	1	Rear Door interior light switch LH	\$	Sn	139.20	X
51	1	Rear Door power window motor (master) LH	\$	Tn	274.97	?
52	1	Rear Door regulator gear LH	\$	Bz	55.30	✓
53	1	Rear Door regulator handle LH	\$	Sn	65.30	X
54	1	Rear Door 1/4 glass with moulding	\$	Sn	215.00	X
55	1	Rear Fender LH	\$	Bz	1,145.00	✓
56	1	Rear Fender Inner Trim LH	\$	Sn	418.44	} X
57	1	Rear Fender Inner Cowling LH	\$	Sn	76.60	
58	1	Rear Tail Lamp LH	\$	Bz	479.30	
59	1	Rear Bumper	\$	Sn	1,202.00	
60	1	Rear Bumper Side Retainer LH	\$	Sn	68.76	
61	1	Rear Bumper Reflectors LH	\$	Sn	119.74	

TOTAL	\$	17,860.31
10%	\$	1,786.03
	\$	16,074.28

Special Nett

1	4	Front Bumper Fastener Clip	\$	nn	24.00	X
2	1 Set	Front Fender Liner Clip	\$	nn	30.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-293**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9281E - ECICS

3	1Set	Rear Bumper Parking Sensor	\$	sn	300.00	X
4	1 Set	Rear Bumper Fastener Clip	\$	nn	30.00	X
5	1 Set	Rear Fender Liner Clip	\$	nn	30.00	X
6	1	Door Sticker "Trans-cab"	\$	nn	80.00	bsn
7	1	Door Sticker "6555-3333"	\$	nn	80.00	bsn
8	1set	Side Rocker Panel Garnish Clip LH	\$	rec	60.00	✓
9	1	Front Tyre LH	\$	sn	360.00	X
10	1	Front Wheel Rim LH	\$	sn	254.00	X
11	1	Hub Cup Rim Front LH	\$	sn	35.00	X
12	1	Rear Tyre LH	\$	sn	360.00	X
13	1	Rear Wheel Rim LH	\$	sn	254.00	X
14	1	Hub Cup Rim RR LH	\$	sn	35.00	X

TOTAL	\$	1,908.00
TOTAL PARTS	\$	17,982.28

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,200.00 100d

To Rust-Proofing Of The Affected Areas.

\$ 220.00 9d

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

Putty and Spray Painting Of The Affected Portion.

\$ 4,050.00 100d

To Check Electrical Lighting Concerned.

\$ 170.00 2d

To check steering geometry and computer wheel
alignment

\$ 220.00 6d

Towing fees

\$ nn 120.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ 170.00 12d

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ 170.00 1ed

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-293**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9281E - ECICS

TOTAL	\$	9,490.00
Over All Total	\$	27,472.28

REPAIR DAYS~~15 DAYS~~*7 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: