

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*Air Duct Hose	0.00	0.00	*60.00 F CRA -
44	1		*Air Duct Resonator Box	0.00	0.00	*60.00 F DE -
45	1		*Fuse Box Top Cover	0.00	0.00	*50.00 F ? CRA
46	1		*Wire Hardness (Engine)	0.00	0.00	*1,600.00 F ? X SVL
47	1		*Wire Hardness (1set)	0.00	0.00	*3,200.00 F ? 2400
48	1		*Alternator	0.00	0.00	*650.00 F ? CRA
49	1		*Alternator Beet	0.00	0.00	*50.00 F ? CRA
50	1		*Aircon Compressor	0.00	0.00	*450.00 F ? CRA
51	1		*Intake Manifold	0.00	0.00	*210.00 F Cut -
52	1		*Front Windscreen	0.00	0.00	*400.00 F CRA -
53	1		*Front Windscreen Moulding 1set	0.00	0.00	*40.00 F Free -
54	1		*Sealant	0	0.00	*45.00 FS SN -
55	1		*Engine Undercover Centre	0.00	0.00	*95.00 F MIS -
56	2		*Engine Undercover LH/RH	0.00	0.00	*80.00 F DE -
57	10		*Engine Undercover Clips	0.00	0.00	*15.00 F Free -
58	1		*Wiper Tank	0.00	0.00	*65.00 F DE -
59	1		*Radiator Spare Tank	0.00	0.00	*55.00 F DE -
60	1		*Wiper Tank Motor	0.00	0.00	*85.00 F ? -
61	1		*Engine Mounting Front	0.00	0.00	*65.00 F ? -
62	1		*Engine Mounting LH/RH (LH-\$95;RH-\$125)	0.00	0.00	*220.00 F ? -
63	1		*Engine Mounting Bracket Front	0.00	0.00	*50.00 F ? -
64	1		*Dashboard	0.00	0.00	*650.00 F Free -
65	1		*Driver Airbag	0.00	0.00	*850.00 F ACT -
66	1		*Driver Airbag Coil Spring	0.00	0.00	*170.00 F ACT -
67	1		*Passenger Airbag	0.00	0.00	*1,150.00 F ACT -
68	1		*Airbag Control Unit	0.00	0.00	*600.00 F ACT -
69	2		*Front Impact Sensor RH/LH	0.00	0.00	*520.00 F ACT -
70	2		*Seatbelt LH/RH	0.00	0.00	*560.00 F ACT -
71	2		*Seatbelt Buckle RH Seatbelt buckle LH	0.00	0.00	*220.00 F ? 110 -
72	1		*Coolant	0	0.00	*45.00 FS SN -
73	1		*Auto Transmission Fluid Original	0.00	0.00	*88.00 F Free -
74	1	REPAIR	*Passenger Door	0.00	0.00	-
75	1	REPAIR	*Driver Door	0.00	0.00	-
76	1		*Front Grille with Logo	0.00	0.00	*150.00 F Free -
77	1		*Sealant	0	0.00	*45.00 FS SN -

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 17,651.00
+ Margin on L,N Items 10.00% (\$\$) 1,717.10

Total Parts (\$\$) 19,368.10

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS