

ASS. REC. BY:

REF: CS/MSG17022722/R1rbet

Special Instruction:

SUPERVISOR:

Rasul

ASSIGNMENT (Office)

PERSON:

Kwok Woon Chao

of

MSIG

Date/Time:

29/11/17 @ 2.34pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLD G534Z

Insured:

at Workshop m/s

Hitachi Capital Asia

Tel:

64663022

of

No. 8 Fourth Lok Yung Road, 629705

Policy No:

MSD/VPCP/17-061233

Claim No:

MSC/V/17-061805

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

(Client's Record)

D.O.A.

17/11/2017

CA

(REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:25pm @ 29/11/17

Person Contacted:

IRIS

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

To check tyre, Brake, Vehicle Condition and get a
mechanic's Record.

SLD G534Z - CS/MSG17022722/R1rbet - D.O.A. - 17/11/17

30/11/17

Sent preli through menimen; seek mandate

1/12/17

Mandate approve; Inform Grant authorise repair & excess.

Page

0399A

ASSIGNMENT

Form: 101 Date: 2016 Jun
Estimated Cost: 00 TP / WS / TP RES / CD RES / EVA / INV / MV
To Inspect Vehicle No: SLD 6534Z
at Workshop/mile: HITACHI CAPITAL
of: No. 8, Fourth Locking Rd
Insured: MSIA / 00
Policy No:
Claims No:
Sum Insured: Excess: 1500
(Client's Record)
Make of Ven:

To check tyre, body
(Policy Condition) vehicle condition
performance record
Remark: The veh had commenced its
repair at the time of inspection.

NS	O/S

Est. or Market Value: 91K
IDAO Accident Report: Consistent? Yes or No
GIA / PR. Seen: Consistent? Yes or No
Est. Repairs: days Res: Yes or No
Lum. Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle IN / OUT

Veh No: SLD 6534Z Reg: 2016 Jun
Type: (C) M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: TOYOTA COROLLA ALTIS Cl: 1.6 1598
Colour: GREEN A/C: Insured / Std / Nil / NA
Sp. Reading: 87135 T-Ratio: Insured / Std / Nil / NA
Eng No:
C No: MR053REH 104 55 3415
Gen. Cond: Good / (P) Poor / Burnt
Steering: (C) / Jammed / Leaked / Burnt or
Brake: (C) / Jammed / Leaked / Burnt or
Mod: Nil / STD / STD AIR / Rim or
Tyre Size: P 205/55R16
R
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook
Front: Rear:
R/Bal: S mm R/Bal: S mm
L/Bal: S mm L/Bal: S mm
D/OA: 17/4/17 D/OI: 21/11/17
Survey held at: HITACHI CAPITAL
Des. of Damages: (C) / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action Instruction
21/9/18 Mandate for supplementary & check item
4/10/18 Mandate approve
12/10/18 Re-mandate for item 45 and item 50

Confirm \$26,644.80, i 18 days
Red: \$7,59.30, 21%.

RECEIVED 2 OCT 2018

Date/Time File Pass (C) ☐ Prel. Report
2/10/18 ☒ Final Report
Date/Time File Return (C)

Days Of Repair: 18
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Tech: \$
☐ Web: \$

Report Format: 2D
Lump Sum: 26,644.80

Survey Fee	350
Transport	
Food	10
Other	
Total	360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17022722/R1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 29-11-2017	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLD 6534Z
Policy No.	MSD/PCP/17-001233	Coverage (\$)	0.00	
Claim No.	MSC/V/17-001805	Excess (\$)	0.00	
Assign From	MERIMEN (KWOK WOON CHOO)	Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/11/2017	Inspection Date	29/11/2017	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022722/R1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-11-2017	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLD 6534Z
Policy No.	MSD/PCP/17-001233	Coverage (\$)	0.00
Claim No.	MSC/V/17-001805	Excess (\$)	0.00
Assign From	MERIMEN (KWOK WOON CHOO)	Assign Date	29/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/11/2017	Inspection Date	29/11/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	18 Nov 2017 Sendback Est.	29 Nov 2017 12:06 \$529,138.10	29 Nov 2017 14:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLD6534Z	Date of Loss:	17/11/2017 07:00 - :59
Claim Type:	OD / MSC/V/17-001805	Policy/Cover Note No.:	MSD/VPCP/17-001233 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018
		Excess:	\$51,500.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/11/2017]		
Driver/Custodian:	CHRISTOPHER LIM TSING YEW (45 / Male), NRIC: S7210087E, Tel: +6597704746		
Adj Asp. Remarks:	TO REVERT - TO CHECK TYRE, BRAKE, VEHICLE CONDITION AND GET A MAINTENANCE RECORD.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: SLD6534Z	Accident Date	: 17/11/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MSD/VPCP/17-001233
Assignment Date	: 29/11/2017	Excess	: S\$1,500.00
Date of Inspection	: 29/11/2017	Est. Duration of Repair	: 18.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,138.10
Revised Amount	:S\$	18,156.10
Check Items (Estimated)	:S\$	7,172.00
Total	:S\$	25,328.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	91,000.00
COE / PARF Rebate	:S\$	56,760.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,240.00

Remarks

(X) The vehicle is economical for repair.

Tyre condition : Serviceable

Brake condition : In Order

Vehicle condition : Good

Mainteneince recorded uploaded.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

SLD6534Z (MSC/V/17-001805)
OD
Nov 17 2017 7:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 01/12/2017 08:14 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18156.10) - SLD6534Z - Claim Handler: Kwok Woon Choo

Approved:18156.10:a if c; check items to be confirmed

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, December 01, 2017 9:02 AM
To: 'KeanYap.Chong@hcspl.com.sg'
Cc: SUR
Subject: SLD 6534Z MSIG OD DOA : 17/11/2017

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLD 6534Z (excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	0399N

Vehicle Details

Vehicle No.	SLD6534Z
Vehicle to be Exported	Yes
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour	Silver
Manufacturing Year	2016
Engine No.	1ZRX582913
Chassis No.	MR053REH104553415
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$16,800.00
Original Registration Date	24 Jun 2016
First Registration Date	24 Jun 2016
Transfer Count	0
Actual ARF Paid	\$16,800.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Jun 2026
PARF Rebate Amount	\$12,600.00

Intended COE Rebate Details

COE Expiry Date	23 Jun 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$55,200.00
COE Rebate Amount	\$44,160.00
Total Rebate Amount	\$56,760.00

The information contained herein is correct as at 29 Nov 2017

OK

97,000
56,760

34,240

34K

sgCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

 (CAR OF THE YEAR)
 Vote for your favourite car!

All

Car Name or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS



toyota corolla altis classic

Available Year

Vehicle Type

Dealer Type

☒ Past Models

☐ Current Models

Submit

Home » New Cars » Past Cars » Toyota Past Cars » Toyota Corolla Altis

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Vehicle Inspection



Related Articles



Toyota regains top spot



This is Toyota's Corolla 50th Anniversary Edition



Toyota unveils custom SEMA 2010 builds



Eight newbie mistakes all P-plate drivers make

View More

Past Car

Models no longer being sold by local distributors.

Model unavailable since Dec 2013

Toyota Corolla Altis

[Overview](#) | [Pricing](#) | [Photos](#) | [Research](#) | [Reviews](#) | [Specs](#) | [Features](#) | [Similar](#) | [Accessories](#) | [Promo](#)
[Submit a Review](#)[Report Error](#)[Share](#)

Like 90%



Details

Distributor Borneo Motors

Hotline 66311188 / 66311189

Built in Thailand (launched 2008)

Successor Toyota Corolla Altis (2014)

Predecessor Toyota Corolla Altis (2000-2007)

Pricelist **25-Nov Pricelist** [Select Another Date](#)

[View All Available Toyota Models](#)[View All Past Toyota Models](#)

USER RATINGS:

[77 reviews]

Submodel

Last Recorded Price

Fuel Economy

Power

Transmission

Detailed Info

1.6 LX (A)

\$79,988 (Aug 2010)

12.8km/L

121bhp

4-speed (A)

[Specs](#) | [Features](#)

1.8 (A)

\$98,988 (Aug 2010)

12.9km/L

130bhp

4-speed (A)

[Specs](#) | [Features](#)

1.6 Classic (A)

\$121,988 (Nov 2012)

14.5km/L

121bhp

4-speed (A)

[Specs](#) | [Features](#)

1.6 Elegance (A)

\$125,988 (Nov 2012)

14.5km/L

121bhp

4-speed (A)

[Specs](#) | [Features](#)

1.6 Sportivo (A)

\$136,988 (Nov 2012)

14.5km/L

121bhp

4-speed (A)

[Specs](#) | [Features](#)

1.8 (A)

\$158,988 (Nov 2012)

15.4km/L

130bhp

7-speed (A) CVT

[Specs](#) | [Features](#)

Toyota Corolla Altis Review

Car Review - Toyota Corolla Altis 1.6 (A)

07 Oct 2010 | Toyota Reviews

Are the minor changes to the Altis good enough to improve its drive? Join us as we find out more.



The Good

- Elegant and matured outlook
- Interior is classic and comfortably well round
- New quality is top notch



The Bad

- Body roll is evident
- Handling can be further improved
- Nothing much has changed aesthetically

CONSUMER REVIEWS

Best car I ever owned!

The best car I have driven so far and is a Toyota Corolla Altis Elegance. It is quite a good car compared to other type of cars. The engine is also quite powerful and the engine noise is not that loud. Gear shi...

[Read More](#)

A Good Car.

I bought one made in 2006, last year. It is an extreme difference compare to my previous 2006 Altis. It is so much easier to handle and the pick up is almost on par with my FX2. Gear change is unnot...

[Read More](#)[Submit a review](#)

Receive 3 MCF points when you submit a review

[View All 77 Consumer Reviews](#)

Current Model

Price

User Rating

Toyota Corolla Altis (Launch Date: January 2014)



1.6 Standard (A)

\$115,988 A

5.1 Reviews

1.6 Elegance (A)

\$120,988 A

Editors Review

Items for Toyota

[Leather Upholstery](#)[Mugen Style Door Vase](#)[TAC Curved Head Rest Pillow](#)[Compare](#)

SINGAPORE ACCIDENT STATEMENT

-> prepare quotation for insurance
claim
SMRT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2017 09:50
Date Of Accident	17/11/2017 07:20
Exact Location Of Accident	ANG MO KIO AVE 5 EXIT BEFORE CTE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD6534Z
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE HIRE
------------------	--------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHRISTOPHER LIM TSING YEW
NRIC No	S7210087E
Date Of Birth	29/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	16/07/1994
Driving Experience	23 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97704746
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - LESSEE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4519999 - FAX NO: 65535679

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: THE VIDEO FOOTAGE IS WITH TRAFFIC POLICE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD1463X

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver MOK YEW LEONG

NRIC/Passport Number S1688223B

Contact Number 97479466

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBD1463X

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17/11/17

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2.40pm

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/11/2017 at about 7.20 hrs, while I (SLD 6534 Z) was driving along Ang Mo Kio Ave 5 towards Yio Chu Kang Road at the most left lane. As I was approaching the traffic light before the CTE exit, I discovered the the traffic light had turned red as such I quickly applied footbrake immediately. However due to the slippery road surface as it was drizzling, my vehicle could not stop in time resulting in my vehicle to collide onto the oncoming vehicle's (GBD 1463 X) left side which is making a right turn. After which I called for police assistance and we decided to exchange particulars. Traffic police came to the scene and I was issued with a police case and reference E/2017/11/0050. The passenger who is sitting at the front left of GBD 1463 X injured her left arm from the accident and was conveyed to hospital by ambulance. At the point of time, my 2 children (1 son and 1 daughter) was seated at the back of the passenger's seat and they are not injured. The driver of GBD 1463 X did not suffer any injury. I wish to state that there is a built in camera in my vehicle and the memory card was seized by the traffic police. My vehicle's front was severely dented and was towed away. I do not have the particulars of the person conveyed to hospital.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17/11/17
2.40pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20171117/2019

1 of 4

Report No. T/20171117/2019

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/11/2017 10:05	Vide Report No.: E/20171117/0050	Station Diary No.: 11
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHRISTOPHER LIM TSING YEW			Address: APT BLK 271B SENGKANG CENTRAL #15-269 SINGAPORE 542271		
ID Type / ID No.: NRIC NO / S7210087E			Contact No.: Home/Office: Mobile: 97704746		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 29/03/1972	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB CAR DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 17/11/2017 07:20	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 5 EXIT BEFORE CTE EXIT				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 65 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD1463X	Van	MERCEDES BENZ	CITAN 109 CDI VAN EXTRA- LONG - 2 SEATERS	Silver	Slightly Damaged	1
SLD6534Z	Car	TOYOTA	COROLLA ALTIS CLASSIC 1.6 CVT	Silver	Seriously Damaged	2



Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Mok Yew Leong	ID No.	S1688223B
Related Vehicle	GBD1463X (Van)	Contact No.	97479466
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHRISTOPHER LIM TSING YEW	ID No.	S7210087E
Related Vehicle	SLD6534Z (Car)	Contact No.	97704746
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/11/2017 at about 0720hrs, while I (SLD6534Z) was driving along Ang Mo Kio Avenue 5 towards Yio Chu Kang road at the most left lane. As I was approaching the traffic light before the CTE exit, I discovered that the traffic light had turned red as such I quickly applied footbrake immediately. However due to the slippery road surface as it was drizzling, my vehicle couldn't stop in time resulted in my vehicle to collide onto the oncoming vehicle's (GBD1463X) left side which is making a right turn. After which I called for police assistance and we alighted to exchange particulars. Traffic Police came to scene and I was issued with a police case card reference E/20171117/0050. The passenger who is sitting at the front left of GBD1463X was injured from the accident and was conveyed to the hospital.

At the point of time my 2 children (1 Son and 1 daughter) was seated at the back of the passenger's seat and they are not injured. The driver of GBD1463X did not suffer any injury.

I wish to state that there is built in camera in my vehicle and the memory card was seized by the Traffic Police. My vehicle's front was severely dented and was towed away. I do not have the particulars of the person conveyed to hospital.

Particulars of the GBD1463X driver:

Name: Mok Yew Leong
NRIC: S1688223B
HP: 97479466



**SINGAPORE
POLICE FORCE**



T/20171117/2019

3 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20171117/2019

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20171117/2019

4 of 4

Report No. T/20171117/2019

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 TAY YU ZHI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SSI TAN CHIN YONG
Contact No.: 65476178

Signature Of Informant:

Date/Time:
17/11/2017 10:05

Classification Of Case:

Authentication Stamp
NP 168



SN 085

Signature:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn: Bernard Tan (Mr) 68662706 \ 97727146
(Bernard Tan / Damian Chan)

Invoice No : NR10056245
Date : 06/10/2016
Mileage : 17074 km
Terms : 30 days
Due Date : 05/11/2016
Page : 1 / 2

Collection Date : 06/10/2016 Time : By : Self Parking Lot :
Delivery Date : 06/10/2016 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. Normal Service -

		Qty	\$\$Unit	\$\$Amt	\$\$Labor
1. Normal Service					
1 Castrol EDGE Fully Synthetic Engine Oil	Castrol Edge 完全合成エンジンオイル	4.00			
2 Toyota Oil Filter YZZE2		1.00			
3 Every 10,000km interval service - to service engine, engine oil & oil filter change - To check Vehicle Condition (Engine,Brake,All Beltings)& Adjust if Necessary - To vacuum interior and clean up vehicle	10000km毎の定期点検 エンジンオイル、オイルフィルター交換。 原動機、駆動系、緩衝装置、懸架装置、制動装置、電装系、等の点検および清掃。	1.00	130.00	130.00	

SubTotal : 130.00 0.00

Less:

1 Under Hitachi Capital Auto Leasing Maintenance Contract -130.00

SubTotal : -130.00

Grand Total : 0.00

Add 0 % GST : 0.00

Net Total After GST : 0.00

 Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Bernard Tan (Mr) 68662706 \ 97727146
(Bernard Tan / Damian Chan)

Invoice No : NR10056245
Date : 06/10/2016
Mileage : 17074 km
Terms : 30 days
Due Date : 05/11/2016
Page : 2 / 2

Interest of 1% per month will be charged on any amount outstanding from due date

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.


Customer Signature's & Chop

Service Manager
Job done by :

メンテナンス報告書

Name : Bernard Tan (Mr)
 Regn No. : SLD6534Z
 Car Model : Toyota Altis
 Inspector Name : CHUN

Date : 06/10/2016
 Speedo (km) : 17074
 振当 : TODA



5 Just renewed 4 Still Good 3 Ordinal Condition 2 Renew/repair may be needed soon 1 Necessary to rectify or renew now

Battery Model :		46B24LS		Tyre Model :		205/55R16	
Battery Voltage							
Cranking :		11.73 V		Engine Off :		12.69 V	
				Charging :		13.72 V	
Tyre Condition		Before		After			
Tyre Pressure Front :		30.00 psi		32.00 psi			
Tyre Pressure Rear :		30.00 psi		32.00 psi			

この度は、JUN TAIYO SERVICE CENTRE をご利用いただき、誠にありがとうございます。今回のメンテナンスは完了いたしました。下記○印の項目に関しましては、今後修理または部品交換されることをお勧めする内容です。

	Particulars	S\$Price
☐	Recommend to replace timing belt, timing bearing, timing oil seals, water pump, thermostat, fan belt, fan belt tensioner bearing, water hoses, radiator	
☐	Recommend to replace front & rear absorber, stoppers, front absorber mounting & bearing, front & rear stabilizer linkage, center bush	
☐	Recommend to do flushing auto transmission oil	
☐	Recommend to renew brake oil & bleeding	
☐	Recommend to flushing coolant system, renew coolant & bleeding	
☐	Recommend to remove carbon throttle body & idling control valve	
☐	Recommend to do flushing engine system, refill engine oil & engine oil treatment	
☐	Recommend to do electrical 4 wheel alignment & tyres balancing	

Memo :

FUTURE コンディションが悪くなっており、今後問題が発生する可能性があります。

NEXT 次回メンテナンス時には処理されることをお勧めします。

お問い合わせは日本語で----

電話 : 64663022

Fax : 68966591

Email: juntaiyo@hcspl.com.sg

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
 60 Woodlands
 Industrial Park E4
 Singapore 757705

Attn : Bernard Tan (Mr) 68662706 \ 97727148
 (Bernard Tan / Damian Chan)

Invoice No : NR10059992
 Date : 06/02/2017
 Mileage : 32684 km
 Terms : 0 days
 Due Date : 06/02/2017
 Page : 1 / 2

Collection Date : 06/02/2017 Time : By : self Parking Lot :
 Delivery Date : 06/02/2017 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
 REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. Normal Service -

		Qty	\$\$Unit	\$\$Amt	\$\$Labor
1. Normal Service					
1 Liqui Moly Fully Synthetic Engine Oil Grade : (5W40)		4.50			
2 Toyota General A/C Filter CA-1114	エアコンフィルター	1.00	30.00	30.00	
3 Toyota Air Filter A1417	エアーフィルター	1.00	35.00	35.00	
4 Toyota Oil Filter YZZE2		1.00			
5 Every 10,000km interval service - to service engine, engine oil & oil filter change - To check Vehicle Condition (Engine,Brake,All Beltings)& Adjust if Necessary - To vacuum interior and clean up vehicle	10000km毎の定期点検 エンジンオ イル、オイルフィルター交換。 原動機、駆動系、緩衝装置、懸 架装置、制動装置、電装 系、等の点検および清掃。	1.00	133.00	133.00	

SubTotal : 198.00 0.00

Less:

1 Under Hitachi Capital Auto Leasing
Maintenance Contract -198.00

SubTotal : -198.00

Grand Total : 0.00

Add 0 % GST : 0.00

Net Total After GST : 0.00

 Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Bernard Tan (Mr) 68662706 \ 97727146
(Bernard Tan / Damian Chan)

Invoice No : NR10059992
Date : 06/02/2017
Mileage : 32684 km
Terms : 0 days
Due Date : 06/02/2017
Page : 2 / 2

Interest of 1% per month will be charged on any amount outstanding from due date

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :

Hitachi Capital Asia Pacific Pte. Ltd.


Customer Signature's & Chop

Service Manager
Job done by : weng

メンテナンス報告書

Name : Bernard Tan (Mr)
 Regn No. : SLD6534Z
 Car Model : Toyota Ailis
 Inspector Name : WENG

Date : 06/02/2017
 Speedo (km) : 32684
 車里 : LIANG



5 Just renewed 4 Still Good 3 Ordinal Condition 2 Renew/repair may be needed soon 1 Necessary to rectify or renew now

Battery Model :		46B24LS		Tyre Model :		205/55/R16	
Battery Voltage							
Cranking :		11.80 V		Engine Off :		12.87 V	
				Charging :		14.10 V	
Tyre Condition		Before		After			
Tyre Pressure Front :		28.00 psi		33.00 psi			
Tyre Pressure Rear :		28.00 psi		33.00 psi			

この度は、JUN TAIYO SERVICE CENTRE をご利用いただき、誠にありがとうございます。今回のメンテナンスは完了いたしました。下記○印の項目に関しましては、今後修理または部品交換されることをお勧めする内容です。

	Particulars	SSPrice
☐	Recommend to replace timing belt,timing bearing, timing oil seals, water pump, thermostat, fan belt, fan belt tensioner bearing, water hoses, radiator	
☐	Recommend to replace front & rear absorber, stoppers, front absorber mounting & bearing, front & rear stabilizer linkage, center bush	
☐	Recommend to do flushing auto transmission oil	
☐	Recommend to renew brake oil & bleeding	
☐	Recommend to flushing coolant system, renew coolant & bleeding	
☐	Recommend to remove carbon throttle body & idling control valve	
☐	Recommend to do flushing engine system, refill enginer oil & engine oil treatment	
☐	Recommend to do electrical 4 wheel alignment & tyres balancing	
Memo :		

FUTURE コンディションが悪くなっており、今後問題が発生する可能性があります。

NEXT 次回メンテナンス時には処理されることをお勧めします。

お問い合わせは日本語で——

電話 : 64663022

Fax : 68966591

Email: juntaiyo@hcspl.com.sg

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
 60 Woodlands
 Industrial Park E4
 Singapore 757705

Attn : Bernard Tan (Mr) 63690111 \ 97727146
 (Bernard Tan / Damian Chan)

Invoice No : NR10062753
 Date : 27/04/2017
 Mileage : 52615 km
 Terms : 0 days
 Due Date : 27/04/2017
 Page : 1 / 2

Collection Date : 27/04/2017 Time : By : Self Parking Lot :
 Delivery Date : 27/04/2017 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
 REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. Normal Service -

	Qty	\$\$Unit	\$\$Amt	\$\$Labor
1. Normal Service				
1 Toyota Front Brake Pads 12630 / 02310	1.00	125.00	125.00	
2 Toyota Oil Filter 90915-YZZE2	1.00			
3 Liqui Moly Fully Synthetic Engine Oil Grade : (5W40)	4.00			
4 Every 10,000km interval service - to service engine, engine oil & oil filter change - To check Vehicle Condition (Engine,Brake,All Beltings)& Adjust if Necessary - To vacuum interior and clean up vehicle	1.00	133.00	133.00	
10000km毎の定期点検 エンジンオイル、オイルフィルター交換。 原動機、駆動系、緩衝装置、懸架装置、制動装置、電装系、等の点検および清掃。				

SubTotal : 258.00 0.00

Less:

1 Under Hitachi Capital Auto Leasing
 Maintenance Contract -258.00

SubTotal : -258.00

Grand Total : 0.00

Add 0 % GST : 0.00

Net Total After GST : 0.00

Brake Pad Remarks:

☒ Front Brake Pad 1 ☐ Rear Brake Pad

 Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Bernard Tan (Mr) 63690111 \ 97727146
(Bernard Tan / Damian Chan)

Invoice No : NR10062753
Date : 27/04/2017
Mileage : 52615 km
Terms : 0 days
Due Date : 27/04/2017
Page : 2 / 2

Interest of 1% per month will be charged on any amount outstanding from due date

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

Customer Signature's & Chop

Service Manager
Job done by : BAO

メンテナンス報告書

Name : Bernard Tan (Mr)

Regn No. : SLD6534Z


Date : 27/04/2017

Car Model : Toyota Altis

Speedo (km) : 52615

Inspector Name : BAO

車台 : LIANG



5 Just renewed 4 Still Good 3 Ordinal Condition 2 Renew/repair may be needed soon 1 Necessary to rectify or renew now

Battery Model : 46B24LS	Tyre Model : 205/55/R16
Battery Voltage	
Cranking : 11.80 V	Engine Off : 12.87 V
	Charging : 13.93 V

Tyre Condition	Before	After
Tyre Pressure Front :	25.00 psi	32.00 psi
Tyre Pressure Rear :	25.00 psi	32.00 psi

この度は、JUN TAIYO SERVICE CENTRE をご利用いただき、誠にありがとうございます。今回のメンテナンスは完了いたしました。下記○印の項目にしましては、今後修理または部品交換されることをお勧めする内容です。

	Particulars	SSPrice
☐	Recommend to replace timing belt, timing bearing, timing oil seals, water pump, thermostat, fan belt, fan belt tensioner bearing, water hoses, radiator	
☐	Recommend to replace front & rear absorber, stoppers, front absorber mounting & bearing, front & rear stabilizer linkage, center bush	
☐	Recommend to do flushing auto transmission oil	
☐	Recommend to renew brake oil & bleeding	
☐	Recommend to flushing coolant system, renew coolant & bleeding	
☐	Recommend to remove carbon throttle body & idling control valve	
☐	Recommend to do flushing engine system, refill engine oil & engine oil treatment	
☐	Recommend to do electrical 4 wheel alignment & tyres balancing	
Memo :		

FUTURE コンディションが悪くなっており、今後問題が発生する可能性があります。

NEXT 次回メンテナンス時には処理されることをお勧めします。

お問い合わせは日本語で……

電話 : 64663022

Fax : 68966591

Email: juntaiyo@hcspl.com.sg

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Damian Chan 63690111 \ 90615576 & 92252599
(Damian Chan/ChongKaren@smrt.com.sg)

Invoice No : NR10064368
Date : 15/06/2017
Mileage : 65193 km
Terms : 0 days
Due Date : 15/06/2017
Page : 1 / 2

Collection Date : 15/06/2017 Time : 2.00 self By : Parking Lot :
Delivery Date : 15/06/2017 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. Normal Service -

	Qty	SSUnit	SSAmt	SSLabor
1. Normal Service				
1 Liqui Moly Fully Synthetic Engine Oil Grade : (5W40)	4.50			
2 Oil Drain Plug	1.00			
3 Toyota Oil Filter 90915-YZZE2	1.00			
4 Toyota Wiper Rubber 350mm	1.00	18.00	18.00	
5 Toyota Wiper Rubber 650mm	1.00	24.00	24.00	
6 Every 10,000km interval service - to service engine, engine oil & oil filter change - To check Vehicle Condition (Engine,Brake,All Beltings)& Adjust if Necessary - To vacuum interior and clean up vehicle	1.00	133.00	133.00	
10000km毎の定期点検 エンジンオイル、オイルフィルター交換。 原動機、駆動系、緩衝装置、懸架装置、制動装置、電装系、等の点検および清掃。				

SubTotal : 175.00 0.00

Less:

1 Under Hitachi Capital Auto Leasing
Maintenance Contract -175.00

SubTotal : -175.00

Grand Total : 0.00

Add 0 % GST : 0.00

Net Total After GST : 0.00

 Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co,Reg No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Damian Chan 63690111 \ 90615576 & 92252599
(Damian Chan/ChongKaren@smrt.com.sg)

Invoice No : NR10064368
Date : 15/06/2017
Mileage : 65193 km
Terms : 0 days
Due Date : 15/06/2017
Page : 2 / 2

Interest of 1% per month will be charged on any amount outstanding from due date

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.


Customer Signature's & Chop

Service Manager
Job done by : Meng

メンテナンス報告書

Name : Damian Chan
 Regn No. : SLD6534Z
 Car Model : Toyota Altis
 Inspector Name : Meng

Date : 15/06/2017
 Speedo (km) : 65193
 車主 : NICKY



5 Just renewed 4 Still Good 3 Ordinal Condition 2 Renew/repair may be needed soon 1 Necessary to rectify or renew now

Battery Model :		46b24ls		Tyre Model :		205/55r16	
Battery Voltage							
Cranking :		11.12 V		Engine Off :		12.43 V	
				Charging :		13.82 V	
Tyre Condition		Before		After			
Tyre Pressure Front :		29.00 psi		32.00 psi			
Tyre Pressure Rear :		29.00 psi		32.00 psi			

この度は、JUN TAIYO SERVICE CENTRE をご利用いただき、誠にありがとうございます。今回のメンテナンスは完了いたしました。
 下記○印の項目に関しては、今後修理または部品交換されることをお勧めする内容です。

	Particulars	SSPrice
☐	Recommend to replace timing belt,timing bearing, timing oil seals, water pump, thermostat, fan belt, fan belt tensioner bearing, water hoses, radiator	
☐	Recommend to replace front & rear absorber, stoppers, front absorber mounting & bearing, front & rear stabilizer linkage, center bush	
☐	Recommend to do flushing auto transmission oil	
☐	Recommend to renew brake oil & bleeding	
☐	Recommend to flushing coolant system, renew coolant & bleeding	
☐	Recommend to remove carbon throttle body & idling control valve	
☐	Recommend to do flushing engine system, refill engine oil & engine oil treatment	
☐	Recommend to do electrical 4 wheel alignment & tyres balancing	
Memo :		

FUTURE エンジンが悪くなっており、今後問題が発生する可能性があります。

NEXT 次回メンテナンス時には処理されることをお勧めします。

お問い合わせは日本語で-----

電話 : 64663022

Fax : 68966591

Email: juntaiyo@hcspl.com.sg

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64863022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Damian Chan 63690111 \ 90615576 & 92252599
(Damian Chan/ChongKaren@smrt.com.sg)

Invoice No : NR10064527
Date : 20/06/2017
Mileage : km
Terms : 0 days
Due Date : 20/06/2017
Page : 1 / 1

Collection Date : 20/06/2017 Time : By : SELF Parking Lot :
Delivery Date : 20/06/2017 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. HARD STARTING -

	Qty	S\$Unit	S\$Amt	S\$Labor
1. HARD STARTING				
1 Amaron Battery 55B24LS	1.00	120.00	120.00	
			SubTotal :	120.00 0.00
Less:				
1 Under Hitachi Capital Auto Leasing Maintenance Contract				-120.00
			SubTotal :	-120.00
			Grand Total :	0.00
			Add 0 % GST :	0.00
			Net Total After GST :	0.00

Interest of 1% per month will be charged on any amount outstanding from due date.

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.

Customer Signature's & Chop

Service Manager
Job done by : BAO

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel: 64663022 Fax: 68966591
 Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
 60 Woodlands
 Industrial Park E4
 Singapore 757705

Attn : Damian Chan 63690111 \ 90615576 & 92252599
 (Damian Chan/ChongKaren@smrt.com.sg)

Invoice No : NR10069174
 Date : 16/10/2017
 Mileage : 80606 km
 Terms : 0 days
 Due Date : 16/10/2017
 Page : 1 / 2

Collection Date : 16/10/2017 Time : 9AM self By : Parking Lot :
 Delivery Date : 16/10/2017 Time : By : Contract : 61585 (27/06/2016-26/06/2021)
 REGN. No. : SLD6534Z Make : Toyota Altis

CUSTOMER'S REQUEST(S)

1. Normal Service - 80K servicing

	Qty	S\$Unit	S\$Amt	S\$Labor
1. Normal Service				
1 Liqui Moly Fully Synthetic Engine Oil Grade : (5W40)	4.50			
2 Toyota Oil Filter 90915-YZZE2	1.00			
3 Toyota ATF CVTF FE	4.00	22.00	88.00	
4 Hankook K425 Kinergy Eco 205/55R16	2.00	108.00	216.00	
5 Every 40,000km interval service - to service engine, engine oil & oil filter change - To check Vehicle Condition (Engine,Brake,All Beltings)& Adjust if Necessary - To vacuum interior and clean up vehicle	1.00	159.00	159.00	
				40000km毎の定期点検 エンジンオイル、オイルフィルター交換。 原動機、駆動系、緩衝装置、懸架装置、制動装置、電装系、等の点検および清掃。

SubTotal : 463.00 0.00

Less:

1 Under Hitachi Capital Auto Leasing Maintenance Contract -463.00

SubTotal : -463.00

Grand Total : 0.00

Add 0 % GST : 0.00

Net Total After GST : 0.00

Tyre Remarks:

☒ Front Tyre 2 ☐ Rear Tyre

 Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel: 64663022 Fax: 68966591
Co.Reg.No. 199400399N GST Reg. No. M2-0118999-3

TAX INVOICE

M/S : Strides Transportation Pte Ltd
60 Woodlands
Industrial Park E4
Singapore 757705

Attn : Damian Chan 63690111 \ 90615576 & 92252599
(Damian Chan/ChongKaren@smrt.com.sg)

Invoice No : NR10069174
Date : 16/10/2017
Mileage : 80606 km
Terms : 0 days
Due Date : 16/10/2017
Page : 2 / 2

Interest of 1% per month will be charged on any amount outstanding from due date

All claims must be made within seven days

CUSTOMER'S ACKNOWLEDGEMENT

Received the above mentioned vehicle in satisfactory condition

All cheques should be crossed and made payable to :
Hitachi Capital Asia Pacific Pte. Ltd.


Customer Signature's & Chop

Service Manager
Job done by : YEAP

メンテナンス報告書

Name : Damian Chan
Regn No. : SLD6534Z
Car Model : Toyota Altis
Inspector Name : YEAP

Date : 16/10/2017
Speedo (km) : 80606
車番 : LIANG



5 Just renewed 4 Still Good 3 Ordinal Condition 2 Renew/repair may be needed soon 1 Necessary to rectify or renew now

Battery Model : 55B24L	Tyre Model : 205/55/R16
Battery Voltage	
Cranking : 11.08 V	Engine Off : 12.87 V
Charging : 13.97 V	

Tyre Condition	Before	After
Tyre Pressure Front :	27.00 psi	32.00 psi
Tyre Pressure Rear :	27.00 psi	32.00 psi

この度は、JUY TAIYO SERVICE CENTRE をご利用いただき、誠にありがとうございます。今回のメンテナンスは完了いたしました。下記○印の項目に関しては、今後修理または部品交換されることをお勧めするものです。

Particulars	SSPrice
☐ Recommend to replace timing belt, timing bearing, timing oil seals, water pump, thermostat, fan belt, fan belt tensioner bearing, water hoses, radiator	
☐ Recommend to replace front & rear absorber, stoppers, front absorber mounting & bearing, front & rear stabilizer linkage, center bush	
☐ Recommend to do flushing auto transmission oil	
☐ Recommend to renew brake oil & bleeding	
☐ Recommend to flushing coolant system, renew coolant & bleeding	
☐ Recommend to remove carbon throttle body & idling control valve	
☐ Recommend to do flushing engine system, refill engine oil & engine oil treatment	
☐ Recommend to do electrical 4 wheel alignment & tyres balancing	
Memo :	

FUTURE コンディションが悪くなっており、今後問題が発生する可能性があります。

NEXT 次回メンテナンス時には処理されることをお勧めします。

お問い合わせは日本語で――

電話 : 64663022

Fax : 68966591

Email : juntaiyo@hcspl.com.sg

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLD6534Z
Policy No:	MSD/VPCP/17-001233	Date of Loss:	17/11/2017
Vehicle Reg. No.:	SLD6534Z	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD			
Driver: CHRISTOPHER LIM TSING YEOW			
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg Date:	24/06/2016
Vehicle Colour:	SILVER		
Engine No:	1ZRX582913	Chassis No:	MR053REH104553415
Odometer:	70128 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Description of Accident/Loss	PLEASE REFER TO THE POLICE REPORT.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	19,368.10
Miscellaneous Items	0.00
Labour	9,770.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	29,138.10
- Excess (S\$)	1,500.00
(S\$)	27,638.10
+ GST 7.00% (S\$)	1,934.67
Nett Amount (S\$)	29,572.77

 This claim is handled by: **SUN ZHU MEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2017)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper	0.00	0.00	*230.00 FMS
2	10		*Front Bumper Clips	0.00	0.00	*350.00 FMS
3	2		*Front Bumper Retainer Outer RH/LH	0.00	0.00	*10.00 FMS
4	2		*Front Bumper Retainer Inner RH/LH	0.00	0.00	*10.00 FMS
5	1		*Front Grille Top Garnish	0.00	0.00	*35.00 FMS
6	10		*Top Grille Clips	0.00	0.00	*15.00 FMS
7	1		*Headlamp Chrome Moulding RH/LH	0.00	0.00	*60.00 FMS
8	1		*Headlamp Full Set Assembly RH	0.00	0.00	*320.00 FMS
9	1		*Headlamp Full Set Assembly LH	0.00	0.00	*320.00 FMS
10	1		*Front Bumper Lower Grille	0.00	0.00	*50.00 FMS
11	2		*Front Bumper Fog Lamp RH/LH	0.00	0.00	*170.00 FMS
12	1		*Front Nuber Plate with Casing	0	0.00	*45.00 FMS
13	1		*Bonnet	0.00	0.00	*270.00 FMS
14	2		*Bonnet Hinge LH/RH	0.00	0.00	*60.00 FMS
15	1		*Bonnet Lock	0.00	0.00	*60.00 FMS
16	1		*Bonnet Insulator	0.00	0.00	*95.00 FMS
17	8		*Insulator Clips	0.00	0.00	*12.00 FMS
18	1		*Front Reinforcement	0.00	0.00	*110.00 FMS
19	1		*Front Reinforcement Sponge	0.00	0.00	*35.00 FMS
20	1		*Support Panel	0.00	0.00	*220.00 FMS
21	1		*Brace Panel	0.00	0.00	*40.00 FMS
22	1		*Horn	0.00	0.00	*50.00 FMS
23	1		*Wiper Garnish	0.00	0.00	*240.00 FMS
24	2		*Front Chassis Extension RH/LH	0.00	0.00	*70.00 FMS
25	1		*Air Condenser	0.00	0.00	*270.00 FMS
26	1		*Radiator	0.00	0.00	*380.00 FMS
27	2		*Radiator Top Bracket	0.00	0.00	*50.00 FMS
28	2		*Radiator Bottom Bush	0.00	0.00	*30.00 FMS
29	1		*Radiator Fan Cowling Set	0.00	0.00	*90.00 FMS
30	1		*Radiator Fan Cowling Top	0.00	0.00	*50.00 FMS
31	1		*Radiator Fan Motor	0.00	0.00	*180.00 FMS
32	1		*Radiator Fan Blade	0.00	0.00	*55.00 FMS
33	1		*Radiator Top Hose	0.00	0.00	*25.00 FMS
34	1		*Radiator Bottom Hose	0.00	0.00	*20.00 FMS
35	2		*Front Fender RH/LH	0.00	0.00	*380.00 FMS
36	2		*Front Fender Emblem RH/LH	0.00	0.00	*36.00 FMS
37	2		*Front Fender Shield RH/LH	0.00	0.00	*110.00 FMS
38	1		*Battery Top Bracket	0.00	0.00	*25.00 FMS
39	1		*Battery	0	0.00	*300.00 FMS
40	1		*Battery Base Panel	0.00	0.00	*65.00 FMS
41	1		*Battery Base Plastic Cover	0.00	0.00	*60.00 FMS
42	1		*Air Duct	0.00	0.00	*65.00 FMS

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*Air Duct Hose	0.00	0.00	*60.00 F CRA
44	1		*Air Duct Resonator Box	0.00	0.00	*60.00 F DE
45	1		*Fuse Box Top Cover	0.00	0.00	*50.00 F ? CRA
46	1		*Wire Hardness (Engine)	0.00	0.00	*1,600.00 F ? X SVL
47	1		*Wire Hardness (1set)	0.00	0.00	*3,200.00 F ? X SVL
48	1		*Alternator	0.00	0.00	*650.00 F ? CRA
49	1		*Alternator Beel	0.00	0.00	*50.00 F ? CRA
50	1		*Aircon Compressor	0.00	0.00	*450.00 F ? CRA
51	1		*Intake Manifold	0.00	0.00	*210.00 F cut
52	1		*Front Windscreen	0.00	0.00	*400.00 F CRA
53	1		*Front Windscreen Moulding 1set	0.00	0.00	*40.00 F new
54	1		*Sealant	0	0.00	*45.00 FS new
55	1		*Engine Undercover Centre	0.00	0.00	*95.00 F MIS
56	2		*Engine Undercover LH/RH	0.00	0.00	*80.00 F DE
57	10		*Engine Undercover Clips	0.00	0.00	*15.00 F new
58	1		*Wiper Tank	0.00	0.00	*65.00 F DE
59	1		*Radiator Spare Tank	0.00	0.00	*55.00 F DE
60	1		*Wiper Tank Motor	0.00	0.00	*85.00 F ?
61	1		*Engine Mounting Front	0.00	0.00	*65.00 F ?
62	1		*Engine Mounting LH/RH (LH-\$95, RH-\$125)	0.00	0.00	*220.00 F ?
63	1		*Engine Mounting Bracket Front	0.00	0.00	*50.00 F ?
64	1		*Dashboard	0.00	0.00	*650.00 F new
65	1		*Driver Airbag	0.00	0.00	*850.00 F ACT
66	1		*Driver Airbag Coil Spring	0.00	0.00	*170.00 F ACT
67	1		*Passenger Airbag	0.00	0.00	*1,150.00 F ACT
68	1		*Airbag Control Unit	0.00	0.00	*600.00 F ACT
69	2		*Front Impact Sensor RH/LH	0.00	0.00	*520.00 F ACT
70	2		*Seatbelt LH/RH	0.00	0.00	*560.00 F ACT
71	2		*Seatbelt Buckle RH Seatbelt buckle LH	0.00	0.00	*220.00 F ?
72	1		*Coolant	0	0.00	*45.00 FS new
73	1		*Auto Transmission Fluid Original	0.00	0.00	*88.00 F new
74	1	REPAIR	*Passenger Door	0.00	0.00	-
75	1	REPAIR	*Driver Door	0.00	0.00	-
76	1		*Front Grille with Logo	0.00	0.00	*150.00 F new
77	1		*Sealant	0	0.00	*45.00 FS new

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 17,651.00
+ Margin on L,N Items 10.00% (\$\$) 1,717.10

Total Parts (\$\$) 19,368.10

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,400.00 2,000
2	Putty, blend and paint affected area	New	2,200.00 1,800
3	Check Wiring and ensure proper function	New	120.00 60
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 100
5	Conduct four wheel alignment / side slip test	New	150.00 80
6	Realign chassis member	New	600.00 300
7	Remove & re-install undercarriage parts	New	350.00 150
8	Remove and reinstall door lock & mechanism	New	300.00 X
9	Remove & reinstall exhaust manifold / centre pipe	New	200.00 100
10	Diagnostic Check & Reset (Engine) engine	New	420.00 200
11	Repair and Realign A and B Pillar	New	400.00 200
12	Remove Upholstery Trim and Cushion	New	500.00 200
13	Remove and install Dashboard	New	300.00 150
14	Remove and refit windscreen	New	150.00 120
15	Remove and replace airbag complete unit	New	400.00 250
16	Remove and reinstall engine and gearbox unit to facilitate realign chassis frame	New	500.00 300
17	Conduct Car O liner adjustment	New	X photo 600.00 300 X
	- Diagnose reset air bag system programming Airbag		500 200
	- Remove & replace wire harness complete self		300 150
Gross Labour Cost (S\$)			9,770.00

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Rasul
Hp 90010068
18 days
29/11/17 @ 1650
Excess: 1500
Revert
Resury 64 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HITACHI
 Inspire the Next

(SUPPLEMENTARY)

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLD6534Z
Policy No:	MSD/VPCP/17-001233	Date of Loss:	17/11/2017
Vehicle Reg. No.:	SLD6534Z	Driveable?	
Driver Age/Info:	45 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD			
Driver: CHRISTOPHER LIM TSING YEW			
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	24/06/2016
Vehicle Colour:	SILVER		
Engine No:	1ZRX582913	Chassis No:	MR053REH104553415
Odometer:	70128 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Description of Accident/Loss	PLEASE REFER TO THE POLICE REPORT.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	4,316.00
Miscellaneous Items	0.00
Labour	350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,666.00
+ GST 7.00% (\$\$)	326.62
Nett Amount (\$\$)	4,992.62
+ Previous Estimates (\$\$)	29,572.77
Claim Total (\$\$)	34,565.39

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Feb 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue/Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/10/02/2018 13:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Aircon discharge hose	0.00	0.00	*150.00 F bot
2	1		*Aircon suction hose	0.00	0.00	*210.00 F bot
3	1		*Aircon pressure liquid pipe	0.00	0.00	*280.00 F bot
4	1		*Auto transmission ATF oil sump pan	0.00	0.00	*75.00 F bot
5	1		*Brake ABS actuator pump	0.00	0.00	*1,900.00 F bot
6	1		*Front center crossmember	0.00	0.00	*160.00 F bot
7	1		*Front wheel house RH	0.00	0.00	*180.00 F bot
8	1		*Bonnet lock cable	0.00	0.00	*30.00 F bot
9	1		*Engine top cover cylinder	0.00	0.00	*85.00 F bot
10	1		*Airbag wire LH	0.00	0.00	*40.00 F bot
11	1		*Bonnet lock clip holder	0.00	0.00	*10.00 F bot
12	2		*Front reinforcement bracket LH / RH	0.00	0.00	*80.00 F bot
13	1		*Front chassis side plate RH	0.00	0.00	*30.00 F bot
14	1		*Front chassis side plate LH	0.00	0.00	*60.00 F bot
15	1		*Air cleaner assembly	0.00	0.00	*250.00 F bot
16	1		*Radiator fan/cooling computer	0.00	0.00	*170.00 F bot
17	1		*Battery carrier	0.00	0.00	*25.00 F bot
18	1		*Wiper washer inlet neck	0.00	0.00	*25.00 F bot
19	1		*Auto transmission fluid (ATF) 4 Litre	0	0.00	*120.00 FS bot
20	1		*Brake fluid	0	0.00	*60.00 FS bot

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,940.00
+ Margin on L,N Items 10.00% (S\$)	376.00
Total Parts (S\$)	4,316.00

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/10/02/2018 13:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Diagnostic reset air bag system and programming	New	200.00
2	Remove and replace wire harness complete set	New	150.00
Gross Labour Cost (S\$)			350.00

Hitachi Capital Asia Pacific Pte. Ltd/SLD5534Z/10/02/2018 13:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

@ Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2017)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper	0.00	0.00	230.00 FM13
2	10		*Front Bumper Clips	0.00	0.00	350.00 FALC
3	2		*Front Bumper Retainer Outer RH/LH	0.00	0.00	10.00 FALC
4	2		*Front Bumper Retainer Inner RH/LH	0.00	0.00	70.00
5	1		*Front Grille Top Garnish	0.00	0.00	35.00 F CRA
6	10		*Top Grille Clips	0.00	0.00	15.00 FALC
7	1		*Headlamp Chrome Moulding RH/LH	0.00	0.00	60.00 F CRA
8	1		*Headlamp Full Set Assembly RH	0.00	0.00	320.00 F B/R
9	1		*Headlamp Full Set Assembly LH	0.00	0.00	320.00 F B/R
10	1		*Front Bumper Lower Grille	0.00	0.00	50.00 FM13
11	2		*Front Bumper Fog Lamp RH/LH	0.00	0.00	170.00 F CRA
12	1		*Front Nuber Plate with Casing	0	0.00	45.00 F FM13
13	1		*Bonnet	0.00	0.00	270.00 F FALC
14	2		*Bonnet Hinge LH/RH	0.00	0.00	60.00 F FA
15	1		*Bonnet Lock	0.00	0.00	60.00 FM
16	1		*Bonnet Insulator	0.00	0.00	95.00 F DE
17	8		*Insulator Clips	0.00	0.00	12.00 FALC
18	1		*Front Reinforcement	0.00	0.00	110.00 F BT
19	1		*Front Reinforcement Sponge	0.00	0.00	35.00 F FM13
20	1		*Support Panel	0.00	0.00	220.00 F B/R
21	1		*Brace Panel	0.00	0.00	40.00 F BT
22	1		*Horn	0.00	0.00	50.00 F FALC
23	1		*Wiper Garnish	0.00	0.00	240.00 F FALC
24	2		*Front Chassis Extension RH/LH	0.00	0.00	70.00 F BT
25	1		*Air Condenser	0.00	0.00	270.00 FM
26	1		*Radiator	0.00	0.00	380.00 F BT
27	2		*Radiator Top Bracket	0.00	0.00	50.00 F BT
28	2		*Radiator Bottom Bush	0.00	0.00	30.00 F FALC
29	1		*Radiator Fan Cowling Set	0.00	0.00	90.00 F CRA
30	1		*Radiator Fan Cowling Top	0.00	0.00	50.00 F CRA
31	1		*Radiator Fan Motor	0.00	0.00	180.00 F ?
32	1		*Radiator Fan Blade	0.00	0.00	55.00 F ?
33	1		*Radiator Top Hose	0.00	0.00	25.00 F ?
34	1		*Radiator Bottom Hose	0.00	0.00	20.00 F ?
35	2		*Front Fender RH/LH	0.00	0.00	380.00 F FALC
36	2		*Front Fender Emblem RH/LH	0.00	0.00	36.00 F FALC
37	2		*Front Fender Shield RH/LH	0.00	0.00	110.00 F DE
38	1		*Battery Top Bracket	0.00	0.00	25.00 F BT
39	1		*Battery	0	0.00	300.00 F FALC
40	1		*Battery Base Panel	0.00	0.00	65.00 F ?
41	1		*Battery Base Plastic Cover	0.00	0.00	60.00 F ?
42	1		*Air Duct	0.00	0.00	65.00 F CRA

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06, Not valid without Reference section.

Generated using Merimen e-Claims IEAS

4318

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	1		*Air Duct Hose	0.00	0.00	✓ *60.00 F (RA)
44	1		*Air Duct Resonator Box	0.00	0.00	✓ *60.00 F DE
45	1		*Fuse Box Top Cover	crack 0.00	0.00	✓ *50.00 F EX
46	1		*Wire Hardness (Engine)	0.00	0.00	X *1,600.00 F ?
47	1		*Wire Hardness (1set)	0.00	0.00	✓ *3,200.00 F ? \$2400
48	1		*Alternator	0.00	0.00	✓ *650.00 F ?
49	1		*Alternator Belt	0.00	0.00	✓ *50.00 F ?
50	1		*Aircon Compressor	0.00	0.00	✓ *450.00 F EX
51	1		*Intake Manifold	0.00	0.00	✓ *210.00 F Act
52	1		*Front Windscreen	0.00	0.00	✓ *400.00 F CRA
53	1		*Front Windscreen Moulding 1set	0.00	0.00	✓ *40.00 F Act
54	1		*Sealant	0	0.00	✓ *45.00 F SA
55	1		*Engine Undercover Centre	0.00	0.00	✓ *95.00 F MIS
56	2		*Engine Undercover LH/RH	0.00	0.00	✓ *80.00 F DE
57	10		*Engine Undercover Clips	0.00	0.00	✓ *15.00 F Act
58	1		*Wiper Tank	0.00	0.00	✓ *65.00 F DE
59	1		*Radiator Spare Tank	0.00	0.00	✓ *55.00 F DE
60	1		*Wiper Tank Motor	0.00	0.00	✓ *85.00 F ?
61	1		*Engine Mounting Front	0.00	0.00	✓ *65.00 F ?
62	1		*Engine Mounting LH/RH (LH-\$95; RH-\$125)	0.00	0.00	✓ *220.00 F ?
63	1		*Engine Mounting Bracket Front	0.00	0.00	✓ *50.00 F ?
64	1		*Dashboard	0.00	0.00	✓ *650.00 F Act
65	1		*Driver Airbag	0.00	0.00	✓ *850.00 F Act
66	1		*Driver Airbag Coil Spring	0.00	0.00	✓ *170.00 F Act
67	1		*Passenger Airbag	0.00	0.00	✓ *1,150.00 F Act
68	1		*Airbag Control Unit	0.00	0.00	✓ *600.00 F Act
69	2		*Front Impact Sensor RH/LH	0.00	0.00	✓ *520.00 F Act
70	2		*Seatbelt LH/RH	0.00	0.00	✓ *560.00 F Act
71	1		*Seatbelt Buckle RH Seatbelt buckle LH	0.00	0.00	✓ *220.00 F ? \$110
72	1		*Coolant	0	0.00	✓ *45.00 F FS
73	1		*Auto Transmission Fluid Original	slant 0.00	0.00	✓ *88.00 F FS
74	1	REPAIR	*Passenger Door	0.00	0.00	X
75	1	REPAIR	*Driver Door	0.00	0.00	X
76	1		*Front Grille with Logo	0.00	0.00	✓ *150.00 F Act
77	1		*Sealant	repeat 0	0.00	X *45.00 F FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 17,651.00
+ Margin on L,N Items 10.00% (\$\$) 1,717.10

Total Parts (\$\$) 19,368.10

Hitachi Capital Asia Pacific Pte. Ltd/SLD6534Z/29/11/2017 12:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary item \$3760 + 10% = \$4136 ✓

supplementary slant \$180 ✓

supplementary labour \$350 ✓

parts \$14178 + 10% = \$15595.80 ✓

slant \$373 ✓

labour \$6010 ✓

* Total PIP \$26644.80 @ 18day \$

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 1800	2,400.00 2,000
2	Putty, blend and paint affected area	New 1600	2,200.00 1,800
3	Check Wiring and ensure proper function	New	120.00 60
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00 100
5	Conduct four wheel alignment / side slip test	New	150.00 80
6	Realign chassis member	New	600.00 300 250
7	Remove & re-install undercarriage parts	New photo	350.00 150
8	Remove and reinstall door lock & mechanism	New	300.00 X
9	Remove & reinstall exhaust manifold / centre pipe	New photo	200.00 100
10	Diagnostic Check & Reset (Tuning)	New	420.00 200
11	Repair and Realign A and B Pillar	New	X 400.00 200
12	Remove Upholstery Trim and Cushion	New	X 500.00 200
13	Remove and install Dashboard	New	300.00 150
14	Remove and refit windscreen	New	150.00 120
15	Remove and replace airbag complete unit	New	400.00 250
16	Remove and reinstall engine and gearbox unit to facilitate realign chassis frame	New	500.00 300
17	Conduct Car O liner adjustment	New photo	600.00 300 X
Gross Labour Cost (S\$)			9,770.00

Hitachi Capital Asia Pacific Pte. Ltd/SLD65342/29/11/2017 12:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

RASUL
Hp 90010068
18 days
29/11/17 @ 1650
Excess: 1500
Revert
Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

SLD6534Z (MSC/V/17-001805)
OD
Nov 17 2017 7:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/10/2018 11:47 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$26118.60) - SLD6534Z - Claim Handler: Kwok Woon Choo

Approved:26118.60:a if c

Janice Lee (LKKAUTO)

From: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Sent: Friday, October 05, 2018 1:11 PM
To: Janice Lee (LKKAUTO)
Cc: Taufikh (LKKAUTO); Vonn, LM Siow; HengCheong, Poon
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases) SLD6534Z DOA: 17/11/2017
Attachments: juntaiyo@hcspl.com.sg_20181005_101231.pdf

Hi Janice,

Understand from Vonn, when they went through this case with Taufikh, only the photos for the supplementary were missing which he needs to confirm with Rasul whether taken by him in order to confirm Grant's amount.

Reference to your revised amount \$26,094.80, we bought the 2 items not given as per attached.

Please revise your total amount to \$26,644.80 as proposed by Grant.

Thank you & regards,

Jamilah

Admin Assistant

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6265

e: jamilahbegum@hcspl.com.sg

w: www.hitachi-capital.com.sg

8217
fuse cover
Minn
187
188

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>

Sent: Friday, October 5, 2018 10:24 AM

To: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>

Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases) SLD6534Z DOA: 17/11/2017

compers- 8140 236
8141 237
men n

Hi Jamilah,

Calculation as below:

Parts : \$13,678.00

10% : \$1,045.80

SN : \$373.00

SUPP PARTS : \$3,760.00

10% : \$4,136.00

SN : \$180.00

LABOUR + SUPP LABOUR : \$6,360.00

Overall total : \$26,094.80

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim [<mailto:jamilahbegum@hcspl.com.sg>]

Sent: Thursday, October 04, 2018 5:51 PM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases)
SLD6534Z DOA: 17/11/2017

Dear Janice,

Grant finalised amount to Rasul which was cc to you on 10/02/2018, was P/P \$26,644.80 before Excess and GST.

Noticed difference of \$526.20. Please provide details.

Thank you & regards,

Jamilah

Admin Assistant

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6265

e: jamilahbegum@hcspl.com.sg

w: www.hitachi-capital.com.sg

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Sent: Thursday, October 4, 2018 5:30 PM

To: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases)

Dear Jamilah,

Kindly confirm \$26,118.60 @ 18 days

Thank you.



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

NO: DLI9196628

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
23	T53208-02210	BRACE PANEL DU1E33-2	1	40.00	40.00
24	T55708-02650	WIPER GRILLE COWLING DB1117S	1	240.00	240.00
25	T88450-02350	CONDENSER -12280 DB2C	1	270.00	270.00
26	T16410-0D390	RADIATOR ASSY DB1A50	1	380.00	380.00
27	T16533-0T070	RADIATOR TOP BRACKET DDS	2	25.00	50.00
28	T16535-0D140	SUPPORT RADIATOR LOWER BUSH DU1A164	2	15.00	30.00
29	T16711-0T101	FAN SHROUD DBAATS	1	90.00	90.00
30	T16712-0D150	FAN SHROUD TOP DU1A833-1	1	50.00	50.00
31	T16363-0T140	FAN MOTOR DB1010	1	180.00	180.00
32	T16361-0D201	FAN BLADE DU1AB20-7	1	55.00	55.00
33	T16573-0D100	HOSE RADIATOR NO.3 TOP DDS	1	25.00	25.00
34	T16572-0T130	RAD HOSE NO.3 BOTTOM DB1010	1	20.00	20.00
35	T53801-02240	FENDER FR RH DB1117S	1	190.00	190.00
36	T53802-02220	FENDER FR LH DB1117S	1	190.00	190.00
37	T75444-02700	VVTI RH DDS	1	18.00	18.00
38	T75444-02A20	VVTI LH DU1AS310	1	18.00	18.00
39	T53875-02630	FENDER LINER FR RH DB1117S	1	55.00	55.00
40	T53876-02680	FENDER LINER FR LH DB1117S	1	55.00	55.00
41	T74404-02550	BATTERY TOP BRACKET DU1D40-3	1	25.00	25.00
42	T17751-0T150	INLET AIR CLEANER DU1G20-1	1	65.00	65.00
43	T17881-0T130	AIR CLEANER HOSE DU1AC36-4	1	60.00	60.00
44	T17893-0T080	RESONATOR DU1AB2-3	1	60.00	60.00
45	T82662-02390	FUSE BOX TOP COVER DU1A140	1	50.00	50.00
46	T27060-01290	ALTERNATOR DU1AD1B	1	650.00	650.00
47	T90916-02679	FAN BELT 6PK1230 DD1B80-1	1	50.00	50.00
48	T88310-171	COMPRESSOR DB1117S	1	450.00	450.00
49	T17120-0T090	INTAKE MANIFOLD DBCC1S	1	210.00	210.00
50	T51451-02090	ENG UND CVR CTR DB1117S	1	95.00	95.00

Reprint:1 / LSK / 1/12/2017 12:57:20 PM

Cont'd



Print Received Message

This mail is associated with :

SLD6534Z (MSC/V/17-001805)

OD

Nov 17 2017 7:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Hitachi Capital Asia Pacific Pte. Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/10/2018 13:43 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$26644.80) - SLD6534Z - Claim Handler: Kwok Woon Choo

Approved:26644.80:a if c

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, October 23, 2018 2:12 PM
To: 'Jamilah, Binte MohdKassim'
Cc: Taufikh (LKKAUTO); Vonn, LM Siow; HengCheong, Poon
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases) SLD6534Z DOA: 17/11/2017

Dear Jamilah,

Confirm \$26,644.80 @ 18 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jamilah, Binte MohdKassim [mailto:jamilahbegum@hcspl.com.sg]
Sent: Friday, October 05, 2018 1:11 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>
Subject: RE: LKK OUTSTANDING CASE FINALISE (BY GRANT CHONG) - URGENT 2017 Accident Cases (Rasul Cases) SLD6534Z DOA: 17/11/2017

Hi Janice,

Understand from Vonn, when they went through this case with Taufikh, only the photos for the supplementary were missing which he needs to confirm with Rasul whether taken by him in order to confirm Grant's amount.

Reference to your revised amount \$26,094.80, we bought the 2 items not given as per attached.

Please revise your total amount to \$26,644.80 as proposed by Grant.

Thank you & regards,

Jamilah

Admin Assistant

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2017 Sendback Est	29 Nov 2017 12:06 S\$29,138.10	29 Nov 2017 14:34 Edit Adj Rpt	S\$26,644.80 Edit Estimates	S\$26,644.80 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 Feb 2018 11:43	10 Feb 2018 13:51 S\$4,666.00	10 Feb 2018 13:51			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLD6534Z	Date of Loss:	17/11/2017 07:00 - :59 [16 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / MSC/V/17-001805	Policy/Cover Note No.:	MSD/VPCP/17-001233 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018
		Excess:	S\$1,500.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/12/2017]		
Driver/Custodian:	CHRISTOPHER LIM TSING YEW (45 / Male), NRIC: S7210087E, Tel: +6597704746		
Adj Asg. Remarks:	TO REVERT - TO CHECK TYRE, BRAKE, VEHICLE CONDITION AND GET A MAINTENANCE RECORD.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (19/10/2018): Alert - Adj Mandate Approved (S\$26644.80) - SLD6534Z - Claim Handler: Kwok Woon ...
- MSIG_SG (04/10/2018): Alert - Adj Mandate Approved (S\$26118.60) - SLD6534Z - Claim Handler: Kwok Woon ...
- MSIG_SG (01/12/2017): Alert - Adj Mandate Approved (S\$18156.10) - SLD6534Z - Claim Handler: Kwok Woon ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD6534Z (MSC/V/17-001805)
OD
Nov 17 2017 7:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			☒		
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)								Thumbnail	Print			
1	18/11/17 10:48	Accident Statement								Load HTM				
2	29/11/17 12:06	Repairer Estimates								Load HTM				
3	10/02/18 13:51	Repairer Estimates Suppl. #1								Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	30/11/17 18:33	Adjuster Immediate Advice								Load HTM				
2	21/09/18 14:24	Adjuster Immediate Advice								Load HTM				
3	12/10/18 08:49	Adjuster Immediate Advice								Load HTM				
Photos/Images									3 per page			☒		
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)								Thumbnail	Print			
1	18/11/17 10:33	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
2	18/11/17 10:33	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
3	18/11/17 10:33	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
4	18/11/17 10:33	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
5	18/11/17 10:39	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
6	18/11/17 10:39	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
7	18/11/17 10:39	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
8	18/11/17 10:40	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
9	18/11/17 10:40	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
10	18/11/17 10:40	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
11	18/11/17 10:40	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
12	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
13	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
14	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
15	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
16	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
17	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
18	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
19	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
20	18/11/17 10:44	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	30/11/17 18:55	General View								Load JPG	☒			
2	30/11/17 18:55	General View								Load JPG	☒			
3	30/11/17 18:55	General View								Load JPG				

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
				☒
4	30/11/17 18:55	General View	 Load.JPG	☒
5	30/11/17 18:55	General View	 Load.JPG	☒
6	30/11/17 18:55	General View	 Load.JPG	☒
7	30/11/17 18:55	General View	 Load.JPG	☒
8	30/11/17 18:55	General View	 Load.JPG	☒
9	30/11/17 18:55	General View	 Load.JPG	☒
10	30/11/17 18:55	General View	 Load.JPG	☒
11	30/11/17 18:55	General View	 Load.JPG	☒
12	30/11/17 18:55	General View	 Load.JPG	☒
13	30/11/17 18:55	General View	 Load.JPG	☒
14	30/11/17 18:55	General View	 Load.JPG	☒
15	30/11/17 18:55	General View	 Load.JPG	☒
16	30/11/17 18:55	General View	 Load.JPG	☒
17	30/11/17 18:55	General View	 Load.JPG	☒
18	30/11/17 18:55	General View	 Load.JPG	☒
19	30/11/17 18:55	General View	 Load.JPG	☒
20	30/11/17 18:55	General View	 Load.JPG	☒
21	30/11/17 18:55	General View	 Load.JPG	☒
22	30/11/17 18:55	General View	 Load.JPG	☒
23	30/11/17 18:55	General View	 Load.JPG	☒
24	30/11/17 18:55	General View	 Load.JPG	☒
25	30/11/17 18:55	General View	 Load.JPG	☒
26	30/11/17 18:55	General View	 Load.JPG	☒
27	30/11/17 18:55	General View	 Load.JPG	☒
28	30/11/17 18:55	General View	 Load.JPG	☒
29	30/11/17 18:55	General View	 Load.JPG	☒
30	30/11/17 18:55	General View	 Load.JPG	☒
31	30/11/17 18:55	General View	 Load.JPG	☒
32	30/11/17 18:55	General View	 Load.JPG	☒
33	30/11/17 18:55	General View	 Load.JPG	☒
34	30/11/17 18:55	General View	 Load.JPG	☒
35	30/11/17 18:55	General View	 Load.JPG	☒
36	30/11/17 18:55	General View	 Load.JPG	☒
37	30/11/17 18:55	General View	 Load.JPG	☒
38	30/11/17 18:55	General View	 Load.JPG	☒
39	30/11/17 18:55	General View	 Load.JPG	☒
40	30/11/17 18:55	General View	 Load.JPG	☒
41	30/11/17 18:55	General View	 Load.JPG	☒
42	30/11/17 18:55	General View	 Load.JPG	☒
43	30/11/17 18:55	General View	 Load.JPG	☒
44	30/11/17 18:55	General View	 Load.JPG	☒
45	30/11/17 18:55	General View	 Load.JPG	☒
46	30/11/17 18:55	General View	 Load.JPG	☒
47	30/11/17 18:55	General View	 Load.JPG	☒
48	30/11/17 18:55	General View	 Load.JPG	☒
49	30/11/17 18:55	General View	 Load.JPG	☒
50	30/11/17 18:55	General View	 Load.JPG	☒
51	30/11/17 18:55	General View	 Load.JPG	☒
52	30/11/17 18:55	General View	 Load.JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
53	30/11/17 18:55	General View	 Load JPG	☒
54	30/11/17 18:55	General View	 Load JPG	☒
55	30/11/17 18:55	General View	 Load JPG	☒
56	30/11/17 18:55	General View	 Load JPG	☒
57	30/11/17 18:55	General View	 Load JPG	☒
58	30/11/17 18:55	General View	 Load JPG	☒
59	30/11/17 18:55	General View	 Load JPG	☒
60	30/11/17 18:55	General View	 Load JPG	☒
61	30/11/17 18:55	General View	 Load JPG	☒
62	30/11/17 18:55	General View	 Load JPG	☒
63	30/11/17 18:55	General View	 Load JPG	☒
64	30/11/17 18:55	General View	 Load JPG	☒
65	30/11/17 18:55	General View	 Load JPG	☒
66	30/11/17 18:55	General View	 Load JPG	☒
67	30/11/17 18:55	General View	 Load JPG	☒
68	30/11/17 18:55	General View	 Load JPG	☒
69	30/11/17 18:55	General View	 Load JPG	☒
70	30/11/17 18:55	General View	 Load JPG	☒
71	30/11/17 18:55	General View	 Load JPG	☒
72	30/11/17 18:55	General View	 Load JPG	☒
73	30/11/17 18:55	General View	 Load JPG	☒
74	30/11/17 18:55	General View	 Load JPG	☒
75	30/11/17 18:55	General View	 Load JPG	☒
76	30/11/17 18:55	General View	 Load JPG	☒
77	30/11/17 18:55	General View	 Load JPG	☒
78	30/11/17 18:55	General View	 Load JPG	☒
79	30/11/17 18:55	General View	 Load JPG	☒
80	30/11/17 18:55	General View	 Load JPG	☒
81	30/11/17 18:55	General View	 Load JPG	☒
82	30/11/17 18:55	General View	 Load JPG	☒
83	30/11/17 18:55	General View	 Load JPG	☒
84	30/11/17 18:55	General View	 Load JPG	☒
85	30/11/17 18:55	General View	 Load JPG	☒
86	30/11/17 18:55	General View	 Load JPG	☒
87	30/11/17 18:55	General View	 Load JPG	☒
88	30/11/17 18:55	General View	 Load JPG	☒
89	30/11/17 18:55	General View	 Load JPG	☒
90	30/11/17 18:55	General View	 Load JPG	☒
91	30/11/17 18:55	General View	 Load JPG	☒
92	30/11/17 18:55	General View	 Load JPG	☒
93	30/11/17 18:55	General View	 Load JPG	☒
94	30/11/17 18:55	General View	 Load JPG	☒
95	30/11/17 18:55	General View	 Load JPG	☒
96	30/11/17 18:55	General View	 Load JPG	☒
97	30/11/17 18:55	General View	 Load JPG	☒
98	30/11/17 18:55	General View	 Load JPG	☒
99	30/11/17 18:55	General View	Load JPG	☒
100	30/11/17 18:55	General View	Load JPG	☒
101	30/11/17 18:55	General View	Load JPG	☒
102	30/11/17 18:55	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
103	30/11/17 18:55	General View	 Load JPG	☒
104	30/11/17 18:55	General View	 Load JPG	☒
105	30/11/17 18:55	General View	 Load JPG	☒
106	30/11/17 18:55	General View	 Load JPG	☒
107	30/11/17 18:55	General View	 Load JPG	☒
108	30/11/17 18:55	General View	 Load JPG	☒
109	30/11/17 18:55	General View	 Load JPG	☒
110	30/11/17 18:55	General View	 Load JPG	☒
111	30/11/17 18:55	General View	 Load JPG	☒
112	30/11/17 18:55	General View	 Load JPG	☒
113	30/11/17 18:55	General View	 Load JPG	☒
114	30/11/17 18:55	General View	 Load JPG	☒
115	30/11/17 18:55	General View	 Load JPG	☒
116	30/11/17 18:55	General View	 Load JPG	☒
117	30/11/17 18:55	General View	 Load JPG	☒
118	30/11/17 18:55	General View	 Load JPG	☒
119	30/11/17 18:55	General View	 Load JPG	☒
120	30/11/17 18:55	General View	 Load JPG	☒
121	30/11/17 18:55	General View	 Load JPG	☒
122	30/11/17 18:55	General View	 Load JPG	☒
123	30/11/17 18:55	General View	 Load JPG	☒
124	30/11/17 18:55	General View	 Load JPG	☒
125	30/11/17 18:55	General View	 Load JPG	☒
126	30/11/17 18:55	General View	 Load JPG	☒
127	30/11/17 18:55	General View	 Load JPG	☒
128	30/11/17 18:55	General View	 Load JPG	☒
129	30/11/17 18:55	General View	 Load JPG	☒
130	30/11/17 18:55	General View	 Load JPG	☒
131	30/11/17 18:55	General View	 Load JPG	☒
132	30/11/17 18:55	General View	 Load JPG	☒
133	30/11/17 18:55	General View	 Load JPG	☒
134	30/11/17 18:55	General View	 Load JPG	☒
135	30/11/17 18:55	General View	 Load JPG	☒
136	30/11/17 18:55	General View	 Load JPG	☒
137	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
138	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
139	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
140	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
141	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
142	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
143	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
144	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
145	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
146	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
147	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
148	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
149	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
150	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
151	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
152	21/09/18 14:28	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
153	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
154	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
155	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
156	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
157	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
158	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
159	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
160	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
161	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
162	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
163	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
164	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
165	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
166	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
167	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
168	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
169	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
170	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
171	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
172	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
173	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
174	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
175	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
176	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
177	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
178	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
179	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
180	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
181	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
182	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
183	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
184	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
185	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
186	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
187	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
188	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
189	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
190	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
191	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
192	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
193	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
194	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
195	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
196	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
197	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
198	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
199	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
200	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
201	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
202	21/09/18 14:28	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
203	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
204	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
205	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
206	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
207	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
208	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
209	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
210	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
211	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
212	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
213	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
214	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
215	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
216	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
217	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
218	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
219	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
220	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
221	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
222	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
223	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
224	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
225	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
226	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
227	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
228	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
229	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
230	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
231	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
232	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
233	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
234	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
235	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
236	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
237	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
238	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
239	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
240	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
241	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
242	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
243	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
244	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
245	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
246	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
247	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
248	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
249	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
250	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
251	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
252	21/09/18 14:28	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
253	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
254	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
255	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
256	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
257	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
258	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
259	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
260	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
261	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
262	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
263	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
264	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
265	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
266	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
267	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
268	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
269	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
270	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
271	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
272	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
273	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
274	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
275	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
276	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
277	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
278	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
279	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
280	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
281	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
282	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
283	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
284	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
285	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
286	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
287	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
288	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
289	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
290	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
291	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
292	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
293	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
294	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
295	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
296	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
297	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
298	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
299	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
300	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
301	21/09/18 14:28	Reinspection Photo	 Load JPG	☒
302	21/09/18 14:28	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
303	21/09/18 14:28	Reinspection Photo		Load JPG	☒
304	21/09/18 14:28	Reinspection Photo		Load JPG	☒
305	21/09/18 14:28	Reinspection Photo		Load JPG	☒
306	21/09/18 14:28	Reinspection Photo		Load JPG	☒
307	21/09/18 14:28	Reinspection Photo		Load JPG	☒
308	21/09/18 14:28	Reinspection Photo		Load JPG	☒
309	21/09/18 14:28	Reinspection Photo		Load JPG	☒
310	21/09/18 14:28	Reinspection Photo		Load JPG	☒
311	21/09/18 14:28	Reinspection Photo		Load JPG	☒
312	21/09/18 14:28	Reinspection Photo		Load JPG	☒
313	21/09/18 14:28	Reinspection Photo		Load JPG	☒
314	21/09/18 14:28	Reinspection Photo		Load JPG	☒
315	21/09/18 14:28	Reinspection Photo		Load JPG	☒
316	21/09/18 14:28	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/11/17 16:39	TP REPORT GBD1463X		Load PDF	
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	18/11/17 09:58	Sketch Plan [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 18:54	SLD 6534Z MAINTENEINCE RECORD		Load PDF	
2	30/11/17 19:00	ESTIMATE		Load PDF	
3	21/09/18 14:27	SLD 6534Z ADJUSTMENT ESTIMATE + SUPPLEMENTARY		Load PDF	
4	04/10/18 10:55	SLD 6534Z SUPPLEMENTARY EST		Load PDF	
5	12/10/18 08:55	Re-mandate Item 45 & 50		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	18/11/17 10:48	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	18/11/17 10:33	Accident Photo		Load JPG	☒
2	18/11/17 10:33	Accident Photo		Load JPG	☒
3	18/11/17 10:33	Accident Photo		Load JPG	☒
4	18/11/17 10:33	Accident Photo		Load JPG	☒
5	18/11/17 10:39	Accident Photo		Load JPG	☒
6	18/11/17 10:39	Accident Photo		Load JPG	☒
7	18/11/17 10:39	Accident Photo		Load JPG	☒
8	18/11/17 10:40	Accident Photo		Load JPG	☒
9	18/11/17 10:40	Accident Photo		Load JPG	☒
10	18/11/17 10:40	Accident Photo		Load JPG	☒
11	18/11/17 10:40	Accident Photo		Load JPG	☒
12	18/11/17 10:44	Accident Photo		Load JPG	☒
13	18/11/17 10:44	Accident Photo		Load JPG	☒
14	18/11/17 10:44	Accident Photo		Load JPG	☒
15	18/11/17 10:44	Accident Photo		Load JPG	☒
16	18/11/17 10:44	Accident Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
17	18/11/17 10:44	Accident Photo	 Load JPG	☒
18	18/11/17 10:44	Accident Photo	 Load JPG	☒
19	18/11/17 10:44	Accident Photo	 Load JPG	☒
20	18/11/17 10:44	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No.	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/11/17 09:58	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022722/R1RBE2

Date: 24/10/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Policy No: MSD/PCP/17-001233

Date of Loss: 17/11/2017

Nature of Claim:

OD

Claim No:

MSC/V/17-001805

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD6534Z

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)

Engine No: 1ZRX582913

Reg. Date: 24/06/2016 (Man. Year: 2016)

Chassis No: MR053REH104553415

Colour: Grey

Odometer: 87135 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$91,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Hankook 5 mm

Rear Left Side:

Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side:

Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,684.10	20,284.80	3,399.30	14.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,120.00	6,360.00	3,760.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,804.10	26,644.80	7,159.30	21.18
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	32,304.10	25,144.80	7,159.30	22.16
+ GST 7.00/7.00% (S\$)	2,261.29	1,760.14	501.15	22.16
Nett Amount (S\$)	34,565.39	26,904.94	7,660.45	22.16

INSPECTION

Date of Assignment: 29/11/2017 Present Location:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

Date Inspected: 29/11/2017 Inspected At:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

No 8 Fourth Lok Yang Road

Singapore 629705

Estimated Period of Repair: 18.0 days

Adjuster: MOHD RASUL**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD6534Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Bumper	Missing	230.00 F	*230.00 F
2	10		*Front Bumper Clips	Necessary	350.00 F	*15.00 F
3	2		*Front Bumper Retainer Outer RH/LH	Necessary	10.00 F	*10.00 F
4	2		*Front Bumper Retainer Inner RH/LH	Necessary	-	*70.00 F
5	1		*Front Grille Top Garnish	Cracked	35.00 F	*35.00 F
6	10		*Top Grille Clips	Necessary	15.00 F	*15.00 F
7	1		*Headlamp Chrome Moulding RH/LH	Serviceable	60.00 F	*- F
8	1		*Headlamp Full Set Assembly RH	Broken	320.00 F	*320.00 F
9	1		*Headlamp Full Set Assembly LH	Broken	320.00 F	*320.00 F
10	1		*Front Bumper Lower Grille	Missing	50.00 F	*50.00 F
11	2		*Front Bumper Fog Lamp RH/LH	Cracked	170.00 F	*170.00 F
12	1		*Front Nuber Plate with Casing	Missing	45.00 FS	*45.00 FS
13	1		*Bonnet	Buckled	270.00 F	*270.00 F
14	2		*Bonnet Hinge LH/RH	Bent	60.00 F	*60.00 F
15	1		*Bonnet Lock	Bent	60.00 F	*60.00 F
16	1		*Bonnet Insulator	Deformed	95.00 F	*95.00 F
17	8		*Insulator Clips	Necessary	12.00 F	*12.00 F
18	1		*Front Reinforcement	Bent	110.00 F	*110.00 F
19	1		*Front Reinforcement Sponge	Missing	35.00 F	*35.00 F
20	1		*Support Panel	Buckled	220.00 F	*220.00 F
21	1		*Brace Panel	Bent	40.00 F	*40.00 F
22	1		*Horn	Scratched	50.00 F	*50.00 F
23	1		*Wiper Garnish	Cut	240.00 F	*240.00 F
24	2		*Front Chassis Extension RH/LH	Serviceable	70.00 F	*- F
25	1		*Air Condenser	Bent	270.00 F	*270.00 F
26	1		*Radiator	Bent	380.00 F	*380.00 F
27	2		*Radiator Top Bracket	Bent	50.00 F	*50.00 F
28	2		*Radiator Bottom Bush	Cut	30.00 F	*30.00 F
29	1		*Radiator Fan Cowling Set	Cracked	90.00 F	*90.00 F
30	1		*Radiator Fan Cowling Top	Cracked	50.00 F	*50.00 F
31	1		*Radiator Fan Motor	Shorted	180.00 F	*180.00 F
32	1		*Radiator Fan Blade	Cut	55.00 F	*55.00 F
33	1		*Radiator Top Hose	Twisted	25.00 F	*25.00 F
34	1		*Radiator Bottom Hose	Twisted	20.00 F	*20.00 F
35	2		*Front Fender RH/LH	Buckled	380.00 F	*380.00 F
36	2		*Front Fender Emblem RH/LH	Necessary	36.00 F	*36.00 F
37	2		*Front Fender Shield RH/LH	Deformed	110.00 F	*110.00 F
38	1		*Battery Top Bracket	Bent	25.00 F	*25.00 F
39	1		*Battery	Cut	300.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*Battery Base Panel	Bent	65.00 F	*65.00 F
41	1		*Battery Base Plastic Cover	Cracked	60.00 F	*60.00 F
42	1		*Air Duct	Cracked	65.00 F	*65.00 F
43	1		*Air Duct Hose	Cracked	60.00 F	*60.00 F
44	1		*Air Duct Resonator Box	Deformed	60.00 F	*60.00 F
45	1		*Fuse Box Top Cover	Cracked	50.00 F	*50.00 F
46	1		*Wire Hardness (Engine)	Serviceable	1,600.00 F	*- F
47	1		*Wire Hardness (1set)	Cut	3,200.00 F	*2,400.00 F
48	1		*Alternator	Cracked	650.00 F	*650.00 F
49	1		*Alternator Beet	Cut	50.00 F	*50.00 F
50	1		*Aircon Compressor	Cracked	450.00 F	*450.00 F
51	1		*Intake Manifold	Cut	210.00 F	*210.00 F
52	1		*Front Windscreen	Cracked	400.00 F	*400.00 F
53	1		*Front Windscreen Moulding 1set	Necessary	40.00 F	*40.00 F
54	1		*Sealant	Necessary	45.00 FS	*45.00 FS
55	1		*Engine Undercover Centre	Missing	95.00 F	*95.00 F
56	2		*Engine Undercover LH/RH	Deformed	80.00 F	*80.00 F
57	10		*Engine Undercover Clips	Necessary	15.00 F	*15.00 F
58	1		*Wiper Tank	Deformed	65.00 F	*65.00 F
59	1		*Radiator Spare Tank	Deformed	55.00 F	*55.00 F
60	1		*Wiper Tank Motor	Shorted	85.00 F	*85.00 F
61	1		*Engine Mounting Front	Bent	65.00 F	*65.00 F
62	1		*Engine Mounting LH/RH (LH-\$95;RH-\$125)	Bent	220.00 F	*220.00 F
63	1		*Engine Mounting Bracket Front	Bent	50.00 F	*50.00 F
64	1		*Dashboard	Torn	650.00 F	*650.00 F
65	1		*Driver Airbag	Activated	850.00 F	*850.00 F
66	1		*Driver Airbag Coil Spring	Activated	170.00 F	*170.00 F
67	1		*Passenger Airbag	Activated	1,150.00 F	*1,150.00 F
68	1		*Airbag Control Unit	Activated	600.00 F	*600.00 F
69	2		*Front Impact Sensor RH/LH	Activated	520.00 F	*520.00 F
70	2		*Seatbelt LH/RH	Activated	560.00 F	*560.00 F
71	2		*Seatbelt Buckle RH Seatbelt buckle LH	Activated	220.00 F	*110.00 F
72	1		*Coolant	Necessary	45.00 FS	*45.00 FS
73	1		*Auto Transmission Fluid Original	Necessary	88.00 F	*88.00 FS
74	1	REPAIR	*Passenger Door (NPA)	Repair	-	*- F
75	1	REPAIR	*Driver Door (NPA)	Repair	-	*- F
76	1		*Front Grille with Logo	Necessary	150.00 F	*150.00 F
77	1		*Sealant	Not Necessary	45.00 FS	*- FS
Supplementary #1						
78	1		*Aircon discharge hose	Bent	150.00 F	*150.00 F
79	1		*Aircon suction hose	Bent	210.00 F	*210.00 F
80	1		*Aircon pressure liquid pipe	Bent	280.00 F	*280.00 F
81	1		*Auto transmission ATF oil sump pan	Dented	75.00 F	*75.00 F
82	1		*Brake ABS actuator pump	Cracked	1,900.00 F	*1,900.00 F
83	1		*Front center crossmember	Bent	160.00 F	*160.00 F
84	1		*Front wheel house RH	Bent	180.00 F	*180.00 F
85	1		*Bonnet lock cable	Distorted	30.00 F	*30.00 F
86	1		*Engine top cover cylinder	Deformed	85.00 F	*85.00 F
87	1		*Airbag wire LH	Distorted	40.00 F	*40.00 F
88	1		*Bonnet lock clip holder	Distorted	10.00 F	*10.00 F
89	2		*Front reinforcement bracket LH / RH	Bent	80.00 F	*80.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1		*Front chassis side plate RH	Bent	30.00 F	*30.00 F
91	1		*Front chassis side plate LH	Bent	60.00 F	*60.00 F
92	1		*Air cleaner assembly	Cracked	250.00 F	*250.00 F
93	1		*Radiator fan/cooling computer	Cracked	170.00 F	*170.00 F
94	1		*Battery carrier	Distorted	25.00 F	*25.00 F
95	1		*Wiper washer inlet neck	Deformed	25.00 F	*25.00 F
96	1		*Auto transmission fluid (ATF) 4 Litre	Necessary	120.00 FS	*120.00 FS
97	1		*Brake fluid	Necessary	60.00 FS	*60.00 FS
					Sub Total (S\$)	21,591.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	2,093.10
					Total Parts (S\$)	23,684.10

18,491.00

1,793.80

20,284.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,400.00	2,000.00
2	Putty, blend and paint affected area	New	2,200.00	1,800.00
3	Check Wiring and ensure proper function	New	120.00	60.00
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00	100.00
5	Conduct four wheel alignment / side slip test	New	150.00	80.00
6	Realign chassis member	New	600.00	300.00
7	Remove & re-install undercarriage parts	New	350.00	150.00
8	Remove and reinstall door lock & mechanism	New	300.00	0.00
9	Remove & reinstall exhaust manifold / centre pipe	New	200.00	100.00
10	Diagnostic Check & Reset	New	420.00	200.00
11	Repair and Realign A and B Pillar	New	400.00	200.00
12	Remove Upholstery Trim and Cushion	New	500.00	200.00
13	Remove and install Dashboard	New	300.00	150.00
14	Remove and refit windscreen	New	150.00	120.00
15	Remove and replace airbag complete unit	New	400.00	250.00
16	Remove and reinstall engine and gearbox unit to facilitate realign chassis frame	New	500.00	300.00
17	Conduct Car O liner adjustment	New	600.00	0.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
18	Diagnostic reset air bag system and programming	New	200.00	200.00
19	Remove and replace wire harness complete set	New	150.00	150.00
Gross Labour Cost (\$\$)			10,120.00	6,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >