

22/03/2002

ASS. REC. BY:

REF: CS/FWD17022727/Rlvb97

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

Merimen

From (Person):

clara H

of

FWD

Date/Time: 29/11/17 @ 12.22pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 4059H

Insured:

at Workshop m/s

Charm's Customcraft

Tel:

62717054

of Blk 1010 Bkt Merah Lane 3, # 01-105, 159724

Policy No: PNPV2017-00001503

Claim No: 12017 00008211

Sum Insured:

Excess: \$500.00

D.O.A. 25/11/2017

Make of Veh:

(Client's Record)

30/11/2017

H.O.D. Endorsement:

CA / ☒ REV / REP. / REV 24 HRS

Date/Time: 3.30pm @ 29/11/17

Person Contacted:

Sharon

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 4059H - CC4/FWD17022576/K1493-D.O.A. 25/11/2017
1/12/17	Revert by merimen
1/12/17	Rec approved from clara by merimen
1/12/17	@ 1036am Informed Sharon CIA ex \$500
14/12/17	@ 158pm Sharon said vehicle just released

Passer

REF: FWD

1766

ASSIGNMENT

From: Date: 30/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 4059H
at Workshop mis: Churn's Customcraft

of: Blk 1010, Bkt Merah Lane 3 #01-105, 159724

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: 79K

IDAO Accident Report: Consistent? : Yes or No

GIA / PR. Sent: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No: SLA 4059H Yr Reg: 2016 P6B

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MA20A 3 1.5 L. C: 1496

Colour: BLUE A.O. Insured / Std / NI / NA

Reading: 35481 T. Paid: Insured / Std / NI / NA

Eng No:

C/N: 3M 6BM 42A860 328638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R. Bal: 6 mm

L. Bal: 6 mm

D.O.A: 28/11/17

Survey held at:

CHURN'S CUSTOMCRAFT

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRT MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/12/17 Final fig \$ 4506 confirmed by email (Ref 836, 1672)

02/01/2018

RECEIVED 02 JAN 2018

Date/Time File Passed: ☐ Prel. Report

☐ Final Report

Date/Time File Returned:

2/1- typist

Report Format: merimen

Lump Sum / I.B.I: 4506 1/2

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech Insp: \$

☐ Assessment: \$

Survey Fee:

Transportation:

U/C - P.P. \$

Print:

Other:

Total:

200
50
50
10

Survey Department Check List (Case Handler)

Reference No.: **es FWD 17025727 Rlvb**

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

26/12/17

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD17022727/R1vb

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 29-11-2017



Code : FWD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLA 4059H
Policy No.	PNPV2017-00001503	Coverage (\$)	0.00
Claim No.	1201700008211	Excess (\$)	500.00
Assign From	MERIMEN (CLARA LI)	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/11/2017	Inspection Date	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2017 11:08 Sendback Est	29 Nov 2017 11:25 S\$5,192.00	29 Nov 2017 12:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ANG WEE LIANG, ID: S8136766C, Tel: +6590035988, Email: WEE.LIANG.ANG@GMAIL.COM		
Vehicle Reg. No.:	SLA4059H	Date of Loss:	25/11/2017 12:00 - :59
Claim Type:	OD / 1201700008211	Policy/Cover Note No.:	PNPV2017-00001503 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/12/2017]		
Driver/Custodian:	ANG WEE LIANG (36 / Male), NRIC: S8136766C, Tel: +6590035988		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SLA4059H (1201700008211)

OD
Nov 25 2017 12:00PM
[ANG WEE LIANG]
Charn's Customcraft

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 01/12/2017 09:18 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4648.00) - SLA4059H - Claim Handler: Clara Li Zi Rong

Approved:4648.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 01 Dec 2017

Preliminary Advice

Vehicle No	: SLA4059H	Accident Date	: 25/11/2017
Make	: MAZDA 3	Policy No.	: PNPV2017-00001503
Assignment Date	: 29/11/2017	Excess	: S\$500.00
Date of Inspection	: 30/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: CHARN'S CUSTOMCRAFT (HQ) BLOCK 1010 BUKIT MERAH LANE 3, #01-105 SINGAPORE 159724		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,192.00
Revised Amount	:S\$	3,475.00
Check Items (Estimated)	:S\$	1,173.00
Total	:S\$	4,648.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	43,176.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,824.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 17:27
Date Of Accident	25/11/2017 12:30
Exact Location Of Accident	ALONG SERANGOON AVE 2 TO AMK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA4059H
Insured/Policyholder	
Name Of Registered Owner	ANG WEE LIANG
NRIC No	S8136766C
Email Address	WEE.LIANG.ANG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90035988
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00001503
Cover Note Number	

Driver

Name of Driver	ANG WEE LIANG
NRIC No	S8136766C
Date Of Birth	22/11/1981
Occupation	INDOOR
Date Of Driving Pass	21/09/2006
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90035988
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	WEE.LIANG.ANG@GMAIL.COM

Address	BLK 308B PUNGGOL WALK #14-360
Postcode	822308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7790X
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	NG SWEE BEE
NRIC/Passport Number	S0548582G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: SLA 4059H
ACCIDENT DATE: 25/1/17


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.



Policyholder's Signature

Date & Time: 27 Nov 17 09:20


Driver's Signature

(If driver is not the policyholder)

Date & Time: 27 Nov 17 09:20


CHARN'S CUSTOMCRAFT

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25 Nov, 1230pm I was driving the car along ~~the~~ Serangoon Ave 2 and turning towards Ang Mo Kio Ave 1. I have already pressed the pedal brake and expected the car to decelerate, however the car did not decelerate and brake as usual despite a hard press.

The car (SCA405911) hit the taxi (SHC7790X) bottom bumper, my car was hit at the side (left). First thing we verify that all passengers and drivers are both safe, no physically injuries on both sides are reported.

I followed up with taxi driver MR NG SWEE BEE (S0548582 G) on 26 Nov, 1pm he is still fine.

OWN DAMAGE ☒ 3RD PARTY CLAIM ☐ REPORTING ONLY ☐ OWN WORKSHOP ☐

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

27 Nov 2017

Driver's Signature

(If driver is not the policyholder)

Date & Time:

27 Nov 2017

CHARN'S CUSTOMCRAFT

Reporting Centre Person's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6766C

Vehicle Details

Vehicle No.	SLA4059H
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Blue
Manufacturing Year	2015
Engine No.	P520337565
Chassis No.	JM6BM42A8G0328638
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$15,269.00
Original Registration Date	29 Feb 2016
First Registration Date	29 Feb 2016
Transfer Count	0
Actual ARF Paid	\$10,269.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Feb 2026
PARF Rebate Amount	\$7,701.00

Intended COE Rebate Details

COE Expiry Date	28 Feb 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$43,000.00
COE Rebate Amount	\$35,475.00
Total Rebate Amount	\$43,176.00

The information contained herein is correct as at 30 Nov 2017

OK

79,000
43,176

35,824



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6766C

Vehicle Details

Vehicle No.	SLA4059H
Vehicle to be Exported	Yes
Intended De-registration Date	30 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour	Blue
Manufacturing Year	2015
Engine No.	P520337565
Chassis No.	JM6BM42A8G0328638
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$15,269.00
Original Registration Date	29 Feb 2016
First Registration Date	29 Feb 2016
Transfer Count	0
Actual ARF Paid	\$10,269.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Feb 2026
PARF Rebate Amount	\$7,701.00

Intended COE Rebate Details

COE Expiry Date	28 Feb 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$43,000.00
COE Rebate Amount	\$34,400.00
Total Rebate Amount	\$42,101.00

The information contained herein is correct as at 29 Nov 2017

OK

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

PASS DATE 21 Sep 2004

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg

Licence No: S8136766C

428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

S8136766C

LEE LIANG WEI LIANG

21 Nov 1981

21 Sep 2004

S8136766C

Charn's Customcraft (Co.Reg.No:25151300M)

Block 1010 Bukit Merah Lane 3, #01-105

Singapore 159724

Tel: 62717054 Fax: 62736676 Email: charns@singnet.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type: OD (Own Damage)
Policy No: PNPV2017-00001503
Vehicle Reg. No.: **SLA4059H**
Driver Age/Info: 36 / MALE
TP Injury Involved? NO

Ref. No:
Date of Loss: 25/11/2017
Driveable?
Party At Fault: UNKNOWN
Third Party YES
Involved?
Contact No: +6590035988

Insured/Claimant: ANG WEE LIANG
Driver: ANG WEE LIANG

Make/Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A)

Vehicle Reg. 29/02/2016
Date:

Vehicle Colour: Blue
Engine No: P520337565
Odometer: 35481 KM

Chassis No: JM6BM42A8G0328638

Paint Type:
Total Loss? **NO**
Est. Duration of
Repair (day) 6

Description of
Accident/Loss
Present Location: CHARN'S CUSTOMCRAFT (HQ)

COST OF CLAIMS**Amount**

Parts	3,002.00
Miscellaneous Items	70.00
Labour	2,120.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$) 5,192.00
+ GST 7.00% (\$\$) 363.44
Nett Amount (\$\$) 5,555.44

This claim is handled by: SHARON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2017)

Parts: 143 MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Charn's Customcraft/SLA4059H/29/11/2017 11:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	0.00	0.00	PH / *400.00 F
2	18		*Front bonnet seal clips	0.00	0.00	acc / 45.00 F
3	1		*Front bonnet hinge LH	0.00	0.00	? / *30.00 F
4	1		*Front bonnet hinge RH	0.00	0.00	? / *30.00 F
5	1		*Front bumper	0.00	0.00	DE / 400.00 F
6	1		*Front bumper retainer LH	0.00	0.00	acc / 14.00 F
7	1		*Front bumper retainer RH	0.00	0.00	X / *14.00 F
8	1		*Front bumper tow cover	0.00	0.00	? / *18.00 F
9	1		*Front grille	0.00	0.00	Cut / 90.00 F
10	1		*Front grille chrome LH	0.00	0.00	Cut / 100.00 F
11	1		*Front grille logo	0.00	0.00	acc / 25.00 F
12	1		*Front bumper foglight cover LH	0.00	0.00	SCB / 30.00 F
13	1		*Front bumper lower grille cover LH (Triangle)	0.00	0.00	MUS / 18.00 F
14	1		*Front headlamp LH	0.00	0.00	SCB / 350.00 F
15	1		*Front headlamp RH	0.00	0.00	? / *350.00 F
16	1		*Front bumper reinforcement	0.00	0.00	? / *260.00 F
17	1		*Front bumper inner garnish	0.00	0.00	? / *80.00 F
18	1		*Front bumper top garnish (above grille)	0.00	0.00	? / *70.00 F
19	4		*Front bumper top garnish rivets	0.00	0.00	acc / 28.00 F
20	2		*Front bumper top garnish clips	0.00	0.00	acc / 10.00 F
21	1		*Front support panel top garnish	0.00	0.00	? / *200.00 F
22	7		*Front support panel top garnish clips (BIG)	0.00	0.00	acc / 21.00 F
23	2		*Front support panel top garnish clips (SMALL)	0.00	0.00	acc / 9.00 F
24	1		*Front support panel	0.00	0.00	R / 250.00 F
25	1		*Front top side panel LH	0.00	0.00	PH / 80.00 F
26	1		*Front top side panel RH	0.00	0.00	PH / 80.00 F

F=Franchise part.

Total Parts (S\$) 3,002.00

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Front no.plate (S/NETT)	35.00
2	1	Radiator coolant (S/NETT)	35.00
Sub Total (S\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Check wiring function	New	40.00
2	To remove, reinstall air-con condenser and refill gas (REPLACE SUPPORT PANEL)	New	100.00
3	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fenders LH/RH, front bumper, front CHASSIS LH/RH and affected areas. (BULKHEAD SHIFTED)	New	800.00
4	Putty and respray front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fender LH/RH, front bumper, front CHASSIS LH/RH and affected areas.	New	1,180.00
Gross Labour Cost (S\$)			2,120.00

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rahul
Hp 90010068

7 days

P/P

30/11/17 @ 1410

EXCESS: 500

REVERT

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 December, 2017 10:38 AM
To: Charn's Customcraft; SUR
Subject: RE: Finalization - SLA 4059 H - Mazda 3

Sensitivity: Confidential

Dear Sharon,

Confirmed finalize amount \$4,506.00 before excess \$500 and GST

No of days: 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft [mailto:charns@singnet.com.sg]
Sent: Tuesday, 19 December, 2017 1:09 PM
To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Finalization - SLA 4059 H - Mazda 3
Importance: High
Sensitivity: Confidential

Hi Veron

Kindly find attached for finalization.

Parts - \$2616.00

S/N: \$70.00

Lab: \$1820.00

Total: \$4506.00 (before GST/Excess)

Please confirm

Thanks & Regards,

Sharon Lee

Charn's Customcraft

Tel: 6272 5429 Fax: 6273 6676

Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2017)
 Parts: 143 MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Charn's Customcraft/SLA4059H/29/11/2017 11:25
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front bonnet	0.00	0.00	400.00 F	✓
2	18		*Front bonnet seal clips	0.00	0.00	45.00 F	✓
3	1		*Front bonnet hinge LH	0.00	0.00	30.00 F	✓
4	1		*Front bonnet hinge RH	0.00	0.00	30.00 F	✓
5	1		*Front bumper	0.00	0.00	400.00 F	✓
6	1		*Front bumper retainer LH	0.00	0.00	14.00 F	✓
7	1		*Front bumper retainer RH	0.00	0.00	14.00 F	✓
8	1		*Front bumper tow cover	0.00	0.00	18.00 F	✓
9	1		*Front grille	0.00	0.00	90.00 F	✓
10	1		*Front grille chrome LH	0.00	0.00	100.00 F	✓
11	1		*Front grille logo	0.00	0.00	25.00 F	✓
12	1		*Front bumper foglight cover LH	0.00	0.00	30.00 F	✓
13	1		*Front bumper lower grille cover LH (Triangle)	0.00	0.00	18.00 F	✓
14	1		*Front headlamp LH	0.00	0.00	350.00 F	✓
15	1		*Front headlamp RH	0.00	0.00	350.00 F	✓
16	1		*Front bumper reinforcement	0.00	0.00	260.00 F	✓
17	1		*Front bumper inner garnish	0.00	0.00	80.00 F	✓
18	1		*Front bumper top garnish (above grille)	0.00	0.00	70.00 F	✓
19	4		*Front bumper top garnish rivets	0.00	0.00	28.00 F	✓
20	2		*Front bumper top garnish clips	0.00	0.00	10.00 F	✓
21	1		*Front support panel top garnish	0.00	0.00	200.00 F	✓
22	7		*Front support panel top garnish clips (BIG)	0.00	0.00	21.00 F	✓
23	2		*Front support panel top garnish clips (SMALL)	0.00	0.00	9.00 F	✓
24	1		*Front support panel	0.00	0.00	250.00 F	✓
25	1		*Front top side panel LH	0.00	0.00	80.00 F	✓
26	1		*Front top side panel RH	0.00	0.00	80.00 F	✓

F=Franchise part.

Total Parts (S\$)

3,002.00

2541

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Lkk
Rasu

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
Parts: 143 MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Charn's Customcraft/SLA4059H/05/12/2017 10:28
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
				0.00	0.00	*150.00 F
1	1		*Front Foglight LH			
Total Parts (S\$)						150.00

F=Franchise part.

75% CR

Charn's Customcraft/SLA4059H/05/12/2017 10:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
		<u>Miscellaneous Items</u>	
1	1	Front no.plate (S/NETT)	35.00
2	1	Radiator coolant (S/NETT)	35.00
Sub Total (S\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Labour Items</u>		
1	Check wiring function	New	40.00
2	To remove, reinstall air-con condenser and refill gas (REPLACE SUPPORT PANEL)	New	100.00
3	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fenders LH/RH, front bumper, front CHASSIS LH/RH and affected areas. (BULKHEAD SHIFTED)	New	880.00
4	Putty and respray front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fender LH/RH, front bumper, front CHASSIS LH/RH and affected areas.	New	1100.00
Gross Labour Cost (S\$)			2120.00

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rahul
Hp 90010068

7 days

P/P

30/11/17 @ 1410

Excess: 500

Revert

Resurvey by paint

P- 2616.00
S/N - 70.00
Lab - 1820.00
4506.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-3 CO. REG NO: 194502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0107509
A/C CODE: 3C25
DATE: 01 Dec 2017
TERMS: 60Days
SALESMAN: 0007

Page: 1

S: CHARN'S CUSTOMCRAFT
BIK 1010, #01-105 BUKIT MERAH LANE
S'PORE 159724

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
4059H						
BHY0-52-31XA	FRT BONNET	RWH	1	400.00		400.00 ✓
J001-56-741	CLIPS, BONNET SEAL	RCR	10	2.50		25.00 ✓
ZZJ001-56-741	CLIPS, BONNET SEAL	RCR	8	2.50		20.00 ✓
B45A-52-410A	HINGE RH, FRT BONNET	RCR	1	30.00		30.00 ✓
B45A-52-420A	HINGE LH, FRT BONNET	RCR	1	30.00		30.00 ✓
FNN1-50-031B BB	FRT BUMPER (HALOGEN)	RWH	1	400.00		400.00 ✓
BN1-50-001E	RETAINER LH, FRT BUMPER	RCR	1	14.00		14.00 ✓
BHN1-50-712A	PROTECT (UP) GRILLE (MATERIAL COLOR)	RWH	1	90.00		90.00 ✓
BHN1-50-7K1A	MOULD LH, FRT	RWH	1	100.00		100.00 ✓
C235-51-731A	LOGO, FRT GRILLE	RCR	1	25.00		25.00 ✓
BHN1-50-C21A	COVER LH, HOLE-LAMP	RCR	1	30.00		30.00 ✓
BHN1-50-102	COVER LH, FRT BUMPER	RCR	1	18.00		18.00 ✓

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-3 CO. REG NO: 19850269
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0107509

Page: 2

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
B4F4-51-0L0A	HEAD LAMP LH (HALOGEN)	RWH	1	350.00		350.00 ✓
B45A-50-070	REINF. ASSY, FRT BUMPER	RWH	1	260.00		260.00 ✓
BHN3-50-1C0	INNER GARNISH	RWH	1	80.00		80.00 ✓
BHN1-50-717C	BRACKET, GRILLE, RADIATOR	RWH	1	70.00		70.00 ✓
TK21-50-355	RIVET	RCR	4	7.00		28.00 ✓
S51S-51-833	CHIPS, TOP GARNISH	RCR	2	5.00		10.00 ✓
BHN1-50-033 33	GRILLE, UP, RADIATOR	RWH	1	200.00		200.00 ✓
GD7A-50-EA1	CLIPS, TOP GARNISH (BIG)	RCR	7	3.00		21.00 ✓
S51S-51-833	CLIPS, TOP GARNISH (SMALL)	RCR	2	5.00		10.00 ✓
B45A-53-150	MEMBER, SHROUD-UPPER	RWH	1	80.00		80.00 ✓

TOTAL SIN 2,291.00
ADD GST @ 7% 160.37
GRAND TOTAL SIN 2,451.37

CONFIRMED & ACCEPTED BY
received in Good Order & Condition
Goods Sold Are Not Returnable

R & O R

SOLD BY LING

Original/0007/01/12/2017 2:13:17 PM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-3 CO. REG NO: 198502696R
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: RL0107521
A/C CODE: 3C25
DATE: 04 Dec 2017
TERMS: 60Days
SALESMAN: 0007

Page:1

TO: CHARN'S CUSTOMCRAFT
BLK 1010, #01-105 BUKIT MERAH LANE
S'PORE 159724

A: 4059H

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
CHR5-53-110B	FRT SUPPORT PANEL	RWH	1	250.00		250.00
TOTAL						SIN 250.00
ADD GST @ 7%						17.50
GRAND TOTAL						<u>SIN 267.50</u>

FIRMED & ACCEPTED BY

ved in Good Order & Condition
Sold Are Not Returnable

E. & O. E.

SOLD BY LING

Original/0007/04/12/2017 10:05:28 AM

CHIN HON MOTOR & TRADING PTE LTD

GST REG NO: M2-0072042-J CO. REG NO: 198502696K
62 RACE COURSE ROAD SINGAPORE 218568
TEL: 62963915 FAX: 62966306 Email: chinhon@singnet.com.sg

TAX INVOICE

NO: KL0107534
A/C CODE: 3C25
DATE: 06 Dec 2017
TERMS: 60Days
SALESMAN: 0007

Page: 1

AS: CHARN'S CUSTOMCRAFT
BIK 1010, #01-105 BUKIT MERAH LANE
S'PORE 139724

LA 4059H

Item No	Description	Location	Qty	Unit Price	Dsc%	Amount
B45A-51-360A	LAMP LH.F.TURN	RCR	1	75.00		75.00

TOTAL **SIN 75.00**

ADD GST @ 7% 5.25

GRAND TOTAL **SIN 80.25**

SL9459H
Fwd / 09

E. & O. E.

SOLD BY LING

Reprint: 2/0007/06/12/2017 9:32:32 AM

UNFIRMED & ACCEPTED BY
received in Good Order & Condition
and Are Not Returnable

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2017 11:08	29 Nov 2017 11:25	29 Nov 2017 12:22	S\$4,506.00	S\$4,506.00		Pending for Survey Report
	Sendback Est	S\$5,192.00	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	05 Dec 2017 10:28	05 Dec 2017 10:28	05 Dec 2017 10:28			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANG WEE LIANG , ID: S8136766C, Tel: +6590035988, Email: WEE.LIANG.ANG@GMAIL.COM		
Vehicle Reg. No.:	SLA4059H	Date of Loss:	25/11/2017 12:00 - :59
Claim Type:	OD / 1201700008211	Policy/Cover Note No.:	PNPV2017-00001503 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/12/2017]		
Driver/Custodian:	ANG WEE LIANG (36 / Male), NRIC: S8136766C, Tel: +6590035988		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- FWD_SG (01/12/2017): Alert - Adj Mandate Approved (S\$4648.00) - SLA4059H - Claim Handler: Clara Li Zi...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLA4059H (1201700008211)

OD

Nov 25 2017 12:00PM

[ANG WEE LIANG]

Charn's Customcraft

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
									1 per page		
Assessment Reports											
No	Finalized On	Charn's Customcraft (HQ)							Thumbnail		
1	29/11/17 11:25	Repairer Estimates							Load HTM		
2	05/12/17 10:28	Repairer Estimates Suppl. #1							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		
1	01/12/17 08:51	Adjuster Immediate Advice							Load HTM		
									3 per page		
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		
1	01/12/17 08:28	General View							Load JPG		
2	01/12/17 08:28	General View							Load JPG		
3	01/12/17 08:28	General View							Load JPG		
4	01/12/17 08:28	General View							Load JPG		
5	01/12/17 08:28	General View							Load JPG		
6	01/12/17 08:28	General View							Load JPG		
7	01/12/17 08:28	General View							Load JPG		
8	01/12/17 08:28	General View							Load JPG		
9	01/12/17 08:28	General View							Load JPG		
10	01/12/17 08:28	General View							Load JPG		
11	01/12/17 08:28	General View							Load JPG		
12	01/12/17 08:28	General View							Load JPG		
13	01/12/17 08:28	General View							Load JPG		
14	01/12/17 08:28	General View							Load JPG		
15	01/12/17 08:28	General View							Load JPG		
16	01/12/17 08:28	General View							Load JPG		
17	01/12/17 08:28	General View							Load JPG		
18	01/12/17 08:28	General View							Load JPG		
19	01/12/17 08:28	General View							Load JPG		
20	01/12/17 08:28	General View							Load JPG		
21	01/12/17 08:28	General View							Load JPG		
22	01/12/17 08:28	General View							Load JPG		
23	01/12/17 08:28	General View							Load JPG		
24	01/12/17 08:28	General View							Load JPG		
25	01/12/17 08:28	General View							Load JPG		
26	01/12/17 08:28	General View							Load JPG		
27	01/12/17 08:28	General View							Load JPG		
28	01/12/17 08:28	General View							Load JPG		
29	01/12/17 08:28	General View							Load JPG		
30	01/12/17 08:28	General View							Load JPG		
31	01/12/17 08:28	General View							Load JPG		

32	01/12/17 08:28	General View	1	Load JPG	☒
33	01/12/17 08:28	General View	1	Load JPG	☒
34	01/12/17 08:28	General View	1	Load JPG	☒
35	01/12/17 08:28	General View	1	Load JPG	☒
36	01/12/17 08:28	General View	1	Load JPG	☒
37	01/12/17 08:28	General View	1	Load JPG	☒
38	01/12/17 08:28	General View	1	Load JPG	☒
39	01/12/17 08:28	General View	1	Load JPG	☒
40	01/12/17 08:28	General View	1	Load JPG	☒
41	01/12/17 08:28	General View	1	Load JPG	☒
42	01/12/17 08:28	General View	1	Load JPG	☒
43	01/12/17 08:28	General View	1	Load JPG	☒
44	01/12/17 08:28	General View	1	Load JPG	☒
45	01/12/17 08:28	General View	1	Load JPG	☒
46	01/12/17 08:28	General View	1	Load JPG	☒
47	01/12/17 08:28	General View	1	Load JPG	☒
48	01/12/17 08:28	General View	1	Load JPG	☒
49	01/12/17 08:28	General View	1	Load JPG	☒
50	01/12/17 08:28	General View	1	Load JPG	☒
51	01/12/17 08:28	General View	1	Load JPG	☒
52	01/12/17 08:28	General View	1	Load JPG	☒
53	01/12/17 08:28	General View	1	Load JPG	☒
54	01/12/17 08:28	General View	1	Load JPG	☒
55	01/12/17 08:28	General View	1	Load JPG	☒
56	01/12/17 08:28	General View	1	Load JPG	☒
57	01/12/17 08:28	General View	1	Load JPG	☒
58	01/12/17 08:28	General View	1	Load JPG	☒
59	01/12/17 08:28	General View	1	Load JPG	☒
60	01/12/17 08:28	General View	1	Load JPG	☒
61	01/12/17 08:28	General View	1	Load JPG	☒
62	01/12/17 08:28	General View	1	Load JPG	☒
63	01/12/17 08:28	General View	1	Load JPG	☒
64	01/12/17 08:28	General View	1	Load JPG	☒
65	01/12/17 08:28	General View	1	Load JPG	☒
66	01/12/17 08:28	General View	1	Load JPG	☒
67	01/12/17 08:28	General View	1	Load JPG	☒
68	01/12/17 08:28	General View	1	Load JPG	☒
69	01/12/17 08:28	General View	1	Load JPG	☒
70	01/12/17 08:28	General View	1	Load JPG	☒
71	01/12/17 08:28	General View	1	Load JPG	☒
72	01/12/17 08:28	General View	1	Load JPG	☒
73	01/12/17 08:28	General View	1	Load JPG	☒
74	01/12/17 08:28	General View	1	Load JPG	☒
75	01/12/17 08:28	General View	1	Load JPG	☒
76	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
77	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
78	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
79	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
80	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
81	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒

82	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
83	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
84	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
85	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
86	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
87	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
88	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
89	26/12/17 10:27	Reinspection Photo	1	Load JPG	☒
			1 per page	☐	☒
Documentation			Thumbnail	Print	
No	Finalized On	Charn's Customcraft (HQ)	1	Load PDF	
1	29/11/17 11:24	Log card (if available)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF	
1	01/12/17 08:56	ESTIMATE	1	Load PDF	
2	02/01/18 15:00	SUPPLEMENTARY			

Linked Accident Report Documents

			View	View in Browser
			1 per page	☐
Assessment Reports			Thumbnail	Print
No	Finalized On	Charn's Customcraft (HQ)	1	Load HTM
1	27/11/17 17:46	Accident Statement		
			3 per page	☐
Photos/Images			Thumbnail	Print
No	Finalized On	Charn's Customcraft (HQ)	1	Load JPG
1	27/11/17 17:41	Accident Photo	1	Load JPG
2	27/11/17 17:41	Accident Photo	1	Load JPG
3	27/11/17 17:41	Accident Photo	1	Load JPG
4	27/11/17 17:41	Accident Photo	1	Load JPG
5	27/11/17 17:41	Accident Photo	1	Load JPG
6	27/11/17 17:41	Accident Photo	1	Load JPG
7	27/11/17 17:41	Accident Photo	1	Load JPG
8	27/11/17 17:41	Accident Photo	1	Load JPG
9	27/11/17 17:41	Accident Photo	1	Load JPG
			1 per page	☐
Documentation			Thumbnail	Print
No	Finalized On	Charn's Customcraft (HQ)	1	Load JPG
1	27/11/17 17:44	Sketch Plan	1	Load JPG
2	27/11/17 17:44	Sketch Plan #2	1	Load JPG
3	27/11/17 17:44	NRIC	1	Load JPG
4	27/11/17 17:44	DL	1	Load JPG
5	27/11/17 17:44	DL	1	Load JPG

Documents Checklist

DOCUMENTS CHECKLIST There are no document checklists configured.	Reset Save Print
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD17022727/R1VBS2

Date: 02/01/2018

REFERENCE

Insured/Claimant: ANG WEE LIANG Policy No: PNPV2017-00001503
Date of Loss: 25/11/2017 Nature of Claim: OD Claim No: 1201700008211

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA4059H
Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A)
Reg. Date: 29/02/2016 (Man. Year: 2015)
Colour: Blue
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$79,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: P520337565
Chassis No: JM6BM42A8G0328638
Odometer: 35481 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,152.00	2,616.00	536.00	17.01
Miscellaneous Items	70.00	70.00	0.00	0.00
Labour	2,120.00	1,820.00	300.00	14.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,342.00	4,506.00	836.00	15.65
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	5,342.00	4,006.00	1,336.00	25.01
+ GST 7.00/7.00% (S\$)	373.94	280.42	93.52	25.01
Nett Amount (S\$)	5,715.94	4,286.42	1,429.52	25.01

INSPECTION

Date of Assignment: 29/11/2017 Present Location:
Date Inspected: 30/11/2017 Inspected At:

Charn's Customcraft (HQ)
Charn's Customcraft (HQ)
Block 1010 Bukit Merah Lane 3, #01-105
Singapore 159724

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2018)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA4059H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet	Bent	400.00 F	*400.00 F
2	18		*Front bonnet seal clips	Necessary	45.00 F	*45.00 F
3	1		*Front bonnet hinge LH	Bent	30.00 F	*30.00 F
4	1		*Front bonnet hinge RH	Bent	30.00 F	*30.00 F
5	1		*Front bumper	Deformed	400.00 F	*400.00 F
6	1		*Front bumper retainer LH	Necessary	14.00 F	*14.00 F
7	1		*Front bumper retainer RH	Serviceable	14.00 F	*- F
8	1		*Front bumper tow cover	Serviceable	18.00 F	*- F
9	1		*Front grille	Cut	90.00 F	*90.00 F
10	1		*Front grille chrome LH	Cut	100.00 F	*100.00 F
11	1		*Front grille logo	Necessary	25.00 F	*25.00 F
12	1		*Front bumper foglight cover LH	Scratched	30.00 F	*30.00 F
13	1		*Front bumper lower grille cover LH (Triangle)	Missing	18.00 F	*18.00 F
14	1		*Front headlamp LH	Scratched	350.00 F	*350.00 F
15	1		*Front headlamp RH	Serviceable	350.00 F	*- F
16	1		*Front bumper reinforcement	Bent	260.00 F	*260.00 F
17	1		*Front bumper inner garnish	Cracked	80.00 F	*80.00 F
18	1		*Front bumper top garnish (above grille)	Cracked	70.00 F	*70.00 F
19	4		*Front bumper top garnish rivets	Necessary	28.00 F	*28.00 F
20	2		*Front bumper top garnish clips	Necessary	10.00 F	*10.00 F
21	1		*Front support panel top garnish	Cracked	200.00 F	*200.00 F
22	7		*Front support panel top garnish clips (BIG)	Necessary	21.00 F	*21.00 F
23	2		*Front support panel top garnish clips (SMALL)	Necessary	9.00 F	*10.00 F
24	1		*Front support panel	Cracked	250.00 F	*250.00 F
25	1		*Front top side panel LH	Bent	80.00 F	*80.00 F
26	1		*Front top side panel RH	Serviceable	80.00 F	*- F
Supplementary #1						
27	1		*Front Foglight LH	Cracked	150.00 F	*75.00 F
F=Franchise part.						
Total Parts (\$\$)					3,152.00	2,616.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Front no.plate (S/NETT) (CRACKED)	35.00	35.00
2	1	Radiator coolant (S/NETT) (NECESSARY)	35.00	35.00
Sub Total (S\$)			70.00	70.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Check wiring function	New	40.00	40.00
2	To remove, reinstall air-con condenser and refill gas (REPLACE SUPPORT PANEL)	New	100.00	80.00
3	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fenders LH/RH, front bumper, front CHASSIS LH/RH and affected areas. (BULKHEAD SHIFTED)	New	880.00	700.00
4	Putty and respray front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fender LH/RH, front bumper, front CHASSIS LH/RH and affected areas.	New	1,100.00	1,000.00
Gross Labour Cost (S\$)			2,120.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >