

Charn's Customcraft (Co.Reg.No:25151300M)

Block 1010 Bukit Merah Lane 3, #01-105

Singapore 159724

Tel: 62717054 Fax: 62736676 Email: charns@singnet.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:
Policy No:	PNPV2017-00001503	Date of Loss: 25/11/2017
Vehicle Reg. No.:	SLA4059H	Driveable?
Driver Age/Info:	36 / MALE	Party At Fault: UNKNOWN
TP Injury Involved?	NO	Third Party Involved? YES
Insured/Claimant:	ANG WEE LIANG	Contact No: +6590035988
Driver:	ANG WEE LIANG	

Make/Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Vehicle Reg. Date:	29/02/2016
Vehicle Colour:	Blue		
Engine No:	P520337565	Chassis No:	JM6BM42A8G0328638
Odometer:	35481 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Description of Accident/Loss	REFER TO SKETCH
Present Location:	CHARN'S CUSTOMCRAFT (HQ)

COST OF CLAIMS

	Amount
Parts	3,002.00
Miscellaneous Items	70.00
Labour	2,120.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,192.00
+ GST 7.00% (S\$)	363.44
Nett Amount (S\$)	5,555.44

This claim is handled by: **SHARON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 29 Nov 2017)

Parts: 143 **MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: Charn's Customcraft/SLA4059H/29/11/2017 11:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	0.00	0.00	400.00 F
2	18		*Front bonnet seal clips	0.00	0.00	45.00 F
3	1		*Front bonnet hinge LH	0.00	0.00	30.00 F
4	1		*Front bonnet hinge RH	0.00	0.00	30.00 F
5	1		*Front bumper	0.00	0.00	400.00 F
6	1		*Front bumper retainer LH	0.00	0.00	14.00 F
7	1		*Front bumper retainer RH	0.00	0.00	14.00 F
8	1		*Front bumper tow cover	0.00	0.00	18.00 F
9	1		*Front grille	0.00	0.00	90.00 F
10	1		*Front grille chrome LH	0.00	0.00	100.00 F
11	1		*Front grille logo	0.00	0.00	25.00 F
12	1		*Front bumper foglight cover LH	0.00	0.00	30.00 F
13	1		*Front bumper lower grille cover LH (Triangle)	0.00	0.00	18.00 F
14	1		*Front headlamp LH	0.00	0.00	350.00 F
15	1		*Front headlamp RH	0.00	0.00	350.00 F
16	1		*Front bumper reinforcement	0.00	0.00	260.00 F
17	1		*Front bumper inner garnish	0.00	0.00	80.00 F
18	1		*Front bumper top garnish (above grille)	0.00	0.00	70.00 F
19	4		*Front bumper top garnish rivets	0.00	0.00	28.00 F
20	2		*Front bumper top garnish clips	0.00	0.00	10.00 F
21	1		*Front support panel top garnish	0.00	0.00	200.00 F
22	7		*Front support panel top garnish clips (BIG)	0.00	0.00	21.00 F
23	2		*Front support panel top garnish clips (SMALL)	0.00	0.00	9.00 F
24	1		*Front support panel	0.00	0.00	250.00 F
25	1		*Front top side panel LH	0.00	0.00	80.00 F
26	1		*Front top side panel RH	0.00	0.00	80.00 F

F=Franchise part.

Total Parts (\$\$) **3,002.00**

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Front no.plate (S/NETT)	35.00
2	1	Radiator coolant (S/NETT)	35.00
Sub Total (\$\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Check wiring function	New	40.00
2	To remove, reinstall air-con condenser and refill gas (REPLACE SUPPORT PANEL)	New	100.00
3	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fenders LH/RH, front bumper, front CHASSIS LH/RH and affected areas. (BULKHEAD SHIFTED)	New	880.00
4	Putty and respray front inner panel, front support panel, front top side panel LH/RH, front bonnet, front fender LH/RH, front bumper, front CHASSIS LH/RH and affected areas.	New	1,100.00
Gross Labour Cost (\$\$)			2,120.00

Charn's Customcraft/SLA4059H/29/11/2017 11:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rahul
Hp 90010068

7 days

P/P

30/11/17 @ 1410

EXCESS: 500

REVERT

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: