

INS. CASE OWNER:

Gerald

CC4 / LPC17022729 / Aca357

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

29/11/17

Date / Time:

29/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 2436T

Claim No.:

17/17/17/VC00/020230

Name of Insured:

NTT COPIER MACHINES &amp; SUPPLIES

Policy No.:

21/17/VC00/099795

Insured Tel No.:

HP:

Make / Model:

TOYOTA DYNA 150 - 3.0 D (M)

Excess Sec II :SS

D.O.A: 21/11/17

Place of Accident:

SLE TOWARDS CTE 11.5/KM

Is driver the owner?

( YES ☒ NO )

Nature of Accident:

If NO, Driver Name / Age: REKAJAN SEJAN

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No.: 8433 6975

(V/L: YES / NO)

Insured Liability:

%

Final? YES No

SGC 4845D



INSRS:

WSP: Pacific Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

04/12/17 (Ashu)

SGC 4845D - NS/INC15003524/RT43d1 DOA 17/11/17

GBD 2436T - X

\* NO ESTIMATE &amp; PA.

TENDRY TO REJECT TP CLAIM.

9/1/18

SEEK APPROVAL TO REJECT TP CLAIM.

9/1/18

MANDATE APPROVE TO REJECT TP CLAIM.

Email WSP TO REJECT TP CLAIM.

RECEIVED 24 AUG 2018

Reject Case

By (staff): Ashu

Approved by: Ashu

Date: 24/8/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 36

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

TP: Lost Control

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

Tick only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

450

COPY SENT 24/8/18

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 28 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGC4845D Yr Regn: 2006 Jan  
 Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Wish cc 1794  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: - T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZNE100280251  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/55R16  
 R: 205/55R16  
 BS / DUN / EXNOVA (GY) / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front Rear  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 29/11/17  
 Survey held at Precise  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Lon Pac.

45: +10.500 (RED: +34.859.79 77%)

MV: 58K

PV: 47.5K.

Nett: 10.5K

Date/Time: File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Photos: \_\_\_\_\_

Charts: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                | Ref : CC4/LPC17022729/Aea3 |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                | Date : 29-11-2017          |  |
|                                                                                                                                        |                                                                                | Code : LPC2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                |                            |                                                                                     |
| Insured Veh.                                                                                                                           | GBD 2436T                                                                      | Veh. Inspected             | SGC 4845D                                                                           |
| Policy No.                                                                                                                             | Z/17/VC00/099795                                                               | Coverage (\$)              | 0.00                                                                                |
| Claim No.                                                                                                                              | 17/17/17/VC00/020230                                                           | Excess (\$)                | 0.00                                                                                |
| Assign From                                                                                                                            |                                                                                | Assign Date                | 29/11/2017                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                |                            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                | c.c                        | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN                                                                         | Year of Reg.               |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                | Colour                     |                                                                                     |
| Odometer                                                                                                                               | -                                                                              | Steering                   |                                                                                     |
| Brakes                                                                                                                                 |                                                                                | Modification               |                                                                                     |
| General                                                                                                                                |                                                                                |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                |                            |                                                                                     |
|                                                                                                                                        | Size                                                                           | Make                       | Balance                                                                             |
| R/H Front Tyre                                                                                                                         |                                                                                |                            | mm                                                                                  |
| L/H Front Tyre                                                                                                                         |                                                                                |                            | mm                                                                                  |
| R/H Rear Tyre                                                                                                                          |                                                                                |                            | mm                                                                                  |
| L/H Rear Tyre                                                                                                                          |                                                                                |                            | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                |                            |                                                                                     |
|                                                                                                                                        |                                                                                |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                |                            |                                                                                     |
| Accident Date                                                                                                                          | 21/11/2017                                                                     | Inspection Date            | 29/11/2017                                                                          |
| Survey held at                                                                                                                         | PRECISE AUTO SERVICE<br>NO.1 KAKI BUKIT AVE 6<br>#02-34/36<br>SINGAPORE 417883 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                |                            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                |                            |                                                                                     |

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

09-03-18

Date Of Accident : 21-11-17

OUR REF : SGC 4845D/T/17

Soh Keng Hock

Blk 504 Jelpang Road

#08-360

Singapore 670504

Adrian

Date in/out : 22/11/17 to 30/01/18

ESTIMATE BILL ON VEH. NO. : SGC 4845D

MODEL : TOYOTA WISH 1.8 AUTO

CHASSIS NO : ZNE100280251

## LIST ITEM

|                                          |                   |          |        |
|------------------------------------------|-------------------|----------|--------|
| Tail Gate                                |                   | 1,217.85 | ✓      |
| Tail Gate Lock                           |                   | 289.80   | ✓      |
| Tail Gate Lock Striker                   | new               | 123.05   | ✓      |
| Tail Gate Weather Stripe                 | cut               | 290.85   | ✓      |
| Tail Gate Stopper                        | new 2pcs @ 43.70  | 87.40    | ✗      |
| Tail Gate Chorme                         | cut               | 289.90   | ✓      |
| Tail Gate Chorme Clips                   | new 2pcs @ 12.90  | 25.80    | -10    |
| Tail Gate Badge                          | new               | 61.70    | ✓      |
| Tail Gate Inner Board                    | defected          | 581.40   | ✓      |
| Tail Gate Inner Board Clips              | new 8pcs @ 12.90  | 103.20   | 30     |
| Tail Gate Inner handle Holder            | new               | 182.75   | ✗      |
| Tail Gate Hingde                         | new 2pcs @ 71.10  | 142.20   | ✗      |
| Tail Gate Absorber                       | new 2pcs @ 298.80 | 597.60   | ✗      |
| Rear Windscreen Glass                    | shattered         | 944.85   | ✓      |
| Rear Windscreen Glass Inner Cover (Side) | cut 2pcs @ 281.9  | 563.80   | ✓      |
| Rear Windscreen Glass Inner Cover (Top)  | new               | 272.45   | ✗      |
| Rear Windscreen Glass Inner Trim (Side)  | new 2pcs @ 591.60 | 1,183.20 | 271.60 |

|                                        |               |               |
|----------------------------------------|---------------|---------------|
| Rear Windscreen Glass Inner Trim (Top) |               | 588.10 ✓      |
| Rear Windscreen Glass Top Moulding     |               | 181.85 ✓      |
| Rear Windscreen Glass Side Moulding    | 2pcs @ 180.75 | 361.50 ✓      |
| Rear Windscreen Glass Inner Seal       |               | 50.00 ✓       |
| Rear Windscreen Glass Clips            | 14pcs @ 12.90 | 180.60 30     |
| Tail Lamp Assy                         | 2pcs @ 280.85 | 561.70 150.85 |
| Tail Lamp Sealant                      | 2pcs @ 50.00  | 100.00 X      |
| Tail Lamp Clips                        | 4pcs @ 12.90  | 51.60 10      |
| Tail Lamp Base Panel                   | 2pcs @ 281.40 | 562.80 ✓      |
| Rear Bumper Fascia                     |               | 1,078.90 467  |
| Rear Bumper Side Retainer              | 2pcs @ 121.25 | 242.50 176    |
| Rear Bumper Side Attachment            | 2pcs @ 131.35 | 262.70 124    |
| Rear Bumper Reflector                  | 2pcs @ 121.20 | 242.40 ✓      |
| Rear Bumper Screw Clips                | 2pcs @ 12.90  | 25.80 ✓       |
| Rear Bumper Stay - RH                  |               | 43.70 ✓       |
| Rear Bumper Clips                      | 10pcs @ 12.90 | 129.00 30     |
| Rear Number Plate Lamp                 | 2pcs @ 83.55  | 167.10 X      |
| Rear End Panel (Outer)                 |               | 581.90 ✓      |
| Rear End Panel (Inner)                 |               | 561.70 ✓      |
| Rear End Panel (Side RH & LH)          | 2pcs @ 182.25 | 364.50 ✓      |
| Rear End Panel Top Trim                |               | 372.40 ✓      |
| Rear End Panel Top Trim Clips          | 4pcs @ 12.90  | 51.60 10      |
| Rear End Panel Stopper Cover           | 2pcs @ 46.60  | 93.20 X       |
| Rear Floor Panel                       |               | 972.40 X      |
| Rear Floor Panel Side Board - RH       |               | 264.80 X      |
| Rear Floor Side Panel - RH             |               | 277.25 X      |
| Rear Floor Panel Under Member          |               | 381.60 X      |
| Rear Floor Panel Insulator Cloth       |               | 561.80 X      |

|                                       |             |                               |
|---------------------------------------|-------------|-------------------------------|
| Rear Floor Panel Board (Centre)       |             | 591.40 ✓                      |
| Rear Floor Panel Board Under Garnish  |             | 289.90 ✗                      |
| Rear Fender - RH                      | Distorted   | 972.40 ✓                      |
| Rear Fender Inner Trim Board          | Deformed RH | 2pcs @ 781.85 1,563.70 781.85 |
| Rear Fender Inner Trim Board Clips    | new         | 16pcs @ 12.90 206.40 60       |
| Rear Fender Splash Shield             | new         | 2pcs @ 164.60 329.20 ✗        |
| Rear Fender Splash Shield Clips       | new         | 6pcs @ 12.90 77.40 ✗          |
| Rear Fender Air Vent - RH             | Deformed    | 164.70 ✓                      |
| Exhaust Silencer                      |             | 781.85 ✗                      |
| Exhaust Silencer Heater Shield        |             | 282.25 ✗                      |
| Exhaust Silencer Hook                 |             | 3pcs @ 43.90 131.70 ✗         |
| Spare Tyre Carrier                    | new         | 371.70 ✗                      |
| Rear Sub Chassis Frame Member - RH    | Page        | 681.75 ✗                      |
| Rear Fender Glass - RH                | Shattered.  | 581.40 ✓                      |
| Rear Fender Glass Inner Trim          | Repeated    | 781.45 ✗                      |
| Rear Fender Glass Moulding            | new         | 2pcs @ 172.85 345.70 65       |
| Rear Fender Glass Clips               | new         | 8pcs @ 12.90 103.20 20        |
| Rear Fender Glass Inner Seal          | new         | 50.00 30                      |
| Rear Fender Inner Extension Panel o/s | new         | 591.60 ✗                      |
| Rear Wiper Blade                      |             | 132.25 ✗                      |
| Rear Wiper Arm                        |             | 181.90 ✗                      |
| Rear Wiper Arm Cover                  |             | 43.75 ✗                       |
| Rear Wiper Motor                      |             | 591.60 ✗                      |
| Bonnet Lock                           |             | 131.75 ✗                      |
| Bonnet Lock Cable                     |             | 161.10 ✗                      |
| Bonnet Stopper                        |             | 2pcs @ 43.90 87.80 ✗          |
| Bonnet Lock Brace Panel               | new         | 181.70 ✗                      |

|                                     |               |            |          |
|-------------------------------------|---------------|------------|----------|
| Bonnet Chorme                       |               |            | 155.30 ✓ |
| Bonnet Inner Rubber Beading Clips   | 6pcs @ 12.90  | 77.40 ✗    |          |
| Head Lamp Assy                      | 2pcs @ 681.75 | 1,363.50   | 681.75   |
| Head Lamp Clips                     | 2pcs @ 43.90  | 87.80 ✓    |          |
| Front Grille                        |               | 131.75 ✓   |          |
| Front Grille Top Clips With Stopper | 2pcs @ 53.90  | 107.80 ✗   |          |
| Front Grille Clips                  | 2pcs @ 12.90  | 25.80      | 10       |
| Front Bumper Fascia                 |               | 480.20 ✓   |          |
| Front Bumper Side Retainer          |               | 131.75 ✓   |          |
| Front Bumper Sporge                 |               | 141.10 ✓   |          |
| Front Bumper Reinforcement          |               | 173.55 ✓   |          |
| Front Bumper Air Guide              |               | 108.85 ✓   |          |
| Front Bumper Fog Lamp Cover         | 2pcs @ 43.90  | 87.80 ✓    |          |
| Front Bumper Clips                  | 10pcs @ 12.90 | 129.00     | 30       |
| Front Support Panel                 |               | 880.20 ✓   |          |
| Front Support Panel Top Garnish     |               | 121.10 ✗   |          |
| Horn Assy                           | 2pcs @ 182.25 | 364.50 ✗   |          |
| Aircon Condensor                    |               | 981.75 ✓   |          |
| Aircon Condensor Top Mounting       | 2pcs @ 63.10  | 122.20 ✓   |          |
| Aircon Condensor Bottom Mounting    | 2pcs @ 63.90  | 127.80 ✓   |          |
| Aircon Suction Pipe                 |               | 298.10 ✗   |          |
| Radiator Assy                       |               | 1,210.20 ✓ |          |
| Radiator Top Mounting               | 2pcs @ 63.90  | 127.80 ✓   |          |
| Radiator Bottom Mounting            | 2pcs @ 61.10  | 122.20 ✓   |          |
| Radiator Fan Cowling                |               | 231.20 ✗   |          |
| Front Fender L.H                    |               | 488.20 ✗   |          |
| Front Fender Splash Shield          |               | 168.10 ✓   |          |
| Front Fender Splash Shield Clips    | 8pcs @ 12.90  | 103.20     | 30       |

|                               |         |            |
|-------------------------------|---------|------------|
| Front Center Crossmember      | Best    | 480.00 ✓   |
| Front Knuckle Arm LH          |         | 581.10 ✓   |
| Front Lower Arm               |         | 374.45 ✓   |
| Front Lower Arm Ball Joint    | HH      | 182.20 ✓   |
| Front Anti Roll Bar           | 182     | 360.10 ✓   |
| Front Anti Roll Bar Link      |         | 196.60 ✓   |
| Steering Rack Assy            |         | 1,505.20 ✓ |
| Front Wheel Bearing Kit LH    |         | 516.50 ✓   |
| Engine Under Mounting - Front | 3 No. m | 171.20 ✓   |
| Engine Under Mounting - Rear  |         | 192.80 ✓   |

Less Discount 25% :

39,789.05  
9,947.26  
29,841.79

#### SPECIAL NETT ITEM

|                                    |                    |                              |
|------------------------------------|--------------------|------------------------------|
| Front Bumper Lower Spoiler (Acc)   | Missing            | 680.00 ✓                     |
| Rear Bumper Lower Spoiler (Acc)    | Missing            | 680.00 ✓                     |
| Rockel Panel Spoiler - n/s         | as lead            | 550.00 ✓                     |
| Auto Gear Box Assy (2nd)           | crash d            | 2,800.00 ✓ 1500              |
| Auto Transmission Fluid            | as                 | 80.00 ✓ 40                   |
| Rim Assy (Sport) Front & Rear LH   | Front LH cut       | 2pcs @ 650.00 ✓ 1,300.00 400 |
| Tyre Assy                          | Front LH purchased | 2pcs @ 280.00 ✓ 560.00 180   |
| Battery Assy                       | as                 | 200.00 ✓                     |
| Front Number Plate                 | Missing            | 45.00 ✓ 30                   |
| Front Number Plate Casing          | Missing            | 29.00 ✓                      |
| Tail Gate Outer Switch             | as                 | 180.00 ✓                     |
| Rear Floor Panel Board             | as                 | 120.00 ✓                     |
| Rear Fender Glass Solar Film (Acc) | as                 | 2pcs @ 50.00 ✓ 100.00 50     |
| Rear Windscreen Glass Solar Film   | as                 | 50.00 ✓                      |
| Rear Windscreen Glass Sealant      | as                 | 60.00 ✓                      |

|                                                                   |           |          |      |
|-------------------------------------------------------------------|-----------|----------|------|
| Reverse Sensor With Control Unit                                  | MISSING   | 380.00   | 200  |
| Rear Number Plate                                                 | 3/1/1/1/1 | 45.00    |      |
| Rear Number Plate Casing                                          |           | 29.00    |      |
| Rear Fender Glass Sealant                                         | 4479      | 50.00    | 30   |
| <b>LABOUR CHARGE</b>                                              |           |          |      |
| Towing (3 Trip)                                                   |           | 240.00   | 60   |
| To check & reconnect snap wiring                                  |           | 120.00   | 60   |
| To tuff coat affected areas                                       |           | 220.00   | 100  |
| To remove & refix interior upholstery                             |           | 180.00   | 20   |
| To remove & refix front undercarriage components                  |           | 480.00   | 200  |
| To remove & refix auto gear box                                   |           | 380.00   | X    |
| To remove & refix radiator & top up gas                           |           | 180.00   | 60   |
| To remove & refix condensor & top up gas                          | 4600      | 180.00   | 60   |
| To adjust chassis alignment on car O liner                        |           | 380.00   | X    |
| To remove & refix rear windscreen glass & rear fender glass RH    |           | 280.00   | 180  |
| To remove & refix exhaust                                         |           | 120.00   | X    |
| To adjust wheel alignment                                         |           | 120.00   | 20   |
| To respray affected areas                                         |           | 2,200.00 | 1700 |
| To renew damaged parts, straighten & repair and aligned all parts |           | 2,500.00 | 2000 |

|              |           |
|--------------|-----------|
| TOTAL :      | 45,359.79 |
| GST 7% :     | 3,175.19  |
| AMOUNT DUE : | 48,534.97 |

LKX Auto Consultants hence notify the Reparer of the following:

- To respray before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

**Catherine Chong (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 28 November, 2017 10:19 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG; riaz@justice.com.sg  
**Subject:** FW: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

3.10pm @ 28/11/2017

Vehicle In  
Person @ Irene

Dear Catherine,

Kindly arrange accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Ham [mailto:riaz@justice.com.sg]  
**Sent:** Tuesday, 28 November, 2017 10:17 AM  
**To:** MT\_Claim\_SG  
**Subject:** FW: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

WITHOUT PREJUDICE

Dear Gerald,

We refer to the above matter and to the telephone conversation with your goodself today.

As spoken, please find our email below confirming Mr Marcus Chua as our mutual surveyor – SJE.

Please ask the surveyor in charge to directly liaise with the repairer (Precise Auto Service), Ms Irene Tel. No. 6745 7367.

**Thank you and Best Regards,**

**HAM**

**RIAZ LLC**

Tel: 6534 0110

Fax: 6534 0220

---

**From:** Ham [mailto:riaz@justice.com.sg]  
**Sent:** Friday, November 24, 2017 10:44 AM  
**To:** 'mt\_claims@lonpac.com'  
**Subject:** Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

**WITHOUT PREJUDICE**

Dear sirs,

We refer to your fax dated 23 November 2017.

We would like to appoint Mr Marcus Chua as our mutual surveyor - SJE

Please ask the surveyor in charge to directly liaise with the repairer (Precise Auto Service), Ms Irene Tel. No. 6745 7367.

**Thank you and Best Regards,**

**HAM**

**RIAZ LLC**

Tel: 6534 0110

Fax: 6534 0220

## Asher Sng (LKKAUTO)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 9 January 2018 4:07 PM  
**To:** Asher Sng (LKKAUTO)  
**Cc:** MT\_Claim\_SG; Vic (LKKAUTO)  
**Subject:** RE: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise, ACCIDENT INVOLVING GBD 2436T AND SGC 4845D ON 21/11/2017

Dear Asher

Please proceed.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]  
**Sent:** Tuesday, 9 January, 2018 12:47 PM  
**To:** GERALD POH WEE BIN; ONG LI LI  
**Cc:** MT\_Claim\_SG; Vic (LKKAUTO)  
**Subject:** RE: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise, ACCIDENT INVOLVING GBD 2436T AND SGC 4845D ON 21/11/2017

Your Ref: 17/17/17/VC00/020230

Hi Sir,

We refer to the above matter.

Third party reported that unknown lorry collided into the rear right impact caused the vehicle switched to the right and collided by OI.

Insured driver reported that third party cut into his vehicle and collided into his vehicle.

Based on third party report mention that he was collided by an unknown lorry causing his vehicle to encroached into our insured lane causing the accident.

We are of opinion that the liability is not in third party favour due to third party loss control of its vehicle.

In view of the above, we are intending to reject TP claim.

**For your approval/ comments/ instruction.**

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Thursday, 30 November, 2017 4:09 PM

**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** RE: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

Dear Shirley,

We attached a copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Thursday, 30 November, 2017 3:57 PM

**To:** MT\_Claim\_SG

**Cc:** GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI; Asher Sng (LKKAuto); Vic (LKKAuto); Admin A

**Subject:** RE: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

**Your ref:** 17/17/17/VC00/020230

**LKK ref:** CC4/LPC17022729/Aea3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SGC 4845D

Date of survey: 29/11/2017

We have not authorized repairs.

Enclosed for your perusal is:

- TP's GIA report

We will revert preliminary advice in due course.

We have not authorized repairs.

Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Tuesday, 28 November, 2017 3:16 PM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Tuesday, 28 November, 2017 10:19 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG; [riaz@justice.com.sg](mailto:riaz@justice.com.sg)

**Subject:** FW: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

Dear Catherine,

Kindly arrange accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Ham [mailto:riaz@justice.com.sg]  
**Sent:** Tuesday, 28 November, 2017 10:17 AM  
**To:** MT\_Claim\_SG  
**Subject:** FW: Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

WITHOUT PREJUDICE

Dear Gerald,

We refer to the above matter and to the telephone conversation with your goodself today.

As spoken, please find our email below confirming Mr Marcus Chua as our mutual surveyor – SJE.

Please ask the surveyor in charge to directly liaise with the repairer (Precise Auto Service), Ms Irene Tel. No. 6745 7367.

**Thank you and Best Regards,**

**HAM**  
**RIAZ LLC**  
Tel: 6534 0110  
Fax: 6534 0220

---

**From:** Ham [mailto:riaz@justice.com.sg]  
**Sent:** Friday, November 24, 2017 10:44 AM  
**To:** 'mt\_claims@lonpac.com'  
**Subject:** Your Ref: 17/17/17/VC00/020230 Our Ref: SGC 4845d (H) Precise

**WITHOUT PREJUDICE**

Dear sirs,

We refer to your fax dated 23 November 2017.

We would like to appoint Mr Marcus Chua as our mutual surveyor - SJE

Please ask the surveyor in charge to directly liaise with the repairer (Precise Auto Service), Ms Irene Tel. No. 6745 7367.

**Thank you and Best Regards,**

**HAM**  
**RIAZ LLC**  
Tel: 6534 0110  
Fax: 6534 0220

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Friday, 24 August 2018 9:22 AM  
**To:** 'Precise Auto Service'  
**Subject:** ACCIDENT INVOLVING SGC 4845D AND GBD 2436T ON 21/11/2017

Without Prejudice

Hi Sir/Mdm,

We refer to the above matter.

### ACCIDENT INVOLVING SGC 4845D AND GBD 2436T ON 21/11/2017

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client lost control and collided into our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Precise Auto Service <[support@preciseauto.sg](mailto:support@preciseauto.sg)>  
**Sent:** Monday, 12 March 2018 6:51 PM  
**To:** Adrian Ling (LKKAUTO) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>; Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Subject:** ESTIMATE BILL FOR SGC 4845D

Dear Mr. Adrian / Ms. Asher

We enclose herewith the estimate of SGC 4845D for your attention.

Thank you

Best Regards  
Jiang Yanhong

--

T : 6745 7367 | F : 6841 3390

E : [support@preciseauto.sg](mailto:support@preciseauto.sg)

W: [www.preciseauto.sg](http://www.preciseauto.sg)

A : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



**PRECISE AUTO SERVICE**

準 確 汽 車 服 務

*Follow us on social media:*





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC17022729/Aea3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-09-2018



Code : LPC2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | GBD 2436T            | Veh. Inspected | SGC 4845D  |
| Policy No.   | Z/17/VC00/099795     | Coverage (\$)  | 0.00       |
| Claim No.    | 17/17/17/VC00/020230 | Excess (\$)    | 0.00       |
| Assign From  | GERALD               | Assign Date    | 29/11/2017 |

#### 2. Vehicle Particulars & Condition

|              |              |              |            |
|--------------|--------------|--------------|------------|
| Make & Model | TOYOTA WISH  | c.c          | 1794       |
| Engine No.   | HIDDEN       | Year of Reg. | 2006       |
| Chassis No.  | ZNE100280251 | Colour       | SILVER     |
| Odometer     | -            | Steering     | IN ORDER   |
| Brakes       | IN ORDER     | Modification | SPORTS RIM |
| General      | GOOD         |              |            |

#### 3. Conditions of Tyres

|                | Size      | Make     | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 205/55R16 | GOODYEAR | 6 mm    |
| L/H Front Tyre | 205/55R16 | GOODYEAR | 6 mm    |
| R/H Rear Tyre  | 205/55R16 | GOODYEAR | 6 mm    |
| L/H Rear Tyre  | 205/55R16 | GOODYEAR | 6 mm    |

#### 4. Description of Damages

|                                                                                                        |
|--------------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND UNDERCARRIAGE.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------------------------------|

#### 5. General Information

|                |                                                                                |                 |            |
|----------------|--------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 21/11/2017                                                                     | Inspection Date | 29/11/2017 |
| Survey held at | PRECISE AUTO SERVICE<br>NO.1 KAKI BUKIT AVE 6<br>#02-34/36<br>SINGAPORE 417883 |                 |            |

#### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                 |
|-------------------------------------|-----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 28 Working Days |
|-------------------------------------|-----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 4845D

| Qty                         | Description of Parts                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                     |               |                           |                   |
| 1                           | TAIL GATE                                           | DISTORTED     | 1,217.85                  | 1,217.85          |
| 1                           | TAIL GATE LOCK                                      | JAMMED        | 289.80                    | 289.80            |
| 1                           | TAIL GATE LOCK STRIKER                              | NECESSARY     | 123.05                    | 123.05            |
| 1                           | TAIL GATE WEATHER STRIPE                            | CUT           | 290.85                    | 290.85            |
| 2                           | TAIL GATE STOPPER @ \$43.70                         | NOT NECESSARY | 87.40                     | -                 |
| 1                           | TAIL GATE CHROME                                    | CRACKED       | 289.90                    | 289.90            |
| 2                           | TAIL GATE CHROME CLIPS @ \$12.90                    | NECESSARY     | 25.80                     | 10.00             |
| 1                           | TAIL GATE BADGE                                     | NECESSARY     | 61.70                     | 61.70             |
| 1                           | TAIL GATE INNER BOARD                               | DEFORMED      | 581.40                    | 581.40            |
| 8                           | TAIL GATE INNER BOARD CLIPS @ \$12.90               | NECESSARY     | 103.20                    | 30.00             |
| 1                           | TAIL GATE INNER HANDLE HOLDER                       | NOT NECESSARY | 182.75                    | -                 |
| 2                           | TAIL GATE HINGE @ \$71.10                           | NOT NECESSARY | 142.20                    | -                 |
| 2                           | TAIL GATE ABSORBER @ \$298.80                       | NOT NECESSARY | 597.60                    | -                 |
| 1                           | REAR WINDSCREEN GLASS                               | SHATTERED     | 944.85                    | 944.85            |
| 2                           | REAR WINDSCREEN GLASS INNER COVER (SIDE) @ \$281.90 | CUT           | 563.80                    | 563.80            |
| 1                           | REAR WINDSCREEN GLASS INNER COVER (TOP)             | NOT NECESSARY | 272.45                    | -                 |
| 2                           | REAR WINDSCREEN GLASS INNER TRIM (SIDE) @ \$591.60  | O/S DEFORMED  | 1,183.20                  | 591.60            |
| 1                           | REAR WINDSCREEN GLASS INNER TRIM (TOP)              | NOT NECESSARY | 588.10                    | -                 |
| 1                           | REAR WINDSCREEN GLASS TOP MOULDING                  | NECESSARY     | 181.85                    | 181.85            |
| 2                           | REAR WINDSCREEN GLASS SIDE MOULDING @ \$180.75      | NECESSARY     | 361.50                    | 361.50            |
| 1                           | REAR WINDSCREEN GLASS INNER SEAL                    | NECESSARY     | 50.00                     | 50.00             |
| 14                          | REAR WINDSCREEN GLASS CLIPS @ \$12.90               | NECESSARY     | 180.60                    | 30.00             |
| 2                           | TAIL LAMP ASSY @ \$280.85                           | N/S SMASHED   | 561.70                    | 280.85            |
| 2                           | TAIL LAMP SEALANT @ \$50.00                         | NOT NECESSARY | 100.00                    | -                 |
| 4                           | TAIL LAMP CLIPS @ \$12.90                           | NECESSARY     | 51.60                     | 10.00             |
| 2                           | TAIL LAMP BASE PANEL @ \$281.40                     | DISTORTED     | 562.80                    | 562.80            |
| 1                           | REAR BUMPER FASCIA                                  | MISSING       | 1,078.90                  | 468.00            |
| 2                           | REAR BUMPER SIDE RETAINER @ \$121.25                | NECESSARY     | 242.50                    | 116.00            |
| 2                           | REAR BUMPER SIDE ATTACHMENT @ \$131.35              | NECESSARY     | 262.70                    | 124.00            |

Report Ref No. CC4/LPC17022729/Aea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

| Qty | Description of Parts                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | REAR BUMPER REFLECTOR @ \$121.20             | MISSING              | 242.40                    | 242.40            |
| 2   | REAR BUMPER SCREW CLIPS @ \$12.90            | NECESSARY            | 25.80                     | 25.80             |
| 1   | REAR BUMPER STAY - RH                        | DENTED               | 43.70                     | 43.70             |
| 10  | REAR BUMPER CLIPS @ \$12.90                  | NECESSARY            | 129.00                    | 30.00             |
| 2   | REAR NUMBER PLATE LAMP @ \$83.55             | NOT NECESSARY        | 167.10                    | -                 |
| 1   | REAR END PANEL (OUTER)                       | DISTORTED            | 581.90                    | 581.90            |
| 1   | REAR END PANEL (INNER)                       | DISTORTED            | 561.70                    | 561.70            |
| 2   | REAR END PANEL (SIDE RH & LH) @ \$182.25     | NOT NECESSARY        | 364.50                    | -                 |
| 1   | REAR END PANEL TOP TRIM                      | DEFORMED             | 372.40                    | 372.40            |
| 4   | REAR END PANEL TOP TRIM CLIPS @ \$12.90      | NECESSARY            | 51.60                     | 10.00             |
| 2   | REAR END PANEL STOPPER COVER @ \$46.60       | NOT NECESSARY        | 93.20                     | -                 |
| 1   | REAR FLOOR PANEL                             | TO REPAIR SEE LABOUR | 972.40                    | -                 |
| 1   | REAR FLOOR PANEL SIDE BOARD - RH             | NOT NECESSARY        | 264.80                    | -                 |
| 1   | REAR FLOOR SIDE PANEL - RH                   | NOT NECESSARY        | 277.25                    | -                 |
| 1   | REAR FLOOR PANEL UNDER MEMBER                | NOT NECESSARY        | 381.60                    | -                 |
| 1   | REAR FLOOR PANEL INSULATOR CLOTH             | NOT NECESSARY        | 561.80                    | -                 |
| 1   | REAR FLOOR PANEL BOARD (CENTRE)              | NOT NECESSARY        | 591.40                    | -                 |
| 1   | REAR FLOOR PANEL BOARD UNDER GARNISH         | NOT NECESSARY        | 289.90                    | -                 |
| 1   | REAR FENDER - RH                             | DISTORTED            | 972.40                    | 972.40            |
| 2   | REAR FENDER INNER TRIM BOARD @ \$781.85      | O/S DEFORMED         | 1,563.70                  | 781.85            |
| 16  | REAR FENDER INNER TRIM BOARD CLIPS @ \$12.90 | NECESSARY            | 206.40                    | 60.00             |
| 2   | REAR FENDER SPLASH SHIELD @ \$164.60         | NOT NECESSARY        | 329.20                    | -                 |
| 6   | REAR FENDER SPLASH SHILED CLIPS @ \$12.90    | NOT NECESSARY        | 77.40                     | -                 |
| 1   | REAR FENDER AIR VENT - RH                    | DEFORMED             | 164.70                    | 164.70            |
| 1   | EXHAUST SILENCER                             | NOT NECESSARY        | 781.85                    | -                 |
| 1   | EXHAUST SILENCER HEATER SHIELD               | NOT NECESSARY        | 282.25                    | -                 |
| 3   | EXHAUST SILENCER HOOK @ \$43.90              | NOT NECESSARY        | 131.70                    | -                 |
| 1   | SPARE TYRE CARRIER                           | NOT NECESSARY        | 371.70                    | -                 |
| 1   | REAR SUB CHASSIS FRAME MEMBER - RH           | TO REPAIR SEE LABOUR | 681.75                    | -                 |
| 1   | REAR FENDER GLASS - RH                       | SHATTERED            | 581.40                    | 581.40            |
| 1   | REAR FENDER GLASS INNER TRIM                 | REPEATED             | 781.45                    | -                 |
| 2   | REAR FENDER GLASS MOULDING @ \$172.85        | NECESSARY            | 345.70                    | 65.00             |

Report Ref No. CC4/LPC17022729/Aea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

| Qty | Description of Parts                          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------|----------------------|---------------------------|-------------------|
| 8   | REAR FENDER GLASS CLIPS @ \$12.90             | NECESSARY            | 103.20                    | 20.00             |
| 1   | REAR FENDER GLASS INNER SEAL                  | NECESSARY            | 50.00                     | 30.00             |
| 1   | REAR FENDER INNER EXTENTION PANEL O/S         | TO REPAIR SEE LABOUR | 591.60                    | -                 |
| 1   | REAR WIPER BLADE                              | NOT NECESSARY        | 132.25                    | -                 |
| 1   | REAR WPER ARM                                 | NOT NECESSARY        | 181.90                    | -                 |
| 1   | REAR WIPER ARM COVER                          | NOT NECESSARY        | 43.75                     | -                 |
| 1   | REAR WIPER MOTOR                              | NOT NECESSARY        | 591.60                    | -                 |
| 1   | BONNET LOCK                                   | NOT NECESSARY        | 131.75                    | -                 |
| 1   | BONNET LOCK CABLE                             | NOT NECESSARY        | 161.10                    | -                 |
| 2   | BONNET STOPPER @ \$43.90                      | NOT NECESSARY        | 87.80                     | -                 |
| 1   | BONNET LOCK BRACE PANEL                       | NOT NECESSARY        | 181.70                    | -                 |
| 1   | BONNET CHROME                                 | NOT NECESSARY        | 155.30                    | -                 |
| 6   | BONNET INNER RUBBER BEADING CLIPS @ \$12.90   | NOT NECESSARY        | 77.40                     | -                 |
| 2   | HEAD LAMP ASSY @ \$681.75                     | O/S CRACKED          | 1,363.50                  | 681.75            |
| 2   | HEAD LAMP CLIPS @ \$43.90                     | NOT NECESSARY        | 87.80                     | -                 |
| 1   | FRONT GRILLE                                  | MISSING              | 131.75                    | 131.75            |
| 2   | FRONT GRILLE TOP CLIPS WITH STOPPER @ \$53.90 | NOT NECESSARY        | 107.80                    | -                 |
| 2   | FRONT GRILLE CLIPS @ \$12.90                  | NECESSARY            | 25.80                     | 10.00             |
| 1   | FRONT BUMPER FASCIA                           | MISSING              | 480.20                    | 480.20            |
| 1   | FRONT BUMPER SIDE RETAINER                    | NECESSARY            | 131.75                    | 131.75            |
| 1   | FRONT BUMPER SPONGE                           | MISSING              | 141.10                    | 141.10            |
| 1   | FRONT BUMPER REINFORCEMENT                    | BENT                 | 173.55                    | 173.55            |
| 1   | FRONT BUMPER AIR GUIDE                        | MISSING              | 108.85                    | 108.85            |
| 2   | FRONT BUMPER FOG LAMP COVER @ \$43.90         | MISSING              | 87.80                     | 87.80             |
| 10  | FRONT BUMPER CLIPS @ \$12.90                  | NECESSARY            | 129.00                    | 30.00             |
| 1   | FRONT SUPPORT PANEL                           | DISTORTED            | 880.20                    | 880.20            |
| 1   | FRONT SUPPORT PANEL TOP GARNISH               | NOT NECESSARY        | 121.10                    | -                 |
| 2   | HORN ASSY @ \$182.25                          | NOT NECESSARY        | 364.50                    | -                 |
| 1   | AIRCON CONDENSER                              | BENT                 | 981.75                    | 981.75            |
| 2   | AIRCO CONDENSER TOP MOUNTING @ \$63.10        | NECESSARY            | 122.20                    | 122.20            |
| 2   | AIRCON CONDENSER BOTTOM MOUNTING @ \$63.90    | NECESSARY            | 127.80                    | 127.80            |
| 1   | AIRCON SUCTION PIPE                           | NOT NECESSARY        | 298.10                    | -                 |

Report Ref No. CC4/LPC17022729/Aea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

| Qty | Description of Parts                       | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | RADIATOR ASSY                              | BENT                 | 1,210.20                  | 1,210.20          |
| 2   | RADIATOR TOP MOUNTING @ \$63.90            | NECESSARY            | 127.80                    | 127.80            |
| 2   | RADIATOR BOTTOM MOUNTING @ \$61.10         | NECESSARY            | 122.20                    | 122.20            |
| 1   | RADIATOR FAN COWLING                       | NOT NECESSARY        | 231.20                    | -                 |
| 1   | FRONT FENDER LH                            | TO REPAIR SEE LABOUR | 488.20                    | -                 |
| 1   | FRONT FENDER SPLASH SHIELD                 | TORN                 | 168.10                    | 168.10            |
| 8   | FRONT FENDER SPLASH SHIELD CLIPS @ \$12.90 | NECESSARY            | 103.20                    | 30.00             |
| 1   | FRONT CENTER CROSSMEMBER                   | BENT                 | 480.00                    | 480.00            |
| 1   | FRONT KNUCKLE ARM LH                       | NOT NECESSARY        | 581.10                    | -                 |
| 1   | FRONT LOWER ARM                            | NOT NECESSARY        | 374.45                    | -                 |
| 1   | FRONT LOWER ARM BALL JOINT                 | NOT NECESSARY        | 182.20                    | -                 |
| 1   | FRONT ANTI ROLL BAR                        | NOT NECESSARY        | 360.10                    | -                 |
| 1   | FRONT ANTI ROLL BAR LINK                   | NOT NECESSARY        | 196.60                    | -                 |
| 1   | STEERING RACK ASSY                         | NOT NECESSARY        | 1,505.20                  | -                 |
| 1   | FRONT WHEEL BEARING KIT LH                 | NOT NECESSARY        | 516.50                    | -                 |
| 1   | ENGINE UNDER MOUNTING - FRONT              | NOT NECESSARY        | 171.20                    | -                 |
| 1   | ENGINE UNDER MOUNTING - REAR               | NOT NECESSARY        | 192.80                    | -                 |
|     | LESS 25% DISCOUNT                          |                      | -9,947.26                 | -4,487.51         |
|     |                                            |                      | 29,841.79                 | 13,462.54         |
|     | <b>SPECIAL NETT ITEMS</b>                  |                      |                           |                   |
| 1   | FRONT BUMPER LOWER SPOILER (ACC) (SN)      | MISSING              | 680.00                    | 680.00            |
| 1   | REAR BUMPER LOWER SPOILER (ACC) (SN)       | MISSING              | 680.00                    | 680.00            |
| 1   | ROCKER PANEL SPOILER - N/S (SN)            | DEFORMED             | 550.00                    | 550.00            |
| 1   | AUTO GEAR BOX ASSY (2ND) (SN)              | CRACKED              | 2,800.00                  | 1,500.00          |
| 1   | AUTO TRANSMISSION FLUID (SN)               | NECESSARY            | 80.00                     | 40.00             |
| 2   | RIM ASSY (SPORT) FRONT & REAR LH (SN)      | FRONT N/S CUT        | 1,300.00                  | 400.00            |
| 2   | TYRE ASSY @ \$280.00 (SN)                  | FRONT N/S PUNCTURE   | 560.00                    | 180.00            |
| 1   | BATTERY ASSY (SN)                          | NOT NECESSARY        | 200.00                    | -                 |
| 1   | FRONT NUMBER PLATE (SN)                    | MISSING              | 45.00                     | 30.00             |
| 1   | FRONT NUMBER PLATE CASING (SN)             | MISSING              | 29.00                     | 29.00             |
| 1   | TAIL GATE OUTER SWITCH (SN)                | NOT NECESSARY        | 180.00                    | -                 |

Report Ref No. CC4/LPC17022729/Aea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

| Qty                                                                         | Description of Parts                                                                                                                                                                                           | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | REAR FLOOR PANEL BOARD (SN)                                                                                                                                                                                    | NOT NECESSARY | 120.00                    | -                 |
| 2                                                                           | REAR FENDER GLASS SOLAR FILM (ACC) @ \$50.00 (SN)                                                                                                                                                              | O/S NECESSARY | 100.00                    | 50.00             |
| 1                                                                           | REAR WINDSCREEN GLASS SOLAR FILM (SN)                                                                                                                                                                          | NECESSARY     | 50.00                     | 50.00             |
| 1                                                                           | REAR WINDSCREEN GLASS SEALANT (SN)                                                                                                                                                                             | NECESSARY     | 60.00                     | 60.00             |
| 1                                                                           | REVERSE SENSOR WITH CONTROL UNIT (SN)                                                                                                                                                                          | MISSING       | 380.00                    | 200.00            |
| 1                                                                           | REAR NUMBER PLATE (SN)                                                                                                                                                                                         | NOT NECESSARY | 45.00                     | -                 |
| 1                                                                           | REAR NUMBER PLATE CASING (SN)                                                                                                                                                                                  | NOT NECESSARY | 29.00                     | -                 |
| 1                                                                           | REAR FENDER GLASS SEALANT (SN)                                                                                                                                                                                 | NECESSARY     | 50.00                     | 30.00             |
|                                                                             |                                                                                                                                                                                                                |               | 7,938.00                  | 4,479.00          |
|                                                                             | <b>LABOUR</b>                                                                                                                                                                                                  |               |                           |                   |
|                                                                             | TOWING (3 TRIPS)                                                                                                                                                                                               |               | 240.00                    | 60.00             |
|                                                                             | TO CHECK & RECONNECT SNAP WIRING.                                                                                                                                                                              |               | 120.00                    | 60.00             |
|                                                                             | TO TUFF COAT AFFECTED AREAS.                                                                                                                                                                                   |               | 220.00                    | 100.00            |
|                                                                             | TO REMOVE & REFIX INETRIOR UPHOLSTERY.                                                                                                                                                                         |               | 180.00                    | 80.00             |
|                                                                             | TO REMOVE & REFIX FRONT UNDERCARRIAGE COMPONENTS.                                                                                                                                                              |               | 480.00                    | 220.00            |
|                                                                             | TO REMOVE & REFIX AUTO GEAR BOX.                                                                                                                                                                               | NOT NECESSARY | 380.00                    | -                 |
|                                                                             | TO REMOVE & REFIX RADIATOR & TOP UP GAS.                                                                                                                                                                       |               | 180.00                    | 60.00             |
|                                                                             | TO REMOVE & REFIX CONDENSER & TOP UP GAS.                                                                                                                                                                      |               | 180.00                    | 60.00             |
|                                                                             | TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER.                                                                                                                                                                    | NOT NECESSARY | 380.00                    | -                 |
|                                                                             | TO REMOVE & REFIX REAR WINDSCREEN GLASS & REAR FENDER GLASS RH.                                                                                                                                                |               | 280.00                    | 180.00            |
|                                                                             | TO REMOVE & REFIX EXHAUST.                                                                                                                                                                                     | NOT NECESSARY | 120.00                    | -                 |
|                                                                             | TO ADJUST WHEEL ALIGNMENT.                                                                                                                                                                                     |               | 120.00                    | 80.00             |
|                                                                             | TO RESPRAY AFFECTED AREAS.                                                                                                                                                                                     |               | 2,200.00                  | 1,700.00          |
|                                                                             | TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR SUB CHASSIS FRAME MEMBER - RH, REAR FENDER INNER EXTENTION PANEL O/S AND FRONT FENDER LH. |               | 2,500.00                  | 2,000.00          |
|                                                                             |                                                                                                                                                                                                                |               | 7,580.00                  | 4,600.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                                                |               | <b>45,359.79</b>          | <b>22,541.54</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                                                |               |                           | <b>10,500.00</b>  |

Report Ref No. CC4/LPC17022729/Aea3s2



Report Ref No. CC4/LPC17022729/Aea3s2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, with a stylized flourish.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.