



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR17022736/pa3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGSINGAPORE 079120		Date : 29-11-2017	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLR 9449T	Veh. Inspected	SLC 9991Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/11/2017	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

5/12/17 @ 12am
Survey & Repair

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197461839W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190180 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63649773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190532/530 (Motorrad)
Fax. 64796602 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

29 NOV 2017

Estimate No. : b1 44986	Page No. : 1 of 3
Date Estimated : 28/11/2017	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Koh Yu 5 West Coast Walk #21-09 Singapore 127146	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION	VALUE
To replace rear RH door, rear RH fender, RH rocker panel cover and attachment including knock out dent area cause by accident	(5 days) 4250 / 7,650.00
Painting on rear bumper, rear RH fender, rear RH door, RH rocker panel cover, Frt RH door, trunk floor & tail panel X X	3992 / 5,710.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	451 / 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	X 873.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	X 271.00
To remove and install fuel tank to facilitate repairs including conduct checks for leak.	X 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 / 177.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).	451 / 531.00
To replace tyre and wheel rim including balancing. (1x).	X 94.00
To carry out body cavity preservation. (For cut panel).	100 / 531.00
To reconnect electrical components and wirings at the rear section including conduct checks for proper function.	150 / 354.00
Sundries. <i>Nur</i>	150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197402559W GST Reg. No M2-0020081-X



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 67490100 (Sales & Admin)
67490111 (AfterSales)
Fax. 64747770

100, Nanpong Arang Road
East Coast Centre
Singapore 438130
Tel. 67432888 (AfterSales)
Fax. 63449773

111, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 67490528 (AfterSales)
67490533/530 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44986
Date Estimated : 28/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION

VALUE

Total Labour 1: 17,403.00

DESCRIPTION

QTY PRIC

VALUE

ALLOY RIM 7JX16 STAR SPK 654	1	706.40	R	706.40
HUB CAP WITH CHROME EDGE (BMW)	1	23.75	max	23.75
RR RH FENDER	1	1,264.35	R	1,264.35
REINFORCEMENT PLATE C-PILLAR RH	1	48.00	?	48.00
REINFORCEMENT PLATE C-PILLAR RH	1	48.00	X	48.00
REINFORCEMENT PLATE ROCKER PLATE RH	1	48.00	su	48.00
REINFORCEMENT PLATE ROCKER PLATE RH	1	48.00	?	48.00
REINFORCEMENT PLATE UNIVERSAL	1	27.10	?	27.10
RR RH DOOR	1	1,025.45	M	1,025.45
RH LOWER REAR DOOR HINGE	1	55.75	?	55.75
RH UPPER REAR DOOR HINGE	1	55.75	?	55.75
REAR BUMPER RH MOUNT	1	141.65	su	141.65
CARRIER OUTSIDE DOOR HANDLE FRT RH	1	101.05	?	101.05
SYSTEM LATCH RH	1	235.95	?	235.95
REAR DOOR BRAKE	1	67.60	?	67.60
RR RH DOOR INNER WEATHERSTRIP	1	58.00	max	58.00
RR RH DUCT COVER OUTER DOOR	1	68.25	?	68.25
COVER WINDOW GUIDE WEB EXT RR	1	45.70	su	45.70
REAR DOOR EDGE PROTECTOR	1	65.10	?	65.10
REAR RH DOOR WINDOW GUIDE	1	116.70	?	116.70
B PILLAR FINISHER OUTER RH	1	48.05	?	48.05
REAR RH WHEEL HOUSING COVER	1	126.85	?	126.85
RH SILL STRIP PRIMED	1	263.95	R	263.95
SET OF RETAINER STRIPS RH	1	28.25	?	28.25
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	?	19.80
BLIND RIVET AVIBVLB	10	0.55	?	5.50
SCREW (SF PLUS M5X15)	3	0.55	?	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	XM	281.55
PUNCH RIVET N4	32	0.55	?	17.60
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	?	118.35
(DG) CLEANER R1 (100ML)	1	23.85	?	23.85
(S/L) SEAM SEAL 300ML	1	33.80	?	33.80

Total Parts : 5,219.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401158W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747710

280, Kembangan Arang Road
East Coast Centre
Singapore 438185
Tel: 63190988 (AfterSales)
Fax: 63449773

313, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64736601 (AfterSales)
64736624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44986 Page No. : 3 of 3
Date Estimated : 28/11/2017
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

Client: OO / 3rd Party / Uninsured Losses / Direct Settlement

Page No. _____ Date Issued _____

Date & Time: 05/12/17 @ 11:45 Expiry: 30

Surveyor's Name: Rasul Sign: _____

Surveyor's Tel: 92010018 Approved: Yes / No

Authorized Date: _____ Title: _____

INSURANCE PARTS PHOTO BY: S. SURESH YASASAI TEL: 9997 / No

Surveyor's Email: rasul@lkkauto.com

No. of Working Days Estimated: 9-10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: _____

Date: _____

Labour 1	:	17,403.00
Parts	:	5,219.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,583.59
Grand Total	:	24,206.34

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44986
Date Estimated : 28/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Koh Yu
5 West Coast Walk
#21-09

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 127146

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SLC9991Y	V724322	18/04/2016	116d	0			
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT			
# To replace rear RH door fixed quarter glass include conducting water leak checks					413.00		413.00 ✓
<i>To remove & install RH section carpet & garnish to facilitate repairs.</i>					236W		236W ✓
# EXPANDING NUT *	2.05	3.00					6.15 ✓
# RR RH DOOR QUARTER GLASS *	130.75	1.00					130.75 ✓
				Total Labour :			413.00
				Total Parts :			136.90
				Total Labour & Parts :			549.90

23403.65



FINAL REPORT

Estimate No : b1 44986
 Date Estimated : 28/11/2017
 Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
 Koh Yu
 5 West Coast Walk
 #21-09
 Singapore 127146

- ACCOUNT - 121
 AIG Asia Pacific Insurance Pte. Ltd.
 78 Shanton Way
 #08-16 Chartis Building
 Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To replace rear RH door and attachments include making good the rear bumper, rear RH fender, RH rocker panel cover, front RH door and knocking out dents caused by the accident	4250.00		4,250.00	/
To spray paint rear bumper, rear RH fender, rear RH door, RH rocker panel cover and front RH door	3992.00		3,992.00	/
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00	/
(S) : To remove and install RH section carpet and garnish to facilitate repairs	231.00		231.00	(S)
To remove and install PDC assembly to facilitate repairs include conducting checks for proper function	150.00		150.00	/
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	/
To carry out body cavity preservation. (Per panel)	100.00		100.00	/
To check electrical wiring system and lightings at the rear section include conducting checks for proper function	150.00		150.00	/
(S) # To replace rear RH door fixed quarter glass include conducting water leak checks	413.00		413.00	(S)
Sundries	150.00		150.00	/

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING NUT *	2.05	3.00		6.15
RR RH DOOR	1,025.45	1.00		1,025.45
# RR RH DOOR QUARTER GLASS *	130.75	1.00		130.75

SUPPLEMENTARY ITEMS

Total Labour :	10,338.00
Total Parts :	1,162.35
Total Labour & Parts :	11,500.35
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,500.35
GST @7%:	805.02
Grand Total :	12,305.37

Hsiao Tong (LKKAuto)

From: PBSP <prml-pbsp@simedarby.com.sg>
Sent: Monday, 13 August 2018 4:11 PM
To: Rasul (LKKAuto); Hsiao Tong (LKKAuto)
Subject: Re: FINAL REPORT / SLC9991Y

3rd URGENT REMINDER

From: PBSP
Sent: Thursday, 28 June 2018 2:04:32 PM
To: Rasul; Hsiao Tong
Subject: Re: FINAL REPORT / SLC9991Y

2nd Urgent reminder

From: PBSP
Sent: Wednesday, 21 March 2018 4:21:08 PM
To: Rasul; Hsiao Tong
Subject: FINAL REPORT / SLC9991Y

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,338.00
Total Parts : 1,162.35
Total Labour & Parts : 11,500.35

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 1 December, 2017 2:59 PM
To: PBSP
Cc: Admin A; assignments; Zayyer (LKKAuto); Vivian Lau (LKKAuto)
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLC9991Y AND SLR9449T ON 26/11/2017 ***
LKK REF: CC3/LCR17022736/pa3

Without Prejudice

Hi,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 29 November, 2017 6:06 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Zayyer (LKKAuto) <zayyer@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLC9991Y AND SLR9449T ON 26/11/2017 *** LKK REF: CC3/LCR17022736/pa3

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our insured's GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Wednesday, 29 November, 2017 9:25 AM

To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: REQ FOR DIRECT SETTLEMENT- SLC9991Y AND SLR9449T ON 26/11/2017

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 30 August 2018 10:50 AM
To: 'PBSP'
Cc: Rasul (LKKAuto); Admin A
Subject: RE: 5TH URGENT REMINDER: FINAL REPORT / SLC9991Y

Without Prejudice

Hi,

We apologise for late reply.

For COR, recommended amount at P/P **\$11,500.35(before GST)** with **9repair days**.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 28 August 2018 6:14 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: 5TH URGENT REMINDER: FINAL REPORT / SLC9991Y

5TH URGENT REMINDER

From: PBSP
Sent: Monday, 13 August 2018 4:10 PM
To: Rasul; Hsiao Tong
Subject: Re: FINAL REPORT / SLC9991Y

3rd URGENT REMINDER

From: PBSP
Sent: Thursday, 28 June 2018 2:04:32 PM
To: Rasul; Hsiao Tong
Subject: Re: FINAL REPORT / SLC9991Y

2nd Urgent reminder

From: PBSP
Sent: Wednesday, 21 March 2018 4:21:08 PM
To: Rasul; Hsiao Tong
Subject: FINAL REPORT / SLC9991Y

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,338.00
Total Parts : 1,162.35
Total Labour & Parts : 11,500.35

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLC9991 Y	Model:	
Date of Accident:	26.11.17		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate			\$ 24,206.34
Final Repair Cost			\$ 12,305.37
Loss of Use			\$ 600.00 10 days at \$ 60 per day
Rental (if any)			\$ — days
LTA / GIA Search Fee			\$ 5.35
Others:			\$ /
			\$
Final Settlement Sum			\$ 12,910.72

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	\$ 12,305.37
2)	Performance Motors Ltd	\$ 5.35
3)	Koh Yu	\$ 600.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel: +65 6827 7888, Fax: +65 6827 7900
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

**Sime Darby Insurance
Brokers (Singapore) Pte Ltd**
Tel: 6822 2244
Mon to Fri (excluding PH)
(8.30 am - 6.45 pm)

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

SIME MOTOR PRIVATE
Comprehensive

Certificate No. **B 28935457 SMP**

Excess : SGD500

1. **Index Mark and Registration Number of Vehicle**
SLC9991Y

2. **Name of Policyholder**
Koh Yu

3. **Effective Date of the Commencement of Insurance for the purposes of the Act**
18/04/2017

4. **Date of Expiry of Insurance**
17/04/2018

5. **Persons or Classes of Persons entitled to drive***
Koh Yu

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.


* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT PERFORMANCE MOTORS LTD OR AT ANY WORKSHOP OF YOUR CHOICE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers



for Chief Executive Officer

DRIVING LICENCE

Licence Number: **S9317253A**

Name: **KOH YU**

Birth Date: **20 May 1993**

Issue Date: **04 Apr 2013**

0021673600




S9317253A

KOH YU

許裕

CHINESE

20-05-1993 M

SINGAPORE




41212

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3A Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles without clutch pedals <= 2500kg	04 Apr 2013



S9317253A

11-06-2008

NF 4264

Licence No: **S9317253A**

S WEST COAST WALK #21-09
SINGAPORE 127146

UIC No: **S9317253A**

Date: **28/07/2010**

IC: **6500598**

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 1 October 2018 10:21 AM
To: Boyogan, Joane (Joane.Boyogan@aig.com)
Subject: <Seek Mandate> Your Ref:0329650077SG *Our Ref: CC3/LCR17022736/R1pa3
[ACCIDENT INVOLVING SLR 9449T(OI) & SLC 9991Y(TP) ON 26/11/2017]

Your Ref: **0329650077SG**
Our Ref: CC3/LCR17022736/R1pa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SLR 9449T(OI) & SLC 9991Y(TP) ON 26/11/2017

We refer to the above matter.

The accident occurred when our insured driver came out from parking lot and collided onto third party who wa along the main driveway. Liability is not in our insured driver's favour.

We seek your approval to offer to Third Party repairer, "**Performance Motors Limited**" is as follows: -

	<u>Amount Claimed</u>	<u>Amount Revised</u>
1. Cost of Repair (w/GST)	\$25,041.91	\$12,305.37
2. Loss of Use (10days x \$60.00)	\$ 600.00	\$ 600.00 (10days x \$60.00)
3. LTA/ GIA Search Fee	\$ 5.35	\$ 5.35
TOTAL	\$25,647.26	\$12,910.72

Total amount of claim (**Liability 100%**)

\$12,910.72

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLC9991Y (0329650077SG)**
[SLR9449T]
TP
KOH YU
Nov 26 2017 10:00AM
[LCRF Pte Ltd]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 01/10/2018 18:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12910.72) - SLC9991Y - Claim Handler: Boyogan, Joane

Approved:12910.72.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 2 October 2018 11:11 AM
To: 'PBSP'
Cc: Rasul (LKKAuto); Admin A
Subject: RE: 5TH URGENT REMINDER: FINAL REPORT / SLC9991Y

Without Prejudice

Hi,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 12,305.37 (payable to Performance Motors Ltd)
2. Loss of Use (10days x \$60.00)	\$ 600.00 (payable to Koh Yu)
3. LTA/GIA search fee	\$ 5.35 (payable to Performance Motors Ltd)
TOTAL	<u>\$ 12,910.72</u>

We will proceed to close file.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 30 August 2018 10:50 AM
To: 'PBSP' <pml-pbsp@simedarby.com.sg>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: 5TH URGENT REMINDER: FINAL REPORT / SLC9991Y

Without Prejudice

Hi,

We apologise for late reply.

For COR, recommended amount at P/P **\$11,500.35(before GST)** with **9repair days**.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, 28 August 2018 6:14 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: 5TH URGENT REMINDER: FINAL REPORT / SLC9991Y

5TH URGENT REMINDER

From: PBSP

Sent: Monday, 13 August 2018 4:10 PM

To: Rasul; Hsiao Tong

Subject: Re: FINAL REPORT / SLC9991Y

3rd URGENT REMINDER

From: PBSP

Sent: Thursday, 28 June 2018 2:04:32 PM

To: Rasul; Hsiao Tong

Subject: Re: FINAL REPORT / SLC9991Y

2nd Urgent reminder

From: PBSP
Sent: Wednesday, 21 March 2018 4:21:08 PM
To: Rasul; Hsiao Tong
Subject: FINAL REPORT / SLC9991Y

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,338.00
Total Parts : 1,162.35
Total Labour & Parts : 11,500.35

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 1 December, 2017 2:58 PM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLR 9449T(AIG) & SLC 9991Y ON 26/11/2017

Your Ref: **SLR 9449T**
Our Ref: CC3/LCR17022736/pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLR 9449T(AIG) & SLC 9991Y ON 26/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLC 9991Y against your insurance policy.

Based on the accident report and accident scenario, liability is down against us.
We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Koh Yu (the third party claimant) of 5 West Crest
Unit #21-09 S(127146) (address), owner of SLC9991Y (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLC9991Y that was damaged pursuant to the accident which occurred on 26-11-17
(date) along The Parc Condominium (location) involving vehicle no/s
SLR9449T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 05 (day) of 12 (month) 20 17 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by Performance Motors Ltd
(with chop)
Inthiran M. Thurasamy,
Performance Motors Ltd
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for S\$12,325.37 (Repair Cost), S\$600.00 (Loss of rental/use), S\$5.35 (Disbursement), for vehicle no. SLK9991Y that was damaged pursuant to the accident which occurred on 26.11.17 (date) along The Parc Condominium (location) involving vehicle no/s SLK94497. This is pursuant to the inspection conducted on 5.12.17 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Koh Yu ("the third party claimant") of vehicle no. SLK9991Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLK9991Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 02 (day) of 10 (month) 2018 (year)



MRB

Signed by appointed surveyor

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Dart Performance Centre
Singapore 159941
TEL: 63190100 (Sales)

Signed by "the workshop" (with chan)

Performance Motors Limited

A member of the Sime Darby Group
 Co. Reg. No. 197401559W GST Reg. No. M2-002081-x

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 119941
 Tel. 63190100 (Sales & Admin)
 63190211 (AfterSales)
 Fax. 64747770

280, Kangkong Arang Road
 East Coast Centre
 Singapore 438180
 Tel. 63190888 (AfterSales)
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 119944
 Tel. 63190528 (AfterSales)
 63190333/830 (Motorrad)
 Fax. 64798601 (AfterSales)
 64798624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1227083	Page No. : 1 of 2
Date IN : 05/12/2017	Invoice Number : 2004028 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 03/09/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mr Koh Yu
 5 West Coast Walk
 #21-09

Singapore 127146

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
 78 Shenton Way
 #08-16 Chartis Building
 Singapore 079120

REGN. NO. SLC9991Y	CHASSIS NO. V724322	REGN. DATE 18/04/2016	MODEL 116D	MILEAGE 40169
-----------------------	------------------------	--------------------------	---------------	------------------

- - - - LABOUR 1 - - - -

	NETT
To replace rear right door and attachments including make good the rear bumper, rear right fender, right rocker panel cover, front right door and knock out dented area caused by the accident.	4,250.00
To respray rear bumper, rear right fender, both right doors and right rocker panel cover.	3,992.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00
To remove and install right section carpet and garnish to facilitate repairs.	231.00
To remove and install PDC assembly to facilitate repairs including conduct checks for proper function.	150.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications.	451.00
To carry out body cavity preservation.	100.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To replace rear right door fixed quarter glass including conduct water leak checks.	413.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 26.11.2017. 3RD PARTY CAR : SLR9449T.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON 05.12.2017 AT 11:45AM. AUTHORISED REPAIR BY MS HSIAO TONG FROM LKK AUTO ON 01.12.2017 VIA EMAIL.	
PROPOSE LOSS OF USE = \$60x10. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
LTA SEARCH FEE = \$5.35.	0.00
Total Labour 1:	10,338.00

- - - - PARTS - - - -	Qty	Retail Price	NETT
RR RH DOOR	1	1,025.45	1,025.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401553W GST Reg. No. M2-0020881-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64767770

290, Kampong Arang Road
East Coast Centre
Singapore 478190
Tel. 63190888 (AfterSales)
Fax: 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190513/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : B1 1227083	Page No. : 2 of 2
Date IN : 05/12/2017	Invoice Number : 2004028 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 03/09/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

RR RH DOOR QUARTER GLASS	1	130.75	130.75
EXPANDING NUT	3	2.05	6.15
	Total Parts	:	1,162.35

Labour Charges : 10,188.00	Total Labour & Parts Charges : S\$ 11,500.35
Parts Charges : 1,162.35	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 150.00	Invoice Total Amount Exclude GST : S\$ 11,500.35
	GST @ 7% : S\$ 805.02
	Invoice Total Amount Include GST : S\$ 12,305.37

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 12,305.37**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 27 Nov 2017 / 14:30:34

Receipt Date/Time : 27 Nov 2017 / 14:30:34

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171127-001213

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLR9449T As at 26 Nov 2017/10:25:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLR9449T Enquiry Fee 20171127142900378195	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	xxxxxxxxxxxx5164		Credit Card: Visa/MasterCard	5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Nov 2017 Edit Reg		05 Dec 2017 00:00 Edit Adj Rpt	S\$11,500.35 Edit Estimates	S\$11,500.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K								
Main Claimant:	KOH YU, ID: S9317253A								
Vehicle Reg. No.:	SLC9991Y	Date of Loss:	26/11/2017 10:00 - :59 [19 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0329650077SG	Policy/Cover Note No.:	0999995026						
Vehicle Reg. No. (Insured):	SLR9449T	Policy No. (Claimant):	B28935457SMP						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (01/10/2018): Alert - Adj Mandate Approved (S\$12910.72) - SLC9991Y - Claim Handler: Boyogan, J...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC9991Y (0329650077SG)
[SLR9449T]
TP
KOH YU
Nov 26 2017 10:00AM
[LCRF Pte Ltd]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="button" value="v"/>	
Letters/Correspondences										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/08/18 10:52	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	30/08/18 10:52	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
4	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
5	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
6	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
7	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
8	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
9	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
10	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
11	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
12	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
13	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
14	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
15	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
16	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
17	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
18	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
19	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
20	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
21	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
22	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
23	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
24	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
25	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
26	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
27	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
28	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
29	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
30	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
31	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
32	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
33	30/08/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>	
34	30/08/18 10:52	General View							Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
50	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
51	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
52	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
53	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
54	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
55	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
56	30/08/18 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 18:02	TP ESTIMATE	 Load TIF	
2	29/11/17 18:02	TP GIA REPORT	 Load PDF	
3	07/12/17 20:21	TP ESTIMATE - MARKED	 Load PDF	
4	27/09/18 09:22	LETTER TO OI	 Load PDF	
5	01/10/18 10:15	TP OWNER IC & DL	 Load PDF	
6	01/10/18 10:15	LTA	 Load PDF	
7	04/10/18 09:10	WORKSHOP INVOICE	 Load PDF	
8	04/10/18 09:10	AUTHORISATION TO ACT FORM	 Load PDF	
9	04/10/18 09:10	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/11/17 10:27	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR9449T (Insd veh)	Model:	BMW 116D 1.5 (A)
	SLC9991Y (TP veh)		
Date of Accident:	26/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	25,041.91	
Final Repair Cost	:	\$	12,305.37	
Loss of Use	:	\$	600.00	10.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	5.35	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	12,910.72	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 12,310.72
2)	Koh Yu	:	\$ 600.00
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

04 Oct
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17022736/R1PA3Q2
Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999995026
Claimant Vehicle No : SLC9991Y	Insured Vehicle No :	SLR9449T
Date of Loss: 26/11/2017	Nature of Claim: TP	Claim No: 0329650077SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC9991Y	Engine No:	33929525B37D15A
Make & Model:	BMW 116D, 1.5 (A)	Chassis No:	WBA1V72080V724322
Reg. Date:	18/04/2016 (Man. Year: 2016)	Odometer:	40169 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,506.65	1,312.35	4,194.30	76.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,897.00	10,188.00	7,709.00	43.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,403.65	11,500.35	11,903.30	50.86
+ GST 7.00/7.00% (S\$)	1,638.26	805.02	833.24	50.86
Nett Amount (S\$)	25,041.91	12,305.37	12,736.54	50.86
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		12,910.72		

INSPECTION

Date of Assignment:	05/12/2017	
Date Inspected:	05/12/2017 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS	
2	1		*ALLOY RIM 7JX16 STAR SPK 654	Repair	706.40 FS	*- FS	
3	1		*HUB CAP WITH CHROME EDGE (BMW)	Serviceable	23.75 FS	*- FS	
4	1		*RR RH FENDER	Repair	1,264.35 FS	*- FS	
5	1		*REINFORCEMENT PLATE C-PILLAR RH	Serviceable	48.00 FS	*- FS	
6	1		*REINFORCEMENT PLATE C-PILLAR RH	Serviceable	48.00 FS	*- FS	
7	1		*REINFORCEMENT PLATE ROCKER PLATE RH	Serviceable	48.00 FS	*- FS	
8	1		*REINFORCEMENT PLATE ROCKER PLATE RH	Serviceable	48.00 FS	*- FS	
9	1		*REINFORCEMENT PLATE UNIVERSAL	Serviceable	27.10 FS	*- FS	
10	1		*RR RH DOOR	Bent	1,025.45 FS	*1,025.45 FS	
11	1		*RH LOWER REAR DOOR HINGE	Serviceable	55.75 FS	*- FS	
12	1		*RH UPPER REAR DOOR HINGE	Serviceable	55.75 FS	*- FS	
13	1		*REAR BUMPER RH MOUNT	Serviceable	141.65 FS	*- FS	
14	1		*CARRIER OUTSIDE DOOR HANDLE FRT RH	Serviceable	101.05 FS	*- FS	
15	1		*SYSTEM LATCH RH	Serviceable	235.95 FS	*- FS	
16	1		*REAR DOOR BRAKE	Serviceable	67.60 FS	*- FS	
17	1		*RR RH DOOR INNER WEATHERSTRIP	Serviceable	58.00 FS	*- FS	
18	1		*RR RH DUCT COVER OUTER DOOR	Serviceable	68.25 FS	*- FS	
19	1		*COVER WINDOW GUIDE WEB EXT RR	Serviceable	45.70 FS	*- FS	
20	1		*REAR DOOR EDGE PROTECTOR	Serviceable	65.10 FS	*- FS	
21	1		*REAR RH DOOR WINDOW GUIDE	Serviceable	116.70 FS	*- FS	
22	1		*B PILLAR FINISHER OUTER RH	Serviceable	48.05 FS	*- FS	
23	1		*REAR RH WHEEL HOUSING COVER	Serviceable	126.85 FS	*- FS	
24	1		*RH SILL STRIP PRIMED	Repair	263.95 FS	*- FS	
25	1		*SET OF RETAINER STRIPS RH	Not Necessary	28.25 FS	*- FS	
26	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	19.80 FS	*- FS	
27	10		*BLIND RIVET AVIBVLB	Not Necessary	5.50 FS	*- FS	
28	3		*SCREW (SF PLUS M5X15)	Not Necessary	1.65 FS	*- FS	
29	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS	
30	1		*PUNCH RIVET N4 (32 PCS)	Not Necessary	17.60 FS	*- FS	
31	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	118.35 FS	*- FS	
32	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS	
33	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS	
34	3		*EXPANDING NUT	Necessary	6.15 FS	*6.15 FS	
35	1		*RR RH DOOR QUARTER GLASS	Necessary	130.75 FS	*130.75 FS	
					Total Parts (\$\$)	5,506.65	1,312.35

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RH DOOR FIXED QUARTER GLASS INCLUDE CONDUCTING WATER LEAK CHECKS	New	413.00	413.00
2	TO REMOVE & INSTALL RH SECTION CARPET & GARNISH TO FACILITATE REPAIRS	New	231.00	231.00
3	TO REPLACE REAR RH DOOR ,REAR RH FENDER ,RH ROCKER PANEL COVER AND ATTACHMENT INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	7,650.00	4,250.00
4	PAINTING ON REAR BUMPER ,REAR RH FENDER ,REAR RH DOOR ,RH ROCKER PANEL COVER ,FRT RH DOOR ,TRUNK FLOOR & TAIL PANEL	New	5,710.00	3,992.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
6	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	0.00
7	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
8	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING CONDUCT CHECKS FOR LEAK	New	531.00	0.00
9	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
10	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
11	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	0.00
12	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	100.00
13	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	150.00
Gross Labour Cost (\$\$)			17,897.00	10,188.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >