

5/12/17 @ 10am
Survey & Repair

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

29 NOV 2017

Estimate No. : b1 44986	Page No. : 1 of 3
Date Estimated : 28/11/2017	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR -	- ACCOUNT - 121
Koh Yu 5 West Coast Walk #21-09 Singapore 127146	AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION	VALUE
To replace rear RH door, rear RH fender, RH rocker panel cover and attachment including knock out dent area cause by accident	(5 days) 4250 7,650.00
Painting on rear bumper, rear RH fender, rear RH door, RH rocker panel cover, Frt RH door, trunk floor & tail panel	3992 5,710.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	451 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	X 873.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	X 271.00
To remove and install fuel tank to facilitate repairs including conduct checks for leak.	X 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).	451 531.00
To replace tyre and wheel rim including balancing. (1x).	X 94.00
To carry out body cavity preservation. (For cut panel).	100 531.00
To reconnect electrical components and wirings at the rear section including conduct checks for proper function.	150 354.00
Sundries.	3 150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 44986**
Date Estimated : **28/11/2017**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

DESCRIPTION

VALUE

Total Labour 1: **17,403.00**

DESCRIPTION

QTY

PRIC

VALUE

ALLOY RIM 7JX16 STAR SPK 654	1	706.40	R 706.40
HUB CAP WITH CHROME EDGE (BMW)	1	23.75	X 23.75
RR RH FENDER	1	1,264.35	R 1,264.35
REINFORCEMENT PLATE C-PILLAR RH	1	48.00	? 48.00
REINFORCEMENT PLATE C-PILLAR RH	1	48.00	? 48.00
REINFORCEMENT PLATE ROCKER PLATE RH	1	48.00	? 48.00
REINFORCEMENT PLATE ROCKER PLATE RH	1	48.00	? 48.00
REINFORCEMENT PLATE UNIVERSAL	1	27.10	? 27.10
RR RH DOOR	1	1,025.45	R 1,025.45
RH LOWER REAR DOOR HINGE	1	55.75	? 55.75
RH UPPER REAR DOOR HINGE	1	55.75	? 55.75
REAR BUMPER RH MOUNT	1	141.65	? 141.65
CARRIER OUTSIDE DOOR HANDLE FRT RH	1	101.05	? 101.05
SYSTEM LATCH RH	1	235.95	? 235.95
REAR DOOR BRAKE	1	67.60	? 67.60
RR RH DOOR INNER WEATHERSTRIP	1	58.00	new ? 58.00
RR RH DUCT COVER OUTER DOOR	1	68.25	? 68.25
COVER WINDOW GUIDE WEB EXT RR	1	45.70	? 45.70
REAR DOOR EDGE PROTECTOR	1	65.10	? 65.10
REAR RH DOOR WINDOW GUIDE	1	116.70	? 116.70
B PILLAR FINISHER OUTER RH	1	48.05	? 48.05
REAR RH WHEEL HOUSING COVER	1	126.85	? 126.85
RH SILL STRIP PRIMED	1	263.95	R ? 263.95
SET OF RETAINER STRIPS RH	1	28.25	? 28.25
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	? 19.80
BLIND RIVET AVIBVLB	10	0.55	? 5.50
SCREW (SF PLUS M5X15)	3	0.55	? 1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	? 281.55
PUNCH RIVET N4	32	0.55	? 17.60
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	? 118.35
(DG) CLEANER R1 (100ML)	1	23.85	? 23.85
(S/L) SEAM SEAL 300ML	1	33.80	? 33.80

Total Parts : **5,219.75**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44986
Date Estimated : 28/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9991Y	V724322	18/04/2016	116d	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 05/12/17 @ 11:45 Excess S\$ _____
Surveyor's Name Rasul Sign _____
Surveyor's Tel 90010078 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail rasul@lkkauto.com
No. of Working Days Recommend 9-10 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	17,403.00
Parts	:	5,219.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,583.59
Grand Total	:	<u>24,206.34</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **