

INS. CASE OWNER:

Jaclyn

CC 4 / AIG170

22742, m1ea34

IDAC:

Surveyor:

MA CF

DOI:

ASSIGNMENT

29-11-17

Date / Time:

28-11-17

Registered in Merimen:

29-11-17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGF 8981B

Name of Insured:

KOH CHYN

Insured Tel No.:

HP:

9856 5155

Excess Sec II : S\$

D.O.A.:

27/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

37511 7510256

Policy No.:

1700012830

Make / Model:

FORD MONDEO

Place of Accident:

PARK RUS DR 3

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJF 9731P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Em-1



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1/12
10:10

SJF 9731P - X;
 SGF 8981B - 664/AB61 6023282 / Kub 3m7: BOLA 5/1/16
 - 664/AB61 7015086 / APB3: BOLA 25/1/17

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email CSBZ/11

After call ltr to OI:

Shift 10:10pm

CALLER ON CONFIRMED ACCIDENT - ON ROAD ENDED TP. INFORM
 TP CLAIM AGREED TO SETTLE AND ADVISE ABOUT NO ISSUE

Email WSP Liability Case.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 29 JUN 2018

PRELIMINARY ADVICE Date/Time: - Sent By: -

FINALIZATION

Date/Time:

Confirm with: CHAN

Confirm by: MCF

Repair Cost: 46 S\$ 5,500 (5 days) Reduction: 50 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 28-6-18

Confirm with: KAREN

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost: S\$ 5,500.00 01 ROAD ENDED

Loss of Rental (LOR): 1/161 S\$ 535.00 (5 days) x \$100

Loss of Use (LOU): S\$ - (\$ x days)

Loss of Income (LOI): S\$ - (\$ x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search S\$ 35

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost S\$ -

Total: S\$ 6,040.35

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28-6-18

Confirm with: KAREN

Email ☒ Call ☐

Payee 1: S\$ 6,040.35 Name 1: EM-1 AUTO TRACE

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 320 + 20

COPY SENT
29/6/18




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17022742/M1ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-11-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGF 8981B	Veh. Inspected	SJF 9731P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/11/2017	Inspection Date	29/11/2017	
Survey held at	EM-1 AUTO TRADE BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SJF 9731P
Vehicle Model : MIT. LANCER EX
Accident Date : 27.11.2017
Original Reg Date : 18.06.2008

Date : 28.11.2017
Chassis : JMYSRCY2A8U007917
TP Ins. AIG

ESTIMATE

1	1 pc	Boot Lid		✓	823.00	
2	1 pc	Boot Lid Badge		✓	52.00	
3	1 pc	Boot Lid Emblem LANCER		✓	48.00	
4	1 pc	Boot Lid Emblem EX		✓	42.00	
5	1 pc	Boot Lid Emblem MIVEC		✓	48.00	
6	1 pc	Boot Lid Emblem (CC)		✓	40.00	
7	2 pcs	Boot Lid Lamps	223.00	✓	446.00	ovg
8	2 set	Boot Lid Lamp Clips	-25.00	✗	50.00	N/A
9	1 pc	Boot Lid Inner Lock		✓	123.00	wt
10	1 pc	Boot Lid Lock Catch		✗	36.00	R.
11	1 pc	Boot Lid Weatherstrip		✓	189.00	dis
12	1 set	Boot Lid Insulator Clip		✓	40.00	20
13	2 pcs	Boot Lid Hinges	-92.00	✗	184.00	R.
14	2 pcs	Boot Lid Absorber	-136.00	✗	272.00	Qvc
15	1 pc	Rear Bumper		✓	823.00	dat
16	2 pcs	Rear Bumper Side Retainers	36.00	✓	72.00	dis
17	1 set	Rear Bumper Clips		✓	50.00	40
18	2 pcs	Rear Bumper Number Plate Lamps	56.00	✓	112.00	ovg
19	2 pcs	Rear Bumper Number Plate Lamps Bracket	-30.00	✗	60.00	sc
20	1 pc	Rear Bumper Tow Cover		✗	32.00	Qvc
21	1 pc	Rear Bumper Reflectors		✓	58.00	ovg
22	1 pc	Rear Bumper Top Beam		✗	163.00	Nsp
23	1 pc	Rear Bumper Reinforcement		✓	252.00	wt
24	1 pc	Rear Bumper Wiring Harness		✓	256.00	dis/dont
25	1 pc	End Panel		✓	592.00	wt
26	1 pc	End Panel Top Trim		✓	182.00	dis
27	1 set	End Panel Top Trim Clips		✓	30.00	wt
28	1 pc	Rear Key Antenna Sensor		✓	175.00	dis/dont
29	1 pc	Spare Tyre Panel		✗	892.00	R
30	1 pc	Spare Tyre Panel Top Board		✓	195.00	dis

C/F

6,337.00

4781

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle No : SJF 9731P

B/F

6,337.00

1	2 pcs	Taillamps	351.00	702.00	chg
2	2 set	Taillamps Clips	-25.00	-50.00	chg
3	2 pcs	Taillamps Panel	-132.00	-264.00	chg
4	2 pcs	Rear Fender Inner Trim	262.00	-524.00	262.00
5	2 set	Rear Fender Inner Trim Clips	30.00	-60.00	30.00
6	2 pcs	Rear Fender Inner Shield	49.00	-98.00	49.00
7	2 set	Rear Fender Inner Shield Clips	25.00	-50.00	25.00
8	1 pc	Rear Air Vent		48.00	
9	1 pc	Rear Exhaust Silencer		623.00	chg
10	2 pcs	Rear Exhaust Mounting	38.00	-76.00	
11	1 pc	Rear Exhaust Gasket		46.00	
12	1 pc	Rear Exhaust Heat Plate		139.00	

9,017.00

Less 10% 901.70

8,115.30

Special Nett

1	1 pc	Rear No. Plate with Cover		70.00	40.00
2	1 set	Reverse Sensor		250.00	220.00
3	1 set	Body Panel Joint Sealant		120.00	80.00

Labour charge

Panel Beating		1,000.00	800.00
Spray painting		1,000.00	850.00
Check Wiring		50.00	30.00
Anti rust		90.00	60.00
Remove and install carpet and seat.		150.00	60.00
Remove and install reverse sensor		90.00	60.00
Remove and install rear exhaust.		120.00	80.00

\$ 11,055.30

Not Authorised
AAE - JAW PLOZ
LCC Auto (un)
7 wday &
27/4/2017 @

1890
confer
\$5500 + 7 day
agree

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SJF 9731P
Vehicle Model : MIT. LANCER EX
Accident Date : 27.11.2017
Original Reg Date : 18.06.2008

Date : 28.11.2017
Chassis : JMYSRCY2A8U007917
TP Ins. : AIG

ESTIMATE

1	1 pc	Boot Lid		✓	823.00	
2	1 pc	Boot Lid Badge		✓	52.00	
3	1 pc	Boot Lid Emblem LANCER		✓	48.00	
4	1 pc	Boot Lid Emblem EX		✓	42.00	
5	1 pc	Boot Lid Emblem MIVEC		✓	48.00	
6	1 pc	Boot Lid Emblem (CC)		✓	40.00	
7	2 pcs	Boot Lid Lamps	223.00	✓	446.00	avg
8	2 set	Boot Lid Lamp Clips	25.00	✗	50.00	NIN
9	1 pc	Boot Lid Inner Lock		✓	123.00	bt
10	1 pc	Boot Lid Lock Catch		✗	36.00	R
11	1 pc	Boot Lid Weatherstrip		✓	189.00	dis
12	1 set	Boot Lid Insulator Clip		✓	40.00	20
13	2 pcs	Boot Lid Hinges	92.00	✗	184.00	R.
14	2 pcs	Boot Lid Absorber	136.00	✗	272.00	src
15	1 pc	Rear Bumper		✓	823.00	dot
16	2 pcs	Rear Bumper Side Retainers	36.00	✓	72.00	dis
17	1 set	Rear Bumper Clips		✓	50.00	40
18	2 pcs	Rear Bumper Number Plate Lamps	NS (56.00)	✓	112.00	CRP
19	2 pcs	Rear Bumper Number Plate Lamps Bracket	30.00	✗	60.00	NIN
20	1 pc	Rear Bumper Tow Cover		✗	32.00	QV
21	1 pc	Rear Bumper Reflectors		✓	58.00	src
22	1 pc	Rear Bumper Top Beam	NS OVER	✗	163.00	
23	1 pc	Rear Bumper Reinforcement		✓	252.00	BT
24	1 pc	Rear Bumper Wiring Harness		✗	256.00	NIN
25	1 pc	End Panel		✓	592.00	DEFORM
26	1 pc	End Panel Top Trim		✓	182.00	CRP
27	1 set	End Panel Top Trim Clips		✓	30.00	1/2
28	1 pc	Rear Key Antenna Sensor		✗	175.00	NIN
29	1 pc	Spare Tyre Panel		✗	892.00	R
30	1 pc	Spare Tyre Panel Top Board		✓	195.00	dis

C/F

6,337.00

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle No : SJF 9731P

B/F

6,337.00

1	2 pcs	Taillamps	351.00	702.00	CVG
2	2 set	Taillamps Clips	25.00	50.00	NHL
3	2 pcs	Taillamps Panel	132.00	264.00	R.
4	2 pcs	Rear Fender Inner Trim	262.00	524.00	
5	2 set	Rear Fender Inner Trim Clips	30.00	60.00	
6	2 pcs	Rear Fender Inner Shield	49.00	98.00	
7	2 set	Rear Fender Inner Shield Clips	25.00	50.00	
8	1 pc	Rear Air Vent	X	48.00	
9	1 pc	Rear Exhaust Silencer	X	623.00	
10	2 pcs	Rear Exhaust Mounting	38.00	76.00	
11	1 pc	Rear Exhaust Gasket	X	46.00	
12	1 pc	Rear Exhaust Heat Plate	X	139.00	

- EM-1 Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and approved from Insurance Company

Less 10%

9,017.00

901.70

8,115.30

1	1 pc	Rear No. Plate with Cover		70.00	40.
2	1 set	Reverse Sensor		250.00	220
3	1 set	Body Panel Joint Sealant	Weg	120.00	

Labour charge

Panel Beating	1,000.00	800
Spray painting	1,000.00	800
Check Wiring	50.00	30
Anti rust	90.00	60
Remove and install carpet and seat.	150.00	60
Remove and install reverse sensor	90.00	60
Remove and install rear exhaust.	120.00	80

\$ 11,055.30

Noted Anthony
AAFZ Team Pro
LCC Auto (M)
7 Wday 2
27/4/2017 @

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7139C
Vehicle Details	
Vehicle No.	SJF9731P
Vehicle to be Exported	Yes
Intended De-registration Date	29 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour	White
Manufacturing Year	2008
Engine No.	4A910100249
Chassis No.	JMYSRCY2A8U007917
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$16,230.00
Original Registration Date	18 Jun 2008
First Registration Date	18 Jun 2008
Transfer Count	2
Actual ARF Paid	\$16,230.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Jun 2018
PARF Rebate Amount	\$8,115.00
Intended COE Rebate Details	
COE Expiry Date	17 Jun 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$16,930.00
COE Rebate Amount	\$935.00
Total Rebate Amount	\$9,050.00

The information contained herein is correct as at 28 Nov 2017

OK

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 5 December, 2017 11:20 AM
To: 'Chia Sin Muk'
Cc: Vic (LKKAUTO)
Subject: Accident Involving SJF 9731P & SGF 8981B on 27/11/2017

WITHOUT PREJUDICE

Your Ref: SJF 9731P
Our Ref: CC4/AIG17022742/M1ea3

Dear Sir/Madam,

Accident Involving SJF 9731P & SGF 8981B on 27/11/2017

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autotrade@gmail.com

COMPANY REGISTRATION NO: 53105453E

Letter of Demand

M/S BAY SERENE

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIMS DEPARTMENT
AIG BUILDING
78 SHENTON WAY # 07-16
SINGAPORE 079120

Ref No. 18/PI00137/1851TP
Date 18.06.2018

WITHOUT PREJUDICE

Date of Accident	27/11/2017
Our Vehicle Number	SJF 9731P
Model	MITSUBISHI LANCER
Your Insured	SGF 8981B

Lump Sum Repair Cost (Recommended by LKK MA)	\$	5,500.00
LTA Fee	\$	5.35
LOSS OF USE/RENTAL (5days x \$112.35/day)	\$	560.00

Total Amount	:	\$	<u>6,065.35</u>
--------------	---	----	-----------------

Singapore Dollars : Six Thousand Sixty-Five and Cents Thirty-Five Only.



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 5 December, 2017 3:06 PM
To: 'KOHCHYN@SUBMARINA.COM.SG'
Subject: ACCIDENT INVOLVING SGF 8981B AND SJF 9731P ON 27/11/2017



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG17022742/M1ea3

05 DEC 2017

KOH CHYN

Dear Sir/Madam,

ACCIDENT INVOLVING SGF 8981B AND SJF 9731P ON 27/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, BAY SERENE ("the third party claimant")
of BLK 34 Fernvale Link, #19-14, S(797532) (address),
owner of SJF 9731P (vehicle no.) hereby authorize
EM-I AUTO TRADE
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJF 9731P that was
damaged pursuant to the accident which occurred on 27/11/2017 (date) along
LOYANG AVE TOWARDS TAMPINES AVE 7 (location)
involving vehicle no/s SGF 8981B ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 27 day of Nov (month) 20 17 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, EM-1 AUTO TRADE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,500.00 (Repair Cost), S\$535.00 (Loss of Use/Rental), S\$5.35 (Disbursement) for vehicle no. SJF 9731P that was damaged pursuant to the accident which occurred on 27/11/2017 (date) along LOYANG AVE TOWARDS TAMPINES AVE 7 (location) involving vehicle no/s SGF 8981B.

This is pursuant to the inspection conducted on 29/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner BAY SERENE ("the third party claimant") of vehicle no. SJF 9731P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJF 9731P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of June (month) 2018 (year)



MCF

Signed by appointed surveyor



Signed by "the workshop" (with chop)

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autotrade@gmail.com

COMPANY REGISTRATION NO: 53105453E

INVOICE

M/S BAY SERENE

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIMS DEPARTMENT

AIG BUILDING

78 SHENTON WAY # 07-16

SINGAPORE 079120

Ref No. 18/0048/1851TP

Date 28.06.2018

Date of Accident	27/11/2017
Our Vehicle Number	SJF 9731P
Model	MITSUBISHI LANCER
Your Insured	SGF 8981B

Lump Sum Repair Cost (Recommended by LKK MA)	\$	5,500.00
--	----	----------

Total Amount	:	\$	<u>5,500.00</u>
--------------	---	----	-----------------

Singapore Dollars : Five Thousand and Five Hundred Only.





友立旅遊服務私人有限公司

UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Centre, # 02-574,
Singapore 0718.
Tel: 2927656
Fax: (65) 2939720
STPB LIC TA/076

GST Reg. No.: M2-0010671-6

Miss Bay Serene
Blk 34 Fernvale Link
19-14
Singapore 797532

20, Sin Ming Lane,
#08-51, Midview City
Singapore 573968
Tel: 6292 7656

04.12.2017

Singapore

TAX INVOICE

WP2017259

NO.

19

DATE

PARTICULARS

@

\$

cts

Rental of one unit Toyota Corolla Altis 1.6 Auto
Registration no. SJE 440 T self driven
as from 27.11.2017 to 02.12.2017.

5 days at \$105.00 per day

\$ 525.00

Add GST at 7%

\$ 525.00

Amount Due

\$ 36.75

\$ 561.75

(SIN DOLLARS: FIVE HUNDRED SIXTY ONE AND SEVENTY FIVE CENTS ONLY)

Standard Rated Supplies:\$

525.00

Total Amount of GST:\$

36.75

AUTHORISED SIGNATURE



UNIQUE TOURIST SERVICE (PTE) LTD.

20, Sin Ming Lane, #08-51, Midview City, Singapore 573968

TEL: 6292 7656 EMAIL: unqtour@singnet.com.sg

COMPANY REG NO: 197401067R

GST REG NO: M2-0019671-6

CAR RENTAL AGREEMENT

RA No. 21225

VEHICLE NO.

SJE 440T

MAKE/MODEL

TOYOTA COROLLA 1.8

NAME OF HIRER

Bay Serene

ADDRESS

SINGAPORE

OFFICE TEL

RES TEL

HP

NAMED DRIVER

OCCUPATION

NATIONALITY

PASSPORT / NRIC

DATE OF BIRTH

DRIVING LIC NO.

PLACE OF ISSUE

DATE PASS/EXPIRY

ADDITIONAL NAMED DRIVER

Zhao WenLe Benson

ADDRESS

Blk 34 Fernvale Link #19-14

SINGAPORE

OFFICE TEL

RES TEL

HP

OCCUPATION

Army Officer

NATIONALITY

PASSPORT / NRIC

S81414156

DATE OF BIRTH

19/12/81

DRIVING LIC NO.

S81414156

PLACE OF ISSUE

DATE PASS/EXPIRY

BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS

A. COLLISION DAMAGE WAIVER (CDW) AT \$ PER DAY / WEEK / MONTH "X"

B. SURCHARGE OF \$ FOR USE IN MALAYSIA FROM

TO *1250

* THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY.

COMPULSORY EXCESS, DOLLAR

\$ 1200/-

NOTE:

HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS.

YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS

PRINTED OVERLEAF.

FOR SINGAPORE DRIVE ONLY

DATE OUT 27/11/17

TIME OUT 2100

PETROL OUT

E

1/4

1/2

3/4

F

DATE IN

22/12/17

TIME IN

1300HRS

PETROL IN

E

1/4

1/2

3/4

F

RENTAL RATES:

S

C

MONTHLY @ \$

WEEKLY @ \$

DAILY 5 @ \$ 105/-

525.00

G.D.W. FEE

PETROL CONSUMPTION

DELIVERY CHARGE

COLLECTION CHARGE

SUB-TOTAL

GST @ 7%

3675

RENTAL DEPOSIT

TOTAL:

56175

DEPOSIT REFUND

PAYMENT BY: BILL CO / CREDIT CARD / CASH

ATTENDED BY:

OF UNIQUE TOURIST SERVICE (PTE) LTD.

DECLARATION

I HEREBY DECLARE THAT NO MOTOR ACCIDENT HAD OCCURED DURING MY HIRE OF YOUR MOTOR VEHICLE AS STATED IN THE ABOVE MENTIONED SCHEDULE * OR TO ANY SUBSTITUTED VEHICLE AS STATED IN THE MEMORANDUM DATED.

REPLACEMENT VEHICLE NO:

1. ON TIME

2. ON TIME

3. ON TIME

DATE:

SIGNATURE OF HIRER

DATE:

SIGNATURE OF HIRER

SJF9931P



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 28 Nov 2017 / 10:30:58

Receipt Date/Time : 28 Nov 2017 / 10:30:58

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171128-000481

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SGF8981B				
As at 27 Nov 2017/15:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SGF8981B			
	Enquiry Fee	5.00	0.35	5.35
	20171128102946332223			
	Sub-Total	5.00	0.35	5.35
	Total Before Rounding	5.00	0.35	5.35
	Rounding Difference			0.00
	Total Amount Payable			5.35

Paid By

20171128102956853	Direct Debit: eNETS Debit (Internet Banking)	5.35
Total		5.35
Cash Change		0.00
Tendered Amount		5.35
Excess Refundable Amount		0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2017 Edit Reg		28 Nov 2017 00:00 Edit Adj Rpt	\$5,500.00 Edit Estimates	\$5,500.00 View Rpt		Pending for Survey Report Cancel Case



Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KOH CHYN , ID: S7640088A								
Main Claimant:	BAY SERENE , ID: S8527139C								
Vehicle Reg. No.:	SJF9731P	Date of Loss:	27/11/2017 11:00 - :59 [113 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3751175102SG	Policy/Cover Note No.:	1700012830 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGF8981B	Policy No. (Claimant):	10492075						
		Excess:							
Repairer:	Em-1 Auto Trade (Sin Ming) BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68, 575642 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 08/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (30/11/2017): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJF9731P (3751175102SG)
[SGF8981B]
TP
BAY SERENE
Nov 27 2017 11:00AM
[KOH CHYN]
Em-1 Auto Trade

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown									Edit	
Assessment Reports											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail	Print	
1	30/11/17 10:21	Accident Statement From:OD - Reg. No: SGF8981B, Claimant: KOH CHYN									Load HTM	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
2	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
3	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
4	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
5	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
6	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
7	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
8	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
9	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
10	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
11	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
12	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
13	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
14	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
15	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
16	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
17	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
18	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
19	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
20	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
21	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
22	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
23	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
24	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
25	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
26	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
27	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
28	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
29	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	
30	21/03/18 12:45	General View									Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	21/03/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/03/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/03/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	21/03/18 12:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 19:35	EMAIL FROM AIG DD 28.11.2017	 Load PDF	
2	29/11/17 19:35	NOTIFICATION FROM WORKSHOP	 Load TIF	
3	29/11/17 19:35	ACKNOWLEDGEMENT EMAIL TO AIG DD 28.11.2017	 Load PDF	
4	01/12/17 09:52	TP ESTIMATE - MARKED	 Load PDF	
5	01/12/17 09:52	TP GIA REPORT	 Load PDF	
6	05/12/17 15:06	LETTER TO OI	 Load PDF	
7	06/07/18 14:03	WORKSHOP INVOICE	 Load PDF	
8	06/07/18 14:03	AUTHORISATION TO ACT FORM	 Load PDF	
9	06/07/18 14:03	Release Voucher	 Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
10	06/07/18 14:03	RENTAL RECEIPT	 Load PDF	
11	06/07/18 14:03	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGF8981B (Insd veh)	Model:	MITSUBISHI LANCER 1.5
	SJF9731P (TP veh)		MIVEC GLS 4A/T (A)
Date of Accident:	27/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		11,055.30
Final Repair Cost	:	\$		5,500.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	535.00	5 days
LTA / GIA Search Fee	:	\$	5.35	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,040.35	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Trade	: \$	6,040.35
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

06 Jul
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022742/M1EA3Q2

Date: 06/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700012830
 Claimant Vehicle No: SJF9731P Insured Vehicle No: SGF8981B
 Date of Loss: 27/11/2017 Nature of Claim: TP Claim No: 3751175102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJF9731P
 Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910100249
 Reg. Date: 18/06/2008 (Man. Year: 2008) Chassis No: JMYSRCY2A8U007917
 Colour: White Odometer: 176762 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Hankook 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Hankook 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,555.30	5,542.00	3,013.30	35.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,890.00	610.00	24.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,055.30	7,432.00	3,623.30	32.77
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	11,055.30	5,500.00	5,555.30	50.25
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		6,040.35		

INSPECTION

Date of Assignment: 28/11/2017
 Date Inspected: 29/11/2017 Inspected At: Em-1 Auto Trade (Sin Ming)
 BLK 8 SIN MING INDUSTRIAL ESTATE
 SECTOR C #01-68
 Singapore 575642

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	823.00 FL	*823.00 FL
2	1		*BOOT LID BADGE	Necessary	52.00 FL	*52.00 FL
3	1		*BOOT LID EMBLEM LANCER	Necessary	48.00 FL	*48.00 FL
4	1		*BOOT LID EMBLEM X	Necessary	42.00 FL	*42.00 FL
5	1		*BOOT LID EMBLEM MIVEC	Necessary	48.00 FL	*48.00 FL
6	1		*BOOT LID EMBLEM (CC)	Necessary	40.00 FL	*40.00 FL
7	2		*BOOT LID LAMPS	Cracked	446.00 FL	*446.00 FL
8	2		*SET BOOT LID LAMP CLIPS	Not Necessary	50.00 FL	*- FL
9	1		*BOOT LID INNER LOCK	Bent	123.00 FL	*123.00 FL
10	1		*BOOT LID LOCK CATCH	Repair	36.00 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP	Distorted	189.00 FL	*189.00 FL
12	1		*SET BOOT LID INSULATOR CLIP	Necessary	40.00 FL	*20.00 FL
13	2		*BOOT LID HINGES	Repair	184.00 FL	*- FL
14	2		*BOOT LID ABSORBER	Serviceable	272.00 FL	*- FL
15	1		*REAR BUMPER	Deformed	823.00 FL	*823.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Distorted	72.00 FL	*72.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*40.00 FL
18	2		*REAR BUMPER NUMBER PLATE LAMPS	Cracked	112.00 FL	*112.00 FL
19	2		*REAR BUMPER NUMBER PLATE LAMPS BRACKET	Serviceable	60.00 FL	*- FL
20	1		*REAR BUMPER TOW COVER	Serviceable	32.00 FL	*- FL
21	1		*REAR BUMPER REFLECTORS	Cracked	58.00 FL	*58.00 FL
22	1		*REAR BUMPER TOP BEAM	No such part	163.00 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	252.00 FL	*252.00 FL
24	1		*REAR BUMPER WIRING HARNESS	Distorted / Shorted	256.00 FL	*256.00 FL
25	1		*END PANEL	Bent	592.00 FL	*592.00 FL
26	1		*END PANEL TOP TRIM	Distorted	182.00 FL	*182.00 FL
27	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
28	1		*REAR KEY ANTENNA SENSOR	Distorted / Shorted	175.00 FL	*175.00 FL
29	1		*SPARE TYRE PANEL	Repair	892.00 FL	*- FL
30	1		*SPARE TYRE PANEL TOP BOARD	Distorted	195.00 FL	*195.00 FL
31	2		*TAILLAMPS	Cracked	702.00 FL	*702.00 FL
32	2		*SET TAILLAMPS CLIPS	Not Necessary	50.00 FL	*- FL
33	2		*TAILLAMPS PANEL	Repair	264.00 FL	*- FL
34	1		*REAR FENDER INNER TRIM	N/S Distorted	524.00 FL	*262.00 FL
35	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FL	*30.00 FL
36	1		*REAR FENDER INNER SHIELD	N/S Distorted	98.00 FL	*49.00 FL
37	1		*SET REAR FENDER INNER SHIELD CLIPS	N/S Necessary	50.00 FL	*25.00 FL
38	1		*REAR AIR VENT	Distorted	48.00 FL	*48.00 FL
39	1		*REAR EXHAUST SILENCER	Serviceable	623.00 FL	*- FL
40	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 FL	*- FL
41	1		*REAR EXHAUST GASKET	Necessary	46.00 FL	*46.00 FL
42	1		*REAR EXHAUST HEAT PLATE	Repair	139.00 FL	*- FL
43	1		*REAR NO.PLATE WITH COVER	Distorted	70.00 FS	*40.00 FS
44	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*220.00 FS
45	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,457.00	6,120.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	901.70	578.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					8,555.30	5,542.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	90.00	60.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	150.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
7	REMOVE AND INSTALL REAR EXHAUST	New	120.00	80.00
Gross Labour Cost (S\$)			2,500.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >