



中国私人有限公司
CHOONG KOK AGENCY PTE LTD

Co Reg No.: 198502667H
www.cka.com.sg
admin@cka.com.sg

MAIN SHOWROOM No. 79, Kaki Bukit Ave 1
Shunli Industrial Park, Singapore 417952
Tel: 6748 5455 Fax: 6748 3433

JURONG AREA Blk 343, Jurong East
Street 31 #01-63, Singapore 600343
Tel: 6566 6180 Fax: 6566 6606

BUKIT BATOK: 50 Bukit Batok St 23
Midview Building #01-20, Singapore 659578
Tel: 6861 3005 Fax: 6861 3008

27/11/2017

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Motor Claim Department

Estimate bill for motorcycle Daelim Roadwin R125 FBD7463G 3rd party claim against SLR442X Involved an accident on 30/09/2017

1.	1pc	View Mirror / cut	\$ 80.00
2.	1pc	Front Fender / CRA	\$ 135.00
3.	1pc	Clutch Lever / cut	\$ 28.00
4.	1pc	Meter Inner Panel / CRA	\$ 135.00
5.	1pc	Side Cowling LH / cut	\$ 280.00
6.	1pc	Sticker LH / MCL	\$ 150.00
7.	1pc	Rear Signal Assy LH / cut	\$ 48.00

\$ 856.00 /

Less 10% \$ 85.60

\$ 770.40 /

Rear Box Assy / cut \$ 200.00 /

Spray Paint (LH portion) ? \$ 250.00

Workmanship \$ 300.00 120

\$ 1520.40 1090.4

GST 1 Day \$ 106.43 20%: 850

\$ 1626.83
=====

(umpsum repair -

After repair photos.

Choong Kok - 82880282

20/11/17

Auto Consultant's hence, the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

WOODLANDS AREA:
#01-27 Harvest @ Woodlands
Singapore 757322
Tel: 6334 3855
Tel: 6334 6155

TAX INVOICE
GST Reg No. M2-0072013-0

