



SLQ3920T

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 27/11/2017

Vehicle Reg. No. : SLQ3920T
Vehicle Reg. Date: 7-Jul-2017
Make / Model : GRACE 1.5 DX HYBRID CV
Engine No. : LEB5255560
Chassis No. : GM41105545

COST OF CLAIMS

Parts Cost / List Items : \$ 7,267.30
Plus/Less 20% \$ 1,453.46
Total Cost / List : \$ 5,813.84
Special Nett Items : \$ 900.00
Total Parts Amount : \$ 6,713.84
Total Labour Amount : \$ 4,430.00
Gross Total : \$ 11,143.84
GST % : 7% \$ 780.07
Nett Amount : \$ 11,923.91

Surveyor Name and Company :

RASUL (CLKK)
Date of survey : 30/11/2017 1510
Part by Part / Lump Sum : 8 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : rasul@clkkauto-con
Fax No : _____
HP No : 90010068

This claim is handled by : EDMOND

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLQ3920T**
 Vehicle Reg. Date: **7/7/2017**
 Make / Model : **GRACE 1.5 DX HYBRID CVT ABS D/AIRBAG 2V**
 Engine No. : **LEB5255560**
 Chassis No. : **GM41105545**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	PG /	\$ 837.00		
2	1	REAR BUMPER CLIP - SET	neu /	\$ 50.00		
3	1	REAR BUMPER SIDE RETAINER	neu /	\$ 60.00		
4	1	REAR BUMPER REFLECTOR	X	\$ 180.00		
5	1	REAR FENDER INNER SHIELD LH	PG /	\$ 130.00		
6	1	REAR FENDER INNER SHIELD CLIP - SET	neu /	\$ 120.00		
7	1	TAILLAMP LH	SCA /	\$ 280.00		
8	1	TAILLAMP CLIPS	neu /	\$ 20.00		
9	1	REAR FENDER LH	PA /	\$ 1,350.00		
10	1	REAR FENDER AIR DUCT LH	CR /	\$ 150.00		
11	1	REAR BOOT	X	\$ 650.00		
12	1	REAR BOOT WEATHERSTRIP	X	\$ 125.00		
13	1	REAR DOOR RH	PA /	\$ 900.00		
14	1	REAR DOOR TRIM RH	R ?	\$ 800.00		
15	1set	REAR DOOR TRIM CLIPS	neu /	\$ 50.00		
16	1	REAR DOOR HINGES RH	X	\$ 75.00		
17	1	REAR DOOR STICKER RH	neu /	\$ 50.00		
18	1	REAR DOOR WEATHERSTRIP FRONT	neu /	\$ 50.00		
19	1	REAR DOOR WEATHERSTRIP LOWER	neu /	\$ 40.00		
20	1	REAR DOOR WEATHERSTRIP REAR	neu /	\$ 40.00		
21	1	REAR DOOR LOCK RH	X	\$ 350.00		
22	1	REAR DOOR REGULATOR WITH MOTOR RH	X	\$ 320.00		
23	1	REAR DOOR OUTER HANDLE RH	X	\$ 150.00		
24	1	REAR RIM LH	X		\$ 350.00	
25	1	REAR WHEEL HUP CAB LH	SCA /		\$ 200.00	
26	1	REAR TYRE LH	X		\$ 350.00	
27	1	REAR SHOCK ABSORBER LH	PG ?	\$ 225.00		
28	1	REAR SHOCK ABSORBER TOP MOUNTING LH	PG ?	\$ 40.20		
29	1	REAR SHOCK ABSORBER STOPPER LH	PG ?	\$ 27.60		
30	1	REAR WHEEL HUB RH with bearing LH	R ?	\$ 197.50		
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

GM41105545

[illegible]