

REF:

CC3/ALH17022747 / Atb n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: \$400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 110K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 15 88% days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S6M1800A. Yr Regn: 2015 May.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 cc 1798

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 58897. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8K2FA117375

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18.

R: 245/40R18

BS / DUN / EXNOVA ☒ GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 29/4/17

Survey held at: Premium

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Part by Part \$21317.24 Cred: 18762.56 : 4676)

RECEIVED 11 OCT 2018

File Pass to:

☐ : Prel. Report☒ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - \$4

Phone:

Other:

Report Format: 00

Lump Sum / I.B.I: (\$ 21317.24

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17022747/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 30-11-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGM 1800A
Policy No. 2100413971	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/11/2017	Inspection Date	29/11/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: SGM1800A	Accident Date	: 28/11/2017
Make	: AUDI A4	Policy No.	: 2100413971
Assignment Date	: 30/11/2017	Excess	: S\$0.00
Date of Inspection	: 29/11/2017	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,377.00
Revised Amount	:S\$	20,501.00
Check Items (Estimated)	:S\$	3,185.00
Total	:S\$	23,686.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.000
COE / PARF Rebate	:S\$	75,565.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,435.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: SGM1800A	Accident Date	: 28/11/2017
Make	: AUDI A4	Policy No.	: 2100413971
Assignment Date	: 30/11/2017	Excess	: S\$0.00
Date of Inspection	: 29/11/2017	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,377.00
Revised Amount	:S\$	20,501.00
Check Items (Estimated)	:S\$	3,185.00
Total	:S\$	23,574.00

23686

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.000
COE / PARF Rebate	:S\$	75,565.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,435.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9773E
Vehicle Details	
Vehicle No.	SGM1800A
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	AUDI
Vehicle Model	A4 1.8 TFSI MU ATTRACTION
Primary Colour	Black
Manufacturing Year	2015
Engine No.	CJE100729
Chassis No.	WAUZZZ8K2FA117375
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	\$31,308.00
Original Registration Date	29 May 2015
First Registration Date	29 May 2015
Transfer Count	0
Actual ARF Paid	\$25,832.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 May 2025
PARF Rebate Amount	\$19,374.00
Intended COE Rebate Details	
COE Expiry Date	28 May 2025
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$75,002.00
COE Rebate Amount	\$56,191.00
Total Rebate Amount	\$75,565.00

The information contained herein is correct as at 30 Nov 2017

OK

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1209773E



Name



CHAN KIM LENG

曾金龍

Race

CHINESE

Date of Birth

02-08-1956

Sex

M

Country of Birth

SINGAPORE

0943430



NRIC No: S1209773E

Blood Group

O+

Date of issue

09-05-1993

APT BLK 757 PASIR RIS STREET 71 #10-168
SINGAPORE 510757

NRIC No: S1209773E

Date: 21/03/2013

No: 7325315



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100413971-02000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PAF Yes

1) VEHICLE REGISTRATION NO.

SGM1800A

2) NAME OF INSURED

CHAN KIM LENG

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

29 May 2017

4) DATE OF EXPIRY OF INSURANCE

28 May 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 22 May 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-216
PREMIUM LEASING - CW
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1209773E
Name:

CHAN KIM LENG

Birth Date: 02 Aug 1956
Issue Date: 03 Nov 2003



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

11 Nov 1983



NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1174/2017/GW
Date : 28-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. CHAN KIM LENG
Address : BLK 757 PASIR RIS STREET 71
Singapore 510757
Telephone : HP +6596186277
Type of Claim : Own Damage Claims
Policy No. : 2100413971-02000
Vehicle No : **SGM1800A**
Model Code : Audi A4 1.8 TFSI MU.
Model / Year : May-15
Engine No : CJE 100729
Chassis No : WAUZZZ8K2FA117375
Mileage : 58896 KM
Date In : 28/11/2017
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Nov-17
Place of Accident : LOR SIREH PINANG CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGM 1800 A

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assv.	S/N \$ 360.00 ✓
2	To remove and transfer aircon condensor, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,000.00 ✓
3	To dismantle front bumper, both front fenders and bonnet. Renew front bumper, both front fenders, bonnet and both front headlights. Re-organise front crash management components. Reinstall all parts removed	\$ 5,400.00 3500. ✓
4	To respray front bumper, both fenders and bonnet.	\$ 3,000.00 2100 ✓
5	To carry out diagnostic check	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 9,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 1800 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>	\$ 1,954.00	✓ ✓ 1563.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 217.00	? X
3	CLOSING ELEMENT LOWER CENTRE <i>turn</i>	\$ 185.00	? 148
4	FRONT BUMPER GRILLE LOWER CENTRE <i>could</i>	\$ 112.00	✓ 89.20
5	CLOSING ELEMENT UPPER CENTRE <i>could</i>	\$ 161.00	? 128.80
6	FRONT BUMPER RADIATOR GRILLE <i>could</i>	\$ 899.00	✓ 718.80
7	FRONT BUMPER AIR GRILLE-LHS <i>at</i>	\$ 112.00	✓ 89.20
8	FRONT BUMPER AIR GRILLE-RHS <i>new</i>	\$ 112.00	X
9	FRONT BUMPER SIDE REINFORCEMENT <i>Best</i>	\$ 742.00	✓ 593.60
10	FRONT BUMPER BRAKET - LHS/RHS <i>Best</i>	2 \$ 356.00	? 284.80
11	FRONT BUMPER SUPPORT- LH/RH <i>Best</i>	2 \$ 20.00	✓ 16
13	FRONT BUMPER GUIDE SECTION- LHS/RHS <i>new</i>	2 \$ 58.00	? 46.40
14	FRONT BUMPER COVER <i>could</i>	\$ 104.00	✓ 82.80
15	SIGN "CAUTION" <i>new</i>	\$ 12.00	✓ 9.04
16	FRONT BUMPER FOAM FILLER PIECE <i>Del'd</i>	\$ 101.00	✓ 80.80
17	FRON FENDER -RHS/LHS <i>Best</i>	2 \$ 1,664.00	✓ 1331.20
18	FRONT FENDER BRACKET- LHS/RHS <i>Best</i>	2 \$ 88.00	? X
19	BRACKET FOR DEFORMATION- LHS/RHS <i>Best</i>	2 \$ 84.00	? X
20	FRONT FENDER BRACE-LHS/RHS <i>Best</i>	2 \$ 200.00	? X 79.44
SUB SPARE PARTS		\$ 7,181.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 1800 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	STONE CHIP GUARD -LHS/ RHS <i>new</i>	2 \$ 76.00	- 60.80
22	FRONT WHEEL HOUSING LINER - LHS/RHS <i>new</i>	2 \$ 416.00	+ X
23	FRONT HEADLAMP - LHS/RHS <i>cracked</i>	2 \$ 4,076.00	- 3260.80
24	FRONT HEADLAMP BRACKET - LHS/RHS <i>cracked</i>	2 \$ 178.00	? 141.76
25	FRONT HEADLIGHT MOUNTING-LHS/RHS <i>cracked</i>	2 \$ 200.00	? 158.87
26	HEADLIGHT WASHER <i>2 it cracked</i>	2 \$ 360.00	? 144.00
27	BONNET <i>Dented</i>	\$ 2,262.00	- 1809.60
28	BONNET PROTECTIVE FILM <i>new</i>	\$ 39.00	- 30.48
29	BONNET CATCH HOOK <i>But</i>	\$ 118.00	- 94.40
30	BONNET EDGE PROTECTION <i>new</i>	\$ 23.00	- 18.40
31	BONNET LID LOCK WITH MICRO SWITCH <i>cracked</i>	\$ 180.00	? 144
32	LOCK CARRIER <i>new</i>	\$ 878.00	- 702.40
33	LOCK CARRIER BRACE- LHS/RHS <i>new</i>	2 \$ 76.00	? X
34	LOCK CARRIER AIR GUIDE- LHS /RHS <i>behind</i>	2 \$ 42.00	? 33.12
35	CHARGE AIR COOLER <i>new</i>	\$ 471.00	+ 376.40
36	A/C PRESSURE SWITCH SCHRADER VALVE <i>new</i>	\$ 45.00	+ 7
37	PRESSURE SENDER <i>new</i>	\$ 159.00	+ 7
38	COOLANT RADIATOR WITH OIL COOLER <i>new</i>	\$ 1,179.00	+ 7
39	RUBBER BUSH <i>new</i>	3 \$ 38.00	+ 7
40	SUPPORT FOR COOLANT REGULATOR <i>new</i>	\$ 64.00	+ 7
SUB SPARE PARTS		\$ 10,880.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGM 1800 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	COOLANT CONCENTRATE <i>new</i>	\$ 132.00	+ 105.28
42	TWIN FAN RING <i>new</i>	\$ 217.00	+ X
43	RADIATOR FAN LH/RH <i>new</i>	\$ 1,366.00	+ X
44	CRONTROL UNIT FOR RADIATOR FAN <i>new</i>	\$ 715.00	+ X
45	FRONT NO. PLATE <i>Dented</i>	S/N \$ 25.00	✓ 25
46	SUNDRIES <i>new</i>	\$ 800.00	? 166.32
TOTAL SPARE PARTS		\$ 21,316.00	
TOTAL LABOUR CHARGES		\$ 18,061.00	
GRAND TOTAL		: \$ 39,377.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

31268

33700.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 29/11/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/1174/2017/GW Date 29-Dec-17 Service Advisor Chang Pages 1 Regn No SGM 1800 A Model No Audi A4 1.8 TFSI MU	
Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To renew frontal chassis frame console bracket and align to position.	\$ 1,800.00	\$ 1,000.00
<u>Parts</u>			
1	CHASSIS FRAME FRONT SECURING PLATE - LH/RH 2 <i>2nd</i>	\$ 56.00	\$ 44.80
2	CHASSIS FRAME SHOCK ABSORBER MOUNTING - LH/RH 2 <i>2nd</i>	\$ 146.00	\$ 115.36
3	SIGNAL HORN - LH/RH 2	\$ 348.00	\$ 278.40
4	HORN BRACKET - LH/RH 2 <i>2nd</i>	\$ 42.00	\$ 32.32
5	HEADLIGHT WASHER HOSE 2 <i>2nd</i>	\$ 157.00	\$ 125.60
6	HEADLIGHT WASH CYLINDER ELBOW FITTINGS 2	\$ 43.00	\$ 35.84
	Materials :	\$ 792.00	\$ 632.32
	Labours :	\$ 1,800.00	\$ 1,000.00
	Grand Total :	\$ 2,592.00	\$ 1,632.32

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1174/2017/GW
Date : 28-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

You recommended 10 days

We took 15 days exclude 2 Sundays

with added jobs - jb - 28 May 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. CHAN KIM LENG
Address : BLK 757 PASIR RIS STREET 71
Singapore 510757
Telephone : HP +6596186277
Type of Claim : Own Damage Claims
Policy No. : 2100413971-02000
Vehicle No : **SGM1800A**
Model Code : Audi A4 1.8 TFSI MU.
Model / Year : May-15
Engine No : CJE 100729
Chassis No : WAUZZZ8K2FA117375
Mileage : 58896 KM
Date In : 28/11/2017
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Nov-17
Place of Accident : LOR SIREH PINANG CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGM 1800 A

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To remove and transfer aircon condensor, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N	\$ 1,000.00	\$	1,000.00
3	To dismantle front bumper, both front fenders and bonnet. Renew front bumper, both front fenders, bonnet and both front headlights. Re-organise front crash management components. Reinstall all parts removed.		\$ 5,400.00	\$	3,500.00
4	To respray front bumper, both fenders and bonnet.		\$ 3,000.00	\$	2,100.00
5	Added labour charges - see attached		\$ 1,800.00	\$	1,000.00
6	To carry out diagnostic check	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 11,752.00	\$	8,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 1800 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,954.00	\$ 1,563.20
2	FRONT BUMPER FIXING PARTS	\$ 217.00	
3	CLOSING ELEMENT LOWER CENTRE	\$ 185.00	\$ 148.00
4	FRONT BUMPER GRILLE LOWER CENTRE	\$ 112.00	\$ 89.20
5	CLOSING ELEMENT UPPER CENTRE	\$ 161.00	\$ 128.80
6	FRONT BUMPER RADIATOR GRILLE	\$ 899.00	\$ 718.80
7	FRONT BUMPER AIR GRILLE-LHS	\$ 112.00	\$ 89.20
8	FRONT BUMPER AIR GRILLE-RHS	\$ 112.00	\$ X89.20
9	FRONT BUMPER SIDE REINFORCEMENT	\$ 742.00	\$ 593.60
10	FRONT BUMPER BRAKET - LHS/RHS	2 \$ 356.00	\$ 284.80
11	FRONT BUMPER SUPPORT- LH/RH	2 \$ 20.00	\$ 16.00
13	FRONT BUMPER GUIDE SECTION- LHS/RHS	2 \$ 58.00	\$ 46.40
14	FRONT BUMPER COVER	\$ 104.00	\$ 82.80
15	SIGN "CAUTION"	\$ 12.00	\$ 9.04
16	FRONT BUMPER FOAM FILLER PIECE	\$ 101.00	\$ 80.80
17	FRON FENDER -RHS/LHS	2 \$ 1,664.00	\$ 1,331.20
18	FRONT FENDER BRACKET- LHS/RHS	2 \$ 88.00	
19	BRACKET FOR DEFORMATION- LHS/RHS	2 \$ 84.00	
20	FRONT FENDER BRACE-LHS/RHS	2 \$ 200.00	\$ 79.44
SUB SPARE PARTS		\$ 7,181.00	\$ 5,350.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGM 1800 A

S/N	Parts Description	Damage Parts & Prices		
			S/NETT	REMARKS
		c/f	\$	5,350.48
21	STONE CHIP GUARD -LHS/ RHS	2 \$	76.00	\$ 60.80
22	FRONT WHEEL HOUSING LINER - LHS/RHS	2 \$	416.00	
23	FRONT HEADLAMP - LHS/RHS	2 \$	4,076.00	\$ 3,260.80
24	FRONT HEADLAMP BRACKET - LHS/RHS	2 \$	178.00	\$ 141.76
25	FRONT HEADLIGHT MOUNTING-LHS/RHS	2 \$	200.00	\$ 158.88
26	HEADLIGHT WASHER	2 \$	360.00	\$ 144.00
27	BONNET	\$	2,262.00	\$ 1,809.60
28	BONNET PROTECTIVE FILM	\$	39.00	\$ 30.48
29	BONNET CATCH HOOK	\$	118.00	\$ 94.40
30	BONNET EDGE PROTECTION	\$	23.00	\$ 18.40
31	BONNET LID LOCK WITH MICRO SWITCH	\$	180.00	\$ 144.00
32	LOCK CARRIER	\$	878.00	\$ 702.40
33	LOCK CARRIER BRACE- LHS/RHS	2 \$	76.00	
34	LOCK CARRIER AIR GUIDE- LHS /RHS	2 \$	42.00	\$ 33.12
35	CHARGE AIR COOLER	\$	471.00	\$ 376.40
36	A/C PRESSURE SWITCH SCHRADER VALVE	\$	45.00	
37	PRESSURE SENDER	\$	159.00	
38	COOLANT RADIATOR WITH OIL COOLER	\$	1,179.00	
39	RUBBER BUSH	3 \$	38.00	
40	SUPPORT FOR COOLANT REGULATOR	\$	64.00	
	SUB SPARE PARTS	:	\$ 10,880.00	\$ 12,325.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGM 1800 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 12,325.52
41	COOLANT CONCENTRATE	\$ 132.00	\$ 105.28
42	TWIN FAN RING	\$ 217.00	
43	RADIATOR FAN LH/RH	\$ 1,366.00	
44	CRONTROL UNIT FOR RADIATOR FAN	\$ 715.00	
45	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
46	<i>Added parts - see attached</i>	\$ 792.00	\$ 632.32
47	SUNDRIES	\$ 800.00	\$ 166.32
TOTAL SPARE PARTS		\$ 22,108.00	\$ 13,254.44
TOTAL LABOUR CHARGES		\$ 18,061.00	\$ 8,152.00
GRAND TOTAL		\$ 40,169.00	\$ 21,406.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:
Surveyed Date	:
Authorised Date	:
Excess Cost	:
Liability	:
Remarks	:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGM 1800 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1177/2017/MAS

2 Oct 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGM 1800 A, Audi A4 1.8T FSI Mu

With reference to the above-mentioned vehicle, no **SGM 1800 A**, claimant, **Mr. Chan Kim Leng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012978 – S\$21,953.45
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGM 1800 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017		30 Nov 2017 09:25 Edit Adj Rpt	S\$21,317.24 Edit Estimates	S\$21,317.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHAN KIM LENG, ID: S1209773E, Tel: +6596186277, Email: NOEMAIL								
Vehicle Reg. No.:	SGM1800A	Date of Loss:	28/11/2017 00:00 - :59 [29 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 8440685546SG	Policy/Cover Note No.:	2100413971 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/12/2017]								
Driver/Custodian:	CHAN KIM LENG (61 / Male), NRIC: S1209773E, Tel: +6596186277								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- AIG_SG (19/07/2018): Alert - Adj Mandate Approved (S\$21317.24) - SGM1800A - Claim Handler: Dally Amri... - AIG_SG (18/07/2018): Alert - Adj Mandate Maintained - SGM1800A - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (06/12/2017): Alert - Adj Mandate Approved (S\$19669.00) - SGM1800A - Claim Handler: Dally Amri... - LOIS_KL_CHANG (06/12/2017): Re: Alert - Adj Mandate Approved (S\$18837.00) - SGM1800A - Claim Handler: Dally ... - LOIS_KL_CHANG (04/12/2017): Re: Alert - Adj Mandate Approved (S\$18837.00) - SGM1800A - Claim Handler: Dally ... - AIG_SG (01/12/2017): Alert - Adj Mandate Approved (S\$18837.00) - SGM1800A - Claim Handler: Dally Amri... - AIG_SG (01/12/2017): SGM1800A / OD / 28/11/2017 / Coverage & Excess update									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGM1800A (8440685546SG)**

OD

Nov 28 2017 12:00AM

[CHAN KIM LENG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Assessment Reports															1 per page			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	30/11/17 15:26	Adjuster Immediate Advice														Load HTM		
2	18/07/18 13:21	Adjuster Immediate Advice														Load HTM		
3	18/07/18 17:40	Adjuster Immediate Advice														Load HTM		
Photos/Images															3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	30/11/17 14:05	General View														Load JPG		
2	30/11/17 14:05	General View														Load JPG		
3	30/11/17 14:05	General View														Load JPG		
4	30/11/17 14:05	General View														Load JPG		
5	30/11/17 14:05	General View														Load JPG		
6	30/11/17 14:05	General View														Load JPG		
7	30/11/17 14:05	General View														Load JPG		
8	30/11/17 14:05	General View														Load JPG		
9	30/11/17 14:05	General View														Load JPG		
10	30/11/17 14:05	General View														Load JPG		
11	30/11/17 14:05	General View														Load JPG		
12	30/11/17 14:05	General View														Load JPG		
13	30/11/17 14:05	General View														Load JPG		
14	30/11/17 14:05	General View														Load JPG		
15	30/11/17 14:05	General View														Load JPG		
16	30/11/17 14:05	General View														Load JPG		
17	30/11/17 14:05	General View														Load JPG		
18	30/11/17 14:05	General View														Load JPG		
19	30/11/17 14:05	General View														Load JPG		
20	30/11/17 14:05	General View														Load JPG		
21	30/11/17 14:05	General View														Load JPG		
22	30/11/17 14:05	General View														Load JPG		
23	30/11/17 14:05	General View														Load JPG		
24	30/11/17 14:05	General View														Load JPG		
25	30/11/17 14:05	General View														Load JPG		
26	30/11/17 14:05	General View														Load JPG		
27	30/11/17 14:05	General View														Load JPG		
28	30/11/17 14:05	General View														Load JPG		
29	30/11/17 14:05	General View														Load JPG		
30	30/11/17 14:05	General View														Load JPG		
31	30/11/17 14:05	General View														Load JPG		
32	30/11/17 14:05	General View														Load JPG		
33	30/11/17 14:05	General View														Load JPG		
34	30/11/17 14:05	General View														Load JPG		
35	30/11/17 14:05	General View														Load JPG		
36	30/11/17 14:05	General View														Load JPG		
37	30/11/17 14:05	General View														Load JPG		
38	30/11/17 14:05	General View														Load JPG		

39	30/11/17 14:05	General View	1	Load JPG	☒
40	30/11/17 14:05	General View	1	Load JPG	☒
41	30/11/17 14:05	General View	1	Load JPG	☒
42	30/11/17 14:05	General View	1	Load JPG	☒
43	30/11/17 14:05	General View	1	Load JPG	☒
44	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
45	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
46	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
47	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
48	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
49	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
50	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
51	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
52	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
53	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
54	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
55	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
56	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
57	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
58	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
59	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
60	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
61	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
62	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
63	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
64	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
65	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
66	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
67	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
68	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
69	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
70	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
71	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
72	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
73	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
74	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
75	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
76	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
77	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
78	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
79	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
80	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
81	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
82	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
83	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
84	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
85	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
86	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
87	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
88	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
89	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
90	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
91	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
92	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒

93	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
94	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
95	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
96	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
97	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
98	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
99	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
100	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
101	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
102	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
103	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
104	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
105	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
106	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
107	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
108	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
109	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
110	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
111	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
112	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
113	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
114	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
115	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
116	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
117	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
118	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
119	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
120	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
121	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
122	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
123	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
124	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
125	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
126	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
127	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
128	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
129	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
130	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
131	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
132	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
133	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
134	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
135	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
136	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
137	06/12/17 09:03	Reinspection Photo	1	Load JPG	☒
Documentation			1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 14:06	Driver's Driving License	1	Load PDF	
2	30/11/17 14:06	Singapore Accident Statement	1	Load PDF	
3	30/11/17 14:06	workshop estimate	1	Load PDF	
4	30/11/17 14:06	Certificate of Insurance	1	Load PDF	
5	18/07/18 13:27	mark estimate	1	Load PDF	
6	18/07/18 13:27	supplementary	1	Load PDF	
7	12/10/18 11:23	WORKSHOP INVOICE	1	Load PDF	
8	12/10/18 11:23	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/17 15:11	Accident Statement	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/17 15:08	Accident Photo	 Load JPG	☒
2	28/11/17 15:08	Accident Photo	 Load JPG	☒
3	28/11/17 15:08	Accident Photo	 Load JPG	☒
4	28/11/17 15:08	Accident Photo	 Load JPG	☒
5	28/11/17 15:08	Accident Photo	 Load JPG	☒
6	28/11/17 15:08	Accident Photo	 Load JPG	☒
7	28/11/17 15:08	Accident Photo	 Load JPG	☒
8	28/11/17 15:08	Accident Photo	 Load JPG	☒
9	28/11/17 15:08	Accident Photo	 Load JPG	☒
10	28/11/17 15:08	Accident Photo	 Load JPG	☒
11	28/11/17 15:08	Accident Photo	 Load JPG	☒
12	28/11/17 15:08	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/11/17 15:01	Sketch Plan	 Load JPG	☒
2	28/11/17 15:01	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17022747/ATBN2

Date: 12/10/2018

REFERENCE

Insured/Claimant: CHAN KIM LENG Policy No: 2100413971
Date of Loss: 28/11/2017 Nature of Claim: OD Claim No: 8440685546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGM1800A
Make & Model: AUDI A4, 1.8 TFSI (A) Engine No: CJE100729
Reg. Date: 29/05/2015 (Man. Year: 2015) Chassis No: WAUZZZ8K2FA117375
Colour: Black Odometer: 58897 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,948.32	13,165.24	8,783.08	40.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,752.00	8,152.00	3,600.00	30.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,700.32	21,317.24	12,383.08	36.74
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	32,900.32	20,517.24	12,383.08	37.64
+ GST 7.00/7.00% (S\$)	2,303.02	1,436.21	866.81	37.64
Nett Amount (S\$)	35,203.34	21,953.45	13,249.89	37.64

INSPECTION

Date of Assignment: 30/11/2017
Date Inspected: 29/11/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,954.00 FS	*1,563.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	217.00 FS	*- FS
3	1		*CLOSING ELEMENT LOWER CENTRE	Torn	185.00 FS	*148.00 FS
4	1		*FRONT BUMPER GRILLE LOWER CENTRE	Cracked	112.00 FS	*89.20 FS
5	1		*CLOSING ELEMENT UPPER CENTRE	Damaged	161.00 FS	*128.80 FS
6	1		*FRONT BUMPER RADIATOR GRILLE	Cracked	899.00 FS	*718.80 FS
7	1		*FRONT BUMPER AIR GRILLE-LHS	Cut	112.00 FS	*89.20 FS
8	1		*FRONT BUMPER AIR GRILLE-RHS	Not Necessary	112.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT	Bent	742.00 FS	*593.60 FS
10	2		*FRONT BUMPER BRACKET-LHS/RHS	Bent	356.00 FS	*284.80 FS
11	2		*FRONT BUMPER SUPPORT-LH/RH	Damaged	20.00 FS	*16.00 FS
12	2		*FRONT BUMPER GUIDE SECTION-LHS/RHS	Necessary	58.00 FS	*46.40 FS
13	1		*FRONT BUMPER COVER	Cracked	104.00 FS	*82.80 FS
14	1		*SIGN CAUTION	Necessary	12.00 FS	*9.04 FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	101.00 FS	*80.80 FS
16	2		*FRONT FENDER-RHS/LHS	Buckled	1,664.00 FS	*1,331.20 FS
17	2		*FRONT FENDER BRACKET-LHS/RHS	Not Necessary	88.00 FS	*- FS
18	2		*BRACKET FOR DEFORMATION-LHS/RHS	Not Necessary	84.00 FS	*- FS
19	1		*FRONT FENDER BRACE-LHS/RHS	N/s Bent	200.00 FS	*79.44 FS
20	2		*STONE CHIP GUARD-LHS/RHS	Necessary	76.00 FS	*60.80 FS
21	2		*FRONT WHEEL HOUSING LINER-LHS/RHS	Not Necessary	416.00 FS	*- FS
22	2		*FRONT HEADLAMP-LHS/RHS	Cracked	4,076.00 FS	*3,260.80 FS
23	2		*FRONT HEADLAMP BRACKET-LHS/RHS	Damaged	178.00 FS	*141.76 FS
24	2		*FRONT HEADLIGHT MOUNTING-LHS/RHS	Damaged	200.00 FS	*158.88 FS
25	1		*HEADLIGHT WASHER	N/s Cracked	360.00 FS	*144.00 FS
26	1		*BONNET	Dented	2,262.00 FS	*1,809.60 FS
27	1		*BONNET PROTECTIVE FILM	Necessary	39.00 FS	*30.48 FS
28	1		*BONNET CATCH HOOK	Bent	118.00 FS	*94.40 FS
29	1		*BONNET EDGE PROTECTION	Necessary	23.00 FS	*18.40 FS
30	1		*BONNET LID LOCK WITH MICRO SWITCH	Damaged	180.00 FS	*144.00 FS
31	1		*LOCK CARRIER	Cracked	878.00 FS	*702.40 FS
32	2		*LOCK CARRIER BRACE-LHS/RHS	Not Necessary	76.00 FS	*- FS
33	2		*LOCK CARRIER AIR GUIDE-LHS/RHS	Deformed	42.00 FS	*33.12 FS
34	1		*CHARGE AIR COOLER	Not Necessary	471.00 FS	*376.40 FS
35	1		*A/C PRESSURE SWITCH SCHRADER VALVE	Not Necessary	45.00 FS	*- FS
36	1		*PRESSURE SENDER	Not Necessary	159.00 FS	*- FS
37	1		*COOLANT RADIATOR WITH OIL COOLER	Not Necessary	1,179.00 FS	*- FS
38	1		*RUBBER BUSH	Not Necessary	38.00 FS	*- FS
39	3		*SUPPORT FOR COOLANT REGULATOR	Not Necessary	64.00 FS	*- FS
40	1		*COOLANT CONCENTRATE	Necessary	132.00 FS	*105.28 FS
41	1		*TWIN FAN RING	Not Necessary	217.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*RADIATOR FAN LH/RH	Not Necessary	1,366.00 FS	*- FS
43	1		*CONTROL UNIT FOR RADIATOR FAN	Not Necessary	715.00 FS	*- FS
44	1		*FRONT NO PLATE	Dented	25.00 FS	*25.00 FS
45	1		*SUNDRIES	Necessary	800.00 FS	*166.32 FS
46	2		*CHASSIS FRAME FRONT SECURING PLATE-LH/RH	Damaged	44.80 FS	*44.80 FS
47	2		*CHASSIS FRAME SHOCK ABSORBER MOUNTING-LH/RH	Damaged	115.36 FS	*115.36 FS
48	2		*SIGNAL HORN-LH/RH	Damaged	278.40 FS	*278.40 FS
49	2		*HORN BRACKET-LH/RH	Bent	32.32 FS	*32.32 FS
50	1		*HEADLIGHT WASHER HOSE	Damaged	125.60 FS	*125.60 FS
51	1		*HEADLIGHT WASHER CYLINDER ELBOW FITTINGS	Damaged	35.84 FS	*35.84 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,948.32 13,165.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW FRONTAL CHASSIS FRAME CONSOLE BRACKET AND ALIGN TO POSITION	New	1,800.00	1,000.00
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND TRANSFER AIRCON CONDENSOR,RADIATOR,CHARGED AIR COOLER,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY PUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
4	TO DISMANTLE FRONT BUMPER,BOTH FRONT FENDERS AND BONNET.RENEW FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND BOTH FRONT HEADLIGHTS.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,400.00	3,500.00
5	TO RESPRAY FRONT BUMPER,BOTH FENDERS AND BONNET	New	3,000.00	2,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			11,752.00	8,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >