

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1173/2017/JT
Date : 28-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tong Hoi Chak
Address : 7 Thompson Lane
#14-05
Singapore 297725
Telephone : HP +65 9618 1130
Type of Claim : Own Damage Claims
Policy No. : 2100479443-01
Vehicle No : **SDZ 8188 E**
Model Code : Audi A3 SB 1.4 TFSI S-tronic
Model / Year : Aug-16
Engine No : CZC 564048
Chassis No : WAUZZZ8V6GA168387
Mileage : -
Date In : 27-Nov-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Nov-17
Place of Accident : Sixth Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDZ 8188 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00	✓
2	To remove & transfer air con condenser, radiator, additional radiator, electrical fans & control unit. To carry out vacuum/regas & to pressurise cooling system.	S/N \$ 1,000.00	?
3	To dismantle front bumper, RHS front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, RHS front fender, RHS headlight and bonnet. Re-organize front crash management components. Reinstall all parts removed.	\$ 4,500.00	1750.
4	To respray front bumper, RHS front fender, bonnet and bonnet hinges.	S/N \$ 2,600.00	1650.
5	To renew RHS front tire. Carry out wheel alignment.	S/N \$ 280.00	✗.
6	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>8,932.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDZ 8188 E.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>Distorted</i>	\$ 1,546.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 157.00	✗
3	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 130.00	✗
4	FRONT BUMPER PULL STRAP <i>new</i>	4 \$ 170.00	✗
5	FRONT BUMPER GUIDE - RHS <i>Dist</i>	\$ 51.00	✓
6	FRONT AIR GRILLE - RHS <i>wt</i>	\$ 90.00	✓
7	RADIATOR GRILLE ?	\$ 544.00	?
8	RADIATOR GRILLE BACK COVER ?	\$ 83.00	?
9	CAUTION SIGN ?	\$ 12.00	?
10	FRONT FENDER - RHS <i>Distorted</i>	\$ 708.00	✓
11	FRONT FENDER INNER BRACKET - RHS ?	\$ 40.00	?
12	FRONT FENDER OUTER BRACKET - RHS ?	\$ 23.00	?
13	FRONT FENDER CLOSING ELEMENT - RHS ?	\$ 52.00	?
14	FRONT FENDER BRACE - RHS ?	\$ 81.00	?
15	FRONT WHEEL HOUSE LINER - RHS <i>Del d</i>	\$ 146.00	✓
16	WHEEL HOUSE LINER ATTACHMENT PARTS - RHS ?	\$ 75.00	?
17	HEADLIGHT - RHS <i>Smashed</i>	\$ 1,708.00	✓
18	GAS DISCHARGE BULB - RHS <i>new</i>	\$ 394.00	✗
19	GAS DISCHARGE BULB CTRL UNIT - RHS ?	\$ 1,002.00	?
20	DAY RUNNING LIGHT POWER MODULE - RHS ?	\$ 492.00	?
TOTAL SPARE PARTS CHARGES - FRONT		\$ 7,504.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDZ 8188 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACKET - RHS ?	\$	37.00 ?
22	HEADLIGHT WASHER - RHS ?	\$	160.00 ?
23	BONNET <i>Dented</i>	\$	2,372.00 ✓
24	BONNET ATTACHMENT PARTS <i>me</i>	\$	138.00 ✓
25	BONNET HINGE - LHS/RHS <i>me</i>	\$	104.00 +
26	BONNET EDGE SEAL <i>me</i>	\$	23.00 ✓
27	BONNET CATCH HOOK <i>me</i>	\$	76.00 +
28	BONNET STRIKER - LHS/RHS <i>me</i>	\$	186.00 +
29	BONNET SWITCH <i>me</i>	2 \$	338.00 +
30	LOCK CARRIER ?	\$	630.00 ?
31	COOLANT ?	\$	132.00 ?
32	FRONT TIRE <i>me</i>	TBC	+
33	FRONT NO. PLATE ?	S/N \$	25.00 ?
34	SUNDRIES ?	\$	500.00 ?
TOTAL SPARE PARTS CHARGES		:	<u>\$ 12,225.00</u>
TOTAL LABOUR CHARGES		:	<u>\$ 8,932.00</u>
GRAND TOTAL		:	<u><u>\$ 21,157.00</u></u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 29/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant