

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

1/12
AmEW5343Y - NA (M/G 13003273/5) : OIA: 18/02/18
SDN8292A. X

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: ASHER 05/12/17

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

1/12/2018 CALLED OI NO RESPONSE.

RECD TP VIDEO SAVE IN CV: ASHER, 2017

1/12/18 CALLED OI CONFIRMED ACCIDENT. OI MENTION HE WAS STATIONARY
WHEN TP HIT HIS VEH. INFORM TP CLAIM AGREED TO SERVE A
BEST AND ANGE ABOUT NCD ISSUE.

VIDEO SHOW DID HIT TP VEH WHEN TP DROVE PAST OI.

EMAIL RSP LIABILITY CLM.

13/2/18 FILE PASS TO TYPST TO PREPARE REPORT.

RECEIVED 25 APR 2018

RECEIVED 13 FEB 2018

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 18/1/18

Confirm with: TAP CARLINE

Confirm by: MTH

Repair Cost:

P/P SS 21,998.24

(

" days)

Reduction:

28 %

Email

Call

FINAL SETTLEMENT

Date/Time: 23/4/18

Confirm with: CARLINE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost:

0/161

SS 23,538.12

OI REPAIRING INTO PARKING LOT

Loss of Rental (LOR): 0/161

SS 2,034.40

(

16 days)

x 120

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 25,594.50

Global Sum SS:

FINAL PAYMENT

Date/Time: 23.4.18

Confirm with: CARLINE

Email

Call

Payee 1:

SS 25,540.10

Name 1:

PERFORMANCE MOTORS LIMITED.

Payee 2: (Strike if N.A.)

SS 9,054.40

Name 2:

B&O RENT A CAR PTE LTD.

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
25/4/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9320 + 420



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/AIG17022760/ea3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 30-11-2017	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDN 8292A	Veh. Inspected	EW 5343Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/11/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



18/12/2017
Summary & repair
Approved
After repair

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 NOV 2017

Estimate No. : b1 45001
Date Estimated : 29/11/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Wee Thiam Hee, Edwin (Huang Tianxi,
Blk 461 Hougang Avenue 10
#10-976

Singapore 530461

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EW5343Y	G864955	13/09/2017	520D	0

DESCRIPTION

Replace right rear side fender right rear door, right lower side skirting and remove attachment etc include knock on accident dent

5950 ✓ 8,500.00

Spray painting rear bumper, rear right side fender, right lower side skirting, rear right door, tail end pan and floor pan

4417 ✓ 4,908.00
4,820

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 ✓ 873.00

To replace rear windscreen glass including conduct water leak tests.

551 ✓ 649.00

To supply and install rear windscreen solar film.

451X ✓ 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 ✓ 177.00
301

To remove old PDC assembly, replace damaged parts and reconnect bumper including conduct checks for proper function.

150 ✓ 177.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (4X).

451 ✓ 531.00

To replace tyre and wheel rim including balancing. (1x) right rear

79 ✓ 94.00
80

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1-door).

451 ✓ 531.00

To carry out body cavity preservation.
(For cut panel).

451 ✓ 531.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 45001**
Date Estimated : **29/11/2017**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EW5343Y	G864955	13/09/2017	520D	0

DESCRIPTION

To carry out body cavity preservation.
(For cut panel).

451 ✓ 531.00

To supply and install rear right window glass
solar film.

361X 425.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 ✓ 177.00

To remove and install fuel tank to facilitate repairs
including conduct checks for leak.

?45L 531.00

Sundries.

new ✓ 150.00

Total Labour 1: **19,316.00**

DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN
CLAMP
SET WHEEL BEARING - right rear
LIGHT ALLOY RIM 8JX18 W SPK 632
HUB CAP WITH CHROME EDGE
REAR RH DOOR ALUMINIUM
REAR RH SIDE PANEL
Reinforcemen
Reinforcemen
Door hinge,
Door hinge,
Roof molding
PLASTIC NUT
STRIKER WITH PAD
SYSTEM LOCK REAR RH (SCA/ZS)
REAR DOOR BRAKE
RR RH DRIVE SOFT CLOSE AUTOMATIC
REAR WINDOW GREEN (ESG)
RR RH DOOR SIDE WINDOW FIXED GREEN
Sealing endp
Window channel
Seal, end pa
Seal, rear p
RR RH DOOR WINDOW FRAME TOP FINISHE
RR RH DOOR WINDOW FRAME TOP FINISHE
REAR RH DOOR WINDOW GUIDE
RR RH DOOR OUTER CHANNEL COVER (ALU
Cover, windo
Window guide
RR RH DOOR COLUMN B COVER (GLANZSCH

QTY PRIC

6 0.80
2 0.85
1 577.50
1 938.30
1 34.90
1 1,773.45
1 1,796.10
1 48.00
1 48.00
1 55.75
1 55.75
1 196.90
4 0.85
1 21.20
1 679.70
1 85.55
1 231.60
1 818.95
1 414.85
1 30.10
1 61.90
1 19.90
1 19.90
1 233.30
1 233.30
1 104.05
1 118.35
1 40.95
1 6.15
1 49.10

VALUE

nn X 4.80
nn X 1.70
nn X 577.50
cut 938.30
ne - 34.90X
bt 1,773.45
bt 1,796.10
? 48.00
? 48.00
? 55.75
? 55.75
X ? 196.90
nn ? 3.40
? 21.20
? 679.70
? 85.55
? 231.60
ne 818.95
? 414.85
? 30.10
? 61.90
? 19.90
? 19.90
? 233.30
? 233.30
? 104.05
ne 118.35
? 40.95
? 6.15
? 49.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45001
Date Estimated : 29/11/2017
Prepared By : Chua Kee Sin

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EW5343Y	G864955	13/09/2017	520D	0

DESCRIPTION

RH WINDOW GUIDE WEB COVER (GLANZSCH
Lid window uide b pillarg
REAR RH DOOR LOWER SEAL
REAR DOOR EDGE PROTECTION
(S/L) DOOR WEATHERSTRIP
TRUNK LID GASKET
Paint protec
RH SUPPORTING LEDGE
RH SUPPORTING LEDGE
RH SUPPORTING LEDGE
RH SUPPORTING LEDGE
RH SILL TRIM PRIMED
CAVITY PROTECTION WAX REMOVER 500ML
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
PUNCH RIVET N4
(DG) BODYWORK ADHESIVE K5A (50ML)
(DG) CLEANER R1 (100ML)
(DG) CLEANER R1 (100ML)
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP206)
(DG/SL) GLASS PRIMER 30ML (VP206)
(S/L) SEAM SEAL 300ML

QTY	PRIC	VALUE
1	98.25	98.25
1	16.60	16.60
1	39.90	39.90
1	199.45	199.45
1	163.15	163.15
1	98.15	98.15
1	4.85	4.85
1	18.60	18.60
1	18.60	18.60
1	18.60	18.60
1	18.60	18.60
1	403.00	403.00
1	18.45	18.45
15	0.55	8.25
3	0.55	1.65
1	281.55	281.55
39	0.55	21.45
1	118.35	118.35
1	23.85	23.85
1	23.85	23.85
1	23.85	23.85
2	131.55	263.10
1	131.55	131.55
1	27.85	27.85
1	27.85	27.85
1	33.80	33.80

Total Parts : 10,806.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 18/12/17 01545 Excess \$0
Surveyor's Name Tanphu Sign [Signature]
Surveyor's Tel 97498749 Authorized Yes / No
Authorized Date [Signature] Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PNL Yes / No

Surveyor's E-mail tanphu@lkhauto.com
No. of Working Days Recommend 10-11 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

30253.70

Signature:	
Labour 1	19,316.00
Parts	10,806.55
Labour 2	0.00
Excess	0.00
Total GST @ 7%	2,108.58
Grand Total	32,231.13

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

30539.04

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45001
Date Estimated : 29/11/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wee Thiam Hee, Edwin (Huang Tianxi,
Blk 461 Hougang Avenue 10
#10-976

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 530461

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE
EW5343Y	G864955	13/09/2017	520D	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# 3M S/F PREMIUM FRONT WINDSCREEN	252.34	1.00		252.34 <i>me</i>
# CLIP *	3.30	10.00		33.00 <i>me</i>

Total Labour :	0.00
Total Parts :	285.34
Total Labour & Parts :	285.34

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45001
Date Estimated : 29/11/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wee Thiam Hee, Edwin (Huang Tianxi,
Blk 461 Hougang Avenue 10
#10-976

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 530461

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
EW5343Y	G864955	13/09/2017	520D	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear RH fender, rear RH door and attachments, RH side skirting include making good the tail end panel, trunk floor plate, RH roof frame and knocking out dents caused by the accident	5950.00		5,950.00			
* To spray paint rear bumper, rear RH fender, RH side skirting, RH roof frame, rear RH door, tail end panel and trunk floor plate	4820.00		4,820.00			
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00			
* To replace rear windscreen glass include conducting water leak tests	649.00		649.00			
* To reconnect electrical components and wirings at the rear section include conducting checks for proper function (For cut panel)	301.00		301.00			
To remove old PDC assembly, replace damaged parts and reconnect bumper including conduct checks for proper function.	150.00		150.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
To replace rear RH wheel rim include balancing (1x)	80.00		80.00			
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00			
* To carry out body cavity preservation. (For per panel)	100.00		100.00			
To carry out body cavity preservation. (For cut panel).	451.00		451.00			
To conduct checks on all doors and boot lid central locking system for proper function.	150.00		150.00			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

To remove and install fuel tank to facilitate repairs including conduct checks for leak.	451.00	451.00
Sundries.	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LIGHT ALLOY RIM 8JX18 W SPK 632	938.30	1.00		938.30
3M S/F PREMIUM FRONT WINDSCREEN	252.34	1.00		252.34
REAR RH DOOR ALUMINIUM	1,773.45	1.00		1,773.45
REAR RH SIDE PANEL	1,796.10	1.00		1,796.10
REAR WINDOW GREEN (ESG)	818.95	1.00		818.95
RR RH DOOR OUTER CHANNEL COVER (ALU	118.35	1.00		118.35
# CLIP *	3.30	10.00		33.00
(S/L) DOOR WEATHERSTRIP	163.15	1.00		163.15
RH SUPPORTING LEDGE	18.60	1.00		18.60
RH SILL TRIM PRIMED	403.00	1.00		403.00
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80

SUPPLEMENTARY ITEMS

Total Labour :	14,896.00
Total Parts :	7,102.24
Total Labour & Parts :	21,998.24
Deduction for Excess :	0.00
Total Repair Costs less Excess:	21,998.24
GST @7%:	1,539.88
Grand Total :	23,538.12

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 1 December, 2017 3:05 PM
To: Mei Kwan (LKKAUTO); PBSP
Cc: assignments; Admin A; Vic (LKKAUTO)
Subject: RE: REQ FOR DIRECT SETTLEMENT- EW5343Y AND SDN8292A ON 19/11/2017 ***
LKK REF : CC3/AIG17022760/ea3
Attachments: OI SKETCH PLAN.pdf

Without Prejudice

Hi Caroline

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client collided into our insured stationary vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 30 November, 2017 11:17 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: RE: REQ FOR DIRECT SETTLEMENT- EW5343Y AND SDN8292A ON 19/11/2017 *** LKK REF : CC3/AIG17022760/ea3

Dear Caroline,

We refer to the below email.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 27 February 2018 5:46 PM
To: 'Ler, Bernard-JQ'
Cc: Vic (LKKAuto)
Subject: Your ref : 4587478865SG, ACCIDENT ON 19/11/2017 INVOLVING SDN 8292A (OI) & EW 5343Y (TP)

Your ref : **4587478865SG**
Our ref : CC3/AIG17022760/T1ea3

Dear Sirs,

ACCIDENT ON 19/11/2017 INVOLVING SDN 8292A (OI) & EW 5343Y (TP)

We refer to the above matter.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer "**PERFORMANCE MOTORS LTD**" at **\$ 25,594.52 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 32,676.77	\$ 23,538.12
2. Loss of Rental (16days x \$120) (w/GST)	\$ 2,054.40	\$ 2,054.40 (16days x \$120) (BKW RENTAL)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 34,733.17	<u>\$ 25,594.52</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***EW5343Y (4587478865SG)**
[SDN8292A]

TP

WEE THIAM HEE

Nov 19 2017 1:00AM

[TAN KIM BAK]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 23/04/2018 10:35 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$25594.52) - EW5343Y - Claim Handler: Ler, Bernard-JQ

Approved:25594.52.

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MWRP17153734 Vehicle Registration No: SDN 8292A
Name (as shown in NRIC) : TAN LIM BAE NRIC/FIN/Passport No : SD49333J
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 70 HOUGANG AVENUE 7 #16-05 Singapore (538824)
Contact (Tel) : _____ Mobile No. : 9759 5130
Email Address : _____
Date of Accident : 19 Nov 2017 Time of Accident : 0100hrs
Place of Accident : OPEN SPACE CARPARK OF HOUGANG AVE 10 BLK A02
Insurance Company: ATA ASIA PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To Amend TP claim to OD claim.

Policyholder / Driver's Signature
Date:

29th Nov 2017

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$21,998.24 Edit Estimates	S\$21,998.24 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN KIM BAK, ID: S1249333I, Tel: +6597595130		
Main Claimant:	WEE THIAM HEE, ID: S7928582Z		
Vehicle Reg. No.:	EW5343Y	Date of Loss:	19/11/2017 01:00 - :59 [2 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4587478865SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SDN8292A	Policy No. (Claimant):	GA270163/1
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/12/2017]		
Driver/Custodian (Insured):	TAN KIM BAK (), NRIC: S1249333I, Tel: +6597595130		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (23/04/2018): Alert - Adj Mandate Approved (S\$25594.52) - EW5343Y - Claim Handler: Ler, Bernar...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***EW5343Y (4587478865SG)**
[SDN8292A]

TP

WEE THIAM HEE
Nov 19 2017 1:00AM
[TAN KIM BAK]

Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	04/12/17 16:41	Video - Accident												1 Load MP4				
Letters/Correspondences															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1 Edit				
Assessment Reports															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	01/03/18 09:34	Accident Statement From:OD - Reg. No: SDNB292A, Claimant: TAN KIM BAK												1 Load HTM				
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	18/01/18 11:18	Odometer Reading												1 Load JPG		☒		
2	18/01/18 11:18	Chassis Number												1 Load JPG		☒		
3	18/01/18 11:18	General View												1 Load JPG		☒		
4	18/01/18 11:18	General View												1 Load JPG		☒		
5	18/01/18 11:18	General View												1 Load JPG		☒		
6	18/01/18 11:18	General View												1 Load JPG		☒		
7	18/01/18 11:18	General View												1 Load JPG		☒		
8	18/01/18 11:18	General View												1 Load JPG		☒		
9	18/01/18 11:18	General View												1 Load JPG		☒		
10	18/01/18 11:18	General View												1 Load JPG		☒		
11	18/01/18 11:18	General View												1 Load JPG		☒		
12	18/01/18 11:18	General View												1 Load JPG		☒		
13	18/01/18 11:18	General View												1 Load JPG		☒		
14	18/01/18 11:18	General View												1 Load JPG		☒		
15	18/01/18 11:18	General View												1 Load JPG		☒		
16	18/01/18 11:18	General View												1 Load JPG		☒		
17	18/01/18 11:18	General View												1 Load JPG		☒		
18	18/01/18 11:18	General View												1 Load JPG		☒		
19	18/01/18 11:18	General View												1 Load JPG		☒		
20	18/01/18 11:18	General View												1 Load JPG		☒		
21	18/01/18 11:18	General View												1 Load JPG		☒		
22	18/01/18 11:18	General View												1 Load JPG		☒		
23	18/01/18 11:18	General View												1 Load JPG		☒		
24	18/01/18 11:18	General View												1 Load JPG		☒		
25	18/01/18 11:18	General View												1 Load JPG		☒		

Video			1 per page	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
26	18/01/18 11:18	General View	 Load JPG	✓
27	18/01/18 11:18	General View	 Load JPG	✓
28	18/01/18 11:18	General View	 Load JPG	✓
29	18/01/18 11:18	General View	 Load JPG	✓
30	18/01/18 11:18	General View	 Load JPG	✓
31	18/01/18 11:18	General View	 Load JPG	✓
32	18/01/18 11:18	General View	 Load JPG	✓
33	18/01/18 11:18	General View	 Load JPG	✓
34	18/01/18 11:18	General View	 Load JPG	✓
35	18/01/18 11:18	General View	 Load JPG	✓
36	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
37	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
38	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
39	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
40	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
41	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
42	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
43	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
44	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
45	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
46	18/01/18 11:18	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/11/17 11:13	TP ESTIMATE + TP GIA REPORT	 Load TIF	
2	05/12/17 15:14	LETTER TO OI	 Load PDF	
3	20/12/17 09:25	TP ESTIMATE - MARKED	 Load PDF	
4	26/02/18 14:37	GIA SEARCH	 Load PDF	
5	01/03/18 15:13	RENTAL INVOICE	 Load PDF	
6	05/03/18 16:03	RENTAL AGREEMENT	 Load PDF	
7	26/04/18 09:45	AUTHORISATION TO ACT	 Load PDF	
8	26/04/18 09:45	RELEASE VOUCHER	 Load PDF	
9	26/04/18 09:45	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/12/17 11:43	OI GIA REPORT	 Load PDF	
2	01/03/18 09:33	IVIEW FORM AND UTAKING LETTER From:OD - Reg. No: SDN8292A, Claimant: TAN KIM BAK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDN8292A (Insd veh)	Model:	BMW 520I 2.0 (A)
	EW5343Y (TP veh)		
Date of Accident:	19/11/2017		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		32,676.77
Final Repair Cost	:	\$		23,538.12
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		2,054.40 16 days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		25,594.52
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: <u>24</u>		
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	23,540.12
2)	BKW RENT-A-CAR PTE LTD	: \$	2,054.40
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

26 Apr

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17022760/T1EA3S2
Date: 26/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No: EW5343Y Insured Vehicle No: SDN8292A
Date of Loss: 19/11/2017 Nature of Claim: TP Claim No: 4587478865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EW5343Y**
Make & Model: BMW 520i, 2.0 (A) Engine No: 67749896B47D20A
Reg. Date: 13/09/2017 (Man. Year: 2017) Chassis No: WBAJC32080G864955
Colour: White Odometer: 8528 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,249.04	7,252.24	3,996.80	35.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,290.00	14,746.00	4,544.00	23.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,539.04	21,998.24	8,540.80	27.97
+ GST 7.00/7.00% (S\$)	2,137.73	1,539.88	597.85	27.97
Nett Amount (S\$)	32,676.77	23,538.12	9,138.65	27.97
+ Car Rental (16.0 x S\$120.00/day + 7.00% GST) (S\$)		2,054.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		25,594.52		

INSPECTION

Date of Assignment: 18/12/2017
Date Inspected: 18/12/2017 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	6		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	4.80 FS	*- FS
2	2		*CLAMP	Not Necessary	1.70 FS	*- FS
3	1		*SET WHEEL BEARING - RIGHT REAR	Not Necessary	577.50 FS	*- FS
4	1		*LIGHT ALLOY RIM 8JX18 W SPK 632	Cut	938.30 FS	*938.30 FS
5	1		*HUB CAP WITH CHROME EDGE	Not Necessary	34.90 FS	*- FS
6	1		*REAR RH DOOR ALUMINIUM	Bent	1,773.45 FS	*1,773.45 FS
7	1		*REAR RH SIDE PANEL	Bent	1,796.10 FS	*1,796.10 FS
8	1		*REINFORCEMENT	Not Necessary	48.00 FS	*- FS
9	1		*REINFORCEMENT	Not Necessary	48.00 FS	*- FS
10	1		*DOOR HINGE,	Not Necessary	55.75 FS	*- FS
11	1		*DOOR HINGE,	Not Necessary	55.75 FS	*- FS
12	1		*ROOF MOULDING	Not Necessary	196.90 FS	*- FS
13	4		*PLASTIC NUT	Not Necessary	3.40 FS	*- FS
14	1		*STRIKER WITH PAD	Not Necessary	21.20 FS	*- FS
15	1		*SYSTEM LOCK REAR RH (SCA/ZS)	Not Necessary	679.70 FS	*- FS
16	1		*REAR DOOR BRAKE	Not Necessary	85.55 FS	*- FS
17	1		*RR RH DRIVE SOFT CLOSE AUTOMATIC	Not Necessary	231.60 FS	*- FS
18	1		*REAR WINDOW GREEN (ESG)	Necessary	818.95 FS	*818.95 FS
19	1		*RR RH DOOR SIDE WINDOW FIXED GREEN	Not Necessary	414.85 FS	*- FS
20	1		*SEALING ENDP	Not Necessary	30.10 FS	*- FS
21	1		*WINDOW CHANNEL	Not Necessary	61.90 FS	*- FS
22	1		*SEAL, END PA	Not Necessary	19.90 FS	*- FS
23	1		*SEAL, REAR P	Not Necessary	19.90 FS	*- FS
24	1		*RR RH DOOR WINDOW FRAME TOP FINISHER	Not Necessary	233.30 FS	*- FS
25	1		*RR RH DOOR WINDOW FRAME TOP FINISHER	Not Necessary	233.30 FS	*- FS
26	1		*REAR RH DOOR WINDOW GUIDE	Not Necessary	104.05 FS	*- FS
27	1		*RR RH DOOR OUTER CHANNEL COVER (ALU)	Necessary	118.35 FS	*118.35 FS
28	1		*COVER, WINDO	Not Necessary	40.95 FS	*- FS
29	1		*WINDOW GUIDE	Not Necessary	6.15 FS	*- FS
30	1		*RR RH DOOR COLUMN B COVER (GLANZSCH)	Not Necessary	49.10 FS	*- FS
31	1		*RH WINDOW GUIDE WEB COVER (GLANZSCH)	Not Necessary	98.25 FS	*- FS
32	1		*LID WINDOW UIDE B PILLARG	Not Necessary	16.60 FS	*- FS
33	1		*REAR RH DOOR LOWER SEAL	Not Necessary	39.90 FS	*- FS
34	1		*REAR DOOR EDGE PROTECTION	Not Necessary	199.45 FS	*- FS
35	1		*(S/L) DOOR WEATHERSTRIP	Necessary	163.15 FS	*163.15 FS
36	1		*TRUNK LID GASKET	Not Necessary	98.15 FS	*- FS
37	1		*PAINT PROTEC	Not Necessary	4.85 FS	*- FS
38	1		*RH SUPPORTING LEDGE	Necessary	18.60 FS	*18.60 FS
39	1		*RH SUPPORTING LEDGE	Not Necessary	18.60 FS	*- FS
40	1		*RH SUPPORTING LEDGE	Not Necessary	18.60 FS	*- FS
41	1		*RH SUPPORTING LEDGE	Not Necessary	18.60 FS	*- FS
42	1		*RH SILL TRIM PRIMED	Cut	403.00 FS	*403.00 FS
43	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
44	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
45	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
46	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
47	1		*PUNCH RIVET N4	Necessary	22.00 FS	*22.00 FS
48	1		40pcs *(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
49	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
50	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
51	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
53	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
54	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
55	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
56	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
57	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
58	1		*3M PRENIUM FRONT WINDSCREEN	Necessary	252.34 FS	*252.34 FS
59	10		*CLIP	Necessary	33.00 FS	*33.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	11,249.04	7,252.24
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RIGHT REAR SIDE FENDER RIGHT REAR DOOR, RIGHT LOWER SIDE SKIRTING AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.	New	8,500.00	5,950.00
2	SPRAY PAINTING REAR BUMPER, REAR RIGHT SIDE FENDER, RIGHT LOWER SIDE SKIRTING, REAR RIGHT DOOR, TAIL END PAN AND FLOOR PAN.	New	4,908.00	4,820.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS.	New	873.00	742.00
4	TO REPLACE REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TEST.	New	649.00	649.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	New	531.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	301.00	301.00
7	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
8	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS.	New	531.00	451.00
9	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT REAR.	New	94.00	80.00
10	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION.	New	531.00	451.00
11	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
12	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	100.00
13	TO SUPPLY AND INSTALL REAR RIGHT WINDOW GLASS SOLAR FILM.	New	425.00	0.00
14	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	New	177.00	150.00
15	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
Gross Labour Cost (\$\$)			19,290.00	14,746.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >