Surreyor Tayloh REF: ATh	SSIGNMENT
From: Date: 18.12-1017	Veh No: EW 53435 Yr Regn: 2017 Sep.
Total, Date.	Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
stimated Cost:	Truck / Trailer or
DITP WS/TP RES/OD RES/EVA/INV/MV	Make: BMW S201 0.0 1995
o Inspect Vehicle No: EW 53437 t Workshop m/s Performance	
	- Colodi
303 Alexandra Ru	Sp. reading 85 06
sured:	Eng/No:
olicy No.	C/No: WBA JC320809864955
laims No.	Gen. Cond Good / Fair / Poor / Burnt
um Insured: Excess:	Steering: In order / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ihorder / Jammed / Leaked / Burnt or
Make of Veh: Chuq.	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 245/45/6
(Policy Condition)	R: 417
Remark: The veh had commenced its N/S O	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /
repair at the time of inspection.	TOYO/YOKO or
al. or Market Value:	<u>Front</u> <u>Rear</u>
DAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Balmm
st. Repairs: days Res.: Yes or No	D.O.A. D.O.I. (8/14/2015
.um Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / 6/5 N/S / U/C / Rooftop or
Vehicle: IN / C	DUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
,	
ate/Time_File Pass to? : Preli. Report	Days Of Repair:
. Preli. Report	
) : Final Report	Resurvey No. of Trip: Survey Fee:
	Fee:   : Site Insp (\$ )s -Rssi
0.00	. Oito IIIop 1*
Add	Interview (\$
Report Format :	: Interview (\$ ) Photos : Tech Invs (\$ ) Others