

Surveyor:

Xerox Taufik

DOI:

ASSIGNMENT

28/11/17

Date / Time:

28/11/17

Registered in Merimen:

30/11/17

Pre-assign / CCU / FTE

SHD 3255 X



Insured Vehicle No:

Claim No.:

MULI 710792

Name of Insured:

CPL

Policy No.:

ML000016

Insured Tel No.:

HP:

Make / Model:

H-140

Excess Sec II :SS

D.O.A.:

28/11/17

Place of Accident:

PULUT TIMAH ROAD AFTER SU

Is driver the owner?

(YES / NO)

Nature of Accident:

AVB

If NO, Driver Name / Age:

SEE CHYE YU

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

PBL 6163 L



INSRS:

WSP: Li Sheng

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

11.11.17

2 min

PBL 6163 L - X;

SHD 3255 X - 04/11/16 P1539 / K663 - D.O.A. 28/07/16

04/12/2017:

FILES REVIEWED CASE OF OLO changed lane and collided with TP vehicle. Seek liability mandate via merimen.

20/12/2017

File goes to type mandate report.

20/12/2018

File goes to merimen to close.

COR: 2,100.00

LOR: 5 day - X

30.00 - \$150.00

LTA: 0.35

Total:

2,255.35

RECEIVED 25 DEC 2017

RECEIVED 25 JAN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/01/2018

Confirm with:

Wingon

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

SS

2,100.00

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

Surinder

Tayfer

REF:

III

ASSIGNMENT

From: Date: 28/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBL6163L

at Workshop mis

Li Sheng

of Bk K Pandan Loop #01-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10am

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

FBL6163L

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

C.C.

Colour

M4 / h

A/C

Insured / Std / NI / NA

Sp.Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110 / 70 R17

R:

150 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

28/11/17 @ 1020

Survey held at

Li Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

W/S will pass G1A

(4/9/17: \$2,100.00 / Red: \$5063.75 / 71%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

) \$ + RS \$)

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III17022764/Gka3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 30-11-2017		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3255X	Veh. Inspected	FBL 6163L
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	30/11/2017
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	22/11/2017	Inspection Date	28/11/2017
	Survey held at	LI SHENG AUTOMOBILE TRADING BLK 1, PANDAN LOOP, #01-16 SINGAPORE 128219.		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Att: **INDIA INSURANCE**

Date: 24/11/2017
Vehicle No: FBL6163L
Model: HONDA
Year: 2017
Date of loss: 22/11/2017
Our ref: LSA237TJS

your ref vehicle No: SHD3255X(TP claim)

Qty	Description	List Price	Remarks
1.00	LH FAIRING <i>cut</i> ✓	\$ 398.10	
1.00	HANDLE BAR ?	\$ 190.20	
1.00	HANDLE BAR COLUMN ?	\$ 65.10	
1.00	LH FORK <i>Rx</i>	\$ 201.50	
1.00	LH CLUTCH LEVEL <i>cut</i> ✓	\$ 39.40	
1.00	LH HANDLE BAR BALANCER <i>cut</i> ✓	\$ 34.10	
1.00	LH SIDE MIRROR <i>cut</i> ✓	\$ 75.80	
1.00	LH SIGNAL LAMP <i>cut</i> ✓	\$ 64.20	
1.00	GEAR SHIFT LEVEL <i>bc</i> ✓	\$ 187.10	
1.00	GEAR SHIFT LEVEL RUBBER <i>cut</i> ✓	\$ 39.40	
1.00	GEAR SHIFT BRACKET ?	\$ 189.10	
1.00	ENGINE COVER <i>x</i>	\$ 981.60	
1.00	LH LOWER FAIRING <i>R</i>	\$ 387.20	
1.00	SIDE STAND <i>bt</i> ✓	\$ 91.80	
1.00	LH STRUCT BAR ?	\$ 294.60	
1.00	LH STRUCT BAR BEARING ?	\$ 50.70	
1.00	LH FOOTREST <i>cut</i> ✓	\$ 55.60	
1.00	LH REAR FAIRING <i>cut</i> ✓	\$ 386.20	
1.00	REAR BOX <i>cut</i> ✓	\$ 301.10	
1.00	REAR BOX BRACKET ?	\$ 295.30	
1.00	REAR NUMBER PLATE BRACKET <i>x</i>	\$ 297.10	
1.00	LH PILLION FOOT REST BRACKET <i>Rx</i>	\$ 255.30	
1.00	LH PILLION FOOT REST <i>cut</i> ✓	\$ 45.90	
TOTAL:		\$ 4,926.40	
LESS 10%:		\$ 492.64	
		<u>\$ 4,433.76</u>	

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Att: **INDIA INSURANCE**

Date: 24/11/2017
Vehicle No: FBL6163L
Model: HONDA
Year: 2017
Date of loss: 22/11/2017
Our ref: LSA237TJS

your ref vehicle No: SHD3255X(TP claim)
SPECIAL NETT ITEMS

Qty	Description	Unit Price	Remarks
1.00	IU UNIT CUSTOMISE STICKER <i>cut</i>	\$ 30 50.00	
1.00	FAIRING STICKER <i>cut</i>	\$ 350 550.00	
Total		\$600.00	

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA - REAR	\$ 300 900.00	
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 250 900.00	
1.00	CHECK WIRING	\$ 20 30.00	
1.00	FORK ALIGNMENT	\$ 120 150.00	
1.00	TO REMOVE PETROL TANK	\$ 60 150.00	
TOTAL:		\$ 2,130.00	

SUBTOTAL: \$ 7,163.76

Estimate prepared by: WINSON

Telephone : 97684247

winsonls@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495744
- WP'

22/11/17 @ 1020

5 days

Resurvey ~~new~~ parts

sur@lkkauto.com

taufik@lkkauto.com

Resurvey after repair



Letter of Demand

Our Ref : LSA237TJS

Date : 27/12/2017

INDIA INSURANCE

Attn : Motor Claim Department

Subject : Accident involving vehicle FBL6163L/SHD3255X(TP) on 22/11/2017
Along SIX AVE near Living Café near LP98/1F

Dear Sir/Mdm,

We would like to append our losses as follow-

	<u>Amount(\$)</u>
1) Repair cost	\$2,100.00
2) Loss of use	\$400.00
(5 days \$80 x 5)	
3) Miscellaneous (LTA search fee)	\$5.35
Total	\$2,505.35

ENCLOSED: Copies of repair cost invoices & letter of authority for your perusal and kind attention.

Kindly look into the matter and revert to us as soon as possible .

Thank you.

Regards,

Winson Ong Kim Huat

Hp : 9768 4247

Fax : 67744885

Email : winsonls@yahoo.com.sg

Li Sheng Automobile Trading
Blk K, Pandan Loop
#01-18
Singapore 128236

Block k, Pandan Loop #01-18 Singapore 128236

RCB Reg. No: 52887845W

HP: 91474552; Tel: 67746110; Fax: 67744885

LETTER OF UNDERTAKING & AUTHORITY

I/We Mohammad Azri Bin Ismail NRIC No/Reg No 59341526D
of (address) Blk 824, Jurong West St 81, #03-448, S(640824)
the registered owner (or his/her/their agent) of motor vehicle registration no
FBL 6163L hereby authorize M/S LI SHENG Automobile Trading ("Repairer") to
commence repairs to my/our motor vehicle of the said accident on 22/11/2017
involving motor vehicle(s) SHD 3255X
along Six Ave Near Living Cafe near LP 98/1F.

1. I/We agree to let the Repairer to claim on behalf of my/our goodself for the damages against the insured vehicle of the Third Party(s) insurance company(s).

Or, I/We agree to let the Repairer to claim from my/our insurance company (given the option of claiming against my insurance company should Third Party claim be unsuccessful). And I/we will pay the Excess as stipulated in the insurance policy.
2. I/We irrevocably authorize Mr Toh Chin Huat (S7371516D) of the Repairer to sign all discharge voucher/indemnity forms/legal documents and all necessary documents in connection with and arising out of the above claim. Upon full discharge of liability, the cheque is to be made payable to my Repairer (LI Sheng Automobile Trading).
3. I/We agree that should my/our claim for damages against the Third Party or from my/our insurance company be unsuccessful, I/we undertake to pay to the Repairer the sum of monies as stated in the claim to the insurance company.

And, I/We shall reimburse the Repairer on the difference should the claim fails or non-full liability. (Difference of amount as stated in the claim and insurance offer to settlement).
4. My/Our vehicle is repaired by the Repairer on my/our free will without any inducement threat and/or promise.
5. In the event that the Repairer is compelled to enforce this undertaking, I/We agree that I/We shall pay for the legal cost incurred by the Repairer on a solicitor and client full indemnity basis.

x 

Signature/Co Stamp

Name: Mohammad Azri Bin Ismail

NRIC: 59341526D

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT17110792
Claimant Ref: FBL6163L

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the amt and application of this document."

We/I, Li Sheng Automobile Trading ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2,100.00 (repair cost), S\$ 150.00 (loss of use/rental), S\$ 5.35 (search fee), vehicle no. FBL6163L that was damaged pursuant to the accident which occurred on 22/11/2017 (date) at BUKIT TIMAH ROAD AFTER SIXTH AVENUE (location) involving vehicle no. SHD3255X (insured vehicle). This is pursuant to the inspection conducted on 28/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner MOHAMMAD AZRI BIN ISMAIL ("the third party claimant") of vehicle no. FBL6163L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to FBL6163L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,255.35 to Li Sheng Automobile Trading

Dated this 23 day of Jan, 2018

CLAIMANT:

Signature:



Signed by "the workshop" (with chop)

Name:

Vinson Ong Kim Huat

NRIC:

97788258 B

Address:

18 Pandan Loop
#01-18 S(128 236)

Nationality:

Singaporean

Occupation:

Claim Advisor

WITNESS:

Signature:



Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

Block 51, Paya Ubi Industrial

Address:

Park, UBI Avenue 1, #02-25
(S) 408933

Nationality:

LKK AUTO CONSULTANTS PTE LTD

Occupation:

51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933
Tel: 6256 3561

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 24 Nov 2017 / 13:40:20

Receipt Date/Time : 24 Nov 2017 / 13:39:29

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171124-001065

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD3255X As at 22 Nov 2017/21:40:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHD3255X Enquiry Fee 20171124133748240382	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	xxxxxxxxxxxx6429	Credit Card: Visa /MasterCard		5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Dec 2017 Edit Reg		28 Nov 2017 00:00 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	MOHAMMAD AZRI BIN ISMAIL, ID: S9341526D		
Vehicle Reg. No.:	FBL6163L	Date of Loss:	22/11/2017 21:00 - :59
Claim Type:	TP / MCT17110792	Policy/Cover Note No.:	MCOM0016 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD3255X	Policy No. (Claimant):	AN3152925
		Excess:	
Repairer:	Li Sheng Automobile Trading (HQ) No. 18 Pandan Loop #01-18 Blk K, 129236 West Coast - Tel: 91474552		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (08/01/2018): Alert - Adj Mandate Approved (S\$2255.35) - FBL6163L - Claim Handler: Priya
- III_SG (04/12/2017): Alert - Adj Mandate Approved (S\$0.00) - FBL6163L - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBL6163L (MCT17110792)
[SHD3255X]
TP
MOHAMMAD AZRI BIN ISMAIL
Nov 22 2017 9:00PM
[COMFORT TRANSPORTATION PTE LTD]
Li Sheng Automobile Trading

Upload Documents			Upload Photos			Compose New Letter			View View in Browser							
Video									1 per page	☒						
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print						
1	04/12/17 17:11	Video - Accident							 Load MP4							
Photos/Images									3 per page	☒						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print						
1	08/01/18 14:57	General View							 Load JPG	☒						
2	08/01/18 14:57	General View							 Load JPG	☒						
3	08/01/18 14:57	General View							 Load JPG	☒						
4	08/01/18 14:57	General View							 Load JPG	☒						
5	08/01/18 14:57	General View							 Load JPG	☒						
6	08/01/18 14:57	General View							 Load JPG	☒						
7	08/01/18 14:57	General View							 Load JPG	☒						
8	08/01/18 14:57	General View							 Load JPG	☒						
9	08/01/18 14:57	General View							 Load JPG	☒						
10	08/01/18 14:57	General View							 Load JPG	☒						
11	08/01/18 14:57	General View							 Load JPG	☒						
12	08/01/18 14:57	General View							 Load JPG	☒						
13	08/01/18 14:57	General View							 Load JPG	☒						
14	08/01/18 14:57	General View							 Load JPG	☒						
15	08/01/18 14:57	General View							 Load JPG	☒						
16	08/01/18 14:57	General View							 Load JPG	☒						
17	08/01/18 14:57	General View							 Load JPG	☒						
18	08/01/18 14:57	General View							 Load JPG	☒						
19	08/01/18 14:57	General View							 Load JPG	☒						
20	08/01/18 14:57	General View							 Load JPG	☒						
21	08/01/18 14:57	General View							 Load JPG	☒						
22	08/01/18 14:57	General View							 Load JPG	☒						
23	08/01/18 14:57	General View							 Load JPG	☒						
24	08/01/18 14:57	General View							 Load JPG	☒						
25	08/01/18 14:57	General View							 Load JPG	☒						
26	08/01/18 14:57	General View							 Load JPG	☒						
27	08/01/18 14:57	General View							 Load JPG	☒						
28	08/01/18 14:57	General View							 Load JPG	☒						
29	08/01/18 14:57	General View							 Load JPG	☒						
30	08/01/18 14:57	General View							 Load JPG	☒						
31	08/01/18 14:57	General View							 Load JPG	☒						
32	08/01/18 14:57	General View							 Load JPG	☒						

33	08/01/18 14:57	General View	1	Load JPG	☒
34	08/01/18 14:57	General View	1	Load JPG	☒
35	08/01/18 14:57	General View	1	Load JPG	☒
36	08/01/18 14:57	General View	1	Load JPG	☒
37	08/01/18 14:57	General View	1	Load JPG	☒
38	08/01/18 14:57	General View	1	Load JPG	☒
39	08/01/18 14:57	General View	1	Load JPG	☒
40	08/01/18 14:57	General View	1	Load JPG	☒
41	08/01/18 14:57	General View	1	Load JPG	☒
42	08/01/18 14:57	General View	1	Load JPG	☒
43	08/01/18 14:57	General View	1	Load JPG	☒
44	08/01/18 14:57	General View	1	Load JPG	☒
45	08/01/18 14:57	General View	1	Load JPG	☒
46	08/01/18 14:57	General View	1	Load JPG	☒
47	08/01/18 14:57	General View	1	Load JPG	☒
48	08/01/18 14:57	General View	1	Load JPG	☒
49	08/01/18 14:57	General View	1	Load JPG	☒
50	08/01/18 14:57	General View	1	Load JPG	☒
51	08/01/18 14:57	General View	1	Load JPG	☒
52	08/01/18 14:57	General View	1	Load JPG	☒
53	08/01/18 14:57	General View	1	Load JPG	☒
54	08/01/18 14:57	General View	1	Load JPG	☒

Documentation1 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 15:12	TP GIA REPORT	1	Load PDF	
2	01/12/17 10:19	TP ESTIMATE - MARKED	1	Load PDF	
3	08/01/18 15:18	LOD	1	Load PDF	
4	08/01/18 15:18	LTA SEARCH	1	Load PDF	
5	08/01/18 15:18	ATA FORM	1	Load PDF	
6	29/01/18 14:00	DISCHARGE VOUCHER	1	Load PDF	
7	29/01/18 14:00	WORKSHOP INVOICE	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	01/12/17 08:41	Singapore Accident Statement	1	Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17022764/T1KA3Q2

Date: 29/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016
 Claimant Vehicle No: FBL6163L Insured Vehicle No: SHD3255X
 Date of Loss: 22/11/2017 Nature of Claim: TP Claim No: MCT17110792

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL6163L
 Make & Model: HONDA CB190R, 184cc Engine No: WH161FMK16F00159
 Reg. Date: 07/01/2017 (Man. Year: 2016) Chassis No: LWPCL109G1006007
 Colour: Multi-colour Odometer: 0 km
 Engine Capacity: 184 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 150/60 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,033.76	1,926.83	3,106.93	61.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	750.00	1,380.00	64.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,163.76	2,676.83	4,486.93	62.63
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	7,163.76	2,100.00	5,063.76	70.69
+ Loss of Use (5.0 x S\$30.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,255.35		

INSPECTION

Date of Assignment: 28/11/2017
 Date Inspected: 28/11/2017 Inspected At: Li Sheng Automobile Trading (HQ)
 No. 18 Pandan Loop #01-18 Blk K
 Singapore 129236
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jan 2018)	
Parts:	N/A	HONDA CB190R 184cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL6163L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FAIRING	Cut	398.10 FL	*398.10 FL
2	1		*HANDLE BAR	Not Necessary	190.20 FL	*- FL
3	1		*HANDLE BAR COLUMN	Not Necessary	65.10 FL	*- FL
4	1		*LH FORK	Repair	201.50 FL	*- FL
5	1		*LH CLUTCH LEVEL	Cut	39.40 FL	*39.40 FL
6	1		*LH HANDLE BAR BALANCER	Cut	34.10 FL	*34.10 FL
7	1		*LH SIDE MIRROR	Cut	75.80 FL	*75.80 FL
8	1		*LH SIGNAL LAMP	Cut	64.20 FL	*64.20 FL
9	1		*GEAR SHIFT LEVEL	Bent	187.10 FL	*187.10 FL
10	1		*GEAR SHIFT LEVEL RUBBER	Cut	39.40 FL	*39.40 FL
11	1		*GEAR SHIFT BRACKET	Not Necessary	189.10 FL	*- FL
12	1		*ENGINE COVER	Not Necessary	981.60 FL	*- FL
13	1		*LH LOWER FAIRING	Repair	387.20 FL	*- FL
14	1		*SIDE STAND	Bent	91.80 FL	*91.80 FL
15	1		*LH STRUCT BAR	Not Necessary	294.60 FL	*- FL
16	1		*LH STRUCT BAR BEARING	Not Necessary	50.70 FL	*- FL
17	1		*LH FOOTREST	Cut	55.60 FL	*55.60 FL
18	1		*LH REAR FAIRING	Cut	386.20 FL	*386.20 FL
19	1		*REAR BOX	Cut	301.10 FL	*301.10 FL
20	1		*REAR BOX BRACKET	Not Necessary	295.30 FL	*- FL
21	1		*REAR NUMBER PLATE BRACKET	Not Necessary	297.10 FL	*- FL
22	1		*LH PILLION FOOT REST BRACKET	Repair	255.30 FL	*- FL
23	1		*LH PILLION FOOT REST	Cut	45.90 FL	*45.90 FL
24	1		*IU UNIT CUSTOMISE STICKER	Cut	50.00 FS	*30.00 FS
25	1		*FAIRING STICKER	Cut	550.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,526.40	2,098.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	492.64	171.87
Total Parts (\$\$)	5,033.76	1,926.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR REPAIR ON AFFECTED AREA -REAR	New	900.00	300.00
2	SPRAY PAINT ON AFFECTED AREA	New	900.00	250.00
3	CHECK WIRING	New	30.00	20.00
4	FORK ALIGNMENT	New	150.00	120.00
5	TO REMOVE PETROL TANK	New	150.00	60.00
Gross Labour Cost (S\$)			2,130.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >