

ASS. REC. BY:

REF: CS/MSG17022766 / THb

Special Instruction:

Supervisor:  
Member

Taufik.

## ASSIGNMENT (Office)

From (Person):

Clara Milah Yeo

of

MSG

Date/Time: 29/11/17 @ 4.23pm

Estimated Cost:

Bill to:

OB TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 3161 J

Insured:

at Workshop m/s

Performance Motors

Tel:

9116 5700

of

303 Alexandra Road

Policy No:

B27771430SMP

Claim No:

537350

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A

17/11/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

8:54am @ 30/11/17

Person Contacted:

Mr. Han

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 3161 J - CS/MSG17022057 / Urb-D.O.A : 17/11/2017

G39584758

5/12-

Revert via menmen.

6/12-@10.03am authorise Ng Chen Haw

6/12-11.40 am inform Han authorise repair excess \$1000.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17022766/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 30-11-2017	
			Code : MSG	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected		SKP 3161J
Policy No. B27771430SMP		Coverage (\$)		0.00
Claim No. 537350		Excess (\$)		0.00
Assign From MERIMEN (CLARA MILAH YEO)		Assign Date		30/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date 17/11/2017		Inspection Date		
Survey held at		PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Est	Adj Submitted	Est Auth'd	Status
Main	20 Nov 2017		29 Nov 2017 16:23 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	HAN YAN, ID: G0537819U, Tel: +6597665454, Email: christine6886@msn.cn								
Vehicle Reg. No.:	SKP3161J	Date of Loss:	17/11/2017 16:00 - :59						
Claim Type:	OD / 537350	Policy/Cover Note No.:	B27771430SMP (Comprehensive) Coverage: 29/08/2017 - 28/08/2018						
		Excess:	S\$1,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/11/2017]								
Driver/Custodian:	HAN YAN (31 / Female), NRIC: G0537819U, Tel: +6597665454								
Adj Asg. Remarks:	REVERT - URGENT, CAR IN 29/11. TO SURVEY IN THE MORNING								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

BMW Distributor

## Performance Motors Limited

A member of the Sime Darby Group

REG/CS/PAY/FA

29 NOV 2017



## FACSIMILE MESSAGE

DATE 29/11/17 TIME \_\_\_\_\_

TO MSIG Ins FAX NO. 62257402

ATTENTION Motor Claims NO OF PAGES 10  
(INCLUSIVE OF THIS PAGE)

CC \_\_\_\_\_

ATTENTION \_\_\_\_\_ FAX NO. \_\_\_\_\_

FROM Har FAX NO. 64794601

TEL NO. 91165700

If this fax is not received in order, please do call us. Thank you.

Attached is the repair estimate for \_\_\_\_\_  
(Vehicle Regn. No)

The vehicle is presently ☒ IN/Not IN our workshop.



This is an Own Damage Claim

Please arrange for a surveyor to inspect the vehicle



This is a 3<sup>rd</sup> Party Claim.

If we do not hear from you within the next 24 hours, exclude Saturday and Sunday, we shall proceed with our survey and repair of the vehicle.

CC:

FAX:

Performance Motors Limited

Sales & After-sales  
315 Alcindor Road  
#01-01  
Performance Centre  
Singapore 159944

Telephone  
Sales & Admin:  
6319 0100  
After-sales: 6319 0111

Fax/Sale  
Admin: 6474 7770  
Sales: 6474 6003  
Parts: 6474 6060  
After-sales: 6474 3229

896 Dunearn Road  
#01-01  
Sime Darby Centre  
Singapore 569472

Telephone  
Sales: 6319 0500

Fax/Sale  
Sales: 6469 1709

280 Kampong Arang Rd  
East Coast Centre  
Singapore 438160

Telephone  
Sales: 6319 0600  
After-sales: 6319 0668

Fax/Sale  
Sales: 6344 1232  
Parts: 6344 3182  
After-sales: 6344 0773

Registered office  
896 Dunearn Road  
#04-11  
Sime Darby Centre  
Singapore 569472

Co. Reg. No:  
1974015294

View Received Message

This mail is associated with :

\*SKP3161J (537350)

OD

Nov 17 2017 4:00PM

[HAN YAN]

Performance Motors Limited

Reply   Reply All   Mark as Unread   Print Message   Delete Message   Forward

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 06/12/2017 10:03 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$18424.30) - SKP3161J - Claim Handler: Clara Milah Yeo

Approved:18424.30.

DOCUMENTS SUMMARY

There are no documents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 6 December, 2017 11:40 AM  
**To:** Han Kwan Yong  
**Cc:** Chua Kee Sin; SUR  
**Subject:** AUTHORISE REPAIR FOR SKP 3161J MSIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKP 3161J (Excess \$1000.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Miah Yeo

Date: 05 Dec 2017

**Preliminary Advice**

Vehicle No	: SKP3161J	Accident Date	: 17/11/2017
Make	: BMW 428i	Policy No.	: B27771430SMP
Assignment Date	: 29/11/2017	Excess	: S\$1,000.00
Date of Inspection	: 05/12/2017	Est. Duration of Repair	: 12.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,450.95
Revised Amount	:S\$	18,424.30
Check Items (Estimated)	:S\$	2,185.65
Total	:S\$	20,609.95

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	90,271.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,729.00

**Remarks**

- ( X ) The vehicle is economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.



## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Foreign Passport Country: China
Owner ID	84758
<b>Vehicle Details</b>	
Vehicle No.	SKP3161J
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	B.M.W.
Vehicle Model	428I COUPE M SPORT A/T SR HID NAV HUD
Primary Colour	White
Manufacturing Year	2014
Engine No.	B1150861N20B20A
Chassis No.	WBA3N32000K239059
Maximum Power Output	180.0 kW (241 bhp)
Open Market Value	\$52,804.00
Original Registration Date	29 Aug 2014
First Registration Date	29 Aug 2014
Transfer Count	0
Actual ARF Paid	\$62,048.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Aug 2024
PARF Rebate Amount	\$46,536.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	28 Aug 2024
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$65,001.00
COE Rebate Amount	\$43,735.00
<b>Total Rebate Amount</b>	<b>\$90,271.00</b>

The information contained herein is correct as at 05 Dec 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/11/2017 13:01
Date Of Accident	17/11/2017 16:15
Exact Location Of Accident	ALONG JURONG TOWN HALL ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP3161J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HAN YAN
NRIC No	G0537819U 51307
Email Address	CHRISTINE6886@MSN.CN
Mobile Phone No	(LOCAL) +65-97665454
Alternative Phone No	OFFICE-97665454

### Vehicle Particulars

Manufacturer	BMW
Model	428I-2.0 GRAN COUPE (F36) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 27771430 SMP
Cover Note Number	

### Driver

Name of Driver	HAN YAN
NRIC No	G0537819U
Date Of Birth	09/11/1986
Occupation	INDOOR
Date Of Driving Pass	11/03/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97665454
Fax Number	
Contact Number	OFFICE-97665454
Email Address	CHRISTINE6886@MSN.CN

Address	BLOCK 423 CLEMENTI AVENUE 1 #15-323
Postcode	120423
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGC1087U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHUA ONG AIK
NRIC/Passport Number	S8828628F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

#### Details of Witness

Name	
Phone Number	
Email Address	


**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 2017. 11. 20


Policyholder's Signature  
Date & Time:

 2017. 11. 20

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 12/11/2017 around 4.15pm. I was driving my vehicle SKP3161J along Jurong Town Hall Ave. I was east to Jurong town hall road. While I make signal to filter lane to the right side and my car already 3/4 way to the lane suddenly a car SGC1087U come from behind very fast and hit my car rear side behind.

Reporting Date and Claim


3rd party Claim

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 2017.11.20

Policyholder's Signature:  
Date & Time:

 2017.11.20

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Performance Motors Limited

A member of The Sime Darby Group

Co. Reg. No. 157401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119941

Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel. 63190888 (AfterSales)  
Fax. 63449772

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

Tel. 63186828 (AfterSales)  
63190535/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64788624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 44997  
Date Estimated : 29/11/2017  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Han Yan  
423 Clementi Avenue 1  
#15-323

Singapore 120423

## - ACCOUNT - 66

MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3161J	K239059	29/08/2014	428iA/2	0

## DESCRIPTION

## VALUE

To replace rear bumper & attachments, rear right fender including to knock out rear right wheel house and dented area caused by the accident.

5950 6,800.00

To respray rear bumper, rear right fender, right roof frame right running board panel & cover, tail panel and boot compartment

4767 5,297.00

To carry out body cavity preservation.  
(For cut panel).

451 531.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 873.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

231 271.00

To replace rear side window glass including conduct water leak tests.

381 413.00

To supply and install rear right side window glass solar film.

nnx 425.00

To remove and install fuse box at the rear section to facilitate repairs.

photo. 451 531.00

To remove and install fuel tank to facilitate repairs, including conduct checks for leak.

photo. 451 531.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1X).

451 531.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

300 354.00

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 19740115PW GST Reg. No. M2-0020081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Tampong Arang Road  
East Coast Centre  
Singapore 438182  
Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190928 (AfterSales)  
63190923/930 (Motorrad)  
64796421 (AfterSales)  
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 44997  
Date Estimated : 29/11/2017  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP3161J	K239059	29/08/2014	428iA/2	0

### DESCRIPTION

### VALUE

Sundries. *nee*

✓ 150.00

Total Labour 1: 16,801.00

### DESCRIPTION

### QTY PRIC

### VALUE

# ALLOY RIM 8.5X19 M DOUBLE SP	1	1,608.80	1,608.80
HUB CAP WITH CHROME EDGE (BMW)	1	23.75	23.75
# REAR RH FENDER	1	1,487.45	1,487.45
BUMPER RIVET	10	0.50	5.00
RR BUMPER RH SIDE GUIDE?	1	46.90	46.90
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,233.50	1,233.50
PLASTIC NUT	5	0.85	4.25
# SIDE WINDOW FIXED REAR RH	1	360.80	360.80
# RR RH WHEEL HOUSING COVER?	1	140.95	140.95
EXPANDING NUT	10	0.55	5.50
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	18.45
BLIND RIVET AVIBVLB	15	0.55	8.25
SCREW (SF PLUS M5X15)	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N5	5	0.55	2.75
PUNCH RIVET N4	30	0.55	16.50
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	131.55
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	3	33.80	101.40

Total Parts : 5,649.95

Claims / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 4/12/17 @ 4:45pm 1000

Surveyor's Name Tan Kah

Signature 97445749

Authorized Sign Revent

RESURVEY PARTS PHOTO BY SURVEYOR

Surveyor's Email tan.kah@pullarps.com

No. of Working Days Recommended 10 - 12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1	16,801.00
Parts	5,649.95
Labour 2	0.00
Excess	0.00
Total GST @ 7%	1,571.57

Grand Total : 24,022.52

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 44997  
Date Estimated : 29/11/2017  
Prepared By : Han Kwan Yong

Page No. :

**REPAIR FOR -**  
Han Yan  
423 Clementi Avenue 1  
#15-323

Singapore 120423

**- ACCOUNT - 66**  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKP3161J	K239059	29/08/2014	428iA/2	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear bumper and attachments, rear RH fender include making good the tail end panel, trunk floor plate, RH running board panel & cover, RH roof frame and knocking out dents caused by the accident	5950.00		5,950.00			
To respray rear bumper, rear RH fender, RH roof frame RH running board panel & cover, tail end panel and trunk floor plate	4767.00		4,767.00			
To carry out body cavity preservation. (For cut panel).	451.00		451.00			
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00			
To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00			
To replace rear RH fixed side window glass include conducting water leak tests	413.00		413.00			
* To remove and install fuse box at the rear section to facilitate repairs.	451.00		451.00			
* To remove and install fuel tank to facilitate repairs include conducting checks for leak	451.00		451.00			
* To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
To replace wheel rim include balancing (1x)	80.00		80.00			
To reconnect electrical components and wirings at the rear section including conduct checks for proper function. (For cut panel)	301.00		301.00			
# To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function	150.00		150.00			
Sundries	150.00		150.00			



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SNAP LOCK COUPLING *	3.55	2.00		7.10
ALLOY RIM 8.5X19 M DOUBLE SPK 442	1,608.60	1.00		1,608.60
HUB CAP WITH CHROME EDGE (BMW)	23.75	1.00		23.75
3M S/F PREMIUM REAR SIDE DOOR	210.28	1.00		210.28 (A)
REAR RH FENDER	1,487.45	1.00		1,487.45
BUMPER RIVET	0.50	10.00		5.00
# TRIM PANEL BUMPER REAR BOTTOM (M) *	207.30	1.00		207.30
REAR BUMPER PANEL PRIMED (M/PDC)	1,233.50	1.00		1,233.50
PLASTIC NUT	0.85	5.00		4.25
# BLIND RIVET NUT *	3.90	2.00		7.80
SIDE WINDOW FIXED REAR RH	360.80	1.00		360.80
EXPANDING NUT	0.55	10.00		5.50
# TYPE IDENTIFICATION PLATE (CODED) *	27.90	1.00		27.90
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N5	0.55	10.00		5.50
PUNCH RIVET N4	0.55	40.00		22.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	1.00		131.55
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	1.00		131.55
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85
(S/L) SEAM SEAL 300ML	33.80	3.00		101.40

### # SUPPLEMENTARY ITEMS

Total Labour :	14,588.00
Total Parts :	6,049.33
Total Labour & Parts :	20,637.33
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	19,637.33
GST @7%:	1,374.61
Grand Total :	21,011.94

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 44997  
Date Estimated : 29/11/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Han Yan  
423 Clementi Avenue 1  
#15-323

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 120423

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE		
SKP3161J	K239059	29/08/2014	4281A/2	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
# To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function				150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SNAP LOCK COUPLING *	3.55	2.00		7.10 <i>all</i>
# TRIM PANEL BUMPER REAR BOTTOM (M) *	207.30	1.00		207.30 <i>del</i>
# BLIND RIVET NUT *	3.90	2.00		7.80 <i>all</i>
# TYPE IDENTIFICATION PLATE (CODED) *	27.90	1.00		27.90 <i>all</i>
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	1.00		131.55 <i>all</i>

Total Labour :	150.00
Total Parts :	381.65
Total Labour & Parts :	531.65

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2017		29 Nov 2017 16:23 <a href="#">Edit Adj Rpt</a>	<b>S\$20,637.33</b> <a href="#">Edit Estimates</a>	<b>S\$20,637.33</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>HAN YAN</b> , ID: G0537819U, Tel: +6597665454, Email: christine6886@msn.cn								
Vehicle Reg. No.:	<b>SKP3161J</b>	Date of Loss:	17/11/2017 16:00 - :59 [39 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 537350</b>	Policy/Cover Note No.:	B27771430SMP (Comprehensive) Coverage: 29/08/2017 - 28/08/2018						
		Excess:	S\$1,000.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Clara Milah Yeo</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 29/12/2017]								
Driver/Custodian:	HAN YAN (31 / Female), NRIC: G0537819U, Tel: +6597665454								
Adj Asg. Remarks:	REVERT - URGENT, CAR IN 29/11. TO SURVEY IN THE MORNING								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (10/07/2018): Alert - Adj Mandate Approved (S\$20637.33) - SKP3161J - Claim Handler: Clara Mila...</li> <li>MSIG_SG (06/12/2017): Alert - Adj Mandate Approved (S\$18424.30) - SKP3161J - Claim Handler: Clara Mila...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKP3161J (537350)  
 OD  
 Nov 17 2017 4:00PM  
 [HAN YAN]  
 Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)							Thumbnail	Print	
1	20/11/17 13:13	Accident Statement							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	05/12/17 16:35	Adjuster Immediate Advice							Load HTM		
2	29/06/18 16:58	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)							Thumbnail	Print	
1	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	20/11/17 13:10	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
2	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
3	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
4	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
5	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
6	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
7	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
8	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
9	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
10	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
11	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
12	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
13	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
14	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
15	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
16	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	
17	05/12/17 16:38	General View							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
18	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
19	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
20	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
21	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
22	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
23	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
24	05/12/17 16:38	General View		<input checked="" type="checkbox"/>
25	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
26	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
27	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
28	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
29	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
30	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
31	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
32	04/07/18 14:17	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/11/17 16:13	PML ESTIMATE		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/17 16:37	WORKSHOP ESTIMATE		<input checked="" type="checkbox"/>
2	10/07/18 10:00	ESTIMATE		<input checked="" type="checkbox"/>
3	17/07/18 10:35	SUPPLEMENTARY PART		<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	20/11/17 13:13	Accident Statement		<input checked="" type="checkbox"/>
2	29/11/17 17:18	Addendum Sheet		<input checked="" type="checkbox"/>
3	29/11/17 17:19	Accident Statement Addm. #1		<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
2	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
3	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
4	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
5	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
6	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
7	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
8	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
9	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
10	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
11	20/11/17 13:10	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wah Hong Motors & Credit Pte Ltd (HQ)	Thumbnail	Print
1	20/11/17 13:09	Sketch Plan		<input checked="" type="checkbox"/>
2	20/11/17 13:11	Identity Card		<input checked="" type="checkbox"/>
3	20/11/17 13:11	Driving License		<input checked="" type="checkbox"/>
4	20/11/17 13:11	Certificate of Insurance		<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG17022766/T1TBQ2

Date: 17/07/2018

### REFERENCE

Insured/Claimant: HAN YAN Policy No: B27771430SMP  
Date of Loss: 17/11/2017 Nature of Claim: OD Claim No: 537350

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP3161J**  
Make & Model: BMW 428i, 2.0 Gran Coupe (F36) (A) Engine No: B1150861N20B20A  
Reg. Date: 01/08/2014 (Man. Year: 2014) Chassis No: WBA3N32000K239059  
Colour: White Odometer: 61690 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: S\$150,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,405.63	6,199.33	206.30	3.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,801.00	14,438.00	2,363.00	14.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,206.63</b>	<b>20,637.33</b>	<b>2,569.30</b>	<b>11.07</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,206.63</b>	<b>19,637.33</b>	<b>2,569.30</b>	<b>11.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,554.46</b>	<b>1,374.61</b>	<b>179.85</b>	<b>11.57</b>
<b>Nett Amount (S\$)</b>	<b>23,761.09</b>	<b>21,011.94</b>	<b>2,749.15</b>	<b>11.57</b>

### INSPECTION

Date of Assignment: 29/11/2017  
Date Inspected: 04/12/2017 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941  
Estimated Period of Repair: 10.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
<b>Parts:</b> 143	BMW 428i 2.0 Gran Coupe (F36) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKP3161J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM 8.5X19 M DOUBLE SP	Cut	1,608.60 FS	*1,608.60 FS
3	1		*HUB CAP WITH CHROME EDGE (BMW)	Necessary	23.75 FS	*23.75 FS
4	1		*REAR RH FENDER	Bent	1,487.45 FS	*1,487.45 FS
5	10		*BUMPER RIVET	Necessary	5.00 FS	*5.00 FS
6	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	46.90 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Deformed	1,233.50 FS	*1,233.50 FS
8	5		*PLASTIC NUT	Necessary	4.25 FS	*4.25 FS
9	1		*SIDE WINDOW FIXED REAR RH	Necessary	360.80 FS	*360.80 FS
10	1		*RR RH WHEEL HOUSING COVER	Not Necessary	140.95 FS	*- FS
11	10		*EXPANDING NUT	Necessary	5.50 FS	*5.50 FS
12	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
13	1		*BLIND RIVET AVIBVLB (15PCS)	Necessary	11.00 FS	*11.00 FS
14	5		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
15	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
16	5		*PUNCH RIVET N5	Necessary	5.50 FS	*5.50 FS
17	1		*PUNCH RIVET N4 (30 PCS)	Necessary	22.00 FS	*22.00 FS
18	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
19	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
20	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
21	1		*(DG/SL) GLASS PRIMER 30ML (VP 206)	Necessary	27.85 FS	*27.85 FS
22	3		*(S/L) SEAM SEAL 300ML	Necessary	101.40 FS	*101.40 FS
23	2		*SNAP LOCK COUPLING	Necessary	7.10 FS	*7.10 FS
24	1		*TRIM PANEL BUMPER REAR BOTTOM (M)	Deformed	207.30 FS	*207.30 FS
25	2		*BLIND RIVET NUT	Necessary	7.80 FS	*7.80 FS
26	1		*TYPE IDENTIFICATION PLATE (CODED)	Necessary	27.90 FS	*27.90 FS
27	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
28	1		*3M S/F PREMIUM REAR SIDE DOOR	Necessary	210.28 FS	*210.28 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>6,405.63</b>	<b>6,199.33</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE OLD PDC ASSEMBLY AND RECONNECT TO NEW BUMPER INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION	New	150.00	150.00
2	TO REPLACE REAR BUMPER & ATTACHMENTS ,REAR RIGHT FENDER INCLUDING TO KNOCK OUT REAR RIGHT WHEEL HOUSE AND DENTED AREA CAUSED BY THE ACCIDENT	New	6,800.00	5,950.00
3	TO RESPRAY REAR BUMPER ,REAR RIGHT FENDER ,RIGHT ROOF FRAME RIGHT RUNNING BOARD PANEL & COVER ,TAIL PANEL AND BOOT COMPARTMENT	New	5,297.00	4,767.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
5	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	231.00
7	TO REPLACE REAR SIDE WINDOW GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	413.00	413.00
8	TO SUPPLY AND INSTALL REAR RIGHT SIDE WINDOW GLASS SOLAR FILM	New	425.00	0.00
9	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	New	531.00	451.00
10	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING CONDUCT CHECKS FOR LEAK	New	531.00	451.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	451.00
12	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
13	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	301.00
Gross Labour Cost (S\$)			<b>16,801.00</b>	<b>14,438.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;