

ASS. REC. BY:

Surveyor:

(WS)

ASSIGNMENT (Office)

From (Person): Joanne Yong of FCI Date/Time: 9:30am 30/11

Estimated Cost: Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGY 78704 Insured: SHC 8097H

at Workshop m/s Wearnes Automotive Tel: 91768543

of 249 Alexandra Road

Policy No: Claim No: D17011049MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 27/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 9:34am @ 30/11/17 Person Contacted: Richmond Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SGY 78704-X
	SHC 8097H-CC3/CTI17003557/H1ub3q2-D.O.A.: 18/02/2017
	Part by part \$6224.12. (Red: 8490.58 : 57%)

355



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022767/R1tb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-11-2017



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SHC 8097H	Veh. Inspected	SGY 7870U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D17011049MFSH	Excess (\$)	0.00
	Assign From	CWS (JOANNE YONG)	Assign Date	30/11/2017

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.

Accident Date 27/11/2017 Inspection Date

Survey held at WEARNES AUTOMOTIVE PTE LTD
249 ALEXANDRA ROAD
SINGAPORE 159935

Remarks

5a.

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-11-2017	Our Ref No. D17011049MFSH
Accident Date	27-11-2017	Claim Type. Third Party
Insured Vehicle	SHC8097H	Third Party Vehicle. SGY7870U
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	RICHMOND HO	
Contact No.	64304890/ 91768543	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231222)



PRI Documents



Close X

PRI Header Details

Claim No	D17011049MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : RICHMOND HO)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 91768543 , Phone: 64304890 , Fax: 0 EmailId: RICHMOND.HO@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8097H	TP Vehicle No	SGY7870U
PRI Recieved Date	29-11-2017 08:27:00 PM	Surveyor Appointed Date	30-11-2017 09:28:56 AM	Surveyor Accept Date	30-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7970755D



Name

JOYCE LEE WING KEI
(LI YONGQI)

李詠琪

Race

CHINESE

Date of birth

08-03-1979

Country of birth

HONG KONG

Sex

F

S7970755D

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7970755D

Name

JOYCE LEE WING KEI
(JOYCE LI YONGQI)

Birth Date: 08 Mar 1979

Issue Date: 12 Jun 2006



4376157

NRIC No. S7970755D



Date of issue

25-03-2009

825 BUKIT TIMAH ROAD #04-12
SINGAPORE 589640


NRIC No: S7970755D

Date: 03/10/2016 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 12 Jun 2006



Licence No: S7970755D

SERVICE ESTIMATE

73753 - 000001 SL: SERVICE SALES - PC

Ms Joyce Lee Wing Kei
925 Bukit Timah Road
#04-12

Singapore 589640

Closed by : Richmond Ho

Svc Consultant :

Remarks : Ms Joyce Lee Wing Ke

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 29/11/2017

WIP No. . : 31603

Veh.In/Out: 27/11/2017

*Tel.No. . : Mobile: 98208096

Reg.No. . : SGY7870U

Reg.date . : 31/08/2017

Mileage .. : 0

Chassis No: SALCA2ANXHH716166

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802 TO REPLACE FRONT BUMPER,FRT
BRACKET,FRT RH FENDER,FRT
RH WHEEL TRIM,ETC

0

4800.00 0

~~4,800.00~~ S 1800 ✓

800 TO PUTTY SPRAY PAINT ON FRT
BUMPER,FRT RH FENDER,ETC

0

3000.00 0

~~3,000.00~~ S 2000 ✓

0031 TO REPLACE FRONT RH RIM

0

50.00 0

50.00 S ✓

576501 COMPUTERISED WHEEL ALIGNMENT

0

280.00 0

280.00 S ✓

280 TO CHECK WIRING INCLUDE

0

486.00 0

486.00 S ✓

RESETTING OF ALL ELECTRICAL
MODULES

LLR068323/BUMPER COV

1.0 EA

2126.90

2,126.90 S R

BRACKET - BUMPER MOU

1.0 EA

71.10

71.10 S X nn

BRACKET - BUMPER MOU

1.0 EA

71.10

71.10 S X nn

MOULDING - FRONT WHE

1.0 EA

233.20 177.60

233.20 S R

FENDER FRT RH DSPORT

1.0 EA

1117.40

1,117.40 S R

MOULDING - FRONT WHE

1.0 EA

233.20

233.20 S X repaired

DEFLECTOR - AIR

1.0 EA

72.10

72.10 S X nn

SERVICE ESTIMATE

73753 - C00001 SL: SERVICE SALES - PC

Ms Joyce Lee Wing Kei

925 Bukit Timah Road

#04-12

Singapore 589640

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 29/11/2017

WIP No. . : 31603

Veh.In/Out: 27/11/2017

*Tel.No. . : Mobile: 98208096

Reg.No. . : SGY7870U

Reg.date. : 31/08/2017

Mileage . : 0

Chassis No: SALCA2ANXHH716166

Closed by : Richmond Ho

Svc Consultant :

Remarks : Ms Joyce Lee Wing Kei

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

ADHESIVE SEALER FL2

1.0 EA 425.40

425.40 S ~~X~~ ⁿⁿ

ALLOY WHEEL STYLE 52

1.0 EA 1748.30

1,748.30 S ~~30~~ ^{1430.46}

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Resue
Up 90010068
4 days
26/12/17 @ 1230
Resy 64 part

Labour Total	8,616.00
Parts Total	6,098.70
Package Total	0.00

Gross Total. 14,714.70

Net..... 14,714.70

GST @ 7.0% 1,030.03

Total..... 15,744.75

Paid..... 0.00

Please Pay.. 15,744.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
 Inv.date. : 19/01/2018
 WIP No. . : 31603
 Veh.In/Out: 26/12/2017 30/12/2017
 *Tel.No. . :
 Reg.No. . : SGY7870U
 Reg.date . : 31/08/2017
 Mileage .. : 4,617
 Chassis No: SALCA2ANXHH716166

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Ms Joyce Lee Wing Ke

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPAIR FRT BUMPER,	0	1800.00	0		1,800.00	S
	RHF FENDER, ETC						
800	TO PUTTY SPRAY PAINT ON FRT	0	2000.00	0		2,000.00	S
	BUMPER, FRT RH FENDER, ETC						
0031	TO REPLACE FRONT RH RIM	0	50.00	0		50.00	S
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
419	COMPUTERISED 4-WHEEL ALIGNMENT	0	280.00	0		280.00	S
	MOULDING - FRONT WHEEL	1.0 EA	197.40	10		177.66	S
	ALLOY WHEEL STYLE 52	1.0 EA	1589.40	10		1,430.46	S

Labour Total 4,616.00
 Parts Total 1,608.12
 Package Total 0.00

Gross Total. 6,224.12
 Net..... 6,224.12
 GST @ 7.0% 435.69
 Total..... 6,659.81
 Paid..... 0.00
 Please Pay.. 6,659.81

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022767/R1tbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8097H	Veh. Inspected	SGY 7870U
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17011049MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	LAND ROVER DISCOVERY SP 2.0	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SALCA2ANXHH716166	Colour	BLUE
Odometer	4517	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	PIRELLI	6 mm
L/H Front Tyre	235/55 R19	PIRELLI	6 mm
R/H Rear Tyre	235/55 R19	PIRELLI	6 mm
L/H Rear Tyre	235/55 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/11/2017	Inspection Date	26/12/2017
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 7870U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LLR068323/BUMPER COV (SN)	TO REPAIR SEE LABOUR	2,126.90	-
1	BRACKET-BUMPER MOU (SN)	NOT NECESSARY	71.10	-
1	BRACKET-BUMPER MOU (SN)	NOT NECESSARY	71.10	-
1	MOULDING-FRONT WHE (SN)	SCRATCHED	233.20	177.66
1	FENDER FRT RH DSPORT (SN)	TO REPAIR SEE LABOUR	1,117.40	-
1	MOULDING-FRONT WHE (SN)	REPEATED	233.20	-
1	DEFLECTOR-AIR (SN)	NOT NECESSARY	72.10	-
1	ADHESIVE SEALER FL2 (SN)	NOT NECESSARY	425.40	-
1	ALLOY WHEEL STYLE 52 (SN)	SCRATCHED	1,748.30	1,430.46
			6,098.70	1,608.12
LABOUR				
	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT RH FENDER,FRT RH WHEEL TRIM,ETC.INCLUSIVE OF THE REPAIR OF LLR068323/BUMPER COV AND FENDER FRT RH DSPORT.		4,800.00	1,800.00
	TO PUTTY SPRAY PAINT ON FRT BUMPER,FRT RH FENDER,ETC.		3,000.00	2,000.00
	TO REPLACE FRONT RH RIM.		50.00	50.00
	COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		486.00	486.00
			8,616.00	4,616.00
GRAND TOTAL			14,714.70	6,224.12
RECOMMENDED COST OF REPAIRS				6,224.12

Report Ref No. CS/FCI17022767/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.