

VEHICLE NO : JRX 1558

Yamaha FZ 150i

Nett items

- 1 Towing fee
- 2 Rear box
- 3 Front number plate
- 4 Labour to remove & replace fork tube
& repress front rim
- 5 Remove & replace parts, align & etc
- 6 Putty & respray paint

40.00 ✓
~~230.00~~ 150.00 ✓
~~15.00~~ 50.00 ✓ 10
~~180.00~~ 100
250.00 150
~~280.00~~ 180

Sub-Total

995.00 630

Nett Total

3,279.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you


SG 98 MOTOR PTE LTD

1.G

Passu
Hp 9000068
3 days
4/8
01/12/17 @ 1130

1791
630
2421
209
1936.80

4/5-1,900
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: