

ASS. REC. BY:

REF: CS/FCI17022769/R1vb02 Special Instructions:

Surveyor: Rasul ASSIGNMENT (Office)CW's From (Person): Sithara of FCI Date/Time: 5:38pm @ 29/11/17

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JRX 1558 Insured: SHB 3282Cat Workshop m/s SG 98 Motor Tel: 64524898of Blk 4001 AMK Ind. Prk 1 #01-21Policy No: Claim No: D17 011067 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 27/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 8:52am @ 30/11/17 Person Contacted: Rose Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	JRX 1558 - X
	SHB 3282C - NS/INC16066704/H19h3c2-D.O.A 21/04/2016
4/12/17	Email FCI informed pending est from repairer
12/4/18	LS \$1900 confirmed by email (Fed 1379.20, 429)
13/4/18	Email preli revised to FCI

b/y

Pgme

REF: FCI

ASSIGNMENT

From: _____ Date: **01/12/2017**

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **JRX 1558**

at Workshop/mis: **SG 98 Motor**

of **Bik 4001 AMK Ind. Park 1#01-21**

Insured _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value _____

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days: Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **'wpr'**

Vehicle: IN / OUT

Date: _____ Person Contacted _____

Date / Time Action / Instruction

Veh No: **JRX 1558** Yr Regn: **2017 JAN**

Type: M/Car ☒ Cycle Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **YAMAHA FZ150 I GS** cc: **150**

Colour: **BLUE** A/C: ☐ Insured: ☐ Std: ☐ Nil / NA

Sd Reading: **31330** T-Radio: ☐ Insured: ☐ Std: ☐ Nil / NA

Eng No: _____

C No: **PMYR6341090009223**

Genl Cond: Good ☒ Fair ☐ Poor ☐ Burnt ☐

Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Mod: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: **90/80-17**

R: **120/70-17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **MAXXIS**

Front

Rear

R/Bal: **3** mm R/Bal: **3** mm

L/Bal: mm L/Bal: mm

D.O.A: **27/11/17** D.O.I: **01/12/17**

Survey held at **SG 98 motor**

Des. of Damages ☒ Frn ☐ Rear ☐ O/S ☒ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 17 APR 2018

Date/Time File Pass to: ☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

17/4- typist

Report Format: **CWS**

Lump Sum / I.B: **1900/-**

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp: **5**

☐ Inter. Insp: **5**

☐ Tech. Insp: **5**

☐ Pres. Insp: **5**

Survey Fee

Parachute

130

50

50

80

310

Survey Department Check List (Case Handler)

Reference No. : CS / fcs 17022769 / RMB
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022769/R1vb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-11-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3282C	Veh. Inspected	JRX 1558	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011067MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	30/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/11/2017	Inspection Date	30/11/2017	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Job Sheet (/ClaimWS/Surveyor/JobSheet/231239)



PRI Documents



Close X

PRI Header Details

Claim No	D17011067MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & SG 98 MO
Workshop Name	SG 98 MOTOR PTE LTD (Contact Person : LEENA)	Survey Location & Contact Details	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Mobile: 91711655 , Phone: 64524898 , Fax: 64524866 EmailId: SGMOTOR2000@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3282C	TP Vehicle No	JRX1558
PRI Recieved Date	29-11-2017 05:55:06 PM	Surveyor Appointed Date	29-11-2017 05:37:17 PM	Surveyor Accept Date	30-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001876-9

MOTOR SURVEY ASSIGNMENT

Date	29-11-2017	Our Ref No.	D17011067MFSH
Accident Date	27-11-2017	Claim Type.	Third Party
Insured Vehicle	SHB3282C	Third Party Vehicle.	JRX1558
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21		
Contact Person.	LEENA		
Contact No.	64524898/ 91711655	Fax No.	64524868
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 April 2018 10:49 AM
To: 'Claim Workflow System'
Cc: 'SITHARA@FIRST-INSURANCE.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D17011067MFSH/1, JRX 1558
Attachments: JRX 1558 PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle JRX 1558
Date of survey: 1/12/2017
Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 4 December 2017 8:28 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011067MFSH/1, JRX 1558

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JRX 1558 on 1/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 30 November, 2017 9:05 AM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011067MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 29 November, 2017 5:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011067MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011067MFSH
Our Ref: CS/FCI17022769/R1vb

Date : 13/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. JRX 1558

We thank you for your instruction on 29/11/2017

Please be informed that we had conducted the inspection of the above mentioned
1/12/2017 at the premises of M/s SG 98 MOTOR PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$3,279.20
Revised Estimate Amount	: S\$1,900.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the
front portion and n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 4 December, 2017 8:28 AM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011067MFSH/1, JRX 1558

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JRX 1558 on 1/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 30 November, 2017 9:05 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011067MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 29 November, 2017 5:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011067MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Thursday, 5 April 2018 12:43 PM
To: Rasul (LKKAUTO); Veron Chen (LKKAUTO)
Cc: Sg Motor
Subject: Re: Please finalize the bike JRX 1558

Dear Veron / Rasul

Please finalize the bike JRX 1558.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 13 March 2018, 11:38:14 AM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Veron / Rasul

Please finalize the bike JRX 1558.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Thursday, 22 February 2018, 12:04:03 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Veron / Rasul

Please finalize the bike JRX 1558.

Thank You

Regards

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Wednesday, 31 January 2018, 1:40:26 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Veron / Rasul

Please finalize the bike JRX 1558.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 16 January 2018, 4:48:38 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Veron/Rasul

Please finalize bike JRX 1558

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Thursday, 28 December 2017, 4:01:24 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Veron/Rasul

Please finalize bike JRX 1558

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622

Tel: 64524898 Fax: 64526898

On Tuesday, 19 December 2017, 12:05:49 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul / Veron

Please finalize the bike JRX 1558

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 12 December 2017, 5:29:36 PM GMT+8, Jas Khine (LKKAUTO) <jaskhine@lkkauto.com> wrote:

Dear Linda,

Thank you for your email below.

We will look into the matter and follow up with our surveyor for finalisation COR.

Dear All,

Kindly follow up the matter and chase Rasul to finalise Cost of repair with TP repairer.

No.	Bike No	Date of accident	Surveyor	LKK Ref	Handler
1	FBL 4812K	22/11/2017	Rasul	CS/FCI17022646/R1qb	Shiau Chan
2	FBH 3577S	20/10/2017	Rasul	CC4/AXA17020519/R1pb3	Hsiao Tong
3	JSG 4476	10/11/2017	Rasul	CS/GAI17021163/R1qb	Shiau Chan
4	JRX 1558	27/11/2017	Rasul	CS/FCI17022769/R1vb	Veron
5	FBF 6275D	9/9/2017	Rasul	CC4/AIG17019111/R1ub3	Thin Thin
6	FR 6978Z	27/2/2017	Rasul	CS/FCI17004320/R1vb	Veron
7	FBC 7183U	3/3/2017	Rasul	CS/MSG17004799/R1gh3	Ai Phing
8	JSD 9479	8/7/2017	Rasul	CS/UOI17015769/R1vb	Veron
9	BMQ 1521	30/10/2017	Rasul	CS/MSG17022107/R1tb	Denise

10	JRN 4031	11/7/2017	Rasul	CC4/III17021773/R1ua3	Thin Thin
11	FT 7921U	29/11/2017	Rasul	CC4/LCR17023276/R1za3	Zayer
12	FT 8184Z	30/11/2017	Rasul	CC4/AIG17023304/R1ua3	Thin Thin

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor [mailto:sgmotor2000@yahoo.com.sg]

Sent: Tuesday, 12 December, 2017 4:28 PM

To: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>

Subject: Please finalize the following bikes

Dear Jas/Rasul

Please finalize the bikes as per attached.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

0JRPUA15

No. Pendaftaran : JRX1558
No. ID : 831202135315
Nama Pemunya Berdaftar : CHUA TZE KENT
Alamat : NO 38 JALAN SERI ORKID 26 TAMAN SERI ORKID
81300 SKUDAI JOHOR

No. Chasis/No. Enjin : PMYR034100009223 / 030GE-0009212
Buatan/Nama Model : YAMAHA / FZ150I(S)
Keupayaan Enjin : 150
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2016
Tarikh Pendaftaran : 02/01/2017
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

LESEN KENDERAAN MOTOR

ROAD TRANSPORT ACT 1987 (MOTOR VEHICLES (REGISTRATION AND LICENSING) RULES 1987)

MOTOSIKAL No. SRI: AE 040359

01 JAN 2018

JRX1558

024233 02012017

JRX1558

RM2.00

0101011 WATI 01012018

150 SP AA 2201000

0101011

0101 : 017017JEL000059

0102 :

VRL0204

LESEN KENDERAAN MOTOR (MOTOR VEHICLE LICENSING) CAP MESIN PENERBITAN JABATAN PENGANGKUTAN JALAN



SINGAPORE POLICE FORCE



T/20171127/2040

1 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20171127/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/11/2017 12:19		Vide Report No.:		Station Diary No.: 65	
Informant's Particulars					
Name of Informant: CHUA TZE KENT			Address:		
ID Type / ID No.: FIN NO / G7829879R			Contact No.: Home/Office: Mobile: 82627642		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 33	Date of Birth: 02/12/1983	Type of Informant: Rider		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Storekeeper		Driving Licence Information: Class: 2B Date of Expiry:			

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 27/11/2017 07:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Towards Changi, after Ang Neo				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRX1558	Motorcycle				Slightly Damaged	0
SHB3282C	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20171127/2040

2 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Report No. T/20171127/2040

Rider			
Name	CHUA TZE KENT	ID No.	G7829879R
Related Vehicle	JRX1558 (Motorcycle)	Contact No.	82627642
Hospital/Clinic	HORIZON MECIDAL PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	27/11/2017	Date Discharge	27/11/2017
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

I am making amendments to my Traffic Report vide T/201127/2032.

On 27/11/2017, at about 0730hrs, I was riding my motorcycle bearing registration number JRX1558 along PIE towards Changi. I was riding on the second lane from the right when taxi bearing registration number SHB3282C, from the first lane, abruptly came into my lane without signaling. I immediately pressed on my brakes, causing my motorcycle to skid as such, collided against the rear of the taxi. The taxi driver then stopped his vehicle and alighted to help me up and pushed my motorcycle to the side of the road. Aetos officer arrived at scene a few minutes later. I did not manage to take down the particulars of the taxi driver.

I sustained lacerations on my left leg and my motorcycle was then towed away. No ambulance came to scene and no government property involved. Subsequently, my friend brought me to the clinic for my injury and I was given 7 days MC.



**SINGAPORE
POLICE FORCE**



T/20171127/2040

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 3

Report No. T/20171127/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 SITI NADIA BINTE ROSLI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Signature Of Informant:


Date/Time:

27/11/2017 12:19

Classification Of Case:

Authentication Stamp

NP168



ent on 12/04/18 e 1240

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 8 December 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : JRX 1558

Yamaha FZ 150i

ACCIDENT DATE: 27 November 2017

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Handle Bar	1	195.00	BT ✓
2 Mudguard	1	135.00	SCA ✓
3 Fork Tube	1 set	480.00	R ✓
4 Front LH Side Cover	1	195.00	SCA ✓
5 Front Cowling	1	235.00	SCA ✓
6 Headlamp	1	350.00	CAR ✓
7 LH Signal Lamp	1	85.00	CAR ✓
8 Fuel Tank	1	450.00	BT ✓
9 Rear LH Signal	1	75.00	PRO ✓
10 Gear Pedal	1	75.00	BT ✓
11 Clutch Lever	1	75.00	SCA ✓
12 Gear Shifter	1	68.00	X30 ✓
13 View Mirror	1 set	120.00	PRO ✓
	Sub-Total	2,538.00	1990
	Less 10%	253.80	10%
	Sub-Total	2,284.20	1791

VEHICLE NO : JRX 1558

Yamaha FZ 150i

Nett items

- 1 Towing fee
- 2 Rear box
- 3 Front number plate
- 4 Labour to remove & replace fork tube
& repress front rim
- 5 Remove & replace parts, align & etc
- 6 Putty & respray paint

40.00 ✓
~~230.00~~ 150 scd ✓
~~15.00~~ scd 10
~~180.00~~ 100

~~250.00~~ 150
~~280.00~~ 180

Sub-Total

995.00 630

Nett Total

3,279.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you


SG 98 MOTOR PTE LTD

LG

Rasmi
Hp 9000068

3 days

4/5

01/12/17 @ 1130

1791
630

2421
208
1936.80

4/5-1,900
3 days

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 8 December 2017

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : JRX 1558

Yamaha FZ 150i

ACCIDENT DATE: 27 November 2017

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar	1	195.00 <i>bt</i> ✓
2 Mudguard	1	135.00 <i>scr</i> ✓
3 Fork Tube	1 set	480.00 <i>R</i>
4 Front LH Side Cover	1	195.00 <i>scr</i> ✓
5 Front Cowling	1	235.00 <i>scr</i> ✓
6 Headlamp	1	350.00 <i>CR</i> ✓
7 LH Signal Lamp	1	85.00 <i>ca</i> ✓
8 Fuel Tank	1	450.00 <i>bt</i> ✓
9 Rear LH Signal	1	75.00 <i>scr</i> ✓
10 Gear Pedal	1	75.00 <i>bt</i> ✓
11 Clutch Lever	1	75.00 <i>scr</i> ✓
12 Gear Shifter	1	68.00 <i>bt</i> ✓
13 View Mirror	1 set	120.00 <i>scr</i> ✓
Sub-Total		2,538.00 <i>1990</i>
Less 10%		253.80 <i>10%</i>
Sub-Total		2,284.20 <i>1791</i>

Attn: Mr. Rosul. - 22/4/2018 P. 2/2
 Ok Acceptance, Thank you
 Rosul

VEHICLE NO : JRX 1558

Yamaha FZ 150i

Nett items

- 1 Towing fee
- 2 Rear box
- 3 Front number plate
- 4 Labour to remove & replace fork tube & repress front rim
- 5 Remove & replace parts, align & etc
- 6 Putty & respray paint

40.00 ✓
~~230.00~~ 150.00 ✓
~~15.00~~ 10.00 ✓
~~180.00~~ 100.00 ✓
~~250.00~~ 150.00 ✓
~~280.00~~ 180.00 ✓

Sub-Total

995.00 630

Nett Total

3,279.20

NR: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
 Thank you


 SG 98 MOTOR PTE LTD

16

Rosul
 Hp 90000000
 3 days
 4/3
 01/12/17 @ 1130

1791
 630
 2421
 202

(1936.80)

OK

4/3-1,900

Acceptance.

3 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022769/R1vbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 24-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3282C	Veh. Inspected	JRX 1558
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17011067MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ150I (S)	c.c	150
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMYRG3410G0009223	Colour	BLUE
Odometer	31330	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	MAXXIS	3 mm
L/H Rear Tyre			mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	27/11/2017	Inspection Date	01/12/2017
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. RemarksA) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRX 1558

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	195.00	195.00
1	MUDGUARD	SCRATCHED	135.00	135.00
1	SET FORK TUBE	TO REPAIR SEE LABOUR	480.00	-
1	FRONT LH SIDE COVER	SCRATCHED	195.00	195.00
1	FRONT COWLING	SCRATCHED	235.00	235.00
1	HEADLAMP	CRACKED	350.00	350.00
1	LH SIGNAL LAMP	CRACKED	85.00	85.00
1	FUEL TANK	BENT	450.00	450.00
1	REAR LH SIGNAL	BROKEN	75.00	75.00
1	GEAR PEDAL	BENT	75.00	75.00
1	CLUTCH LEVER	SCRATCHED	75.00	75.00
1	GEAR SHIFTER	SERVICEABLE	68.00	-
1	SET VIEW MIRROR	BROKEN	120.00	120.00
	LESS 10% DISCOUNT		-253.80	-199.00
			2,284.20	1,791.00
SPECIAL NETT ITEMS				
1	REAR BOX (SN)	SCRATCHED	230.00	150.00
1	FRONT NUMBER PLATE (SN)	SCRATCHED	15.00	10.00
			245.00	160.00
LABOUR				
	TOWING FEE.		40.00	40.00
	LABOUR TO REMOVE & REPLACE FORK TUBE & REPRESS FRONT RIM. INCLUSIVE OF THE REPAIR OF FORK TUBE		180.00	100.00
	REMOVE & REPLACE PARTS, ALIGN & ETC.		250.00	150.00
	PUTTY & RESPRAY PAINT.		280.00	180.00
			750.00	470.00
GRAND TOTAL			3,279.20	2,421.00

Report Ref No. CS/FCI17022769/R1vbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	----------

Report Ref No. CS/FCI17022769/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.