

REF:

NS/INC17022716 / Sub 22

ASSIGNMENT

From:

Date:

Veh No:

51B5288Z

Yr Regn:

5/3/2014

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Prius

C.C

1798

at Workshop m/s

Colour

Maroon

A/C:

Insured / Std / NI / NA

of

Sp. Reading

38/667

T/Radio:

Insured / Std / NI / NA

Insured:

PC 5447G

Eng/No:

Policy No.

50931811587

05082017

C/No:

JTDKN 364 305221308

Claims No.

MT/0971608-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi:

Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

5

mm

Est. Repairs:

days

Res.:

Yes or No

D.O.A.

28/11/2017

D.O.I.

2/11/2017

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

SMART

CA / REV / REP. / 24 HRS

Des. of Damages (Frnt) / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

51B 5288Z - 003/ATG 14011353 / Kmy3w2

DOA: 150614 TAX/11/17/2173

PC 5447G - X

LKR.

NIR.

11/12/17 Sebastian confirmed LS \$1600 (Red 8685.60, 847)

RECEIVED 12 DEC 2017

RECEIVED 10 DEC 2017

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

3

1)

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Date/Time, File Return to?

2) 12/12 - typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

1600p

TOTAL

160
35
195

Survey Department Check List (Case Handler)

Reference No. : NS/ INC17022776/ SvB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/12/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022776/Svb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 30-11-2017

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 5447G	Veh. Inspected	SHB 5288Z
Policy No.	5093184587	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/11/2017	Inspection Date	29/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Time of Accident	Estimate	Tentative repair cost
1	MT/0971003-002	SMRT TAXIS PTE LTD	SHB 5289X	SLL 2472C	20/11/2017	14:40	\$24,786.78	\$10,550.00
2	MT/0973267-001	SMRT TAXIS PTE LTD	SHB 268P	FT 9299U	1/12/2017	9:05	\$4,341.40	\$1,100.00
3	MT/0972092-002	SMRT TAXIS PTE LTD	SHF 179S	SGS 4228B	3/12/2017	3:10	\$4,339.88	\$1,700.00
4	MT/0973271-001	SMRT TAXIS PTE LTD	SHB 5239R	FE 1205Y	5/12/2017	9:50	\$389.50	\$80.00
5	MT/0971608-002	SMRT TAXIS PTE LTD	SHB 5288Z	PC 5447G	28/11/2017	13:15	\$10,285.60	\$1,600.00
6	MT/0972214-003	COMFORT TRANSPORTATION PTE LTD	SHC 3205X	SJE 2792P	4/12/2017	8:35	\$5,053.62	\$2,900.00

Claim received from LKK

eBaoTech

General/Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="28/11/2017 13:19"/>						
Vehicle No. (For Motor)	<input type="text" value="PC5447G"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5093184587	EMPEROR INTERNATIONAL TRAVEL PTE LTD	201502886W	GFT	Comprehensive	PC5447G	PC5447G	05/08/2017	
<input type="button" value="Continue"/>									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	5369K
Vehicle Details	
Vehicle No.	SHB5288Z
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2013
Engine No.	2ZR5937067
Chassis No.	JTDKN36U305721308
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$33,120.00
Original Registration Date	05 Mar 2014
First Registration Date	05 Mar 2014
Transfer Count	0
Actual ARF Paid	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	04 Mar 2022
PARF Rebate Amount	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date	04 Mar 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$58,745.00
COE Rebate Amount	\$31,287.00
Total Rebate Amount	\$37,563.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Nov 2017



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/11/2017 14:57
Date Of Accident	28/11/2017 13:15
Exact Location Of Accident	SHORT STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5288Z
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	LEONG SOON WEI JOHNNY
NRIC No	S7319794E
Date Of Birth	11/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	03/07/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY TAXI WAS STATIONARY BEHIND THE BUS PC5447G AND I WAS WAITING FOR MY PASSENGER. SUDDENLY THE BUS PC5447G ENGAGED REVERSE GEAR AND STARTED TO REVERSE. IMMEDIATELY I SOUNDED MY HORN TRY TO ALERT THE BUS. HOWEVER, THE BUS CONTINUE REVERSING AND COLLIDED ONTO THE FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC5447G
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver TUA KIM FOOK
 NRIC/Passport Number G7694589L
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


[illegible]

I/We declare the foregoing particulars are true in every respect.

Driver's Signature _____

John 28/11/2017

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



SMRT Accident Vehicle Repair Estimates

NTUC

C-11A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5288Z
 Ref. No : TAX/11/17/2173
 Reg. Date : 05/03/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LEONG SOON WEI JOHNNY
 Type of Accident : OTHERS
 Date / Time of Accident : 28/11/2017 01:17:00 PM
 Accident Reported Date / Time : 28/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093340
 Special Instruction to ARC, if any :
 PC5447G
 Prepared Date : 28/11/2017 03:20:11 PM



Sebastian.
 29/11/2017.
 - Lump Sum Repair
 - Question Mark Item
 Photo.
 - Photo After Paint.
 30/11/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5721308

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,872.00	0.00
Total Material Charges	: 3,641.30	4,509.38
Other Charges	: 440.00	0.00
TOTAL	: 6,798.30	0.00
Lum Sum Total	: 6,800.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 28/11/2017 06:03:05 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/11/2017 06:01:55 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 X
TO RESPRAY ARM , FR WIPER , RH	180.00	0.00 X
Total Spray Painting & Panel Beating	1,872.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 X
Total Other Costs	440.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No
85211-47100			ARM, FR WIPER, RH	1	296.80	25.00	222.60	Replace	Replace	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Repair	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Repair	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
TOTAL MATERIALS								4,551.66	5,636.72	
TOTAL MATERIALS(Discounted)								3,641.30	4,509.38	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

chia


2-12-17/10:44


2-12-17/14:44

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5288Z
Ref. No : TAX/11/17/2173
Reg. Date : 05/03/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LEONG SOON WEI JOHNNY
Type of Accident : OTHERS
Date / Time of Accident : 28/11/2017 01:17:00 PM
Accident Reported Date / Time : 28/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093340
Special Instruction to ARC, if any :
PC5447G - NTUC IDAC
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email :sebastianyeang @lkkauto.com HP:90036121
LUMPSUM REPAIR
Prepared Date : 28/11/2017 03:20:11 PM



E  F
KM 381665

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

28-11-17

2nd witness

Date

Vehicle to Wega Date In: 30/11/17 Towing:

Time In: 1155

Driver:

Wega Job No: 13982/11

Vehicle sent to SMRT Date In: 2/12/17

Time In: 0940

Driver:

Received by (SMRT):

2/12/17 10:55 Reject 11:30pm

ATTN: Good August

Attached
Supplementary

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5721308

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	845.00		400.00
Total Spray Painting Charges	:	1,872.00		700.00
Total Material Charges	:	1,805.64		860.38
Other Charges	:	440.00		-360.38
TOTAL	:	4,962.64	10,285.60	1,600.00
Lum Sum Total	:	0.00		0.00
No. of Repair Days	:	5.00		3.00
Prepared / Adjusted By	:			SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	:	28/11/2017 06:03:05 AM		29/11/2017 02:44:44 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/11/2017 06:01:55 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0124

Invoice No :

Quotation Date : 5/12

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	400.00 /
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00 /
TO REPSRAY FRONT HOOD	378.00	200.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
TO RESPRAY FRONT FENDER RH	378.00	0.00
TO RESPRAY ARM , FR WIPER , RH	180.00	0.00
Total Spray Painting & Panel Beating	1,872.00	700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-380.38
Total Other Costs	440.00	-360.38

10285-60

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No <i>R</i>
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No <i>✓</i> <i>NAC</i>
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Check	No <i>X</i> <i>NN</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>✓</i> <i>BT</i>
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No <i>X</i> <i>NN</i>
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No <i>✓</i> <i>DT</i>
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace	No <i>✓</i> <i>Jm</i>
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.93	Replace	Replace <i>S</i>	No <i>✓</i> <i>BT</i>
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.93	Replace	Replace <i>S</i>	No <i>✓</i> <i>NN</i>
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.63	Replace	Check	No <i>X</i> <i>NN</i>
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	100.00	0.00	Replace	Repair	No <i>R</i>
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Check	No <i>X</i> <i>NN</i>
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Check	No <i>X</i> <i>NN</i>
85211-47100			ARM, FR WIPER, RH	0	296.80	25.00	0.00	Replace	Not given	No <i>X</i> <i>NN</i>
53802-47050		6505558	FENDER FRT/LH	1	723.40	100.00	0.00	Repair	Repair	No <i>R</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓</i> <i>NEC</i>
53801-47050		6505557	FENDER FRT/RH	0	723.40	25.00	0.00	Repair	Not given	No <i>X</i> <i>NN</i>
75374-47051			NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No <i>X</i> <i>NN</i>
TOTAL MATERIALS							2,821.34	860.38		
TOTAL MATERIALS(Discounted)							1,805.64	860.38		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 860.37 \\
 + 400.00 \\
 + 720.00 \\
 \hline
 1980.37 \\
 - 207 \\
 \hline
 1584.30
 \end{array}$$

45 \$1600/-

Sebastian
11/12/2017



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022776/Svbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 08-01-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 5447G	Veh. Inspected	SHB 5288Z
Policy No.	5093184587	Coverage (\$)	0.00
Claim No.	MT/0971608-002	Excess (\$)	0.00
Assign From		Assign Date	29/11/2017
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305721308	Colour	MAROON
Odometer	381667	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/11/2017	Inspection Date	29/11/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5288Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.87
1	HOOD PANEL (DISC 25%)	DENTED	748.10	561.07
1	HOOD LOCK (DISC 25%)	JAMMED	128.90	96.67
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.93
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.93
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	NUMBER PLATE FRAME	NOT NECESSARY	12.00	-
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
1	ARM, FR WIPER, RH	NOT NECESSARY	296.80	-
1	FENDER FRT / RH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	BUMPER FRT	TO REPAIR	482.00	-
1	SUPPORT SUB-ASSY	TO REPAIR	1,460.40	-
1	FENDER FRT/LH	TO REPAIR	723.40	-
			7,128.60	860.39
<u>LABOUR</u>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		925.00	400.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		2,072.00	700.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,157.00	1,120.00
GRAND TOTAL			10,285.60	1,980.39
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. NS/INC17022776/Svbe2

Report Ref No. NS/INC17022776/Svbe2

YEANG WAI KEEN
Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.