

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5023R - EQ**AAD1711-278***Not Authorized
L1 Sing @ 7750*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5023R - JHOW

VF1ABL15AUC275203

RENAULT

LATITUDE

25.11.2017

EQ**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Pu</i> 1,259.42 X
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
5	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
6	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
7	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.22
8	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 151.41
9	1	BUMPER BRACKET FRT RH	\$	<i>Sn</i> 181.75 X
10	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
11	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
12	1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83
13	1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
14	1	FENDER BRACKET FRT RH	\$	<i>Sn</i> 34.14
15	1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
16	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,707.78
17	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 173.36
18	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
19	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
20	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
21	1	BONNET	\$	<i>R</i> 1,941.63
22	1	DOOR MIRROR RH	\$	<i>CM</i> 1,483.40 ✓
23	1	DOOR MIRROR GLASS RH	\$	242.33 X
24	1	DOOR MIRROR BACK COVER RH	\$	218.46 X
25	1	DOOR MIRROR LAMP RH	\$	194.18 X
26	1	DOOR PANEL FRT RH	\$	<i>B</i> 2,844.66 ✓
27	1	DOOR FRAME PANEL FRT RH	\$	<i>NSP</i> 5,550.98 X
28	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50 X
29	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55 X
30	1	DOOR CHECK FRT RH	\$	<i>Sn</i> 194.77 X
31	1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75 X
32	1	DOOR CATCH FRT RH	\$	<i>Sn</i> 131.23 X
33	1	DOOR GRAB HANDLE FRT RH	\$	<i>Sn</i> 210.96 X
34	1	DOOR HANDLE OUTER FRT RH	\$	<i>R</i> 477.76 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-278**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5023R - EQ

35	1	DOOR HANDLE CAP FRT RH	\$	Sn	35.52	X
36	1	DOOR HANDLE SEAL FRT RH	\$	Sn	7.89	X
37	1	DOOR HANDLE COVER FRT RH	\$	Sn	13.22	X
38	1	DOOR HANDLE MODULE FRT RH	\$	Sn	133.60	X
39	1	DOOR REGULATOR FRT RH	\$	BT	505.19	✓
40	1	DOOR REGULATOR MOTOR FRT RH	\$	TM	796.46	✓
41	1	DOOR REGULATOR GUIDE FRT RH	\$	Sn	120.97	} X
42	1	DOOR FINISHER FRT RH	\$	Sn	515.06	
43	1	DOOR MOULDING FRT RH	\$	Sn	176.82	
44	1	DOOR WHETHERSTRIP FRT RH	\$	Sn	410.27	
45	1	DOOR SEAL LOWER FRT RH	\$	Sn	91.17	
46	1	DOOR SEAL FRT RH	\$	Sn	72.82	
47	1	DOOR GLASS RUNNER SEAL FRT RH	\$	Sn	626.36	
48	1	DOOR WAIST SEAL OUTER FRT RH	\$	Sn	291.27	} X
49	1	ROCKER PANEL OUTER RH	\$	N	987.49	
50	1	DOOR PANEL REAR RH	\$	R	2,844.66	
51	1	DOOR GUIDE REAR RH	\$	Sn	176.82	
52	1	DOOR HINGE UPPER RH	\$	N	274.50	
53	1	DOOR HINGE LOWER	\$	N	300.55	
54	1	DOOR CHECK REAR RH	\$	Sn	203.06	
55	1	DOOR GRAB HANDLE REAR RH	\$	Sn	210.96	} X
56	1	DOOR HANDLE OUTER REAR RH	\$	Sn	126.49	
57	1	DOOR HANDLE CAP REAR RH	\$	Sn	35.52	
58	1	DOOR HANDLE SEAL REAR RH	\$	Sn	7.89	
59	1	DOOR HANDLE COVER REAR RH	\$	Sn	13.22	
60	1	DOOR HANDLE MODULE REAR RH	\$	Sn	133.60	
61	1	DOOR FINISHER REAR RH	\$	Sn	423.10	
62	1	DOOR MOULDING REAR RH	\$	Sn	176.82	} X
63	1	DOOR SEAL REAR RH	\$	Sn	162.02	
64	1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn	334.69	
65	1	FENDER PANEL REAR RH	\$	N	3,299.13	

TOTAL	\$	39,016.05
10%	\$	3,901.61
	\$	35,114.45

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	N	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	N	66.00	X
3	1SET	BUMPER SUPPORT FRT CLIP RH	\$	N	9.80	X
4	1SET	BUMEPR RETAINER FRT CLIP RH	\$	N	12.50	X
5	1	RIM RH FRT	\$	Sn	385.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-278

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5023R - EQ

6	1	TYRE RH FRT	\$	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	80.00	60sm
8	1	DOOR STICKER "Classic"	\$	30.00	15sm
9	1	DOOR STICKER "6555-3333"	\$	80.00	60sm

TOTAL	\$	1,059.30
TOTAL PARTS	\$	36,173.75

To Check Electrical Lighting Concerned.	\$	170.00	200
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	600
Putty and spray painting of the affected portion.	\$	4,500.00	1100
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1200
Towing fees	\$	120.00	X
To rust-proofing of the affected areas.	\$	170.00	600

TOTAL	\$	10,060.00
Over All Total	\$	46,233.75

(PARTS BY PARTS)**Repair Days****15 Days**

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 days