

22/03/2002

ASS. REC. BY:

REF: CG/AGU702789 / Avbn2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Albert Hong of AGU Date/Time: 30-11-2017 2:34pm
 Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 4719Y Insured: STH 5915S

at Workshop m/s 1st Autoworks Tel: _____
 of 23 Kaki Bukit Ave 4 #04-01

Policy No: _____ Claim No: C10001169

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27-11-2017
 (Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 30-11-2017 2:39pm Person Contacted: Ronnie Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 4719Y - x
	STH 5915S - NA / INC 10002540 / 02
	DA: 06/02/2010
11/2/17	Email preli revised to Albert
25/1/18	Adrian confirmed \$ 12,268.30 (Red 15,634.20, 5690)

Signature

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR4719Y Yr Regn: 2017 August
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Chardet Cruze. C.C. 1362
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 3166. T. Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KLJA69896K3549.73.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16.
 R: 205/60R16.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook.
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 30/11/17.
 Survey held at 1st Auto Work.
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TP Budget Direct

RECEIVED 29 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 29/1- typist

Report Format : TP

Lump Sum / I.B.I: (\$) 12,268.30

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) _____

☐ : Interview (\$) _____

☐ : Tech. Insp (\$) _____

☐ : Weekend (\$) _____

Survey Fee: _____

Transaction: _____

1. \$ - RS. \$ _____

Phone: _____

Other: _____

TOTAL

450

Survey Department Check List (Case Handler)

Reference No.: **CS/ AGI 170 22789/ Avb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **29/11/18**
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI17022789/Avb

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 30-11-2017



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 5915S	Veh. Inspected	SLR 4719Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001169	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/11/2017	Inspection Date	30/11/2017
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		

5a. Remarks

--

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 1 December, 2017 2:47 PM
To: 'Albert Hong'
Cc: SUR
Subject: RE: Appoint LKK to conduct TP survey; Our Ref: C10001169, SLR 4719Y
Attachments: SLR 4719Y PRELI ADVISED.pdf

Dear Albert,

Enclosed preliminary revised of vehicle SLR 4719Y
Date of survey: 30/11/2017
Number of days: 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 30 November, 2017 2:36 PM
To: 'Albert Hong' <albert.hong@budgetdirect.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Appoint LKK to conduct TP survey; Our Ref: C10001169

Dear Albert,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Albert Hong [<mailto:albert.hong@budgetdirect.com.sg>]
Sent: Thursday, 30 November, 2017 2:34 PM
To: 'assignments' <assignments@lkkauto.com>
Cc: sur@lkkauto.com
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001169

Hi Catherine,

As spoken earlier, please accept survey assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg



Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Ronnie Tan [<mailto:ronnie.tan@firstautoworks.com.sg>]
Sent: Thursday, 30 November, 2017 10:55 AM
To: Motor Claims <motorclaims@budgetdirect.com.sg>
Cc: albertong@budgetdirect.com.sg
Subject: fw: Firstauto (KB) - Ronnie Tan/ NTUC insurance/TP Our insured SLR 4719Y / DOA 27/11/2017

Date: 29/11/2017

Notice of accident

Firstauto (KB) - Ronnie Tan/ NTUC insurance/TP Our insured SLR 4719Y / DOA 27/11/2017

To: Auto & General Insurance (Singapore) Pte. Ltd.

Dear Sir

We are instructed by Lawrence Tan Chay Leong to notify you of a road traffic accident on 27/11/2017 at about 16.50 at Slip road of upper Paya Lebar Road Into Bartley Road involving our client's/customer's vehicle registration number SKK 6968E and vehicle registration number GBB 3617S driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

Ronnie Tan
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4
#04-01 (South Wing)

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: C10001169
Our ref: CS/AGI17022789/Avb

Date : 1/12/2017

The Motor Claims Department
M/s AUTO & GENERAL INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLR 4719Y


We thank you for your instruction on 30/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/11/2017 at the premises of M/s 1ST AUTOWORKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	27,902.50
Revised Estimate Amount	: S\$	12,358.30
"Check" Items Amount	: S\$	628.30
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Thursday, 30 November, 2017 2:34 PM
To: 'assignments'
Cc: sur@lkkauto.com
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001169
Attachments: ACC REPORT WITH ADDENDUM (NEW TP VEH NUMBER).PDF; Repair Est 1.jpg; Repair Est 2.jpg; Repair Est 3.jpg

Hi Catherine,

As spoken earlier, please accept survey assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: Ronnie Tan [mailto:ronnie.tan@firstautoworks.com.sg]
Sent: Thursday, 30 November, 2017 10:55 AM
To: Motor Claims <motorclaims@budgetdirect.com.sg>
Cc: albertong@budgetdirect.com.sg
Subject: fw: Firstauto (KB) - Ronnie Tan/ NTUC insurance/TP Our insured SLR 4719Y / DOA 27/11/2017

Date: 29/11/2017

Notice of accident

Firstauto (KB) - Ronnie Tan/ NTUC insurance/TP Our insured SLR 4719Y / DOA 27/11/2017

To: Auto & General Insurance (Singapore) Pte. Ltd.

Dear Sir

We are instructed by Lawrence Tan Chay Leong to notify you of a road traffic accident on 27/11/2017 at about 16.50 at Slip road of upper Paya Lebar Road Into Bartley Road involving our client's/customer's vehicle registration number SKK 6968E and vehicle registration number GBB 3617S driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

Ronnie Tan
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4
#04-01 (South Wing)

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 20:37
Date Of Accident	27/11/2017 16:50
Exact Location Of Accident	SLIPROAD OF UPP PAYA LEBAR ROAD INTO BARTLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR4719Y
Insured/Policyholder	
Name Of Registered Owner	LAWRENCE TAN CHAY LEONG
NRIC No	S1128911H
Email Address	LAWTAN2012@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97713979
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE-1.4 T (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093516918
Cover Note Number	

Driver

Name of Driver	LAWRENCE TAN CHAY LEONG
NRIC No	S1128911H
Date Of Birth	02/01/1955
Occupation	INDOOR
Date Of Driving Pass	28/06/1975
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	+65-97713979
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	LAWTAN2012@GMAIL.COM

Address	36 LORONG PAYA LEBAR
Postcode	536334
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	EMAIL TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH5915S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	COLLIN CHAN KOON SIONG
NRIC/Passport Number	S1671877G
Contact Number	96219520
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	LAWRENCE TAN CHAY LEONG
------	-------------------------

Email Address

DETAILS OF INJURED PERSON 1

Name

LAWRENCE TAN CHAY LEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

1. INTRODUCTION

2. I am hereby accepting full liability for the accident as well as the claims process.

3. The Form must be completed by the Policyholder and/or the Authorized Driver.

4. A declaration is made that the information is truthful and accurate as possible. Any false representation or withholding of material facts may result in the insurer's right to reject the policy liability.

5. The form and completion of this form for insurance purposes is not an admission of policy liability on the part of the insured.

6. Any legal matters must be referred to the Police for investigation.

7. The Form will be provided by the Ministry of the Civil Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

8. By the completion of this report by the Insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.

9. Consents under the Personal Data Protection Act (PDPA)

10. I consent, with respect to each and every right:

(a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, store and/or process my personal data/personal information set out in this Form and any other personal information provided by me or collected by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) and have insured vehicles involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/new firms, the Insurers' authority of Singapore and any relevant government agency/authority (such as the police, for the purposes of the PDPA);

(b) administering, handling and/or dealing with my claims including the settlement of the claim and any necessary and/or relevant relating to the claim;

(c) investigating the accident and/or my claim;

(d) administering and/or dealing with my instructions or responding to any enquiries by me;

(e) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as in the context of use of brochures/flyer packages; and/or

(f) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

11. All insurers who have insured vehicles involved in this accident and the Insurers' lawyers/new firms, may be permitted to collect, use, store and/or process my Personal Information for one or more of the above Purposes; and

12. My Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/new firms, which may be based outside of Singapore for one or more of the above Purposes;

13. My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

14. If a third party is collected under (d) above may be shared / disclosed:


(a) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, investigation, law enforcement and government agencies as reasonably required for the purposes stated; or

(b) for complying with regulatory requirements or any regulatory, law or court orders.

Signature of Insurer
 Date of completion
 Signature of Insurer

Signature of Insurer
 Date of completion
 Signature of Insurer

Sketch Plan #2



RELIABLE EVIDENCES OF THE ACCIDENT

I stopped my vehicle at the Slip Road at the
 the very time entering into Barley Road.

From the vehicle SHS916S did not manage
 to stop and collided into my rear. We exchanged
 particulars and proceeded to inform our
 relevant Insurance Companies.

I managed to drive home my vehicle and
 will be seeing a doctor for my neck pain.

DECLARATION

I hereby declare that the above is a true and correct statement of the facts of the accident.

Signature of Driver

Signature of Witness

Signature of Driver

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Police Report



**SINGAPORE
POLICE FORCE**



T201711270207

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-89 SINGAPORE
300013
Tel No. 1800 3309696

Page 1
Report No. T201711270207

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/11/2017 22:14	Video Report No.	Station Diary No.: 49
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LAWRENCE TAN CHAY I - DUNS			Address: 38 LORONG PAYA LEBAR SINGAPORE 536334		
ID Type / ID No. NRIC NO / S' 128911H			Contact No. Home/Office: Mobile: 97713979		
Nationality: SINGAPORE CITIZEN			Email		
Sex: Male	Age: 82	Date of Birth: 02/01/1935	Type of Informant: Driver		
Race: Chinese			Language:		
Occupation: Other university, polytechnic and higher education teachers			Institution / School Name:		
			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident: Injury Others	Drink Driver: No	Date/Time of Accident: 27/11/2017 18:50	Type of Location: Road
Location: Along Road 1 UPPER PAYA LEBAR ROAD			
Slip road before Bentley road			
Weather: Clear		Road Surface: Dry	Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition / No. of Passenger
SJH5955	Car	HONDA	FIT	White	Slightly 0 Damaged
SLR4718Y	Car	CHEVROLET	CRUZE NB 1.4D TURBO 8AT	Silver	Seriously 0 Damaged

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------

Police Report



**SINGAPORE
POLICE FORCE**



14-01711275202

Police Station Of Origin:
Aljunied NPP
15 Joo Sang Road #01-89 SINGAPORE
380013
Tel No: 1800 2600996

Report No: 1420171-0742002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurer/Company	Insurance No.	Effective	Expiry Date
SLR4718Y	NTUC Income Insurance Co-Operative Limited	5043510916	15/09/2017	15/09/2019

Details of Person Involved			
Any Pedestrian Involved, No			
No. of Pedestrians Injured, NIL		Use of Force/Weapon, NA	
Driver			
Name	LAWRENCE TAN CHAY LEONG	ID No.	S1128911H
Related Vehicle	SLR4718Y (Car)	Contact No.	97713971
Hospital/Clinic	HEALTHLINK MEDICAL CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry, NIL
Date Treatment	27/11/2017	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details:

On the 27/11/2017 at about 1850hrs, I was driving my vehicle (SLR4718Y) along Upper Paya Lebar Road turning towards Barkly Road when I met with an accident. I was on the slip road and had drive pass the zebra crossing before coming to a stop at the give way line to look out for oncoming vehicle. As there was oncoming vehicle, I had to stop my vehicle to allow vehicle to pass on the main road. After which, I felt an impact from behind and discovered that a vehicle (SUN88158) had collided into my vehicle. I then called my insurance agency to assist me. I was later advised by my insurance agency to shift my vehicle to the side after taking the photos. I also exchanged particulars with the other party. My vehicle was damaged at the rear bumper as well as the boot of the vehicle. Due to the accident, I suffered neck and back injuries. I went to see the doctor after the accident and was given 3 days of MC.

I wish to state that my vehicle has a front and rear in-car camera.

Police Report



SINGAPORE
POLICE FORCE



T201711270002

Police Station Of Origin:
Ajunied NPF
13 Joo Sang Road #01-68 SINGAPORE
380013
Tel No: 1800 2608998

Page 8

Report No: T201711270002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 55474885 stating the report number as reference.

Signature Of Officer Recording This Report

Sgt 2 NEO ZUC QUAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / ADIT /
SIANG YI TING STEPHANIE
Contact No: 80478414

Signature Of Informant

Date/Time:
27/11/2017 22:14

Classification Of Case:

Authentication Stamp

1800



Sgt 2 Neo Zuc Quan

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel: (65) 5224 0010 Fax: (65) 5224 0050
Operating Hours: Monday to Friday, 09:00 - 17:00
UCN: 5865500200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: Ref OF/2016-2020
5135 Vehicle Registration No: SLR 4719Y
Name (as shown in NRIC): Lawrence Tan Chay Leong NRIC/FIN/Passport No: S1128911H
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 36, Lorong Paya Lebar Singapore 536384
Contact (Tel): - Mobile No.: 97713979
Email Address: lawtan2012@gmail.com
Date of Accident: 27/11/2017 Time of Accident: 4:50 pm
Place of Accident: Slip road of Upper Paya Lebar Road
into Bartley Road
Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

In additional to original report, I also have
made a Police Report on the advice of the
doctor I consulted last night since I
was given 3 days of M.C.

Attached is the police report (3 pages)
for your perusal.

Thanks.

Lawrence Tan Chay Leong
Policyholder / Driver's Signature
Date: 28/11/17

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #10-00 Singapore 048586
 Tel: (65) 6224 0010 Fax: (65) 6274 0090
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S665500206 / GST Reg. No.: M600027735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MIN111715168 / MIN1117156873-01 Vehicle Registration No: SLR4719Y
 Name (as shown in NRIC): Lawrence Tan Chay Leong NRIC/FIN/Passport No: S1128911H
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: 36, Lorong Paya Lebar Singapore 536334
 Contact (Tel): _____ Mobile No.: 97713979
 Email Address: lawtan2012@gmail.com
 Date of Accident: 27/11/17 Time of Accident: 4⁵⁰ pm
 Place of Accident: Slip road of Upper Paya Lebar Road into Bartley Road
 Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I wish to amend the third party vehicle's
number from SJH5916S to SJH5915S.

Policyholder / Driver's Signature

Date: 28/11/17

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date:

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 29/11/2017

Reference: SLR 4719Y

Make: Chevrolet Cruze

To Whom It May Concern

Dear Sir,

*TP Budget Project
Veron*

RE: VEHICLE : SLR 4719Y

CHASSIS NO.: KL1JA6989GK354973

ENGINE NO.: B14NET170230018

Name of insured : Lawrence Tan Chay Leong

Date of accident: 27/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Boot lid <i>Deled</i>	\$ 1,701.00
2	1	Boot lid Emblem <i>new</i>	\$ 71.00
3	1	Boot lid lettering 'CHEVROLET' <i>new</i>	\$ 65.00
4	1	Boot lid lettering 'CRUZE' <i>new</i>	\$ 45.00
5	1	Boot lid Lettering 'LS' <i>new</i>	\$ 25.00
6	1	Boot lid lettering 'Turbo' <i>new</i>	\$ 52.00
7	1	RHR Bootlid Lamp <i>3 new</i>	\$ 399.00
8	1	LHR Bootlid Lamp <i>2 new</i>	\$ 399.00
9	1	Rear Bootlid Handle (plastic) <i>new</i>	\$ 343.00
10	1	Bootlid outer switch assy <i>new</i>	\$ 235.00
11	2	Number plate lamp <i>2 new</i>	\$ 167.00
12	1	LH Bootlid Hinge <i>3 new</i>	\$ 75.00
13	1	RH Bootlid hinge <i>1 new</i>	\$ 75.00
14	1	Rear Bootlid Inner Trim <i>new</i>	\$ 250.00
15	1	Boot lid lock mechanism <i>new</i>	\$ 310.00
16	1	Boot lid striker <i>new</i>	\$ 42.00
17	1	Boot lid weatherstrip <i>new</i>	\$ 189.00
18	1	RHR Tail lamp <i>new</i>	\$ 706.00
19	1	RHR Tail lamp Panel <i>new</i>	\$ 271.00
20	1	LHR Tail lamp <i>new</i>	\$ 706.00
21	1	LHR Tail lamp Panel <i>new</i>	\$ 271.00
22	1	Rear bumper <i>Distorted</i>	\$ 1,391.00
23	1	Rear bumper tow hook cover <i>Deled</i>	\$ 30.00
24	1	Centre Bumper Guide <i>Rehange dm</i>	\$ 75.00
25	1	RHRC Bumper Guide <i>?</i>	\$ 50.00
26	1	LHRC Bumper Guide <i>new</i>	\$ 50.00
27	1	RHR Bumper Guide <i>new</i>	\$ 60.00
28	1	LHR Bumper Guide <i>new</i>	\$ 60.00
29	1	Rear bumper reinforcement <i>But</i>	\$ 736.00
30	1	Rear end panel <i>Deled</i>	\$ 906.00
31	1	Rear end panel trim <i>Deled</i>	\$ 139.00
32	1	Rear spare tyre panel top board <i>new</i>	\$ 325.00
33	1	1st Autoworks Pte Ltd Panel <i>new</i>	\$ 1,383.00

1291

34	1	Rear Exhaust with exhaust muffler <i>Me n</i>	\$ 1,700.00	+
35	1	Rear Speaker Panel <i>Me n</i>	\$ 387.00	+
36	1	Rear Speaker Panel Board <i>Me n</i>	\$ 299.00	+
37	1	LHR Seat Belt	\$ 269.00	+
38	1	RHR Seat Belt	\$ 269.00	+
39	1	LHR Seat Belt Buckle	\$ 379.00	+
40	1	RHR Seat Belt Buckle	\$ 79.00	+
41	1	Air Bag Module	\$ 1,771.00	+
42	1	LHF Seat Belt	\$ 750.00	+
43	1	RHF Seat Belt	\$ 750.00	+
44	1	LHF Seat Belt Buckle	\$ 210.00	+
45	1	RHF Seat Belt Buckle	\$ 210.00	+
46	1	Seat Belt ECU	\$ 1,700.00	+

7047
6341.3

Parts Total: \$ 20,375.00
Less 10%: \$ 2,037.50
Total: \$ 18,337.50

Labour

No.	Labour Description	Price (SGD)	
	<u>Rear portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,800.00	2750
2	Carry out spray painting on accident affected area	\$ 2,200.00	1800.
3	To conduct anti rust of under carriage tuff coat	\$ 250.00	80.
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	30
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	100.
6	To remove and refix reverse sensor and conduct test	\$ 80.00	50.
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	✓
8	Transfer of internal mechanism from old door panel to new door panel	\$ 70.00	+
9	To remove and replace exhaust pipe	\$ 80.00	+
10	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
11	To conduct chasis alignment	\$ 450.00	+
12	To remove and refit fuel tank assy for replacement of Rear Fender	\$ 80.00	+
13	To remove and replace rear windscreen	\$ 120.00	+
14	Remove and replace reverse camera (Labour)	\$ 80.00	50
15	Remove and replace reverse sensor (Labour)	\$ 80.00	50
16	To remove and refit rear axle due to replacement of rear exhaust	\$ 120.00	+
17	To conduct reset of ABS light on	\$ 350.00	+
18	To check diagnostics of vehicle management/control units, reset memories to specification etc.	\$ 480.00	100

5050

Labour Total: \$ 7,730.00

Others

No.	Qty	Other Description	Price (SGD)
<u>Rear Portion</u>			
1	10	Rear Number plate & bracket	\$ 45.00 ✓
2	6	Rear bumper clip (set)	\$ 65.00 30 ✓
3	4	Tail lamp clip (set)	\$ 39.00 ✓
4	8	Rear Bootlid Handle clips	\$ 26.00 +
5	2	Rear fender liner clip (set)	\$ 52.00 x
6	11	Rear Exhaust mounting	\$ 180.00 +
7	12	Inner bootlid Trim Clips	\$ 71.50 +
8	5	Rear fender inner trim clip (set)	\$ 78.00 X
9	1	Rear end panel top granish clip (set)	\$ 32.50 20 ✓
10	1	Rear end panel insulation seal	\$ 120.00 60 ✓
11	8	Rear floor panel insulation seal	\$ 100.00 +
12	8	LHR Inner door trim clips	\$ 52.00 +
13	1	RHR Inner door trim clips	\$ 52.00 x
14	1	Reverse camera	\$ 280.00 +
15	1	Reverse sensor(1 set)	\$ 592.00 ✓
16	1	Towin Charge	\$ 50.00 ✓

236

Other Total: \$ 1,835.00

Total : \$ 27,902.50
Gst 7%: \$ 1,953.18
GRAND TOTAL: \$ 29,855.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Executive
Ronnie Tan
HP : 8298 8933 Fax:6844 5185

Adrian L
30/11/17.

total: 12268.30
(P/P)

P/P 08 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

Auto & General Insurance (Singapore) Pte. Limited
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

GST Ref. No: 20-0000274-Z

Vehicle No: SLR 4719Y
Chasis No : KL1JA6989GK354973
Engine No: B14NET170230018

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	Boot lid	1701.00
2	1	Boot lid Emblem	71.00
3	1	Boot lid lettering 'CHEVROLET'	65.00
4	1	Boot lid lettering 'CRUZE'	45.00
5	1	Boot lid Lettering 'LS'	25.00
6	1	Boot lid lettering 'Turbo'	52.00
7	1	Boot lid lock mechanism	310.00
8	1	Boot lid weatherstrip	189.00
9	1	RHR Tail lamp	706.00
10	1	LHR Tail lamp	706.00
11	1	Rear bumper	1291.00
12	1	Rear bumper tow hook cover	30.00
13	1	Centre Bumper Guide	75.00
14	1	Rear bumper reinforcement	736.00
15	1	Rear end panel	906.00
16	1	Rear end panel trim	139.00

Total: 7047.00
Less 10%: 704.70
Parts Total : 6342.30

Labour

Rear

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2750.00
2	Carry out spray painting on accident affected area	1800.00
3	To conduct anti rust of under carriage tuff coat	80.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
<u>5</u>	Remove and refix seat cushion/upholstery & roof lining to facilitate	100.00
<u>6</u>	To remove and refix reverse sensor and conduct test	50.00
<u>7</u>	To conduct transfer of parts from old bootlid to new bootlid	80.00
<u>8</u>	Remove and replace reverse camera (Labour)	50.00
<u>9</u>	Remove and replace reverse sensor (Labour)	50.00
<u>10</u>	To check diagnostics of vehicle management/control units, reset memories to specification etc	100.00

Labour Total : 5090.00

Other

No. Other Description Price (SGD)

Rear Portion

1	1	Rear Number plate & bracket	45.00
2	6	Rear bumper clip (set)	30.00
3	4	Tail lamp clip (set)	39.00
4	5	Rear end panel top granish clip (set)	20.00
5	1	Rear end panel insulation seal	60.00
6	1	Reverse sensor(1 set)	592.00
7	1	Towin Charge	50.00

Other Total : 836.00

Total : \$12,268.30
GST (7%) \$858.78
Grand Total: \$13,127.08

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI17022789/Avbn2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 02-02-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 5915S	Veh. Inspected	SLR 4719Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001169	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE	c.c	1362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KL1JA6989GK354973	Colour	SILVER
Odometer	3166	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/11/2017	Inspection Date	30/11/2017
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4719Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	1,701.00	1,701.00
1	BOOT LID EMBLEM	NECESSARY	71.00	71.00
1	BOOT LID LETTERING "CHEVROLET"	NECESSARY	65.00	65.00
1	BOOT LID LETTERING "CRUZE"	NECESSARY	45.00	45.00
1	BOOT LID LETTERING "LS"	NECESSARY	25.00	25.00
1	BOOT LID LETTERING "TURBO"	NECESSARY	52.00	52.00
1	RHR BOOTLID LAMP	NOT NECESSARY	399.00	-
1	LHR BOOTLID LAMP	NOT NECESSARY	399.00	-
1	REAR BOOTLID HANDLE (PLASTIC)	NOT NECESSARY	343.00	-
1	BOOTLID OUTER SWITCH ASSY	NOT NECESSARY	235.00	-
2	NUMBER PLATE LAMP	NOT NECESSARY	167.00	-
1	LH BOOTLID HINGE	NOT NECESSARY	75.00	-
1	RH BOOTLID HINGE	NOT NECESSARY	75.00	-
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	250.00	-
1	BOOT LID LOCK MECHANISM	DAMAGED	310.00	310.00
1	BOOT LID STRIKER	NOT NECESSARY	42.00	-
1	BOOT LID WEATHERSTRIP	CUT	189.00	189.00
1	RHR TAIL LAMP	CUT	706.00	706.00
1	RHR TAIL LAMP PANEL	TO REPAIR SEE LABOUR	271.00	-
1	LHR TAIL LAMP	CUT	706.00	706.00
1	LHR TAIL LAMP PANEL	TO REPAIR SEE LABOUR	271.00	-
1	REAR BUMPER	DISTORTED	1,391.00	1,291.00
1	REAR BUMPER TOW HOOK COVER	DEFORMED	30.00	30.00
1	CENTRE BUMPER GUIDE	DAMAGED	75.00	75.00
1	RHRC BUMPER GUIDE	NOT NECESSARY	50.00	-
1	LHRC BUMPER GUIDE	NOT NECESSARY	50.00	-
1	RHR BUMPER GUIDE	NOT NECESSARY	60.00	-
1	LHR BUMPER GUIDE	NOT NECESSARY	60.00	-
1	REAR BUMPER REINFORCEMENT	BENT	736.00	736.00
1	REAR END PANEL	DENTED	906.00	906.00
1	REAR END PANEL TRIM	DEFORMED	139.00	139.00
1	REAR SPARE TYRE PANEL TOP BOARD	NOT NECESSARY	325.00	-

Report Ref No. CS/AGI17022789/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,383.00	-
1	REAR EXHAUST WITH EXHAUST MUFFLER	NOT NECESSARY	1,700.00	-
1	REAR SPEAKER PANEL	NOT NECESSARY	387.00	-
1	REAR SPEAKER PANEL BOARD	NOT NECESSARY	299.00	-
1	LHR SEAT BELT	NOT NECESSARY	269.00	-
1	RHR SEAT BELT	NOT NECESSARY	269.00	-
1	LHR SEAT BELT BUCKLE	NOT NECESSARY	379.00	-
1	RHR SEAT BELT BUCKLE	NOT NECESSARY	79.00	-
1	AIR BAG MODULE	NOT NECESSARY	1,771.00	-
1	LHF SEAT BELT	NOT NECESSARY	750.00	-
1	RHF SEAT BELT	NOT NECESSARY	750.00	-
1	LHF SEAT BELT BUCKLE	NOT NECESSARY	210.00	-
1	RHF SEAT BELT BUCKLE	NOT NECESSARY	210.00	-
1	SEAT BELT ECU	NOT NECESSARY	1,700.00	-
	LESS 10% DISCOUNT		-2,037.50	-704.70
			18,337.50	6,342.30
	<u>SPECIAL NETT ITEMS</u>			
10	REAR NUMBER PLATE & BRACKET (SN)	BENT	45.00	45.00
6	SET REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
4	SET TAIL LAMP CLIP (SN)	NECESSARY	39.00	39.00
8	REAR BOOTLID HANDLE CLIPS (SN)	NOT NECESSARY	26.00	-
2	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	52.00	-
11	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	180.00	-
12	INNER BOOTLID TRIM CLIPS (SN)	NOT NECESSARY	71.50	-
5	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	78.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	32.50	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	60.00
8	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	100.00	-
8	LHR INNER DOOR TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	RHR INNER DOOR TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	280.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	592.00	592.00
			1,785.00	786.00
	<u>LABOUR</u>			
	TOWING CHARGE.		50.00	50.00

Report Ref No. CS/AGI17022789/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF RHR TAIL LAMP PANEL,LHR TAIL LAMP PANEL AND REAR SPARE TYRE PANEL.		2,800.00	2,750.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		2,200.00	1,800.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		250.00	80.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00
	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.		250.00	100.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID.		80.00	80.00
	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL.	NOT NECESSARY	70.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	450.00	-
	TO REMOVE AND REFIT FUEL TANK ASSY FOR REPLACEMENT OF REAR FENDER.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	REMOVE AND REPLACE REVERSE CAMERA (LABOUR).		80.00	50.00
	REMOVE AND REPLACE REVERSE SENSOR (LABOUR).		80.00	50.00
	TO REMOVE AND REFIT REAR AXLE DUE TO REPLACEMENT OF REAR EXHAUST.	NOT NECESSARY	120.00	-
	TO CONDUCT RESET OF ABS LIGHT ON	NOT NECESSARY	350.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.		480.00	100.00
	-		-	-
	-		-	-
	-		-	-
			7,780.00	5,140.00
	GRAND TOTAL		27,902.50	12,268.30

Report Ref No. CS/AGI17022789/Avbn2



RECOMMENDED COST OF REPAIRS			12,268.30
-----------------------------	--	--	-----------

Report Ref No. CS/AGI17022789/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.