

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

Auto & General Insurance (Singapore) Pte. Limited
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

GST Ref. No: 20-0000274-Z

Vehicle No: SLR 4719Y
Chasis No : KL1JA6989GK354973
Engine No: B14NET170230018

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	Boot lid	1701.00
<u>2</u>	1	Boot lid Emblem	71.00
<u>3</u>	1	Boot lid lettering 'CHEVROLET'	65.00
<u>4</u>	1	Boot lid lettering 'CRUZE'	45.00
<u>5</u>	1	Boot lid Lettering 'LS'	25.00
<u>6</u>	1	Boot lid lettering 'Turbo'	52.00
<u>7</u>	1	Boot lid lock mechanism	310.00
<u>8</u>	1	Boot lid weatherstrip	189.00
<u>9</u>	1	RHR Tail lamp	706.00
<u>10</u>	1	LHR Tail lamp	706.00
<u>11</u>	1	Rear bumper	1291.00
<u>12</u>	1	Rear bumper tow hook cover	30.00
<u>13</u>	1	Centre Bumper Guide	75.00
<u>14</u>	1	Rear bumper reinforcement	736.00
<u>15</u>	1	Rear end panel	906.00
<u>16</u>	1	Rear end panel trim	139.00

Total: 7047.00

Less 10%: 704.70

Parts Total : 6342.30

Labour

Rear

No.	Description	Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2750.00
<u>2</u>	Carry out spray painting on accident affected area	1800.00
<u>3</u>	To conduct anti rust of under carriage tuff coat	80.00

<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
<u>5</u>	Remove and refix seat cushion/upholstery & roof lining to facilitate	100.00
<u>6</u>	To remove and refix reverse sensor and conduct test	50.00
<u>7</u>	To conduct transfer of parts from old bootlid to new bootlid	80.00
<u>8</u>	Remove and replace reverse camera (Labour)	50.00
<u>9</u>	Remove and replace reverse sensor (Labour)	50.00
<u>10</u>	To check diagnostics of vehicle management/control units, reset memories to specification etc	100.00

Labour Total : 5090.00

Other

No. Other Description Price (SGD)

Rear Portion

1	1	Rear Number plate & bracket	45.00
2	6	Rear bumper clip (set)	30.00
3	4	Tail lamp clip (set)	39.00
4	5	Rear end panel top granish clip (set)	20.00
5	1	Rear end panel insulation seal	60.00
6	1	Reverse sensor(1 set)	592.00
7	1	Towin Charge	50.00

Other Total : 836.00

Total : \$12,268.30
GST (7%) \$858.78
Grand Total: \$13,127.08

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.