

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Nov-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6101 S

1 pc	n/s head lamp		\$	1,038.00
1 pc	Front bumper		\$	531.00
1 pc	Front bumper n/s side retainer	X	\$	16.00
1 pc	Front bumper n/s protector		\$	51.00
	Front Bumper Engl	\$44	\$	1,636.00
		Less 10%	\$	163.60
			\$	1,472.40

1,512.00

S/NETT

1 set	Front bumper clips		\$	48.00
	Sundry		\$	50.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$	450.00 200
	To putty and spray painting on front bumper		\$	200.00 180
	To apply rustproofing on the repaired and replaced panels.		\$	200.00 X
			\$	2,420.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

2460

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

1 car 16/11/17
29/11/17 1100 hrs.
2 Day
L/S
After Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: