

Singer

From _____ Date _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____			
IDAC Accident Report: _____	Consistent? : Yes or No		
GIA. / PR Seen: _____	Consistent? : Yes or No		
Est. Repairs: _____	days	Res.:	Yes or No
Lum Sum: _____	%	3 Val.:	Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCX218 C Yr Reg: 2016 May
 Type: M/C / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make:	Toyota Alphard		CC	2493
Colour:	Black	A/C	Insured / Std / NI / NA	
Sp. Reading:	30955	T. Radio:	Insured / Std / NI / NA	

Eng/No: _____
C/No: AGH300042194

Gen. Cond: ~~Good~~ / Fair / Poor / BurntSteering: ~~Worries~~ / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F 215/65R16

R: 215/65R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO *or*

Front

R/Bal.	06	mm	R/Bal.	06	mm
--------	----	----	--------	----	----

U/Bal.	06	mm	U/Bal.	06	mm
--------	----	----	--------	----	----

D.O.A. D.O.I. 2017/12/17.

Survey held at Specialist.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

TP ALG.

CaseTime File Page 107

☐: Prel. Report

☐ : Final Report

Data Time File Return 201

Report Format :

Lump Sum / I.B.I.: (S

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

2000

Add Fee: Site Insp (\$

Site Info (S)

☐ Interview (3)

 Tech Info Co

☐ Yearly \$

1000-0000




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17022796/yb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 30-11-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJD 7320R	Veh. Inspected	SCX 218C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/11/2017	Inspection Date	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SCX218C/1711299

01st December 2017

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

JLS

Date of Accident : 24th November 2017
Location : Along Cluny Road
Third Party Claim Vehicle No : SJD 7320 R
Repair Cost For Vehicle No : SCX 218 C (Toyota Alphard)

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot assy <i>Dented</i>	1	1,537.30	\$ 1,537.30 ✓
2	Rear boot emblem (Alphard) <i>NA</i>	1	66.80	\$ 66.80 ✓
3	Rear boot light RH <i>NA</i>	1	476.50	\$ 476.50 +
4	Rear windscreen glass with moulding <i>NA</i>	1	1,580.90	\$ 1,580.90 ✓
5	Rear boot chrome (Upper) <i>NA</i>	1	655.70	\$ 655.70 +
6	Rear boot logo <i>NA</i>	1	66.80	\$ 66.80 ✓
7	Rear boot lock <i>NA</i>	1	763.00	\$ 763.00 ✓
8	Rear bumper fascia <i>Rehnd</i>	1	1,575.80	\$ 1,575.80 ✓
9	Rear bumper clips <i>NA</i>	1 set	38.00	\$ 38.00 ✓
10	Rear bumper side retainer LH&RH <i>2H NA</i>	2	79.70	\$ 159.40 79.70
11	Rear bumper parking sensor (Original) <i>2 pieces damaged</i>	4	381.60	\$ 1,526.40 560
12	Rear bumper reflector LH&RH <i>2H cut</i>	2	54.10	\$ 108.20 54.10
13	Rear bumper towing cover <i>missing</i>	1	29.90	\$ 29.90 ✓
14	Rear bumper quarter panel <i>Repair</i>	1	294.40	\$ 294.40 +
15	Rear end panel <i>Dented</i>	1	595.80	\$ 595.80 ✓
16	Rear boot weather stripe <i>NA</i>	1	304.80	\$ 304.80 +
17	Rear boot stricker <i>NA</i>	1	35.90	\$ 35.90 +
				\$ 9,815.60
Less 25%				\$ 2,453.90
				\$ 7,361.70
18	Rear end panel sealer (s/nett) <i>NA</i>	1	80.00	\$ 80.00 60
19	Rear windscreen sealant (s/nett) <i>NA</i>	1	60.00	\$ 60.00 ✓
				\$ 7,501.70

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardec@singnet.com.sg

Bus. Reg No. 199502604 E GST No: 19-9502604-E

SM/SCX218C/1711299

01st December 2017

Balance b/f

\$ 7,501.70

Labour Charges :-

Amounts

Cut out, renew, knocking, straighten, re-align rear boot assy, rear bumper fascia, rear end panel, rear bumper reinforcement beam, tail lamp LH&RH, rear fender LH&RH, rear floor panel

\$ 1,200.00 ⁰⁰⁰

Remove & refit rear windscreen glass

\$ 180.00 ¹²⁰

Remove & replace rear bumper parking sensor

\$ 120.00 ⁶⁰

Remove & refit interior upholstery, rear seat to facilitate repairs

\$ 280.00 ⁶⁰

Spray painting on damage parts

\$ 1,400.00 ⁸⁰⁰

Check lighting after repairs

\$ 40.00 ³⁰

Labour Charge

\$ 3,220.00

Total Amount

\$ 10,721.70

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Adrian Lj
P/P 01/12/17
OSR

total 5643.15
(P/P)

/ LKK
ADRIAN

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SCX218C/1711299

14th December 2017

WITHOUT PREJUDICE

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

**RE: ACCIDENT INVOLVING VEHICLES SCX 218 C AND SJD 7320 R
ON 24TH NOVEMBER 2017 AT 1850 HRS ALONG CLUNY ROAD**

Dear Sirs,

We refer to the above matter.

Our Client Chia Sing Joo the registered owner of SCX 218 C.

You are the insurer of motor vehicle no. SJD 7320 R, which was involved in the above accident. Please be informed that the collision was caused by the negligent owner/driver of the motor vehicle no. SJD 7320 R, in consequence of which our client has suffered damages and consequential loss.

Attached a few documents for your reference:

- a) Repair bill
- b) GIA report & LTA search
- c) An authorisation letter from the owner (SCX 218 C)

We are claiming as follows: -

LTA search fee	S\$	2.00
Repair cost	S\$	6,038.17
Loss of use (7 days)	S\$	700.00
		<hr/>
	S\$	6,740.17

Dollar: Six Thousands Seven Hundred Forty and Cents Seventeen only.

Kindly let us know whether you are prepare to settle the claim within the next ten (10) days from the date herewith.

Please remit the cheque in favour to "Specialists Motor Pte Ltd" as soon as possible.

Thank you,

Yours faithfully,


Karen Ong

Jas Khine (LKKAUTO)

From: Jas Khine (LKKAUTO)
Sent: Friday, 1 December, 2017 4:44 PM
To: 'KOH0412@GMAIL.COM'
Subject: ACCIDENT INVOLVING SJD 7320R & SCX 218C ALONG/AT CLUNY ROAD ON 24/11/2017

Our Ref: CC6/AIG17022796/Uyb3

01 DECEMBER 2017

KOH KIA HUI LEONARD
132 JALAN DERMAWAN
SINGAPORE 669084

Dear Sir/Madam,

ACCIDENT INVOLVING SJD 7320R & SCX 218C ALONG/AT CLUNY ROAD ON 24/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

This also refers to our tele-conversation earlier.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter/email.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ACCIDENT INVOLVING VEHICLE

SCX 218 C & SD 7620 R on 24th November 2017
at BRT Ms along Chury Road

Letter Of Authority And Undertaking

I/We Chia Sing Joo (NRIC NO) 514971870 of
22A Cornwall Gardens Singapore 269682

the owner/driver of Vehicle No. SCX 218 C hereby authorise your
esteem company Specialists Motor Pte Ltd
as my repairer for my Damaged Vehicle involved in the above accident and to
claim against the negligent party and/or insurance company.

I/We hereby agreed to be bound by the following:-

1. You are authorised to use my/our name to claim against the negligent party and/or insurance company pertaining to the above accident including any other incidental losses. All payments/settlement monies shall be made in favour of your company M/S Specialists Motor Pte Ltd
2. All documents receive by me from third party or insurance company will be sent to your office for follow-up action.
3. Any offer of settlements by the insurer and/or negligent party will be accepted only with your concurrence and approval.
4. Throughout the process of claim, I/We will be obligated to assist and to provide your company with accurate and correct information.
5. I/We agree that I/We shall pay to your company all cost/expenses/damages incurred or suffered by you as a result of the unsuccessful recovery of the claims for the full repair cost and any other incidental cost/expenses by you on my/our behalf.
6. I/We warrant and undertake that all information and statement provided by me/us to you are true and accurate.

Thanking you in anticipation.

Yours faithfully



Date: 30.11.2017

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SPECIALISTS MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,038.17 (Repair Cost), S\$700.00 (Loss of Rental/Use) S\$2.00 (Disbursement), for vehicle no. SCX 218C that was damaged pursuant to the accident which occurred on 24/11/2017 (date) along CLUNY ROAD (location) involving vehicle no/s SJD 7320R.

This is pursuant to the inspection conducted on 01/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHIA SING JOO ("the third party claimant") of vehicle no. SCX 218C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SCX 218C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of 12 (month) 2017 (year)

Signed by appointed surveyor

ump 

Signed by "the workshop" (with chop)



SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SCX218C/1711299

14th December 2017

TAX INVOICE

The Manager
Motor Claim Dept.
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 24th November 2017
Location : Along Cluny Road
Third Party Claim Vehicle No : SJD 7320 R
Repair Cost For Vehicle No : SCX 218 C (Toyota Alphard)

Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear boot assy	1	1537.30	\$ 1,537.30
2	Rear boot emblem (Alphard)	1	66.80	\$ 66.80
3	Rear boot logo	1	66.80	\$ 66.80
4	Rear bumper fascia	1	1575.80	\$ 1,575.80
5	Rear bumper clips	1set	38.00	\$ 38.00
6	Rear bumper side retainer RH	1	79.70	\$ 79.70
7	Rear bumper parking sensor (Original)	2	280.00	\$ 560.00
8	Rear bumper reflector RH	1	54.10	\$ 54.10
9	Rear bumper towing cover	1	29.90	\$ 29.90
10	Rear end panel	1	595.80	\$ 595.80
				\$ 4,604.20
		Less	25%	\$ 1,151.05
				\$ 3,453.15
11	Rear end panel sealer (s/nett)	1	60.00	\$ 60.00
12	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00
				\$ 3,573.15

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SCX218C/1711299

14th December 2017

Balance b/f	\$ 3,573.15
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking, straighten, re-align rear boot assy, rear bumper fascia, rear end panel, rear bumper reinforcement beam, tail lamp LH&RH, rear fender LH&RH, rear floor panel	\$ 1,000.00
Remove & refit rear windscreen glass	\$ 120.00
Remove & replace rear bumper parking sensor	\$ 60.00
Remove & refit interior upholstery, rear seat to facilitate repairs	\$ 60.00
Spray painting on damage parts	\$ 800.00
Check lighting after repairs	\$ 30.00
	<hr/>
	\$ 5,643.15
	Add 7% GST \$ 395.02
Total Amount	<hr/>
	\$ 6,038.17

S/Dollar : Six Thousands Thirty-Eight and Cents Seventeen only.

SPECIALISTS MOTOR PTE LTD





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-179264

Date of Request: 30/11/2017

Your Ref No: Online Purchase

Specialists Motor Pte Ltd
Blk 3018A Ubi Road 1
#01-24/25/26
Singapore 408711

Dear Sir/Madam,

Enquiry Date 30/11/2017
Enquiry By KAREN ONG 1
TP Vehicle No. SJD7320R
Accident Date 24/11/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJD7320R	AIG Asia Pacific Insurance Pte. Ltd.	01/04/2017-31/03/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Dec 2017 Edit Reg		01 Dec 2017 00:00 Edit Adj Rpt	S\$5,643.15 Edit Estimates	S\$5,643.15 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		KOH KIA HUI LEONARD, ID: S14223811							
Main Claimant:		CHIA SING JOO, ID: S1497187D							
Vehicle Reg. No.:		SCX218C	Date of Loss:	24/11/2017 18:00 - :59					
Claim Type:		TP / 5568732042SG	Policy/Cover Note No.:	(Comprehensive)					
Vehicle Reg. No. (Insured):		SJD7320R	Policy No. (Claimant):	MT/00382771					
		Excess:							
Repairer:		Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com							
Claimant's Insurer:		Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/12/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCX218C (5568732042SG)

[SJD7320R]

TP

CHIA SING JOO

Nov 24 2017 6:00PM

[KOH KIA HUI LEONARD]

Specialists Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	19/12/17 10:22	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	19/12/17 10:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
26	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
29	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
30	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
31	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

33	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	19/12/17 10:22	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 15:13	TP GIA REPORT	1	Load PDF	
2	02/01/18 09:19	WORKSHOP INVOICE	1	Load PDF	
3	02/01/18 09:19	AUTHORISATION TO ACT FORM	1	Load PDF	
4	02/01/18 09:19	Release Voucher	1	Load PDF	
5	02/01/18 09:19	GIA SEARCH	1	Load PDF	
6	02/01/18 09:19	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	01/12/17 11:03	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJD7320R (Insd veh)	Model:	TOYOTA ALPHARD 2.5 (A)
	SCX218C (TP veh)		
Date of Accident:	24/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,472.22
Final Repair Cost	:	\$	6,038.17
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,740.17

7.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Specialists Motor Pte Ltd	:	\$ 6,740.17
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

02 Jan
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17022796/AYB3Q2

Date: 02/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: SCX218C

Insured Vehicle No: SJD7320R

Date of Loss: 24/11/2017

Nature of Claim: TP

Claim No: 5568732042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCX218C

Make & Model: TOYOTA ALPHARD, 2.5 (A)

Engine No: 2ARH644163

Reg. Date: 24/05/2016 (Man. Year: 2015)

Chassis No: AGH300042194

Colour: Black

Odometer: 30955 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,501.70	3,573.15	3,928.55	52.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,070.00	1,150.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,721.70	5,643.15	5,078.55	47.37
+ GST 7.00/7.00% (S\$)	750.52	395.02	355.50	47.37
Nett Amount (S\$)	11,472.22	6,038.17	5,434.05	47.37
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,740.17		

INSPECTION

Date of Assignment: 01/12/2017

Date Inspected: 01/12/2017 Inspected At:

Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT ASSY	Dented	1,537.30 FL	*1,537.30 FL
2	1		*REAR BOOT EMBLEM (ALPHARD)	Necessary	66.80 FL	*66.80 FL
3	1		*REAR BOOT LIGHT RH	Not Necessary	476.50 FL	*- FL
4	1		*REAR WINDSCREEN GLASS WITH MOULDING	Not Necessary	1,580.90 FL	*- FL
5	1		*REAR BOOT CHROME (UPPER)	Not Necessary	655.70 FL	*- FL
6	1		*REAR BOOT LOGO	Necessary	66.80 FL	*66.80 FL
7	1		*REAR BOOT LOCK	Not Necessary	763.00 FL	*- FL
8	1		*REAR BUMPER FASCIA	Deformed	1,575.80 FL	*1,575.80 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
10	1		*REAR BUMPER SIDE RETAINER LH & RH	O/S Necessary	159.40 FL	*79.70 FL
11	1		*REAR BUMPER REFLECTOR LH & RH	O/S Cut	108.20 FL	*54.10 FL
12	1		*REAR BUMPER TOWING COVER	Missing	29.90 FL	*29.90 FL
13	1		*REAR BUMPER QUARTER PANEL	Repair	294.40 FL	*- FL
14	1		*REAR END PANEL	Dented	595.80 FL	*595.80 FL
15	1		*REAR BOOT WEATHER STRIP	Not Necessary	304.80 FL	*- FL
16	1		*REAR BOOT STRICKER	Not Necessary	35.90 FL	*- FL
17	1		*REAR END PANEL SEALER	Necessary	80.00 FS	*60.00 FS
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
19	4		*REAR BUMPER PARKING SENSOR (ORIGINAL)	Damaged (2 PCS ONLY)	1,526.40 FL	*560.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,955.60	4,724.20
- List Item Discount on L Items 25.00/25.00% (S\$)	2,453.90	1,151.05

Total Parts (S\$)	7,501.70	3,573.15
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT ,RENEW ,KNOCKING ,STRAIGHTEN ,REALIGN REAR BOOT ASSY ,REAR BUMPER ,FASCIA ,REAR END PANEL,REAR BUMPER REINFORCEMENT BEAM,TAIL LAMP LH & RH ,REAR FENDER LH & RH REAR FLOOR PANEL	New	1,200.00	1,000.00
2	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
3	REMOVE & REPLACE REAR BUMPER PARKING SENSOR	New	120.00	60.00
4	REMOVE & REFIT INTERIOR UPHOLSTERY ,REAR SEAT TO FACILITATE REPAIRS	New	280.00	60.00
5	SPRAY PAINTING ON DAMAGE PARTS	New	1,400.00	800.00
6	CHECK LIGHTING AFTER REPAIRS	New	40.00	30.00
Gross Labour Cost (\$\$)			3,220.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >