

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9487D -

AAD1711-304

Not Authorized
6/By @ 2850/

Vehicle No.:

SHD9487D - CANDY

Chassis No.:

KL1LA69RJB078300

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Date of Accident :

27.11.2017

Third Party Insurer :

Alh

PART

LIST

1	1	Front Bumper	\$	<i>Per</i> 1,202.00	✓
2	1	Front Bumper Retainer RH	\$	<i>Sn</i> 102.00	✓
3	1	Front Bumper Retainer LH	\$	<i>Dis</i> 102.00	✓
4	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25	✓
5	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00	✓
6	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37	✓
7	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Per</i> 32.40	✓
8	1	Headlamp LH	\$	<i>CM</i> 816.00	✓
9	1	Front Shock Absorber Assy LH	\$	<i>Sn</i> 216.17	✓
10	1	Front Lower Arm LH	\$	<i>Sn</i> 283.00	✓
11	1	Front Knuckle Arm LH	\$	<i>Sn</i> 230.00	✓
12	1	Front Fender LH	\$	<i>By</i> 837.60	✓
13	1	Front Fender Liner LH	\$	<i>Sn</i> 47.00	✓
14	1	Resonator (B/S Fender LH) AIR BOX	\$	<i>Sn</i> 134.67	✓
15	1	Resonator Hose	\$	<i>Sn</i> 37.00	✓
16	1	Front Door LH	\$	<i>R</i> 1,133.00	✓
17	1	Front Side View Mirror LH	\$	<i>Sn</i> 939.00	✓
18	1	Side Rocker Panel Garnish LH	\$	<i>Sn</i> 236.40	✓
19	1	Rear Door LH	\$	<i>R</i> 1,133.00	✓

TOTAL	\$	7,988.86
10%	\$	798.89
	\$	7,189.97

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	<i>Per</i> 30.00	✓
2	1 Set	Front Fender Liner Clip LH	\$	<i>nn</i> 30.00	✓
3	1	Door Sticker "Trans-cab" LH	\$	<i>nn</i> 80.00	✓
4	1	Door Sticker " 6555-3333 "LH	\$	<i>nn</i> 80.00	✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-304**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9487D -

5	1set	Side Rocker Panel Garnish Clip LH	\$	<i>nn</i> 60.00 X
6	1	Front Tyre LH	\$	<i>Sh</i> 360.00 X
7	1	Front Wheel Rim LH	\$	<i>Sh</i> 254.00 X
8	1	Hub Cup Rim Front LH	\$	<i>Sh</i> 35.00 X

TOTAL	\$	929.00
TOTAL PARTS	\$	8,118.97

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ *400* 5,400.00

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected
Portion.

\$ *400* 5,350.00

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ *nn* 380.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

REPAIR DAYS The repair survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ **12,250.00**

Over All Total \$ **20,368.97**

10 DAYS

2 days