

22/03/2012

ASS. REC. BY:

REF: CS/MSG17022804/T1969

Special Instruction:

Surveyor:

Taufik.

ASSIGNMENT (Office)

From (Person):

Fievel Foo

of

MSG

Date/Time:

30/11/17 @ 12:18 pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 656 Y

Insured:

SLC 5549 T

at Workshop m/s:

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

A28747260 AVW

Claim No:

538843

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/11/2017

CA / REV / REP. / REV 24 HRS

lwp,

13.12.2017

H.O.D. Endorsement:

Date/Time:

12:22pm @ 30/11/17

Person Contacted:

Caroline

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

(✓)

Estimate

Enthiran

SKT 656 Y - X

SLC 5549 T - CS3 / SM016015378 / Gbs2 - D.O.A: 15/08/2016

18/12/17 @

12:10pm visited to Fievel Foo via Marman.

21/11/18 @

3:53pm confirmed with Caroline final fig to 3766.95. 3 days by email.

Lined to 6563.75, by 2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022804/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 30-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 5549T	Veh. Inspected	SKT 656Y
Policy No.	A28747260AVW	Coverage (\$)	0.00
Claim No.	538843	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/11/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2017		30 Nov 2017 12:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEM CHING MENG (LIN ZHENMING), ID: S6822607D		
Main Claimant:	SAMUEL LIM CHUN DE, ID: S8233415G		
Vehicle Reg. No.:	SKT656Y	Date of Loss:	28/11/2017 22:00 - :59
Claim Type:	TP / 538843	Policy/Cover Note No.:	A28747260AVW (Comprehensive) Coverage: 18/05/2017 - 17/05/2018
Vehicle Reg. No. (Insured):	SLC5549T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/12/2017]		
Driver/Custodian (Insured):	LEM CHING MENG (LIN ZHENMING) (), NRIC: S6822607D		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 June 2018 3:53 PM
To: 'PBSP'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: FINAL REPORT / SKT656Y

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$3,766.95 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 8 June 2018 3:29 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: FINAL REPORT / SKT656Y

Dear Taufikh

As requested.

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Friday, 25 May 2018 9:43:23 AM
To: PBSP
Cc: 'Shiau Chan (LKKAUTO)'
Subject: RE: FINAL REPORT / SKT656Y

Hi Caroline,

Can forward the before paint photos?

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSiG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 18 Dec 2017

Preliminary Advice

Insured Vehicle No	: SLC5549T	Accident Date	: 28/11/2017
TP Vehicle No	: SKT656Y	Assignment Date	: 30/11/2017
Make	: BMW 218I	Est. Duration of Repair	: 4.00
Date of Inspection	: 13/12/2017		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,329.80
Revised Amount	:S\$	3,411.45
Check Items (Estimated)	:S\$	4,629.45
Total	:S\$	8,040.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2017 12:52
Date Of Accident	28/11/2017 23:00
Exact Location Of Accident	FILTER LANE MANDAI AVE & SEMBAWANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT656Y
Insured/Policyholder	
Name Of Registered Owner	SAMUEL LIM CHUN DE
NRIC No	S8233415G
Email Address	SAMLIM07@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90828606
Alternative Phone No	OFFICE-90828606

Vehicle Particulars

Manufacturer	BMW
Model	218
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN828917
Cover Note Number	

Driver

Name of Driver	LIM CHUN RUI MICHELLE
NRIC No	S9028683H
Date Of Birth	28/07/1990
Occupation	INDOOR
Date Of Driving Pass	22/12/2014
Driving Experience	2 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96709007
Fax Number	
Contact Number	
Email Address	MICHELLE.LIMCR@GMAIL.COM

Address	43 JALAN MATA AYER
Postcode	759127
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC5549T
Vehicle Make/Model/Colour	VW JETTA 1.4 TSI WHITE
Details Of Properties	
Name of Driver	LAM CHING MENG
NRIC/Passport Number	
Contact Number	90021980
Address	10A CANBERRA DRIVE
Postcode	768143
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

I am writing this letter to file a report for a car accident in which I was involved on 28.11.17. I, Lim Chun Fui Michelle, was driving my BMW 218i (SK7156Y) along Moulton Avenue at 23:00 and was taking the filter lane to make a left turn onto Sembawang Road. I stopped to give way to oncoming traffic along Sembawang Road, unfortunately a vehicle hit me from behind. That vehicle was a Volkswagen Jetta TS1.4 (SL5549T) and was being driven by Mr Lam Ching Mong. It was lightly drizzling at the time.

There was no personal injury, so we decided to move to the closest bus stop along Sembawang Road to take photographs of the accident and exchange particulars. Photos of the damaged back bumper of the BMW and videos are available.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time:

Driver's Signature (if driver is not the policyholder) / Date & Time:

Witnessed by Reporting Centre Personnel

At car In
on 12.12

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 15740133PW GST Reg. No M2-0020081-X



203, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 NOV 2017

Estimate No. : b1 45004	Page No. : 1 of 2
Date Estimated : 30/11/2017	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Lim Chun De Samuel (Lin Chunde) 43 Jalan Mata Ayer Singapore 759127	- ACCOUNT - 66 MSIG Insurance (S) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT656Y	V456546	21/05/2015	218iA AT	0

DESCRIPTION	VALUE
To replace rear bumper and air attachments	850 ✓ 2,550.00
To repair on rear tail end panel and attachment including knock out dent area cause by accident	plastic & repair tail lamp - 1700
Painting on rear bumper, rear tail end panel?	Repair tail lamp - 1602 934 ✓ 1,781.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	450? 531.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230? 271.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 ✓ 177.00
To replace rear PDC sensor wire harness including reset and checks for proper function	150 ✓ 226.00?
Sundries. <i>new</i>	hel 50? 150.00

Total Labour i: 5,726.00

DESCRIPTION	QTY	PRIC	VALUE
SILENCER CLAMPING BUSH?	1	61.50	61.50
RUBBER MOUNTING?	1	17.05	17.05
REAR SILENCER	1	1,167.45	1,167.45
TAILPIPE TRIM CHROME cut	1	95.15	95.15
HOLDER EXHAUST SYSTEM?	1	55.80	55.80
REAR BUMPER PANEL PRIMED (PDC) de	1	942.75	942.75
RR BUMPER LH SIDE GUIDE?	1	46.65	46.65
RR BUMPER RH SIDE GUIDE?	1	46.65	46.65
REAR BUMPER CARRIER?	1	413.45	413.45
SUPPORT?	1	36.40	36.40
REAR BUMPER TRIM STRIP (CHROM) gra	1	107.55	107.55
RR BUMPER LH INNER SIDE GUIDE?	1	57.15	57.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 19740155FW GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 436190
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63195528 (AfterSales)
63195533/535 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45004
Date Estimated : 30/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT656Y	V456546	21/05/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER RH INNER SIDE GUIDE	1	57.15	57.15
REAR FLAP TOWING EYE PRIMED	1	27.10	27.10
DECOUPING RING PDC TORQUE CONVERTER	4	4.95	19.80
ULTRASONIC SENSOR IMPERIALBLAU(WA89	1	363.05	363.05
Total Parts			4,603.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured Motorist / 1st Settlement

Regn No. _____ Claim No. _____

Date & Time 14/12/17 @ 11:20 Excess S\$ _____

Surveyor's Name Tanfah Sign _____

Surveyor's No 92451849 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanfah@lkkauto.com

No. of Working Days Recommend 3-4 days

Claims OD / 3rd Party / Uninsured Motorist / 1st Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____

Surveyor's No _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Labour 1	:	5,726.00
Parts	:	4,603.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	723.09
Grand Total	:	11,052.89

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

10330.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45004
Date Estimated : 30/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Lim Chun De Samuel (Lin Chunde)
43 Jalan Mata Ayer

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 759127

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKT656Y	V456546	21/05/2015	2181A AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG BLACK D=5MM *	0.90	1.00		0.90

Total Labour :
Total Parts : 0.90
Total Labour & Parts : 0.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45004
Date Estimated : 30/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Lim Chun De Samuel (Lin Chunde)
43 Jalan Mata Ayer

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 759127

REGN NO	CHASSIS NO	REGN DATE	MODEL	MLEAGE
SKT656Y	V456546	21/05/2015	218iA AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAILPIPE TRIM CHROME	95.15	1.00		95.15
REAR BUMPER PANEL PRIMED (PDC)	942.75	1.00		942.75
SUPPORT	36.40	1.00		36.40
REAR BUMPER TRIM STRIP (CHROM)	107.55	1.00		107.55
RR BUMPER LH INNER SIDE GUIDE	57.15	1.00		57.15
# PLUG BLACK D=5MM *	0.90	1.00		0.90
ULTRASONIC SENSOR IMPERIALBLAU(WA89	363.05	1.00		363.05

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,602.95
Total Labour & Parts :	3,766.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,766.95
GST @7%:	263.69
Grand Total :	4,030.64































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2017		30 Nov 2017 12:18 Edit Adj Rpt	S\$3,766.95 Edit Estimates	S\$3,766.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEM CHING MENG (LIN ZHENMING) , ID: S6822607D								
Main Claimant:	SAMUEL LIM CHUN DE , ID: S8233415G								
Vehicle Reg. No.:	SKT656Y	Date of Loss:	28/11/2017 22:00 - :59 [30 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 538843	Policy/Cover Note No.:	A28747260AVW (Comprehensive) Coverage: 18/05/2017 - 17/05/2018						
Vehicle Reg. No. (Insured):	SLC5549T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/12/2017]								
Driver/Custodian (Insured):	LEM CHING MENG (LIN ZHENMING) (), NRIC: S6822607D								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKT656Y (538843)**
[SLC5549T]
TP
SAMUEL LIM CHUN DE
Nov 28 2017 10:00PM
[LEM CHING MENG (LIN ZHENMING)]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 12:10	Adjuster Immediate Advice	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 10:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 10:31	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/06/18 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/11/17 10:36	SKT656Y E-FILE REPORT	 Load PDF	
2	30/11/17 10:36	OI SLC5549T E-FILE, DL & IC	 Load PDF	
3	30/11/17 10:36	ESTIMATE	 Load PDF	
4	30/11/17 12:19	Survey Agree on SJE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/18 09:35	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022804/T1QBQ2

Date: 25/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28747260AVW

Claimant Vehicle No : SKT656Y

Insured Vehicle No : SLC5549T

Date of Loss: 28/11/2017

Nature of Claim: TP

Claim No: 538843

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT656Y

Make & Model: BMW 218I, 1.5 ACTIVE TOURER D/AB LED DSC AB (A)

Engine No: 32499203B38A15A

Reg. Date: 21/05/2015 (Man. Year: 2015)

Chassis No: WBA2A32030V456546

Colour: Blue

Odometer: 38709 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,754.70	1,682.95	3,071.75	64.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,576.00	2,084.00	3,492.00	62.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,330.70	3,766.95	6,563.75	63.54
+ GST 7.00/7.00% (S\$)	723.15	263.69	459.46	63.54
Nett Amount (S\$)	11,053.85	4,030.64	7,023.21	63.54

INSPECTION

Date of Assignment: 30/11/2017

Date Inspected: 13/12/2017 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts:	M1-MPV	BMW 218i 1.5 ACTIVE TOURER D/AB LED DSC AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT656Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*SILENVER CLAMPING BUSH	Not Necessary	61.50 FS	*- FS
3	1		*RUBBER MOUNTING	Not Necessary	17.05 FS	*- FS
4	1		*REAR SILENCER	Not Necessary	1,167.45 FS	*- FS
5	1		*TAILPIPE TRIM CHROME	Cut	95.15 FS	*95.15 FS
6	1		*HOLDER EXHAYST SYSTEM	Not Necessary	55.80 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	942.75 FS	*942.75 FS
8	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	46.65 FS	*- FS
9	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	46.65 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	413.45 FS	*- FS
11	1		*SUPPORT	Necessary	36.40 FS	*36.40 FS
12	1		*REAR BUMPER TRIM STRIP (CHROM)	Cracked	107.55 FS	*107.55 FS
13	1		*RR BUMPER LH INNER SIDE GUIDE	Necessary	57.15 FS	*57.15 FS
14	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	57.15 FS	*- FS
15	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	27.10 FS	*- FS
16	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	19.80 FS	*- FS
17	1		*ULTRASONIC SENSOR IMPERIALBLAU (WA89)	Not Working	1,452.20 FS	*363.05 FS
18	1		*PLUG BLACK D=5MM	Necessary	0.90 FS	*0.90 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,754.70** **1,682.95**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND AIR ATTACHMENTS TO REPAIR ON REAR TAIL END PANEL AND ATTACHMENT INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER ,REAR TAIL END PANEL	New	1,781.00	934.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	0.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	266.00	150.00
Gross Labour Cost (S\$)			5,576.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >