

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 30/11/2017

Reference: SLM9907P
 Make: OPEL ASTRA
 HB 1.0 AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLM9907P
CHASSIS NO.: W0LBE6EA3HG097453
ENGINE NO.: B1170177HRXX0063

Name of insured : SUM XUEYAN
 Date of accident : 25/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	Rear Bumper <i>del</i>	\$ 1,800.00	1600
2	1	LHR Bumper Reflector <i>ut</i>	\$ 98.00	✓
3	1	Rear Number Plate Lamp <i>re n</i>	\$ 132.00	+
4	1	Rear Bumper Lower Trim <i>del</i>	\$ 362.00	✓
5	1	Rear Bumper Reinforcement Bar <i>Best</i>	\$ 716.00	✓
6	1	Rear End Panel <i>re n</i>	\$ 816.00	+
7	1	Rear End Panel Trim <i>re n</i>	\$ 196.00	✓
8	1	Rear End Panel Air Ventilator <i>re n</i>	\$ 72.00	+
9	1	Rear Bumper Centre Bracket <i>re n</i>	\$ 95.00	+
10	1	LHR Bumper Bracket, Guide <i>del</i>	\$ 85.00	✓
11	1	RHR Bumper Bracket, Guide <i>re n</i>	\$ 85.00	+
12	1	LHR Taillamp <i>re n</i>	\$ 618.00	+
13	1	LHR Tailgate Lamp	\$ 666.00	+
14	1	LHR Fender <i>re n</i>	\$ 1,893.00	+
15	1	LHR Fender Liner	\$ 115.00	+

2861
 2574.80

Parts Total: \$ 7,749.00
 Less 10%: \$ 774.90
 Total: \$ 6,974.10

Labour**Labour Description****No.****Price (SGD)****Rear portion**

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 800.00
2	Carry out spray painting on accident affected area	\$ 540.00
3	To conduct anti rust of under carriage tuff coat	\$ 80.00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
5	To remove and refix reverse sensor and conduct test	\$ 80.00

200.
200
x
✓
60

490

Labour Total : \$ 1,530.00**Others****Other Description****No. Qty****Price (SGD)****Rear portion**

1	10	Rear bumper upper clip <i>New</i>	\$ 65.00
2	10	Rear bumper lower clip <i>New</i>	\$ 65.00
3	1	Reverse sensor 1 set <i>27d</i>	\$ 280.00


30.
x
220

250

Other Total: \$ 410.00**GRAND TOTAL: \$ 8,914.10**

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

total: 3314.90

H/S: 2650

03 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: