



FINAL REPORT

Estimate No. : b1 45002
Date Estimated : 29/11/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Yap Tiong Toh
14 Amber Gardens
#05-02

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 439960

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SCE345T	VX38237	30/09/2014	X1 sDrive18d	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident			850.00		850.00
To spray paint rear bumper			934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.			150.00		150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.			150.00		150.00
Sundries.			40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER BOTTOM PANEL (BASIC/PDC	314.45	1.00		314.45
# EXPANDING RIVET *	1.35	10.00		13.50

SUPPLEMENTARY ITEMS

Total Labour :	2,124.00
Total Parts :	327.95
Total Labour & Parts :	2,451.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,451.95
GST @7%:	171.64
Grand Total :	2,623.59