

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9426E -**AAD1711-309***Not Authored*
11 Sep 81200

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9426E - JHOW

KL1LA69RJB072757

CHEVROLET

CHEVROLET EPICA 2.0

28.11.2017

AXA**PART****LIST**

1	1	Front Bumper	\$	K	1,202.00	}
2	1	Front Bumper Reinforcement	\$	K	295.25	
3	1	Front Bumper Lower Absorber	\$	Sn	180.00	
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	Sn	32.40	
5	1	Front Bumper Lower Grille	\$	Sn	78.00	
6	1	Front Bumper Lower Stiffener	\$	Sn	134.37	
7	1	Front Bumper Retainer LH	\$	Sn	102.00	
8	1	Front Headlamp LH	\$	Sn	816.00	
9	1	Front Support Panel Assy	\$	K	1,222.32	
10	1	Bonnet	\$	K	1,250.00	
11	1	Bonnet Moulding	\$	Sn	161.97	
12	1	Side Rocker Panel Garnish LH	\$	Sn	236.40	
13	1	Front Fender LH	\$	R	837.60	✓
14	1	Front Fender Liner LH	\$	Sn	47.00	X
15	1	Resonator (B/S Fender LH) AIR BOX	\$	Sn	134.67	X
16	1	Resonator Hose	\$	Sn	37.00	X
17	1	Radiator Grille (Grille A-Rad)	\$	Sn	367.00	X
18	1	Side Rocker Panel Garnish LH	\$	Sn	236.40	X
19	1	Front Door LH	\$	K	1,133.00	X
20	1	Front Side View Mirror LH	\$	Sn	939.00	X

TOTAL	\$	9,442.38
10%	\$	944.24
	\$	8,498.14

Special Nett

1	1 Set Front Bumper Fastener Clip	\$	nn	30.00	X
2	1 Set Front licence plate with holder	\$	Sn	192.00	X
3	1 Set Radiator Grille Top Cover Clip	\$	nn	10.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-309**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9426E -

4	1 Set Radiator Grille clip	\$	<i>nn</i>	35.00	X
5	1 Set Front Fender Liner Clip	\$	<i>nn</i>	30.00	X
6	1 Door Sticker "Trans-cab"	\$	<i>nn</i>	80.00	X
7	1 Front Tyre LH	\$	<i>sh</i>	360.00	X
8	1 Front Wheel Rim LH	\$	<i>sh</i>	254.00	X
9	1 Front Wheel Rim Hub Cap LH	\$	<i>sh</i>	166.30	X

TOTAL	\$	1,157.30
TOTAL PARTS	\$	9,655.44

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *300*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected
Portion.

\$ 2,700.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

TOTAL	\$	6,280.00
Over All Total	\$	15,935.44

REPAIR DAYS**~~10~~ DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: