

ASS. REC. BY:

REF: CS/MSG17022815 / T11b02

Special Instruction:

Survivor: Taufik.

ASSIGNMENT (Office)

Mentimen

From (Person): Clara Miah Yeo

of MSIG

Date/Time: 30/11/17 @ 3.21pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 8831K

Insured:

at Workshop m/s

Borneo Motors

Tel:

66311505

of

2 Pandan Crescent, 128462

Policy No:

MSD/VPCP/17-00376

Claim No:

MSC/V/17-001870

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

D.O.A

30/11/2017

(Client's Record)

01/12/2017 @ Morning

CA / REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.20pm @ 30/11/17

Person Contacted:

Carine Yeo

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 8831K - X
4/12-	Report via mentimen
4/12-	authorise repair by Ng Chen Hwa
4/12-	email to Carine Yeo authorise repair excess 1.5K
	part by part \$271878.78. 12 days (Red: 18319.08, 39%)

Tanjah

MSIG

ADDITIONAL

From: Date 01/12/17

Estimated Cost:

② TP / WS / TP RES / OD RES / EVA / INV / M /

To inspect vehicle No SLL 8831K

at Workshop No Borneo Motors

at 2pandan Crescent, 128 462

Insured

Policy No

Claims No

Sum Insured Excess \$1,500.00


Client's Record Carine Yeo

Make of car

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value \$174K

IDAC Accident Report Consistent? : Yes or No

GIA / PP / Seen Consistent? : Yes or No

Est. Repairs days Res: Yes or No

Sum. Sum. % 3 Val: Yes or No

OA / ② REV / REP / 24 HRS

Date Person Contacted

Vehicle IN / OUT

SLL 8831K Page 2017 Feb.

Type M / B / M / Cycle / Bus / Van / Lorry / Truck / Prime Mover

Truck / Trailer

Make Toyota Lexus ES250 AT SR 2494

Colour White A.C. Insured Std / Nil / NA

Se. Reading 10827 T. Rep. Insured Std / Nil / NA

Eng No

Ch No JT HRS J146 702094833

Gen. Cond. Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brakes Inorder / Jammed / Leaked / Burnt or

Mod. Nil / S.R. / STD A / Rim or

Tyre Size R 2.5 / 55R17
R.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R. Bal. 6 mm R. Bal. 6 mm

L. Bal. 6 mm L. Bal. 6 mm

D.O.A. 01/12/17 11am

Survey held at Borneo Pandan

Des. of Damages, Fr. Rear : OS / NS / UO / Rooftop or

The U.O. / Chassis frame Body Structure affected due to collision

Date Time Action Instruction

RECEIVED 2018

Date Time File Passed

☐ Prel. Report
☒ Final Report

13 Typist

Date Time File Returned

Days Of Repair 12

Resurvey No. of Trk. 2

Add Fee: ☐ Site Inst. \$

☐ Name \$
☐ Test \$
☐ Agent \$

Report Form No

27,878.78

Survey Fee

Transport

Insurance

Other

Total

450

10

460

TYPE OF CLAIM: ☒ OD ☐ OD/UL ☐ DS

MCA: Carine Yeo

MOTOR ACCIDENT REPORT

Date Of Report: 30/11/17 Time: 1015hrs Date Of Accident: 30/11/17 Time: 0830hrs
 Exact Location Of Accident: SLE near Madan Exit speed camera lamp post number 42
 Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLL 883/K Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 199400399N
 Name Of Registered Owner: Hitechi Capital Asia Pacific Pte Ltd
 Mobile Number: 94870213 Alternative No: Email Address: cys523@yahoo.com.sg

Vehicle Particulars

Manufacturer: Toyota ☐ Lexus ☒ Suzuki ☐ Hino ☐ Model: ESSO Executive
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
 Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIG Insurance Singapore Pte Ltd
 Any In-Car Camera? (applicable for United Overseas Insurance Limited insured only): Yes ☒ (please attach photo) No ☐
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: MSD/VPCP/IT-008T6-00

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Yong Lee Fong NRIC/ Passport / FIN No: S70249270
 Date Of Birth: 14/8/1970 Occupation: Indoor ☒ Outdoor ☐
 Date Of Driving Pass: 21/9/2004 Gender: Male ☒ Female ☐
 Mobile Number: 94870213 Fax No: Alternative No:
 Address: 21 Roswood Drive #12-01 Postal Code: 737917
 Email Address: cys523@yahoo.com.sg
 Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:
 Vehicle Registration Number of Driver's Own Vehicle (if applicable):
 Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Front Portion Number of Passengers in the above vehicle (Including Driver):
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
 Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
 Was any body injured in the Accident? No ☒ Yes ☐
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
 Was any other material or property (e.g. other vehicle) damaged? No ☐ Yes ☐
 Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒
 Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
 Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☐ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SKF 5395P Vehicle Make/Model/Colour:
 Details Of Properties Damage in Accident:
 Name of Driver: Vinil Kumar Gopinathan Nair & Mohd Azhar
 NRIC/Passport/FIN Number: S7060924Z Contact Number:
 Address: 119 Marsiling Rise #07-130 Postal Code: 730119
 Insurance Company Name:
 Nature Of Damage: Frontal Rear No. Of Passenger (Including Driver):

DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name: Phone Number: Email Address:

DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name: Approximate Age: Postal Code:
 Address: Injured person in which vehicle:
 Injuries Sustained: Were seat belt worn? No ☐ Yes ☐ Were injured conveyed to hospital by ambulance? No ☐ Yes ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

SLE near Mandai Exit			
→ A B C D			
A - SLL 8831 K	B - SKA 5396 P	C - SJM 8666 P	D - SLN 6519 R

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

CERTIFICATE OF INSURANCE

Motor Vehicles (Third Party Risks And Compensation) Act (Chapter 189)

Motor Vehicles (Third Party Risks And Compensation) Rules, 1960

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

17/02/2017

Excess : \$1500/-SECT I

Others Excess : Refer to your policy schedule

A0215-101

MSD/VPCP/17-000376-00

CERTIFICATE No.

1. Index Mark and Registration

Number of Vehicle

SLL8831K

2. Name of Policy holder

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

3. Effective date of the Commencement of
Insurance for the purposes of the
Act

10/02/2017

4. Date of Expiry of Insurance

09/02/2018

5. Persons of classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicles or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And Provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use*

1. Use for the carriage of passengers or goods in connection with the policyholder's business.

2. Use for social, domestic & pleasure purposes and business purposes of any person to whom the vehicle is hired.

The Policy does not cover:-

1. Use for racing, pace-making, reliability trial or speed-testing.

2. Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

3. Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

AUTHORIZED SIGNATURE

IMPORTANT NOTICE

This Certificate is not transferable to a new owner of the vehicle.

If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that Effect has to be made. Failure to comply with this obligation is an

offence under the compulsory Insurance Legislation. This Certificate must be returned if the insurance is suspended during its currency.

If you are involved in an accident, full details must be forwarded immediately to the Company.

REPUBLIC OF SINGAPORE



14 Aug 1970
18 Jan 2008



002648795H

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7027927D



Name

YONG LEE FONG

杨 丽 芳

Race

CHINESE

Date of birth

14-08-1970

Sex

F

S7027927D

Country of birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg 21 Sep 2004

NP 428A



Licence No: S7027927D

4320500



NRIC No S7027927D



Date of issue

24-11-2008

21 ROSEWOOD DRIVE #12-01
SINGAPORE 737917

NRIC No: S7027927D

Date: 22/09/2009

No: 6269577

Labour	Parts		Check	
50	794.75	18.7		
4080	410.8	75.14	139.31	
4200	115.51	394.57	139.31	
100	83.47	12.24	100.47	1156.17
816	729.55	4446.43	100.47	35.87
204	47.26	20.22	35.44	232.73
100	47.26	27.2	35.44	196.35
120	12.4	6.12	287.89	131.15
612	11.9	37.4	40.54	44.96
96	10.7	1737.48	1104.15	78.28
<u>10378</u>	71.57		83.47	69.78
	116.7	14345.05	228.99	81
	306.68		240.89	71.57
	962.45		58.73	71.57
	33.1		287.89	74.8
	1860.14		287.89	77.3
	1104.15	total	1193.48	4446.43
	60.26	24723.05	130.56	144.5
	69.1		112.96	11.04
	69.1		112.96	438.6
	139.31		257.8	438.6
	249.64		191.33	152.49
	15.3			819.22
	125.46			<u>19208.81</u>
	122.99			819.22
				195.07
				2301.97
				264.77
				215.81
				269.79
				196.8
				187

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No 0	
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 :10D/SLL8831K/30111'
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: MSD/VPSP/17-00376-00 TOW/DRIVE IN:DRIVE IN ACC DATE: 30.11.2017 DATE-IN: 30.11.2017 EXCESS: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50,100.00/4
2	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				4080.00
3	B	BP-LAB TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, BONNET, BOTH FRONT FENDERS, FRONT SUPPORT, LHS FRONT DOOR, BOTH FRONT CHASSIS FRAME AND FIX NEW PARTS				4896.00
4	B	BP-RES TO SPRAY PAINT ON WHOLE FRONT PORTION INCL FRONT SUPPORT, BOTH FRONT CHASSIS FRAMES AND LHS FRONT DOOR				4200.00
5	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)				100.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Taufik 97495749.
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis	Labour	Revert 31/11/17 @ 11am.
		Materials	Ex \$1500.
		Lubrication/Fluid	Resurvey before paint
		Others	sur@trkauto.com.
			Amount Due 12 days.

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No 0	
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 MOD/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
6	B	BP-MECH TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR, ETC... TO ENABLE REPAIR (NETT)				✓ 816.00
7	B	BP-LAB TO REMOVE AND REPLACE FRONT PARKING SENSOR (NETT)				✓ 204.00 ✓
8	Z	BP-SLANT SUPPLY FRONT SUPPORT SEALANT (NETT)				✓ 100.00 ✓
9	Z	BP-SLANT SUPPLY BOTH FRONT CHASSIS FRAME SEALANT (NETT)				✓ 120.00 ✓
10	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				✓ 612.00 ✓
11	B	BP-MECH TO REMOVE AND REPLACE FRONT WIRE HARNESS (NETT)				? 816.00 ✓
12	L	BP-LPO SUPPLY FRONT NO PLATE AND CASING (NETT)				bt ✓ 96.00 ✓
13	1	L52119-3T910 COVER, FR BUMPER	1.00	935.00	15.00	✓ 794.75
14	2	L52021-33210 REINFORCEMENT	1.00	483.30	15.00	✓ 410.80
15	3	L52611-33280 ABSORBER, FR BUMPER	1.00	135.90	15.00	✓ 115.51
16	4	L53155-33060 SEAL, RADIATOR	1.00	98.20	15.00	✓ 83.47

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre

No.2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1388

Account Detail	Account No S1000004 / ICCUA1	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	Document No 0	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 MOD/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	5	L53102-33080 GRILLE SUB-ASSY, <i>cr</i>	1.00	858.30	15.00	✓ 729.55
18	6	L52146-33070 STAY, FR BUMPER <i>rec</i>	1.00	55.60	15.00	✓ 47.26
19	7	L52145-33070 STAY, FR BUMPER <i>rec</i>	1.00	55.60	15.00	✓ 47.26
20	8	L52197-30040 BUMPER BRACKET, <i>rec</i>	2.00	7.30	15.00	✓ 12.40
21	9	L47749-50090 CLIP <i>rec</i>	10.00	1.40	15.00	✓ 11.90
22	0	T53879-30020 RETAINER, FR FENDER <i>rec</i>	2.00	6.30	15.00	20 40 10.70
23	1	L52126-33120 BRACKET, FOG LAMP ?	1.00	163.90	15.00	139.31
24	2	L52125-33120 BRACKET, FOG LAMP ?	1.00	163.90	15.00	139.31
25	3	L81482-33040 COVER, FOG LAMP, LH ?	1.00	118.20	15.00	100.47
26	4	L81481-33060 COVER, FOG LAMP, RH ?	1.00	118.20	15.00	100.47
27	5	L53128-33020 GRILLE, RADIATOR, ?	1.00	41.70	15.00	35.44
28	6	L53127-33020 GRILLE, RADIATOR, ?	1.00	41.70	15.00	35.44
29	7	L52128-33210 COVER, FR BUMPER <i>de</i>	1.00	84.20	15.00	71.57
30	8	L52114-33450 BRACKET, FR BUMPER <i>cr</i>	1.00	137.30	15.00	116.70
31	9	L53121-33080 MOULDING, RADIATOR <i>cr</i>	1.00	360.80	15.00	306.68
32	0	L53111-33450 GRILLE, RADIATOR <i>cr</i>	1.00	1132.30	15.00	962.45
33	1	S52161-0K040 BUMPER CLIPS <i>rec</i>	10.00	3.90	15.00	33.10
34	2	L53301-33160 HOOD SUB-ASSY <i>bt</i>	1.00	2188.40	15.00	1860.14
35	3	L53341-33200 INSULATOR, HOOD ?	1.00	338.70	15.00	287.89
36	4	L53381-33100 SEAL, HOOD TO ?	1.00	47.70	15.00	40.54

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 30/11/2017

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No 0	
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 MOD/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
37	5	L53812-33230 FENDER, FR LH <i>bt</i>	1.00	1299.00	15.00	1104.15
38	6	L53811-33230 FENDER, FR RH ?	1.00	1299.00	15.00	1104.15
39	7	L53828-33070 PROTECTOR, FR FENDER ?	1.00	98.20	15.00	83.47
40	8	L53875-33220 LINER, FR FENDER RH ?	1.00	269.40	15.00	228.99
41	9	L53876-33230 LINER, FR FENDER, LH ?	1.00	283.40	15.00	240.89
42	0	L53804-33040 BRACKET SUB-ASSY FR <i>rec</i>	1.00	70.90	15.00	60.26
43	1	L53835-33100 BRACE, FR FENDER TO ?	1.00	69.10	15.00	58.73
44	2	L53420-33290 HINGE ASSY, HOOD, LH <i>bt</i>	1.00	81.30	15.00	69.10
45	3	L53410-33290 HINGE ASSY, HOOD, RH <i>bt</i>	1.00	81.30	15.00	69.10
46	4	L53510-33410 LOCK ASSY, HOOD <i>bt</i>	1.00	163.90	15.00	139.31
47	5	L53450-33090 SUPPORT ASSY, HOOD ?	1.00	338.70	15.00	287.89
48	6	L53440-33100 SUPPORT ASSY, HOOD ?	1.00	338.70	15.00	287.89
49	7	L53201-33191 SUPPORT, RADIATOR ? <i>photo sent</i>	1.00	1404.10	15.00	1193.48
50	8	L53295-33080 SEAL, COOL AIR <i>de</i>	1.00	293.70	15.00	249.64
51	9	T90467-07217 CLIP <i>rec</i>	9.00	2.00	15.00	15.30
52	0	L53208-33070 SUPPORT SUB-ASSY, <i>bt</i>	1.00	147.60	15.00	125.46
53	1	L53294-33150 DEFLECTOR, RADIATOR LH <i>de</i>	1.00	144.70	15.00	122.99
54	2	L53293-33140 DEFLECTOR, RADIATOR RH ?	1.00	153.60	15.00	130.56
55	3	L57108-33032 PLATE SUB-ASSY, FR ?	1.00	132.90	15.00	112.96
56	4	L57107-33032 PLATE SUB-ASSY, FR ? <i>photo</i>	1.00	132.90	15.00	112.96

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No 0	
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
57	5	L51442-33200 COVER, ENGINE UNDER, ?	1.00	303.30	15.00	257.80
58	6	L51441-33200 COVER, ENGINE UNDER, ?	1.00	225.10	15.00	191.33
59	7	T90467-07214 CLIP <i>me</i>	10.00	2.20	15.00	18.70
60	8	L67002-33240 PANEL, FR DOOR LH ?	1.00	1360.20	15.00	1156.17
61	9	L75986-33030 STRIPE FR DOOR ?	1.00	42.20	15.00	35.87
62	0	L67862-33100 WEATHERSTRIP, FR ?	1.00	273.80	15.00	232.73
63	1	T67867-12150 RETAINER, DOOR <i>me</i>	17.00	5.20	15.00	75.14
64	2	L68620-33100 CHECK ASSY, FR DOOR, ?	1.00	231.00	15.00	196.35
65	3	L68172-33100 WEATHERSTRIP, FR ?	1.00	154.30	15.00	131.15
66	4	L67492-33150 GARNISH, FR DOOR LWR ?	1.00	52.90	15.00	44.96
67	5	T68740-12120 L/FRT DOOR LOW HINGE, ?	1.00	92.10	15.00	78.28
68	6	T68720-12151 HINGE ASSY, FR DOOR ?	1.00	82.10	15.00	69.78
69	7	L90975-02125 EMBLEM, SYMBOL <i>me</i>	1.00	464.20	15.00	394.57
70	8	L90269-04051 RIVET <i>me</i>	12.00	1.20	15.00	12.24
71	9	L75756-33070 MOULDING FR DOOR	1.00	95.30	15.00	81.00
72	0	L75536-33020 MOULDING, WINDSHIELD LH ? <i>photo</i>	1.00	84.20	15.00	71.57
73	1	L75535-33020 MOULDING, WINDSHIELD RH ?	1.00	84.20	15.00	71.57
74	2	L75545-30170 CLIP, WINDSHIELD ?	10.00	8.80	15.00	74.80
75	3	L75547-51021 ROOF DRIP MLDG CLIP, ?	10.00	9.10	15.00	77.30
76	4	L81106-33B00 UNIT ASSY, HEADLAMP, LH <i>me</i>	1.00	5231.10	15.00	4446.43

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No 0	
	Document Date 30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 MOD/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
77	5	L81105-33D00 UNIT ASSY, HEADLAMP, RH ?	1.00	5231.10	15.00	4446.43 ✓
78	6	L90981-13084 BULB HEADLAMP NO.1 ?	2.00	85.00	15.00	144.50 ✓
79	7	L90981-15021 BULB ?	2.00	6.50	15.00	11.04 ✓
80	8	L81220-48051 LAMP ASSY, FOG, LH ?	1.00	516.00	15.00	438.60 ✓
81	9	L81210-48051 LAMP ASSY, FOG RH ?	1.00	516.00	15.00	438.60 ✓
82	0	L82114-33031 WIRE, ENGINE ROOM, ?	1.00	179.40	15.00	152.49 ✓
83	1	L89341-78010 C1 SENSOR, ULTRASONIC, ? photo	2.00	481.90	15.00	819.22 ✓
84	2	L89348-76010 CLIP, ULTRASONIC ne ✓	2.00	11.90	15.00	20.22 ✓
85	3	L89348-78020 RETAINER, ULTRASONIC ne ✓	2.00	16.00	15.00	27.20 ✓
86	4	L89341-78010 AO SENSOR, ULTRASONIC, ? photo	2.00	481.90	15.00	819.22 ✓
87	5	L89348-35030 CLIP, ULTRASONIC ne ✓	2.00	3.60	15.00	6.12 ✓
88	6	L85315-33461 JAR, WASHER, A ne ✓	1.00	229.50	15.00	195.07 ✓
89	7	L85272-28030 CLAMP, HEADLAMP ne ✓	2.00	22.00	15.00	37.40 ✓
90	8	L88460-33180 CONDENSER ASSY dd ✓	1.00	2044.10	15.00	1737.48 ✓
91	9	T16400-31770 RADIATOR ASSY ?	1.00	2708.20	15.00	2301.97 ✓
92	0	L16711-36120 SHROUD FAN ?	1.00	311.50	15.00	264.77 ✓
93	1	L16361-36030 FAN ?	1.00	253.90	15.00	215.81 ✓
94	2	L16361-36040 FAN ?	1.00	317.40	15.00	269.79 ✓
95	3	S08889-80110 COOLANT, LONG LIF ?	2.00	98.40		196.80 ✓
96	4	L17750-36021 INLET ASSY, AIR ?	1.00	220.00	15.00	187.00 ✓

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202
	Document No	
	Document Date	
	0	
	30/11/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	ASV60R	10/02/2017	SLL8831K	0	14705 10D/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
97	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.				
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						46563.27

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 32,737.86	46,197.86
		Labour 13,364.00	GST 7.00% 3,233.85
		Materials 96.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 49,431.71

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/11/2017
TIME 14:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388


Account Detail		Account No		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1		M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202			
		Document No					
		0					
		Document Date					
		06/12/2017					

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	10/02/2017	SLL8831K	0	14738	SLL8831K

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUPPLEMENTARY ESTIMATE POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				
2	B	BP-LAB TO REMOVE AND REPLACE BOTH HEADLAMP. CHECK AND FOCUS HEADLIGHTS (NETT)				✓ 204.00
3	1	L16561-36020 SEAL, RADIATOR TO	1.00	24.60	15.00	new 20.91
4	2	L16563-36010 SEAL, RADIATOR TO	2.00	8.50	15.00	new 14.44
5	3	L16562-36010 SEAL, RADIATOR TO	1.00	19.90	15.00	new 16.91
6	4	L86520-48030 HORN ASSY LOW	1.00	117.00	15.00	new 99.45

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	355.71
	Please acknowledge receipt of vehicle	Parts	151.71	GST 7.00%
		Labour	204.00	
		Materials	0.00	Less
		Lubrication/Fluid	0.00	
		Others	0.00	
			Amount Due	380.61

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 06/12/2017
TIME 12:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Reg No : MR 8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202			
				Document Date 14/12/2017					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
16	BETGK S3	ASV60R	10/02/2017	SLL8831K	12002	14705	10D/SLL8831K/30111		
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On			
JTHBJGG702094833	2ARF251020		60	Carine Yeo C L	05/12/2017	8.00	14/12/2017 18.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	B	BP-SUNDRY SUNDRIES POLICY NO.: MSD/VPSP/17-00376-00 TOW/DRIVE IN: DRIVE IN ACC DATE: 30.11.2017 DATE-IN: 30.11.2017 EXCESS: 1500.00 DATE SURVEY: 31.11.2017 NO OF REPAIR DAYS: 12 BY: TAUFIKH (LKK) AUTHORISED ON: 04.12.2017							50.00
2	B	BP-LAB TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, BONNET, BOTH FRONT FENDERS, FRONT SUPPORT, LHS FRONT DOOR, BOTH FRONT CHASSIS FRAME AND FIX NEW PARTS				31			4080.00
3	B	BP-RES TO SPRAY PAINT ON WHOLE FRONT PORTION INCL FRONT SUPPORT, BOTH FRONT CHASSIS FRAMES AND LHS FRONT DOOR				*			4200.00
4	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)							100.00
5	B	BP-MECH TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR, ETC... TO ENABLE REPAIR (NETT)				46			816.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total			
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less			
						Amount Due			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/12/2017
 TIME 11:52

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MB 95900000-9
ESTIMATE**Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Account No S1000004 / ICCUA1		Customer Detail M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202				
		Document No 0						
		Document Date 14/12/2017						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
16	BETGK S3	ASV60R	10/02/2017	SLL8831K	12002	14705	10D/SLL8831K/30111	
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBJ1GG702094833		2ARF251020	60	Carine Yeo C L	05/12/2017	8.00	14/12/2017 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
6	B	BP-LAB TO REMOVE AND REPLACE FRONT PARKING SENSOR (NETT)			31			204.00
7	B	BP-LAB TO REMOVE AND REPLACE BOTH HEADLAMPS. CHECK AND FOCUS HEADLIGHTS (NETT)			31			204.00
8	Z	BP-SLANT SUPPLY FRONT SUPPORT SEALANT (NETT)						100.00
9	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)			18			612.00
10	L	BP-LPO SUPPLY FRONT NO PLATE AND CASING (NETT)			E33			96.00
11	V	EXC PO#3011 Excess element of insurance repair to be paid by the insured party			88			-1500.00
12	1	L52119-3T910 COVER, FR BUMPER			1.00	935.00	15.00	794.75
13	2	L52611-33280 ABSORBER, FR BUMPER			1.00	135.90	15.00	115.51
14	3	L53155-33060 SEAL, RADIATOR			1.00	98.20	15.00	83.47
15	4	L53102-33080 GRILLE SUB-ASSY,			1.00	858.30	15.00	729.55
16	5	L52146-33070 STAY, FR BUMPER			1.00	55.60	15.00	47.26
17	6	L52145-33070 STAY, FR BUMPER			1.00	55.60	15.00	47.26
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less		
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLL8831K

CUSTOMER

DATE 14/12/2017
TIME 11:52SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Ref No : 196700000-9

ESTIMATE**Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Account No S1000004 / ICCUA1		Customer Detail M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202	
		Document No 0			
		Document Date 14/12/2017			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BETGK	S3	10/02/2017	SLL8831K	12002	14705	10D/SLL8831K/30111

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBJLGG702094833	2ARF251020	60	Carine Yeo C L	05/12/2017	8.00	14/12/2017 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
18	7	L52197-30040 BRACKET, BUMPER	2.00	7.30	15.00	12.40
19	8	L47749-50090 CLIP, PIN HOLD	10.00	1.40	15.00	11.90
20	9	L53879-30040 RETAINER, FR FENDER	2.00	12.00	15.00	20.40
21	0	L53128-33020 GRILLE, RADIATOR,	1.00	41.70	15.00	35.44
22	1	L52114-33450 BRACKET, FR BUMPER	1.00	137.30	15.00	116.70
23	2	L53121-33080 MOULDING, RADIATOR	1.00	360.80	15.00	306.68
24	3	L53111-33450 GRILLE, RADIATOR	1.00	1132.30	15.00	962.45
25	4	S52161-OK040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10
26	5	L53301-33160 HOOD SUB-ASSY	1.00	2188.40	15.00	1860.14
27	6	L53812-33230 FENDER, FR LH	1.00	1299.00	15.00	1104.15
28	7	L53804-33040 BRACKET SUB-ASSY FR	1.00	70.90	15.00	60.26
29	8	L53510-33410 LOCK ASSY, HOOD	1.00	163.90	15.00	139.31
30	9	L53201-33191 SUPPORT, RADIATOR	1.00	1404.10	15.00	1193.48
31	0	L53295-33080 SEAL, COOL AIR	1.00	293.70	15.00	249.64
32	1	T90467-07217 CLIP	9.00	2.00	15.00	15.30
33	2	L53208-33070 SUPPORT SUB-ASSY,	1.00	147.60	15.00	125.46
34	3	L53294-33150 DEFLECTOR, RADIATOR	1.00	144.70	15.00	122.99
35	4	T90467-07214 CLIP	10.00	2.20	15.00	18.70
36	5	T67867-12150 RETAINER, DOOR	17.00	5.20	15.00	75.14
37	6	L90975-02125 EMBLEM, SYMBOL	1.00	464.20	15.00	394.57

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/12/2017
 TIME 11:52

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**


TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MB 0500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202			
				Document Date 14/12/2017					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
16	BETGK S3	ASV60R	10/02/2017	SLL8831K	12002	14705	10D/SLL8831K/30111		
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On			
JTHBJ1GG702094833	2ARF251020	60	Carine Yeo C L	05/12/2017	8.00	14/12/2017 18.00			
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
38	7	L90269-04051 RIVET				12.00	1.20	15.00	12.24
39	8	L81106-33B00 UNIT ASSY, HEADLAMP, LH				1.00	5231.10	15.00	4446.43
40	9	L89348-76010 CLIP, ULTRASONIC				2.00	11.90	15.00	20.22
41	0	L89348-78020 RETAINER, ULTRASONIC				2.00	16.00	15.00	27.20
42	1	L89348-35030 CLIP, ULTRASONIC				2.00	3.60	15.00	6.12
43	2	L85272-28030 CLAMP, HEADLAMP				2.00	22.00	15.00	37.40
44	3	L88460-33180 CONDENSER ASSY				1.00	2044.10	15.00	1737.48
45	4	L16400-31770 RADIATOR ASSY				1.00	2708.20	15.00	2301.97
46	5	L16561-36020 SEAL, RADIATOR TO				1.00	24.60	15.00	20.91
47	6	L16563-36010 SEAL, RADIATOR TO				2.00	8.50	15.00	14.44
48	7	L16562-36010 SEAL, RADIATOR TO				1.00	19.90	15.00	16.91
49	8	L86520-48030 HORN ASSY LOW				1.00	117.00	15.00	99.45
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		26,378.78	
		Please acknowledge receipt of vehicle		Parts		GST 7.00%		1,846.51	
				Labour		0.00		0.00	
				Materials		0.00			
				Lubrication/Fluid		0.00			
				Others		0.00			
						Amount Due		28,225.29	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLL8831K

CUSTOMER

DATE 14/12/2017
TIME 11:52

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No	Customer Detail					
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/s Hitachi Capital Asia Pacific 111 Somerset Road #11-05 Tripleone Somerset Singapore 238164 Attn: Augustine Mobile: 92325202					
		Document No						
		Document Date						
		0						
		06/12/2017						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
16	BETGK S3	ASV60R	10/02/2017	SLL8831K	0	14738	SLL8831K	
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBJ1GG702094833	ZARF251020	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUPPLEMENTARY ESTIMATE POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						204.00
2	B	BP-LAB TO REMOVE AND REPLACE BOTH HEADLAMP. CHECK AND FOCUS HEADLIGHTS (NETT)						
3	1	L16561-36020	SEAL, RADIATOR TO	1.00	24.60	15.00	20.91	
4	2	L16563-36010	SEAL, RADIATOR TO	2.00	8.50	15.00	14.44	
5	3	L16562-36010	SEAL, RADIATOR TO	1.00	19.90	15.00	16.91	
6	4	L86520-48030	HORN ASSY LOW	1.00	117.00	15.00	99.45	
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		355.71
		Please acknowledge receipt of vehicle		Parts	151.71	GST 7.00%	24.90	
				Labour	204.00	Less	0.00	
				Materials	0.00			
				Lubrication/Fluid	0.00			
				Others	0.00			
						Amount Due	380.61	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 06/12/2017
TIME 12:08

VEHICLE NO SLL8831K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Nov 2017		30 Nov 2017 15:21 Edit Adj Rpt	S\$27,878.78 Edit Estimates	S\$27,878.78 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]		
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N					
Vehicle Reg. No.:	SLL8831K	Date of Loss:	30/11/2017 08:00 - :59			
Claim Type:	OD / MSC/V/17-001870	Policy/Cover Note No.:	MSD/VPCP/17-00376 (Comprehensive) Coverage: 10/02/2017 - 09/02/2018			
		Excess:	S\$1,500.00			
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/12/2017]					
Driver/Custodian:	YONG LEE FONG (47 / Female), NRIC: S7027927D, Tel: +6594870213					
Adj Asg. Remarks:	Please revert. Thanks.					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
- MSIG_SG (01/03/2018): Alert - Adj Mandate Approved (S\$27878.78) - SLL8831K - Claim Handler: Clara Mila... - MSIG_SG (11/12/2017): Alert - Adj Mandate Approved (S\$25078.76) - SLL8831K - Claim Handler: Clara Mila... - MSIG_SG (04/12/2017): Alert - Adj Mandate Approved (S\$24723.05) - SLL8831K - Claim Handler: Clara Mila...			

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLL8831K (MSC/V/17-001870)**

OD

Nov 30 2017 8:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Borneo Motors (S) Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/01/18 16:47	Video - OI video		Load MP4	
Assessment Reports			1 per page		
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	30/11/17 14:48	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/17 11:41	Adjuster Immediate Advice		Load HTM	
2	08/12/17 14:55	Adjuster Immediate Advice		Load HTM	
3	01/03/18 10:31	Adjuster Immediate Advice		Load HTM	
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/17 11:54	General View		Load JPG	
2	04/12/17 11:54	General View		Load JPG	
3	04/12/17 11:54	General View		Load JPG	
4	04/12/17 11:54	General View		Load JPG	
5	04/12/17 11:54	General View		Load JPG	
6	04/12/17 11:54	General View		Load JPG	
7	04/12/17 11:54	General View		Load JPG	
8	04/12/17 11:54	General View		Load JPG	
9	04/12/17 11:54	General View		Load JPG	
10	04/12/17 11:54	General View		Load JPG	
11	04/12/17 11:54	General View		Load JPG	
12	04/12/17 11:54	General View		Load JPG	
13	04/12/17 11:54	General View		Load JPG	
14	04/12/17 11:54	General View		Load JPG	
15	04/12/17 11:54	General View		Load JPG	
16	04/12/17 11:54	General View		Load JPG	
17	04/12/17 11:54	General View		Load JPG	
18	04/12/17 11:54	General View		Load JPG	
19	04/12/17 11:54	General View		Load JPG	
20	04/12/17 11:54	General View		Load JPG	
21	04/12/17 11:54	General View		Load JPG	
22	04/12/17 11:54	General View		Load JPG	
23	04/12/17 11:54	General View		Load JPG	
24	04/12/17 11:54	General View		Load JPG	
25	04/12/17 11:54	General View		Load JPG	

26	04/12/17 11:54	General View	1	Load JPG	☒
27	04/12/17 11:54	General View	1	Load JPG	☒
28	04/12/17 11:54	General View	1	Load JPG	☒
29	04/12/17 11:54	General View	1	Load JPG	☒
30	04/12/17 11:54	General View	1	Load JPG	☒
31	04/12/17 11:54	General View	1	Load JPG	☒
32	04/12/17 11:54	General View	1	Load JPG	☒
33	04/12/17 11:54	General View	1	Load JPG	☒
34	04/12/17 11:54	General View	1	Load JPG	☒
35	04/12/17 11:54	General View	1	Load JPG	☒
36	04/12/17 11:54	General View	1	Load JPG	☒
37	04/12/17 11:54	General View	1	Load JPG	☒
38	04/12/17 11:54	General View	1	Load JPG	☒
39	04/12/17 11:54	General View	1	Load JPG	☒
40	04/12/17 11:54	General View	1	Load JPG	☒
41	04/12/17 11:54	General View	1	Load JPG	☒
42	04/12/17 11:54	General View	1	Load JPG	☒
43	04/12/17 11:54	General View	1	Load JPG	☒
44	04/12/17 11:54	General View	1	Load JPG	☒
45	04/12/17 11:54	General View	1	Load JPG	☒
46	04/12/17 11:54	General View	1	Load JPG	☒
47	04/12/17 11:54	General View	1	Load JPG	☒
48	04/12/17 11:54	General View	1	Load JPG	☒
49	04/12/17 11:54	General View	1	Load JPG	☒
50	04/12/17 11:54	General View	1	Load JPG	☒
51	04/12/17 11:54	General View	1	Load JPG	☒
52	04/12/17 11:55	General View	1	Load JPG	☒
53	04/12/17 11:55	General View	1	Load JPG	☒
54	04/12/17 11:55	General View	1	Load JPG	☒
55	04/12/17 11:55	General View	1	Load JPG	☒
56	04/12/17 11:55	General View	1	Load JPG	☒
57	04/12/17 11:55	General View	1	Load JPG	☒
58	04/12/17 11:55	General View	1	Load JPG	☒
59	04/12/17 11:55	General View	1	Load JPG	☒
60	04/12/17 11:55	General View	1	Load JPG	☒
61	04/12/17 11:55	General View	1	Load JPG	☒
62	04/12/17 11:55	General View	1	Load JPG	☒
63	04/12/17 11:55	General View	1	Load JPG	☒
64	04/12/17 11:55	General View	1	Load JPG	☒
65	04/12/17 11:55	General View	1	Load JPG	☒
66	04/12/17 11:55	General View	1	Load JPG	☒
67	04/12/17 11:55	General View	1	Load JPG	☒
68	04/12/17 11:55	General View	1	Load JPG	☒
69	04/12/17 11:55	General View	1	Load JPG	☒
70	04/12/17 11:55	General View	1	Load JPG	☒
71	04/12/17 11:55	General View	1	Load JPG	☒
72	04/12/17 11:55	General View	1	Load JPG	☒
73	04/12/17 11:55	General View	1	Load JPG	☒

74	11/12/17 11:02	Reinspection Photo	1	Load JPG	
75	11/12/17 11:02	Reinspection Photo	1	Load JPG	
76	11/12/17 11:02	Reinspection Photo	1	Load JPG	
77	11/12/17 11:02	Reinspection Photo	1	Load JPG	
78	11/12/17 11:02	Reinspection Photo	1	Load JPG	
79	11/12/17 11:02	Reinspection Photo	1	Load JPG	
80	11/12/17 11:02	Reinspection Photo	1	Load JPG	
81	11/12/17 11:02	Reinspection Photo	1	Load JPG	
82	01/03/18 10:42	Reinspection Photo	1	Load JPG	
83	01/03/18 10:42	Reinspection Photo	1	Load JPG	
84	01/03/18 10:42	Reinspection Photo	1	Load JPG	
85	01/03/18 10:42	Reinspection Photo	1	Load JPG	
86	01/03/18 10:42	Reinspection Photo	1	Load JPG	
87	01/03/18 10:42	Reinspection Photo	1	Load JPG	
Documentation					
				1 per page ▼	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/11/17 15:22	Repair Estimate	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/17 11:48	WORKSHOP ESTIMATE	1	Load PDF	
2	08/12/17 14:56	supplementary	1	Load PDF	

Linked Accident Report Documents

View [View in Browser ▼](#)

Video			1 per page ▾		
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	01/12/17 12:43	Video - Accident		Load MP4	
Assessment Reports			1 per page ▾		
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	30/11/17 14:48	Accident Statement		Load HTM	
2	01/12/17 12:49	Addendum Sheet		Load JPG	
3	01/12/17 12:49	Accident Statement Addm. #1		Load HTM	
Photos/Images			3 per page ▾		
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	30/11/17 14:46	Accident Photo		Load JPG	
2	30/11/17 14:46	Accident Photo		Load JPG	
3	30/11/17 14:46	Accident Photo		Load JPG	
4	30/11/17 14:46	Accident Photo		Load JPG	
5	30/11/17 14:46	Accident Photo		Load JPG	
6	30/11/17 14:46	Accident Photo		Load JPG	
7	30/11/17 14:46	Accident Photo		Load JPG	
8	30/11/17 14:46	Accident Photo		Load JPG	
9	30/11/17 14:47	Accident Photo		Load JPG	
10	30/11/17 14:47	Accident Photo		Load JPG	
11	30/11/17 14:47	Accident Photo		Load JPG	
12	30/11/17 14:47	Accident Photo		Load JPG	
13	30/11/17 14:47	Accident Photo		Load JPG	
14	30/11/17 14:47	Accident Photo		Load JPG	

15	30/11/17 14:47	Accident Photo	1	Load JPG	
16	30/11/17 14:47	Accident Photo	1	Load JPG	
17	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
18	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
19	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
20	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
21	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
22	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
23	30/11/17 14:47	Accident Scene Photo	1	Load JPG	
Documentation					
				1 per page	
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)		Thumbnail	Print
1	30/11/17 14:47	Accident Sketch Plan	1	Load JPG	
2	30/11/17 14:47	Accident Sketch Plan	1	Load JPG	
3	30/11/17 14:47	Accident Sketch Plan	1	Load JPG	
4	30/11/17 14:47	Identification Card	1	Load JPG	
5	30/11/17 14:47	Accident Sketch Plan	1	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022815/T1TBE2

Date: 06/03/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Policy No:

MSD/VPCP/17-00376

Date of Loss: 30/11/2017

Nature of Claim: OD

Claim No: MSC/V/17-001870

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL8831K	Engine No:	2ARF251020
Make & Model:	LEXUS ES250, 2.5 (A)	Chassis No:	JTHBJ1GG702094833
Reg. Date:	10/02/2017 (Man. Year: 2016)	Odometer:	16827 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	S\$174,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,415.27	17,762.78	15,652.49	46.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,148.00	10,116.00	3,032.00	23.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,563.27	27,878.78	18,684.49	40.13
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	45,063.27	26,378.78	18,684.49	41.46
+ GST 7.00/7.00% (S\$)	3,154.43	1,846.51	1,307.92	41.46
Nett Amount (S\$)	48,217.70	28,225.29	19,992.41	41.46

INSPECTION

Date of Assignment: 30/11/2017

Date Inspected: 01/12/2017

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2018)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL8831K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*BONNET SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*FRONT SUPPORT SEALANT	Necessary	100.00 FS	*100.00 FS
4	1		*BOTH FRONT CHASSIS FRAME SEALANT	Not Necessary	120.00 FS	*- FS
5	1		*FRONT NO PLATE AND CASING	Bent	96.00 FS	*96.00 FS
6	1		*COVER, FR BUMPER	Deformed	794.75 FS	*794.75 FS
7	1		*REINFORCEMENT	Not Necessary	410.80 FS	*- FS
8	1		*ABSORBER, FR BUMPER	Cracked	115.51 FS	*115.51 FS
9	1		*SEAL, RADIATOR	Necessary	83.47 FS	*83.47 FS
10	1		*GRILLE SUB-ASSY	Cracked	729.55 FS	*729.55 FS
11	1		*STAY, FR BUMPER	Necessary	47.26 FS	*47.26 FS
12	1		*STAY, FR BUMPER	Necessary	47.26 FS	*47.26 FS
13	2		*BUMPER BRACKET	Necessary	12.40 FS	*12.40 FS
14	10		*CLIP	Necessary	11.90 FS	*11.90 FS
15	2		*RETAINER, FR FENDER	Necessary	20.40 FS	*20.40 FS
16	1		*BRACKET, FOG LAMP	Not Necessary	139.31 FS	*- FS
17	1		*BRACKET, FOG LAMP	Not Necessary	139.31 FS	*- FS
18	1		*COVER, FOG LAMP, LH	Not Necessary	100.47 FS	*- FS
19	1		*COVER, FOG LAMP, RH	Not Necessary	100.47 FS	*- FS
20	1		*GRILLE, RADIATOR	Deformed	35.44 FS	*35.44 FS
21	1		*GRILLE, RADIATOR	Not Necessary	35.44 FS	*- FS
22	1		*COVER, FR BUMPER	Not Necessary	71.57 FS	*- FS
23	1		*BRACKET, FR BUMPER	Cracked	116.70 FS	*116.70 FS
24	1		*MOULDING, RADIATOR	Cracked	306.68 FS	*306.68 FS
25	1		*GRILLE, RADIATOR	Cracked	962.45 FS	*962.45 FS
26	10		*BUMPER CLIPS	Necessary	33.10 FS	*33.10 FS
27	1		*HOOD SUB-ASSY	Bent	1,860.14 FS	*1,860.14 FS
28	1		*INSULATOR, HOOD	Not Necessary	287.89 FS	*- FS
29	1		*SEAL, HOOD TO	Not Necessary	40.54 FS	*- FS
30	1		*FENDER FR, LH	Bent	1,104.15 FS	*1,104.15 FS
31	1		*FENDER, FR RH	Not Necessary	1,104.15 FS	*- FS
32	1		*PPROTECTOR, FR FENDER	Not Necessary	83.47 FS	*- FS
33	1		*LINER, FR FENDER RH	Not Necessary	228.99 FS	*- FS
34	1		*LINER, FR FENDER, LH	Not Necessary	240.89 FS	*- FS
35	1		*BRACKET SUB-ASSY FR	Necessary	60.26 FS	*60.26 FS
36	1		*BRACE, FR FENDER TO	Not Necessary	58.73 FS	*- FS
37	1		*HINGE ASSY, HOOD, LH	Not Necessary	69.10 FS	*- FS
38	1		*HINGE ASSY, HOOD, RH	Not Necessary	69.10 FS	*- FS
39	1		*LOCK ASSY, HOOD	Bent	139.31 FS	*139.31 FS
40	1		*SUPPORT ASSY, HOOD	Not Necessary	287.89 FS	*- FS
41	1		*SUPPORT ASSY, HOOD	Not Necessary	287.89 FS	*- FS
42	1		*SUPPORT, RADIATOR	Bent	1,193.48 FS	*1,193.48 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SEAL, COOL AIR	Deformed	249.64 FS	*249.64 FS
44	9		*CLIP	Necessary	15.30 FS	*15.30 FS
45	1		*SUPPORT SUB-ASSY	Bent	125.46 FS	*125.46 FS
46	1		*DEFLECTOR, RADIATOR LH	Deformed	122.99 FS	*122.99 FS
47	1		*DEFLECTOR, RADIATOR RH	Not Necessary	130.56 FS	*- FS
48	1		*PLATE SUB-ASSY, FR	Not Necessary	112.96 FS	*- FS
49	1		*PLATE SUB-ASSY, FR	Not Necessary	112.96 FS	*- FS
50	1		*COVER, ENGINE UNDER	Not Necessary	257.80 FS	*- FS
51	1		*COVER, ENGINE UNDER	Not Necessary	191.33 FS	*- FS
52	10		*CLIP	Necessary	18.70 FS	*18.70 FS
53	1		*PANEL, FR DOOR LH	Not Necessary	1,156.17 FS	*- FS
54	1		*STRIPE FR DOOR	Not Necessary	35.87 FS	*- FS
55	1		*WEATHERSTRIP, FR	Not Necessary	232.73 FS	*- FS
56	17		*RETAINER, DOOR	Necessary	75.14 FS	*75.14 FS
57	1		*CHECK ASSY, FR DOOR	Not Necessary	196.35 FS	*- FS
58	1		*WEATHERSTRIP, FR	Not Necessary	131.15 FS	*- FS
59	1		*GARNISH, FR DOOR LWR	Not Necessary	44.96 FS	*- FS
60	1		*L/FRT DOOR LOW HINGE	Not Necessary	78.28 FS	*- FS
61	1		*HINGE ASSY, FR DOOR	Not Necessary	69.78 FS	*- FS
62	1		*EMBLEM, SYMBOL	Cracked	394.57 FS	*394.57 FS
63	12		*RIVET	Necessary	12.24 FS	*12.24 FS
64	1		*MOULDING FR DOOR	Not Necessary	81.00 FS	*- FS
65	1		*MOULDING, WINDSHIELD LH	Not Necessary	71.57 FS	*- FS
66	1		*MOULDING, WINDSHIELD RH	Not Necessary	71.57 FS	*- FS
67	10		*CLIP, WINDSHIELD	Not Necessary	74.80 FS	*- FS
68	10		*ROOF DRIP MLDG CLIP	Not Necessary	77.30 FS	*- FS
69	1		*UNIT ASSY, HEADLAMP, LH	Cracked	4,446.43 FS	*4,446.43 FS
70	1		*UNIT ASSY, HEADLAMP, RH	Not Necessary	4,446.43 FS	*- FS
71	2		*BULB HEADLAMP NO.1	Not Necessary	144.50 FS	*- FS
72	2		*BULB	Not Necessary	11.04 FS	*- FS
73	1		*LAMP ASSY, FOG, LH	Not Necessary	438.60 FS	*- FS
74	1		*LAMP ASSY, FOG RH	Not Necessary	438.60 FS	*- FS
75	1		*WIRE, ENGINE ROOM	Not Necessary	152.49 FS	*- FS
76	2		*SENSOR, ULTRASONIC	Not Necessary	819.22 FS	*- FS
77	2		*CLIP, ULTRASONIC	Necessary	20.22 FS	*20.22 FS
78	2		*RETAINER, ULTRASONIC	Necessary	27.20 FS	*27.20 FS
79	2		*SENSOR, ULTRASONIC	Not Necessary	819.22 FS	*- FS
80	2		*CLIP, ULTRASONIC	Necessary	6.12 FS	*6.12 FS
81	1		*JAR, WASHER, A	Not Necessary	195.07 FS	*- FS
82	2		*CLAMP, HEADLAMP	Necessary	37.40 FS	*37.40 FS
83	1		*CONDENSER ASSY	Dented	1,737.48 FS	*1,737.48 FS
84	1		*RADIATOR ASSY	Dented	2,301.97 FS	*2,301.97 FS
85	1		*SHROUD FAN	Not Necessary	264.77 FS	*- FS
86	1		*FAN	Not Necessary	215.81 FS	*- FS
87	1		*FAN	Not Necessary	269.79 FS	*- FS
88	2		*COOLANT, LONG LIF	Not Necessary	196.80 FS	*- FS
89	1		*INLET ASSY, AIR	Not Necessary	187.00 FS	*- FS
90	1		*SEAL, RADIATOR TO	Necessary	20.91 FS	*20.91 FS
91	2		*SEAL, RADIATOR TO	Necessary	14.44 FS	*14.44 FS
92	1		*SEAL, RADIATOR TO	Necessary	16.91 FS	*16.91 FS
93	1		*HORN ASSY LOW	Cracked	99.45 FS	*99.45 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	33,415.27	17,762.78
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, BONNET, BOTH FRONT FENDERS, FRONT SUPPORT, LHS FRONT DOOR, BOTH FRONT CHASSIS FRAME AND FIX NEW PARTS	New	4,896.00	4,080.00
2	TO SPRAY PAINT ON WHOLE FRONT PORTION INCL FRONT SUPPORT, BOTH FRONT CHASSIS FRAMES AND LHS FRONT DOOR	New	5,600.00	4,200.00
3	TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR, ETC...TO ENABLE REPAIR	New	816.00	816.00
4	TO RESET ECU AND REPROGRAMME	New	612.00	612.00
5	TO REMOVE AND REPLACE FRONT WIRE HARNESS	New	816.00	0.00
6	TO REMOVE AND REPLACE BOTH HEADLAMP. CHECK AND FOCUS HEADLIGHTS	New	204.00	204.00
7	TO REMOVE AND REPLACE FRONT PARKING SENSOR	New	204.00	204.00
Gross Labour Cost (\$\$)			13,148.00	10,116.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >