



MSIG Insurance (S) Pte Ltd
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807619747
Attention : Miss Joslin Lim

Quotation for Repair Costs

Policy Number	Vehicle Registration No	Consultants	Date
28853522 SMF	SLC3045T -Flood damage	Erwin - 92210404	29/11/2017

Item	Description	Quantity	Unit Price S\$	Total Price S\$
1	Apex Seals <i>nei</i> ✓	6	138.50	831.00
2	Apex Seals Spring <i>nei</i> ✓	6	21.60	129.60
3	Side Seals <i>nei</i> ✓	12	69.50	834.00
4	Side Seals Spring <i>nei</i> ✓	12	12.50	150.00
5	Corner Seals <i>nei</i> ✓	12	37.40	448.80
6	Corner Seals Spring <i>nei</i> ✓	12	5.00	60.00
7	Front Side Wall <i>dd</i> ✓	1	1860.00	1860.00
8	Intermediate Side Wall <i>dd</i> ✓	1	2006.91	2006.91
9	Rear Side Wall <i>dd</i> ✓	1	1830.00	1830.00
10	Rotor Housing <i>dis</i> ✓	2	2543.30	5086.60
11	Rotor <i>dis</i> ✓	2	2404.10	4808.20
12	Crank Shaft <i>dis</i> ✓	1	1980.00	1980.00
13	Overhaul Kit (O-rings) <i>nei</i> ✓	1set	690.10	690.10
14	Overhaul casket <i>nei</i> ✓	1	401.30	401.30
15	Rotor Center Ring (inner) <i>nei</i> ✓	1	112.80	112.80
16	Oil metering pump <i>dis</i> ✓	1	2993.50	2993.50
17	Upper O2 sensor <i>nw</i> ✓	1	1187.00	1187.00
18	Lower O2 sensor <i>nw</i> ✓	1	387.70	387.70
19	Air filter ✓	1	120.00	120.00
20	Air flow sensor <i>nw</i> ✓	1	735.60	735.60
21	Catalytic Converter (USED) * ✓	1	1900.00	1900.00
22	Exhaust (USED) * ✓	1	600.00	600.00
23	Spark Plug <i>nei</i> ✓	4	137.50	550.00
24	Engine Oil <i>nei</i> ✓	5L	158.00	158.00
25	Coolant <i>nei</i> ✓	8L	180.00	180.00
26	Oil filter <i>nei</i> ✓	1	15.00 (parts +10%)	15.00
27	Labour charges for overhaul <i>2000</i>	1lot	2500.00	2500.00
28	Towing Charge	1	130.00	130.00
	Gross estimate			32686.11 <i>35441.72</i>
	Policy Excess			1500.00
	Net estimate			31186.11

Remarks :-

Estimated Repair Period : 7-10 days

We are not GST registered.

For & On behalf of
Fujimotorsports Automotive Pte Ltd



Erwin Ho

sur@lkkarto.com
Tanjah 97495749

Ex \$1500

Revent

01/12/17 @ 1430

* Resurvey new parts

10 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fujimotorsports Automotive Pte Ltd

48 Toh Guan Road East, #01-115 Enterprise Hub, Singapore 608586

T. 92210404/93668787 e. fujimotorsports@hotmail.com