

22/03/2002

ASS. REC. BY:

REF: CS/MSG17022817/Tigbert

Special Instruction:

Surveyor:
Munim

Tautith.

ASSIGNMENT (Office)

From (Person):

Joslin Lim

of

MSIG

Date/Time:

30/11/17 @ 14.40pm

Estimated Cost:

Bill to:

① TP/WS/TP RES/OD RES/EVA/INV/MV/CS

disagreement to adopt
'best plus' repair by shop

To Inspect Vehicle No:

SLC3045T

Insured:

at Workshop m/s

Fuji Motorsports

Tel:

92210404

of

#8 Toh Guan Rd East, #01-115, 608586

Policy No:

S28853522SMF

Claim No:

538327

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

(Client's Record)

D.O.A

18/11/2017

CA / REV

REP. / REV 24 HRS

01/12/17

H.O.D. Endorsement:

66431314

Date/Time:

4:14pm @ 30/11/17

Person Contacted:

Erwin

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

~~FLAME CASE~~

SLC3045T-X

922104040000

MSIG

1 Hour Before

go, please call him.
Thank You

COE 2027 Aug

SLC3045T

2007 Aug

1/12/17

Estimated Cost

CD / TP / WS / TP RES / CD RES / EVA / INV / MV

Truck / Trailer or
Make Mazda RX-8 13A
Colour Grey
Year 2007
Engine No 13B529091
VIN 8EAT SESPI42243
Gen Cond Good / Fair / Poor / Burnt
Steering In order / Jammed / Leaked / Burnt or
Brake In order / Jammed / Leaked / Burnt or
Mod Nill / S / Rim / STD A / Rim or
Tyre Size F 245/35R19
R 245/35R19
BS / DUN / EXNOVA / GY / FS / LIZA / MICH / OHTSU / PIR / SUMI
TOYO / YOKO or Kumho

Insured

Policy No

Claims No

Sum Insured Excess \$1,500.00


Client's Record Flood Case

Make of veh

After 11am

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value \$92K

DAD Accident Report Consistent? : Yes or No

GIA / PF / Seen Consistent? : Yes or No

Est. Repairs 10 days Res: Yes or No

Sum Supp 1-B-1 3 Year Yes or No

CA / REV / REP / 24 HRS

Date Person Contacted

Vehicle IN / OUT

The U.C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction
4/12/17 REV in merimen - pending amend est.
5/12/17 2nd REV in merimen - disagreement to adopt cost plus repair uploaded
6/12/17 mandate approved by Huey Ni.
6/12/17 @ 11am spoke to Erwin, CA, EX: 1500 - on p/p.
26/12/17 \$25,774.89; 10 days inform Erwin on COR confirmed with Erwin.
(Red: 6911.22, 21%)

Preli. Report
Final Report

Days Of Repair 10

Resurvey No. of Tric

Survey Fee

Add Fee: Estimated

Estimated
Material
Test
Other

Truck Fee

Report Format OD

Auto Sum 25774.89

350
10
360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022817/T1gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 30-11-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLC 3045T
Policy No.	S28853522SMF	Coverage (\$)	0.00
Claim No.	538327	Excess (\$)	1,500.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/11/2017	Inspection Date	
Survey held at	-		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Main

24 Nov 2017

30 Nov 2017
14:40[Assign](#)[New Assignment](#)[Cancel Case](#)

Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			
Insured: HIA KIM HON, ID: S7733492J, Tel: +6591382718, Email: NOEMAIL		[Created by insurer]	
Vehicle Reg. No.: SLC3045T	Date of Loss: 18/11/2017 15:00 - :59		
Claim Type: OD / 538327	Policy/Cover Note No.: S28853522SMF (Comprehensive)	Coverage: 11/11/2016 - 28/02/2018	
	Excess: S\$1,500.00		
Repairer: Fuji Motorsports Automotive Pte Ltd (HQ) 48 Toh Guan Road East, #01-115 Enterprise Hub, 608586 Jurong East - Tel: 92210404			
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]			
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/12/2017]			
Driver/Custodian: HIA KIM HON (39 / Male), NRIC: S7733492J, Tel: +6591382718			
Adj Asg. Remarks: Flood case. Please revert.			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail	
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete	
Priority	Type	Task Group	Subject
No results.			

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Wednesday, 6 December, 2017 2:16 PM
To: Erwin Ho
Cc: SUR
Subject: SLC 3045T MSIG-OD (DOA 18/11/2017)

Dear Erwin,

Instructed by our client, please proceed to repair the insured vehicle **SLC 3045T (Excess \$1,500)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Erwin Ho [mailto:fujimotorsports@hotmail.com]
Sent: Tuesday, 5 December, 2017 11:47 AM
To: Ai Phing (LKKAUTO) <aiphing@lkkauto.com>
Subject: Re: Quotation for SLC3045T

Dear Ai Phing

The disagreement form duly completed & sign is attached herewith.

Thank you
Erwin Ho

From: Ai Phing (LKKAUTO) <aiphing@lkkauto.com>
Sent: Tuesday, 5 December 2017 10:49:27 AM
To: Erwin Ho
Subject: RE: Quotation for SLC3045T

Dear Erwin,

We will ignore the new estimate.

Joslin Lim

From: Erwin Ho <fujimotorsports@hotmail.com>
Sent: Wednesday, 29 November, 2017 11:02 AM
To: Joslin Lim
Subject: Estimate for SLC3045T under 28853522 SMF
Attachments: SLC3045T Estimate.pdf

Dear Miss Joslin Lim

We are pleased to attach herewith our estimate for the repairs to SLC3045T damage by flood.

Kindly liaise with our Erwin Ho @92210404 for the survey of the said vehicle soonest.

Thank you
Danny Teo
Fujimotorsports Automotive Pte Ltd

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	28 Nov 2017 10:41	Clim Veh Model Changed	(200498) MAZDA RX-8 1.3 (A).	[I] Joslin Lim
2	28 Nov 2017 10:41	Clim Created	Reg No: SLC3045T. Policy No: S28853522SMF. Acct Date: 2017/11/18. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MVA117155335	[I] Joslin Lim
3	30 Nov 2017 10:45	Notification Status Changed	Ins.Status => Incoming Claim	[I] Joslin Lim
4	30 Nov 2017 10:45	Clim Registration Modified	Setl.Type:3->0. Rep:1137->204991. Claim Type:SC->OD.	[I] Joslin Lim
5	30 Nov 2017 10:49	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Flood case. Please revert.	[I] Joslin Lim
6	30 Nov 2017 10:49	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/01	[I] Joslin Lim
7	30 Nov 2017 10:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
8	30 Nov 2017 14:24	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	30 Nov 2017 14:39	Adj Assignment Cancelled		[I] Clara Milah Yeo
10	30 Nov 2017 14:39	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Clara Milah Yeo
11	30 Nov 2017 14:40	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Flood case. Please revert.	[I] Clara Milah Yeo
12	30 Nov 2017 14:40	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/01	[I] Clara Milah Yeo
13	30 Nov 2017 14:40	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Clara Milah Yeo
14	30 Nov 2017 16:10	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	30 Nov 2017 18:07	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
16	01 Dec 2017 10:45	Adj Assignment Cancelled	I.H.S appointment full	[I] Joslin Lim
17	01 Dec 2017 10:45	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
18	01 Dec 2017 10:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):FLOOD case. Please revert.	[I] Joslin Lim
19	01 Dec 2017 10:47	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/02	[I] Joslin Lim
20	01 Dec 2017 10:47	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
21	01 Dec 2017 10:51	Assignment 1st Accessed		[A] Nivitha Govindasamy
22	01 Dec 2017 10:52	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] Nivitha Govindasamy
23	04 Dec 2017 14:52	Adj Rpt Initiated		[A] LOW AI PHING
24	04 Dec 2017 17:59	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/31	[A] LOW AI PHING
25	04 Dec 2017 17:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/31	[A] LOW AI PHING
26	04 Dec 2017 18:01	Adj Mandate Request	Cur Req:32186.11:DAMAGES CONSISTENT. Repair cost economical. Pending verification on part prices.	[A] LOW AI PHING
27	05 Dec 2017 12:01	Adj Mandate Request Cancelled		[A] LOW AI PHING
28	05 Dec 2017 12:10	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/31	[A] LOW AI PHING
29	05 Dec 2017 12:11	Adj Mandate Request	Cur Req:25774.89:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
30	06 Dec 2017 10:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/31	[I] Eng Huey Ni
31	06 Dec 2017 10:45	Adj Mandate Set	Approved:25774.89.	[I] Eng Huey Ni

ACTIVITY

[30/11/2017 14:26] Pauline Soh Li Ping:
Car In, IHS unable to attend (ET-East side, AL-Paperwork, DC-Appr full)

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1657182	04/12/2017 14:52	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLC3045T		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 05 Dec 2017

Preliminary Advice

Vehicle No	: SLC3045T	Accident Date	: 18/11/2017
Make	: MAZDA RX-8	Policy No.	: S28853522SMF
Assignment Date	: 01/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 01/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: FUJI MOTORSPORTS AUTOMOTIVE PTE LTD (HQ) 48 TOH GUAN ROAD EAST, #01-115 ENTERPRISE HUB SINGAPORE 608586		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages is flood case and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,686.11
Revised Amount	:S\$	25,774.89
Check Items (Estimated)	:S\$	-
Total	:S\$	25,774.89

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	44,191.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,809.00

Remarks

(X) The vehicle is economical for repair.

We have not authorise repair.

Disagreement to adopt 'Cost Plus' repair letter by workshop uploaded.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 04 Dec 2017

Preliminary Advice

Vehicle No	: SLC3045T	Accident Date	: 18/11/2017
Make	: MAZDA RX-8	Policy No.	: S28853522SMF
Assignment Date	: 01/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 01/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: FUJI MOTORSPORTS AUTOMOTIVE PTE LTD (HQ) 48 TOH GUAN ROAD EAST, #01-115 ENTERPRISE HUB SINGAPORE 608586		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages is flood case and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,686.11
Revised Amount	:S\$	32,186.11
Check Items (Estimated)	:S\$	-
Total	:S\$	32,186.11

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	44,191.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,809.00

Remarks

(X) The vehicle is economical for repair.

We have not authorise repair.

Pending verification on part prices.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3492J

Vehicle Details

Vehicle No.	SLC3045T
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	RX-8 1.3 A
Primary Colour	Grey
Manufacturing Year	2007
Engine No.	13B529091
Chassis No.	SE3P142243
Maximum Power Output	158.0 kW (211 bhp)
Open Market Value	\$30,312.00
Original Registration Date	30 Aug 2007
First Registration Date	30 Aug 2007
Transfer Count	3
Actual ARF Paid	\$33,344.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	29 Aug 2027
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
PQP Paid	\$45,400.00
COE Rebate Amount	\$44,191.00
Total Rebate Amount	\$44,191.00

The information contained herein is correct as at 04 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2017 10:32
Date Of Accident	18/11/2017 15:00
Exact Location Of Accident	LOR CHENCHARU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3045T
Insured/Policyholder	
Name Of Registered Owner	HIA KIM HON
Co Reg No	S7733492J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91382718
Vehicle Particulars	
Manufacturer	MAZDA
Model	RX8
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S28853522 SMF
Cover Note Number	
Driver	
Name of Driver	HIA KIM HON
NRIC No	S7733492J
Date Of Birth	05/12/1977
Occupation	INDOOR
Date Of Driving Pass	04/09/1999
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident NO COLLISION

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. DRIVER DID NOT BRING CI AT POINT OF REPORTING, VEHICLE NOT AT IDAC. MSIG JOSLIN ASKED TO GO AHEAD WITH THE REPORT. ATTENDED BY LYNDIA

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) Involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok St 33
Singapore 659535
Tel: 6769 3312
Reporting Centre Personnel's Signature
Name: 
Email: vac@idacsingnet.com.sg
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



I was driving from Lorong Chencheng to Sembawang Road
at about 4pm on Saturday 18 Nov. There was a sudden down
pour of heavy rain and the road was flooded with water.
I was following behind another vehicle towards Sembawang Rd
but at the middle of Lorong Chencheng my car suddenly
stopped. I tried to restart the car but I was unsuccessful.
The car was thus stranded at the location while the flood
built up around it. I could see the water entering the car
and collecting on the floor mats. Meanwhile I called for a tow truck.
I waited for an hour until the flood waters subsided,
then waited outside the car for the tow truck to arrive.
The tow truck arrived at about 6:20pm and towed the car
to my workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok St 23
 Singapore 659545
 Tel: 6567 9427 / 6560 3312
 Reporting Centre: 
 Name: 
 Email: vacbb@singnet.com.sg
 NRIC/FIN No.:



MSIG

Vehicle No SLC3045 T
Date of Accident 18/11/2017
Date of Survey 01/12/2017

**DISAGREEMENT TO ADOPT "COST-PLUS" REPAIR BY WORKSHOP
(OWN DAMAGE CLAIM)**

I, ERWIN Ho (workshop's Service Advisor),
hereby confirm that Fujimotorsports Automotive P/L (name of Workshop)
is not agreeable to adopt "Cost-Plus" basis for the settlement of the own
damage claim for vehicle number SLC3045T.

Surveyor

Workshop's Service Advisor

Signature _____

Signature X

Name _____

Name ERWIN Ho

Date/Time _____

Date/Time 5/12/2017



Reason for not signing this form by Workshop's Service Advisor, if applicable
(To be completed by Surveyor):

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7733492J



Name

HIA KIM HON
(XING JINFENG)

那 金 丰

Race

CHINESE

Date of birth

05-12-1977

Sex

M

S7733492J

Country of birth

SINGAPORE

4144680



NRIC No. S7733492J



Date of issue

13-12-2007

APT BLK 331 CLEMENTI AVENUE 2 #08-130
SINGAPORE

NF

Date: 31/01/2011

No: 6501253

Cash Sale / Work Order

No: 18413

快捷拖车服务
SPEED TOWING SERVICE

Blk 151 Petir Road #10-180 Singapore 670151

Reg No. 53116819X

HP: 9001 0855

(24 Hours Towing Services)

Date: 18/11/17

宝号

Messrs: Cash

车号

Vehicle No: SLC3045T

车型

Model: Mazda RX-8

由

From: Lor chencharu

到

To: 48, Toh Guan RD East

时间(日/夜)

Time (day/night): 3:50pm

其他

Others: Roller (Car in flood)

Cash \$: 130

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

经手人

Authorised by: [Signature]

收货人

Received by: _____



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Mazda RX-8

Price Range

Depreciation

2007

Vehicle Type

Home » Used Cars » Direct Owners » Mazda RX-8 1.3A (COE till 01/2027)

Tools & Tips

Car Buying

Car Selling


Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



Mazda RX-8 1.3A (COE till 01/2027)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price

\$89,800

Depreciation

\$9,850 /yr

View models with similar depreciation

Reg Date

13-Jan-2007

(9yrs 1mth 8days COE left)

Manufactured

2006

Mileage

111,000 km (10.2k /yr)

Transmission

Auto

Engine Cap

1,308 cc

Road Tax

\$572 /yr

Power

158.0 kW (211 bhp)

Curb Weight

1,340 kg

Features

Fitted With Rare 18" Staggered Rays Gram Lights Pro Titan Lip Rim With New Tyres, 3 x Defi Gauges, Pivot Controller, IRoad V9 Recorder, And Many More.

Accessories

Knight Sports Exhaust, RacingBeat-REVi Air Intake, AutoExec Bracing-Front, Rear And Under Carriage. Viper Alarm Sys, HKS HIPERMAX GT MAX Coilover, Etc.

Description

Special Offer. Fitted With Full Customized Body Kit. Well Maintain And With Stocks Of New Greddy Radiator, Oil Cooler, Coilover, Air Con Compressor, Rotor, Etc In My Store. Additional Automatic Gear Box Is In My Workshop. Full Servicing Record Available. Free Of Worries For Another Good Years Of Driving On This High Performance Car. All Spare Parts Will Be Given To Successful Buyer. Kindly Call Me Now.

COE

\$50,645

OMV

\$26,402

ARF

\$29,043

Dereg Value

\$46,149 as of today (change)

Seller Informat

Contact Person(s)

Contact No.

Enquiry

USEFUL FORMS

» Indemnity form

» Receipt

» M01

Instructions on consumer deal

Regardless of bu

Compare



MSIG Insurance (S) Pte Ltd
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807619747
Attention : Miss Joslin Lim

Quotation for Repair Costs

Policy Number	Vehicle Registration No	Consultants	Date
28853522 SMF	SLC3045T -Flood damage	Erwin - 92210404	29/11/2017

Item	Description	Quantity	Unit Price S\$	Total Price S\$
1	Apex Seals <i>new</i>	6	138.50	831.00
2	Apex Seals Spring <i>new</i>	6	21.60	129.60
3	Side Seals <i>new</i>	12	69.50	834.00
4	Side Seals Spring <i>new</i>	12	12.50	150.00
5	Corner Seals <i>new</i>	12	37.40	448.80
6	Corner Seals Spring <i>new</i>	12	5.00	60.00
7	Front Side Wall <i>dis</i>	1	1860.00	1860.00
8	Intermediate Side Wall <i>dis</i>	1	2006.91	2006.91
9	Rear Side Wall <i>dis</i>	1	1830.00	1830.00
10	Rotor Housing <i>dis</i>	2	2543.30	5086.60
11	Rotor <i>dis</i>	2	2404.10	4808.20
12	Crank Shaft <i>dis</i>	1	1980.00	1980.00
13	Overhaul Kit (O-rings) <i>new</i>	1set	690.10	690.10
14	Overhaul casket <i>new</i>	1	401.30	401.30
15	Rotor Center Ring (inner) <i>new</i>	1	112.80	112.80
16	Oil metering pump <i>dis</i>	1	2993.50	2993.50
17	Upper O2 sensor <i>new</i>	1	1187.00	1187.00
18	Lower O2 sensor <i>new</i>	1	387.70	387.70
19	Air filter <i>dis</i> / <i>stained</i>	1	120.00	120.00
20	Air flow sensor <i>new</i>	1	735.60	735.60
21	Catalytic Converter (USED) * <i>dis</i> / <i>SN</i> <i>dis</i>	1	1900.00	1200 1900.00
22	Exhaust (USED) * <i>dis</i> / <i>SN</i>	1	600.00	400 600.00
23	Spark Plug <i>new</i>	4	137.50	550.00
24	Engine Oil <i>new</i>	5L	158.00	158.00
25	Coolant <i>new</i>	8L	180.00	180.00
26	Oil filter <i>new</i>	1	15.00 <i>parts</i>	15.00 <i>20%</i>
27	Labour charges for overhaul <i>2000</i>	1lot	2500.00	2500.00
28	Towing Charge <i>new</i>	1	130.00	130.00
	Gross estimate			32686.11
	Policy Excess			1500.00
	Net estimate			31186.11

Remarks :-

Estimated Repair Period : 7-10 days

We are not GST registered.

For & On behalf of

Fujimotorsports Automotive Pte Ltd



Erwin Ho

sur@lkkauto.com

Tanjik 97495749

EX \$1500

Revent

01/12/17 @ 1430

* Resurvey new parts

10 days

6/12/17

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fujimotorsports Automotive Pte Ltd

48 Toh Guan Road East, #01-115 Enterprise Hub, Singapore 608586

T. 92210404/93668787 e. fujimotorsports@hotmail.com



MSIG Insurance (S) Pte Ltd
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807619747
Attention : Miss Joslin Lim

Invoice for Repair Costs

Policy Number/claim Ref	Vehicle Registration No	Consultants	Date
28853522 SMF/538327	SLC3045T –Flood damage	Erwin - 92210404	22/12/2017

Invoice Number : 68/SLC3045T/2017

Item	Description	Quantity	Unit Price S\$	Total Price S\$
1	Apex Seals	6	138.50	831.00
2	Apex Seals Spring	6	21.60	129.60
3	Side Seals	12	69.50	834.00
4	Side Seals Spring	12	12.50	150.00
5	Corner Seals	12	37.40	448.80
6	Corner Seals Spring	12	5.00	60.00
7	Front Side Wall	1	1860.00	1860.00
8	Intermediate Side Wall	1	2006.91	2006.91
9	Rear Side Wall	1	1830.00	1830.00
10	Rotor Housing	2	2543.30	5086.60
11	Rotor	2	2404.10	4808.20
12	Crank Shaft	1	1980.00	1980.00
13	Overhaul Kit (O-rings)	1set	690.10	690.10
14	Overhaul casket	1	401.30	401.30
15	Rotor Center Ring (inner)	1	112.80	112.80
16	Oil metering pump	1	2993.50	2993.50
17	Upper O2 sensor	1	1187.00	1187.00
18	Lower O2 sensor	1	387.70	387.70
19	Air filter	1	120.00	120.00
20	Air flow sensor	1	735.60	735.60
21	Spark Plug	4	137.50	550.00
22	Engine Oil	5L	158.00	158.00
23	Coolant	8L	180.00	180.00
24	Oil filter	1	15.00	15.00
	Gross Total for New parts			27556.11
	Less 20% discount			5511.22
	Net Total for New parts			22044.89
	Add Special Nett Items :-			
25	Labour charges for overhaul	1lot	2000.00	2000.00
26	Towing Charge	1	130.00	130.00
27	Catalytic Converter (USED)	1	1200.00	1200.00
28	Exhaust (USED)	1	400.00	400.00
	Total			25774.89
	Policy Excess			1500.00
	Net repair costs payable			


Remarks :-

Vehicle Delivery Date : 22/12/2017

Payment Terms : COD

We are not GST registered.

For & On behalf of
Fujimotorsports Automotive Pte Ltd

A handwritten signature in black ink, appearing to read 'Danny Teo', is written over a circular company stamp. The stamp contains the text 'FUJIMOTORSPORTS AUTOMOTIVE PTE LTD' around the perimeter and 'Reg. No: 201542931G' in the center. A horizontal dotted line is drawn across the signature.

Danny Teo

Fujimotorsports Automotive Pte Ltd

48 Toh Guan Road East, #01-115 Enterprise Hub, Singapore 608586

T. 92210404/93668787 e. fujimotorsports@hotmail.com



MSIG

CLAIM NO 538327
POLICY NO 28853522 SMF
INSURED Hia Kim Hon

ACCEPTANCE / DISCHARGE FORM

Accident/Incident involving motor vehicle number SLC3045T on 18/11/2017 along Jalan Chencharu damaged by flood.

I, the undersigned, the insured under motor policy no. 28853522 SMF issued by MSIG Insurance (Singapore) Pte. Ltd. hereby acknowledge that my vehicle no. SLC3045T has been repaired to my satisfaction and agree to accept the sum of Singapore Dollars *Twenty Four Thousand Two Hundred Seventy Four & cents Eighty Nine Only (24,274.89)* in full and final settlement and complete discharge of all claims and demands that I may have against MSIG Insurance (Singapore) Pte. Ltd.

I further confirm and authorise MSIG Insurance (Singapore) Pte. Ltd. to pay the said sum directly to Fujimotorsports Automotive Pte Ltd.

It is understood that this settlement is made on the distinct understanding that:

1. I am the only person legally entitled to this payment and there is no other insurance covering this loss or damage.
2. my vehicle no. SLC3045T was not being driven by a person who has been under the influence of liquor or drugs and provided that there is no breach of policy conditions at the material time; otherwise, I/we shall undertake to refund the full outlay to the insurers.

Dated this 22 day of December 2017.

Signature of Claimant
(Company's Stamp if applicable)

Signature of Witness

Name Hia Kim Hon
NRIC No S7733492J
Address Blk 331 Clementi Ave 2
#08-130
Singapore 120331

Name Teo Eng Chew
NRIC No S1613254C
Address Blk 314 Jurong East Street 32
#06-221
Singapore 600314

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800 www.msig.com.sg
Co. Reg. No. 200412212G
A Member of MS&AD

CLM-F03-MTR-OD Claim

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Nov 2017		01 Dec 2017 10:47 Edit Adj Rpt	S\$25,774.89 Edit Estimates	S\$25,774.89 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HIA KIM HON , ID: S7733492J, Tel: +6591382718, Email: NOEMAIL								
Vehicle Reg. No.:	SLC3045T	Date of Loss:	18/11/2017 15:00 - :59						
Claim Type:	OD / 538327	Policy/Cover Note No.:	S28853522SMF (Comprehensive) Coverage: 11/11/2016 - 28/02/2018						
		Excess:	S\$1,500.00						
Repairer:	Fuji Motorsports Automotive Pte Ltd (HQ) 48 Toh Guan Road East, #01-115 Enterprise Hub, 608586 Jurong East - Tel: 92210404								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 31/12/2017]								
Driver/Custodian:	HIA KIM HON (39 / Male) , NRIC: S7733492J, Tel: +6591382718								
Adj Asg. Remarks:	FLOOD case. Please revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (06/12/2017): Alert - Adj Mandate Approved (S\$25774.89) - SLC3045T - Claim Handler: Joslin Lim MSIG_SG (01/12/2017): Cancellation of Assignment: SLC3045T 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC3045T (538327)
 OD
 Nov 18 2017 3:00PM
 [HIA KIM HON]
 Fuji Motorsports Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)							Thumbnail	Print	
1	24/11/17 10:58	Accident Statement							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/12/17 17:59	Adjuster Immediate Advice							Load HTM		
2	05/12/17 12:10	Adjuster Immediate Advice							Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
2	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
3	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
4	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
5	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
6	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
7	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
8	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
9	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
10	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
11	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
12	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
13	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
14	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
15	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
16	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
17	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
18	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
19	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
20	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
21	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
22	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
23	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
24	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
25	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
26	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
27	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
28	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
29	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
30	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	
31	04/12/17 11:18	General View							Load JPG	<input checked="" type="checkbox"/>	

32	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
66	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
67	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
68	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
69	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
70	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
71	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
72	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
73	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
74	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
75	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
76	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
77	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
78	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
79	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
80	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
81	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>

82	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
83	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
84	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
85	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
86	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
87	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
88	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
89	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
90	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
91	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
92	04/12/17 11:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
93	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
94	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
95	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
96	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
97	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
98	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
99	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
100	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
101	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
102	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
103	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
104	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
105	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
106	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
107	26/12/17 10:39	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
108	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
109	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
110	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
111	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
112	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
113	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
114	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
115	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
116	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
117	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
118	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
119	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
120	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
121	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
122	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
123	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
124	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
125	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
126	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
127	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
128	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
129	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
130	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
131	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>

132	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
133	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
134	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
135	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
136	26/12/17 10:40	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/11/17 10:48	Fuji Motor email + Estimate + Towing fee	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/17 09:28	ESTIMATE	1	Load PDF	
2	05/12/17 11:51	DISAGREEMENT TO ADOPT COST PLUS REPAIR BY WORKSHOP	1	Load PDF	
3	03/01/18 09:46	Discharge Voucher	1	Load PDF	
4	03/01/18 09:46	Workshop Invoice	1	Load PDF	

Linked Accident Report Documents

				View	View In Browser
Assessment Reports					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	24/11/17 10:58	Accident Statement	1	Load HTM	
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	24/11/17 10:54	Sketch Plan	1	Load TIF	
2	24/11/17 10:54	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022817/GBE2

Date: 03/01/2018

REFERENCE

Insured/Claimant: HIA KIM HON Policy No: S28853522SMF
Date of Loss: 18/11/2017 Nature of Claim: OD Claim No: 538327

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC3045T**
Make & Model: MAZDA RX-8, 1.3 (A) Engine No: 13B529091
Reg. Date: 30/08/2007 (Man. Year: 2007) Chassis No: SE3P142243
Colour: Grey Odometer: 0 km
Engine Capacity: 1308 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,056.11	23,644.89	6,411.22	21.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	2,130.00	500.00	19.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,686.11	25,774.89	6,911.22	21.14
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	31,186.11	24,274.89	6,911.22	22.16

INSPECTION

Date of Assignment: 01/12/2017
Date Inspected: 01/12/2017 Inspected At: Fuji Motorsports Automotive Pte Ltd (HQ)
48 Toh Guan Road East, #01-115
Enterprise Hub
Singapore 608586
Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Jan 2018)
Parts: M1-COUPE MAZDA RX-8 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC3045T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	6		*APEX SEALS	Necessary	831.00 F	*831.00 FL
2	6		*APEX SEALS SPRING	Necessary	129.60 F	*129.60 FL
3	12		*SIDE SEALS	Necessary	834.00 F	*834.00 FL
4	12		*SIDE SEALS SPRING	Necessary	150.00 F	*150.00 FL
5	12		*CORNER SEALS	Necessary	448.80 F	*448.80 FL
6	12		*CORNER SEALS SPRING	Necessary	60.00 F	*60.00 FL
7	1		*FRONT SIDE WALL	Dented	1,860.00 F	*1,860.00 FL
8	1		*INTERMEDIATE SIDE WALL	Dented	2,006.91 F	*2,006.91 FL
9	1		*REAR SIDE WALL	Dented	1,830.00 F	*1,830.00 FL
10	2		*ROTOR HOUSING	Distorted	5,086.60 F	*5,086.60 FL
11	2		*ROTOR	Distorted	4,808.20 F	*4,808.20 FL
12	1		*CRANK SHAFT	Distorted	1,980.00 F	*1,980.00 FL
13	1		*SET OVERHAUL KIT (O-RINGS)	Necessary	690.10 F	*690.10 FL
14	1		*OVERHAUL CASKET	Necessary	401.30 F	*401.30 FL
15	1		*ROTOR CENTER RING (INNER)	Necessary	112.80 F	*112.80 FL
16	1		*OIL METERING PUMP	Distorted	2,993.50 F	*2,993.50 FL
17	1		*UPPER O2 SENSOR	Not Working	1,187.00 F	*1,187.00 FL
18	1		*LOWER O2 SENSOR	Not Working	387.70 F	*387.70 FL
19	1		*AIR FILTER	Stained	120.00 F	*120.00 FL
20	1		*AIR FLOW SENSOR	Not Working	735.60 F	*735.60 FL
21	1		*CATALYTIC CONVERTER (USED)	Distorted	1,900.00 FS	*1,200.00 FS
22	1		*EXHAUST (USED)	Distorted	600.00 FS	*400.00 FS
23	4		*SPARK PLUG	Necessary	550.00 F	*550.00 FL
24	1		*5L ENGINE OIL	Necessary	158.00 F	*158.00 FL
25	1		*8L COOLANT	Necessary	180.00 F	*180.00 FL
26	1		*OIL FILTER	Necessary	15.00 F	*15.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,056.11	29,156.11
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	5,511.22
Total Parts (\$\$)	30,056.11	23,644.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR OVERHAUL	New	2,500.00	2,000.00
2	TOWING CHARGE	New	130.00	130.00
Gross Labour Cost (\$\$)			2,630.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >