



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SJC 7066 E

Parts	(a) Cost / List Price Items	\$	7,179.14
	Plus/Less 25%	\$	1,794.79
	Total of Cost / List	\$	5,384.36
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	5,679.36
Labour		\$	4,080.00
Total		\$	9,759.36

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
Company : _____
Survey conducted on : 30/11/17 at 3:30 pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SJC 7066 E**
Make & Model : **TOYOTA VIOS**
Chassis No : **MR053HY9305048891**

Submit By : **Carmen Lim**
Year Manufacture : **2008**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$200.00	S.N. ← <i>skt</i>	
2	Rear number plate	1	\$45.00 <i>40</i>	S.N. ← <i>bt</i>	
3	Rear No.plate lamp LH	1	\$56.75 <i>✓</i>	<i>skt</i>	
4	Rear No.plate lamp RH	1	\$56.75 <i>✓</i>	<i>skt</i>	
5	Rear bumper	1	\$451.90 ←	<i>det</i>	
6	Rear bumper clip	10	\$40.00 ←	<i>nk</i>	
7	Rear bumper side retainer LH	1	\$84.90 ←	<i>dis</i>	
8	Rear bumper side retainer RH	1	\$84.90 ←	<i>dis</i>	
9	Rear bumper bracket LH	1	\$76.70 ←	<i>dis</i>	
10	Rear bumper bracket RH	1	\$76.70 ←	<i>dis</i>	
11	Rear bumper reflector LH	1	\$90.70 ←	<i>org</i>	
12	Rear bumper reflector RH	1	\$90.70 ←	<i>org</i>	
13	Bootlid	1	\$861.60 ←	<i>bt</i>	
14	Bootlid lock	1	\$152.70 ←	<i>bt</i>	
15	Bootlid hinge LH	1	\$96.75 <i>✓</i>	<i>R</i>	
16	Bootlid hinge RH	1	\$96.75 <i>✓</i>	<i>R</i>	
17	Bootlid emblem	1	\$46.15 ←	<i>nk</i>	
18	Wording "VIOS"	1	\$44.17 ←	<i>nk</i>	
19	Wording "E"	1	\$39.28 ←	<i>nk</i>	
20	Bootlid garnish	1	\$145.75 ←	<i>dis</i>	
21	Tail end panel	1	\$668.10 ←	<i>bt</i>	
22	Tail end panel garnish	1	\$200.76 ←	<i>dis</i>	
23	Tail end panel garnish clip	8	\$14.00	<i>nk</i>	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SJC 7066 E**
Make & Model : **TOYOTA VIOS**
Chassis No : **MR053HY9305048891**

Submit By : **Carmen Lim**
Year Manufacture : **2008**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip	1	\$196.50 ✓	JPC	
25	Tail lamp LH	1	\$358.50 ✓	arg	
26	Tail lamp RH	1	\$358.20 ✓	CVC	
27	Tail lamp clip	2	\$5.00 ✓	nan	
28	Spare tyre well panel	1	\$696.70 x	R	
29	Spare tyre board	1	\$189.60 ✓	dis	
30	Exhaust chrome surround	1	\$95.04 x	mc	
31	Rear windscreen moulding	1	\$90.35 x	NH	
32	Rear windscreen sealant	1	\$50.00	S.N x NH	
33	LH rear fender	1	\$856.62	x R	
34	RH rear fender	1	\$856.62	x R	
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SJC 7066 E** Submit By : **Carmen Lim**
Make & Model : **TOYOTA VIOS** Year of Manufacture : **2008**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BOOTLID,RR BUMPER,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,600.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BOOTLID,RR BUMPER,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,400.00	1100
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To remove & refit rear windscreen.	\$120.00	X
6	To tuff coat	\$250.00	80
7	To remove & refit exhaust system to assist work load.	\$150.00	X
8	To transfer boot mechanism to new boot	\$120.00	40
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X
10	To remove & refit reverse sensor	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

HSR 48012

Not Author
W/S Repair
After Painted
W/S Auto with
9wdays. 30/11/2017.