

Thurs 07/12 @ 8am
S&R

SGK6611G

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 NOV 2017

Estimate No. : b1 45009
Date Estimated : 30/11/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ong Vincent
18 Dunbar Walk

Singapore 459299

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGK6611G	L597050	11/01/2013	X6 xDrive35i	0

DESCRIPTION

To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident

1700 2,125.00

To respray rear bumper and tail panel

1602 1,781.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 4,340.00

DESCRIPTION

BODY NUT *rec*
Blind rivet *rec*
RR BUMPER CARRIER *bt*
MOUNT BUMPER REAR CENTRE ?
RR BUMPER LH MOUNT ?
RR BUMPER RH MOUNT ?
RR BUMPER COVER BOTTOM *de*
RR BUMPER BOTTOM TRIM PANEL *de*
SHOCK ABSORBER REAR LEFT *lra*
SHOCK ABSORBER REAR RIGHT ?
RR BUMPER LH LOWER TRIM PANE ?
RR BUMPER RH LOWER TRIM PANE ?
RR BUMPER (PRIMED) *de*
HEAT RESISTANT PLATE *bt*
BLIND RIVET *rec*

QTY	PRIC	VALUE
10	0.90	9.00
6	3.70	22.20
1	689.85	689.85
1	244.00	244.00
1	141.65	141.65
1	141.65	141.65
1	376.90	376.90
1	247.45	247.45
1	59.60	59.60
1	59.60	59.60
1	117.85	117.85
1	117.85	117.85
1	1,502.20	1,502.20
1	53.45	53.45
4	1.20	4.80

Total Parts : 3,788.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45009
Date Estimated : 30/11/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGK6611G	L597050	11/01/2013	X6 xDrive35i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>7111704</u>	Claim No. _____
Date&Time <u>7/11/17 @ 4pm</u>	Excess S\$ _____
Surveyor's Name <u>Tanphk</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97405749</u>	Authorised Yes / No _____
Authorised Date <u>wp</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ P.M.L. Yes / No _____	
Surveyor's E-mail <u>tanphk@tkkanderson.com</u>	
No. of Working Days Recommend <u>4 days</u>	

Labour 1	:	4,340.00
Parts	:	3,788.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	568.96
Grand Total	:	<u>8,697.01</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **