

INS. CASE OWNER:

Gerald

CC 4/LPC170 2 2824 1 A ea 302

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

30/11/17

Date / Time:

30/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKC 5339U

Name of Insured:

PENG HUI HUANG

Insured Tel No.:

HP: 9667 3329

Excess Sec II :SS

D.O.A: 28/11/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: YEO YI HONG

Driver Tel No.: 8500 7658

(V/L: YES / NO)

Claim No.:

17/17/17/VC30/020244

Policy No.:

Z17VP05015804

Make / Model:

VOLKSWAGEN GOLF - 1.4 GTI (A)

Place of Accident:

CP ENTRANCE AT BLK 601A
MSCP & JURONG WEST ST 625

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLN 9775Y



INSRS:

WSP: Pegasus

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLN 9775Y - CS3/GAI17021590/46 DOA 07/11/17

SKC 5339U - X

14/12/17 (Ahr) *NO ESTIMATE & PA.

18/01/18

Email WSP Liability Claim.

8.5.18

FILE PASS TO TYPST TO PREPARE REPORT.

RECEIVED 24 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: TP PIR

PRELIMINARY ADVICE Date/Time: 8.5.18

Sent By: Ash.

FINALIZATION

Date/Time:

Confirm with: P1

Confirm by: ADRIAN

Repair Cost:

45 S\$2,150

(4 days)

Reduction:

61 %

Email

Call

FINAL SETTLEMENT

Date/Time: 22.6.18

Confirm with: P1

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

90

If NO or B 28, Ass. Lia:

Repair Cost:

P/WS

S\$2,300.50

OLD MAKING A RM TURN

INTO THE MAIN ROAD.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

C only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$5.35

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$2,305.85

Global Sum S\$:

FINAL PAYMENT

Date/Time: 22.6.18

Confirm with: P1

Email

Call

Payee 1:

S\$2,305.85

Name 1:

PEGASUS ENGINEERING & TRAINING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: P450




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC17022824/Aea3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 30-11-2017	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 5339U	Veh. Inspected	SLN 9775Y
Policy No.	Z17VP05015804	Coverage (\$)	0.00
Claim No.	17/17/17/VC30/020244	Excess (\$)	0.00
Assign From		Assign Date	30/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/11/2017	Inspection Date	30/11/2017
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT, WESTVILLE SINGAPORE 648541		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 30 November, 2017 9:12 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: Third Party Survey - SLN9775Y Your insured - SKC5339U DOA 28.11.2017
Attachments: 29112017185936.pdf

Our Ref : 17/17/17/VC30/020243

Dear Catherine,

Kindly proceed to survey on without prejudice.

Our insured is also pursuing a third party claim.

As the accident was capture by the video from SLN9775Y, please obtain the video footage for our viewing.

30-11-2017 @ 10.03am
Lingling veh in
Get Adrian

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]
Sent: Wednesday, 29 November, 2017 7:02 PM
To: MT_Claim_SG
Subject: Third Party Survey - SLN9775Y Your insured - SKC5339U DOA 28.11.2017

Your Ref: SKC5339U

Our Ref: SLN9775Y

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.
We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Please arrange for a Pre-Repair Inspection under the NIMA Protocol and confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favourable reply.

Please arrange for survey as soon as possible, vehicle is in.
Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLN9775Y
Vehicle to be Exported	Yes
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS 1.5E CVT
Primary Colour	Silver
Manufacturing Year	2017
Engine No.	2NRX157305
Chassis No.	MHFB29F3X02011637
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$12,855.00
Original Registration Date	24 May 2017
First Registration Date	24 May 2017
Transfer Count	0
Actual ARF Paid	\$7,855.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 May 2027
PARF Rebate Amount	\$5,891.00

Intended COE Rebate Details

COE Expiry Date	23 May 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,000.00
COE Rebate Amount	\$41,600.00
Total Rebate Amount	\$47,491.00

The information contained herein is correct as at 29 Nov 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLN9775Y
Vehicle to be Exported	Yes
Intended De-registration Date	29 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS 1.5E CVT
Primary Colour	Silver
Manufacturing Year	2017
Engine No.	2NRX157305
Chassis No.	MHFB29F3X02011637
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$12,855.00
Original Registration Date	24 May 2017
First Registration Date	24 May 2017
Transfer Count	0
Actual ARF Paid	\$7,855.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 May 2027
PARF Rebate Amount	\$5,891.00
Intended COE Rebate Details	
COE Expiry Date	23 May 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,000.00
COE Rebate Amount	\$41,600.00
Total Rebate Amount	\$47,491.00

The information contained herein is correct as at 29 Nov 2017

OK

Third Party Insurer : Lonpac
Insured's Veh No : SKC5339U
Date of accident : 28.11.2017

Messrs Grab Rentals Pte Ltd

Lkk
Date : 29.11.2017

Estimate To Repair : Toyota Vios 1.5E CVT
Vehicle No : SLN9775Y
Chassis No : MHFB29F3X02011637

TP Lonpac
Asher

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	front bumper <i>rehd</i>	\$ 427.90	\$ 427.90
2	1 pc	front bumper reinforcement <i>Best</i>	\$ 379.20	\$ 379.20
3	1 pc	o/s front bumper side retainer <i>m</i>	\$ 65.70	\$ 65.70
4	1 pc	front bumper centre grille <i>rehd</i>	\$ 276.20	\$ 276.20
5	1 pc	front bumper centre grille tow cover <i>rehd</i>	\$ 52.40	\$ 52.40
6	10 pc	front bumper clips <i>m</i>	\$ 4.30	\$ 43.00 <i>30</i>
7	2 pc	front bumper chrome garnish <i>cut</i>	\$ 66.80	\$ 133.60
8	1 pc	front bumper emblem badge <i>new</i>	\$ 97.40	\$ 97.40
9	1 pc	front bumper outer garnish <i>rehd</i>	\$ 87.80	\$ 87.80
10	6 pc	front bumper outer garnish clips <i>m</i>	\$ 5.00	\$ 30.00 <i>10</i>
11	1 pc	front bumper spot light garnish <i>new m</i>	\$ 56.60	\$ 56.60 <i>+</i>
12	1 pc	front bumper lower splashshield cover <i>rehd new</i>	\$ 209.10	\$ 209.10 <i>+</i>
13	1 pc	o/s front fender <i>Repair</i>	\$ 612.50	\$ 612.50 <i>+</i>
14	1 pc	o/s front fender inner cowling <i>new m</i>	\$ 155.00	\$ 155.00 <i>+</i>
15	6 pc	front fender inner cowling clips <i>new/m</i>	\$ 4.30	\$ 25.80 <i>+</i>
16	1 pc	o/s head lamp <i>cut</i>	\$ 588.10	\$ 588.10 <i>+</i>
17	1 pc	o/s head lamp panel <i>Repair</i>	\$ 270.30	\$ 270.30 <i>+</i>
18	1 pc	front bumper air guide top <i>rehd</i>	\$ 77.00	\$ 77.00 <i>—</i>
19	1 pc	front bumper air guide bottom <i>rehd</i>	\$ 59.70	\$ 59.70 <i>—</i>
20	1 pc	front brace panel <i>new m</i>		\$ - <i>+</i>
21	1 pc	bonnet - repair <i>Repair</i>	\$ 757.30	\$ 757.30 <i>+</i>
22	1 pc	front support panel - repair <i>Repair</i>	\$ 494.80	\$ 494.80 <i>+</i>
				\$ 4,899.40
		Less 25 %		\$ 1,224.85
				\$ 3,674.55
SPECIAL NETT ITEMS				
23	1 pc	front licence plate <i>Best</i>	\$ 80.00	\$ 80.00 <i>60</i>
				\$ 80.00
LABOUR & MISC. CHARGES				
1		To check electrical lighting concerned.		\$ 60.00 <i>30</i>
				\$ 60.00
		Grand Total		\$ 3,814.55

Messrs Grab Rentals Pte Ltd

Date : 29.11.2017

Estimate To Repair Toyota Vios 1.5E CVT
Vehicle No : SLN9775Y
Chassis No : MHFB29F3X02011637

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 3,814.55
		<u>LABOUR & MISC. CHARGES</u>		
2		To rust-proofing of the affected areas.		\$ 100.00
3		To check steering geometry and computer wheel alignment.		\$ 150.00
4		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	930	\$ 700.00
5		Putty and spray painting of the affected portion.		\$ 850.00
				\$ 1,700.00
				5614.55
		Grand Total		\$ 5,514.55

h/s Adrian L
30/11/17.
04 ap

total: 2703.75
h/s: 2150

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 18 December, 2017 11:46 AM
To: 'Pegasus Engineering'
Cc: Vic (LKKAuto)
Subject: Accident Involving SLN 9775Y & SKC 5339U on 28/11/2017

WITHOUT PREJUDICE

Your Ref: SLN 9775Y
Our Ref: CC4/LPC17022824/Aea3

Dear Sir/Madam,

Accident Involving SLN 9775Y & SKC 5339U on 28/11/2017

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**GREAT AMERICAN INSURANCE COMPANY**

UEN: T15FC0029B GST REG. NO.: M90370081T
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: +65 6804 6000
FAX: +65 6235 2616

MOTOR COVER NOTE: MTGRAB20171534

The Insured mentioned in this Covernote, having proposed for insurance in respect of the Motor Vehicle described, is hereby **HELD COVERED** under the terms of the Insurer's usual form of Motor Policy applicable thereto for the period mentioned unless the cover be terminated by the Insurer by notice in writing in which case the Insurance will thereupon cease and a proportionate part of the annual premium payable for such insurance will be charged for the time the Company has been on risk.

The Insurer	: GREAT AMERICAN INSURANCE COMPANY
The Insured	: Grab Rentals Pte. Ltd.
Insured Nric/Passport No/ Roc	: 201617200G
Policy Coverage	: Comprehensive
Make And Description Of Vehicle	: Toyota Vios
Vehicle Registration No.	
Year Of Manufacture	: 2017
Engine No.	: 2NRX157305
Chassis No.	: MHFB29F3X02011637
Engine Capacity/ Tonnage/ Seater	: 1496 cc
Hire Purchase	: HL Bank
Value (S\$)	: Market Value of Insured Vehicle at Time of Loss
Period Of Insurance	: From 24/05/2017 to 23/05/2018
Excess (S\$)	: All Claims Excess – S\$2,000.00 Windscreen Excess – S\$100.00
Great American Authorised Workshop	: Authorised Workshop

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA)

Note: This Cover Note is only valid for 60 days from the date of issuance unless replaced by the Certificate of Insurance issued by the Company.

For and on behalf of Great American Insurance Company

Great American Insurance Company
Authorised Signatory

Date of Issue : 11/05/2017
Intermediary : Citrine Systems (S) Pte Ltd (Grab Leasing)

MTR/COVERNOTE/V02/16



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC17022824/Aea3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-07-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 5339U	Veh. Inspected	SLN 9775Y
Policy No.	Z17VP05015804	Coverage (\$)	0.00
Claim No.	17/17/17/VC30/020243	Excess (\$)	0.00
Assign From	GERALD	Assign Date	30/11/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3X02011637	Colour	SILVER
Odometer	43715	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2017	Inspection Date	30/11/2017
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT, WESTVILLE SINGAPORE 648541		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 9775Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	427.90	427.90
1	FRONT BUMPER REINFORCEMENT	BENT	379.20	379.20
1	O/S FRONT BUMPER SIDE RETAINER	NECESSARY	65.70	65.70
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	276.20	276.20
1	FRONT BUMPER CENTRE GRILLE TOW COVER	DEFORMED	52.40	52.40
10	FRONT BUMPER CLIPS @\$4.30	NECESSARY	43.00	30.00
2	FRONT BUMPER CHROME GARNISH @\$66.80	CUT	133.60	133.60
1	FRONT BUMPER EMBLEM BADGE	NECESSARY	97.40	97.40
1	FRONT BUMPER OUTER GARNISH	DEFORMED	87.80	87.80
6	FRONT BUMPER OUTER GARNISH CLIPS @\$5.00	NECESSARY	30.00	10.00
1	FRONT BUMPER SPOT LIGHT GARNISH	NOT NECESSARY	56.60	-
1	FRONT BUMPER LOWER SPLASHIELD COVER	NOT NECESSARY	209.10	-
1	O/S FRONT FENDER	TO REPAIR SEE LABOUR	612.50	-
1	O/S FRONT FENDER INNER COWLING	NOT NECESSARY	155.00	-
6	FRONT FENDER INNER COWLING CLIPS @\$4.30	NOT NECESSARY	25.80	-
1	O/S HEAD LAMP	CUT	588.10	588.10
1	O/S HEAD LAMP PANEL	TO REPAIR SEE LABOUR	270.30	-
1	FRONT BUMPER AIR GUIDE TOP	DEFORMED	77.00	77.00
1	FRONT BUMPER AIR GUIDE BOTTOM	DEFORMED	59.70	59.70
1	FRONT BRACE PANEL (NPA)	NOT NECESSARY	-	-
1	BONNET	TO REPAIR SEE LABOUR	757.30	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	494.80	-
	LESS 25% DISCOUNT		-1,224.85	-571.25
			3,674.55	1,713.75
SPECIAL NETT ITEMS				
1	FRONT LICENCE PLATE (SN)	BENT	80.00	60.00
			80.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	150.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME .INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER,O/S HEAD LAMP PANEL ,BONNET AND FRONT SUPPORT PANEL .		700.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		850.00	500.00
			1,860.00	930.00
	GRAND TOTAL		5,614.55	2,703.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00

Report Ref No. CC4/LPC17022824/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.