

29 Nov. 2017

EQ INSURANCE Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : | Quotation

Vehicle **SJC8605T (Nissan Latio)**

Not Notched
i Lyr 8?
Resurvey After Paint
4 days

S/N	Description	Amount (\$\$)
	Parts Replacement	
	Rear bumper	\$ 678.90
	Rear bumper spoiler	\$ 548.20
	Rear bumper retainer left	\$ 45.20
	Rear bumper retainer right	\$ 45.20
	Rear tailEnd Panel	\$ 639.30
	Rear left lamp panel	\$ 276.20
	Boot lid lock	\$ 178.90
	Boot lib catch	\$ 78.50
	Boot rubber	\$ 165.80
	Rear end panel garnish	\$ 269.60
	Rear exhaust	\$ 692.20
	Tail lamp left	\$ 328.80
	Rear boot hinges (left).	\$ 89.70
	Sub Total:	\$ 4,036.50
	Less 20% 308	\$ 3,228.00
	1 set rear reverse sensor (nett)	\$ 200.00
	Labour Charges	
	To remove and renew and reweld rear bumper assy. new boot lid assy.	
	Cut and reweld rear panel,floor panel.	\$ 1,800.00
	To remove and refix upholstery to facilitate repair	\$ 100.00
	To remove both tail lamps,rear reverse sensor assy.check wiring system to facilitate repair and the same.	\$ 90.00
	To rustproofing on the affected area	\$ 200.00
	To putty and spray paint on rear panel and new parts.	\$ 900.00
	Total:	\$ 6,518.00

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LKK Auto Consultant has notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: