

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

30 NOV 2017

Estimate No. : b1 45000	Page No. : 1 of 2
Date Estimated : 29/11/2017	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Law Vivian Hoi Yuen 50 Coronation Road West #03-06 Astrid Meadows Singapore 269264	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF184R	VP95246	24/04/2012	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace rear bumper and attachments	850 1,700.00
Painting rear bumper.	939 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
Sundries. ?	80.00
Total Labour 1:	3,172.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER TOW HOOK COVER (SET) X	1	43.55	43.55
RR BUMPER CTR GUIDE ?	1	61.35	61.35
RR BUMPER LOWER COVERING ? ✓ SCR	1	20.45	20.45
RR BUMPER LH GUIDE ?	1	55.55	55.55
RR BUMPER RH GUIDE ?	1	55.55	55.55
RR BUMPER (PRIMED) ✓ cut	1	811.10	811.10
RR BUMPER BOTTOM (XLINE/PDC) ✓ SCR	1	314.45	314.45
TRIM EXHAUST SYSTEM ?	1	35.50	35.50
RR BUMPER LH REFLECTOR X	1	34.35	34.35
DECOUPLING RING PDC TORQUE CONVERTE ✓ NEC	4	4.95	19.80
BUMPER PDC SENSOR (SCHWARZ)- ELBOW ?	2	231.10	462.20
Total Parts :			1,913.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45000
Date Estimated : 29/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKF184R	VP95246	24/04/2012	X1 sDrive18i	0

Sebastian.
22/12/2017.

- Part by part repair.
- Question Mark Iron Photo.
- Photo Before Paint.

90036121

sebastianyeang@lkkauto.com.

4 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,172.00
Parts	:	1,913.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	356.01
Grand Total	:	5,441.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **